EXHIBIT A

NHTSA ID No.	. make	model	year	failure_date	full_text
10915473	BUICK	ENCLAVE	2014	2016-06-25	TL* THE CONTACT OWNED A 2014 BUICK ENCLAVE. WHILE DRIVING INTO AN INTERSECTION, THE DRIVER'S SIDE OF THE CONTACT'S VEHICLE WAS STRUCK BY AN ONCOMING VEHICLE. THE CONTACT'S VEHICLE SPUN OFF THE ROAD AND LANDED IN A DITCH. THE FRONT END AND DRIVER'S SIDE OF THE VEHICLE WERE SEVERELY DAMAGED. THE CONTACT WAS UNABLE TO RECALL THE DETAILS OF THE CRASH. THE AIR BAGS DID NOT DEPLOY. THE CONTACT WAS INFORMED THAT THE SEAT BELT FAILED TO LOCK AND PROPERLY RESTRAIN HIM. THE VEHICLE WAS TOWED AND TOTALED. A POLICE REPORT WAS FILED. THE CONTACT RECEIVED INJURIES TO THE RIBS, CLAVICLE, AND SHOULDER, WHICH REQUIRED MEDICAL ATTENTION. THE APPROXIMATE FAILURE MILEAGE WAS 40,000.
10995504	BUICK	ENCORE	2014	2017-06-15	I TOOK MY VEHICLE INTO THE SERRA DEALERSHIP IN WASHINGTON, MI ON 3/20/17 TO HAVE THE FRONTAL AIRBAG AND PRETENSIONER NON DEPOY SAFETY RECALL (16007) REPAIRED. ON, 6/15/17, I WAS IN A CAR ACCIDENT TRAVELING AT ROUGHLY 50 MPH AND MY AIRBAGS DID NOT DEPLOY. A FORD F-150 TURNED INTO ONCOMING TRAFFIC WITHOUT LOOKING CAUSING THE FRONT OF MY VEHICLE TO CRASH INTO THE SIDE OF HER TRUCK. THE OTHER DRIVER WAS ISSUED THE CITATION FROM THE POLICE. MY BUICK ENCORE IS MOST LIKELY TOTALED (AWAITING CONFIRMATION ON THAT).
10726387	CADILLAC	SRX	2014	2015-06-17	I WAS IN A SEVERE CRASH AND SUFFERED A SEVERE CONCUSSION. MY RIBBON FLEW OFF MY HEAD WHEN I CAME TO, I DID LOSE CONSCIOUSNESS AND WOKE UP TO ON STAR TELLING ME MY VEHICLE WAS IN A CRASH. I HAVE SEVERE PAIN IN MY NECK SHOULDER, ABRASIONS TO THE LEFT SIDE OF MY BODY AND BRUISING. THE VEHICLE IS TOTALED BUT THE AIRBAG NEVER DEPLOYED AND IT SHOULD HAVE WITHOUT A DOUBT. THERE WAS SEVERE DAMAGE TO THE ENTIRE VEHICLE.
					TL* THE CONTACT OWNS A 2014 CADILLAC SRX. WHILE DRIVING 65 MPH, THE CONTACT LOST CONTROL OF THE VEHICLE AND IT VEERED OFF THE ROAD IN BOTH DIRECTIONS AND CRASHED. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT DID NOT SUSTAIN INJURIES. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A DEALER WHERE IT WAS DIAGNOSED THAT THE REAR DRIVER SIDE CONTROL ARM NEEDED TO BE REPLACED. THE VEHICLE WAS REPAIRED. THE VEHICLE WAS PREVIOUSLY REPAIRED UNDER NITSA CAMPAIGN NUMBER: 14V571000 (SUSPENSION). THE
10871604	CADILLAC	SRX	2014	2016-05-27	MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 32,000.
10615335	CHEVROLET	EQUINOX	2014	2014-05-24	TL* THE CONTACT OWNS A 2014 CHEVROLET EQUINOX. THE CONTACT STATED THAT WHILE DRIVING 16 MPH, THE CONTACT CRASHED INTO THE DRIVER'S SIDE DOOR OF ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED CHEST, RIGHT KNEE, SHOULDER AND SPINE INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE VEHICLE WAS NOT REPAIRED. THE FAILURE MILEAGE WAS UNKNOWN.
10864509	CHEVROLET	EQUINOX	2014	2016-05-05	I BOUGHT MY 2014 CHEVY EQUINOX NEW. I WAS IN CRASH WHICH I HIT A FULL SIZE CHEVY TRUCK IN THE DRIVER DOOR AND IT TOTALED MY CAR AND NOT ONE AIR BAG CAME. I WAS CROSSING EAST AND WEST THE TRUCK WAS GOING NORTH TO SOUTH
10915132 11124021	CHEVROLET CHEVROLET	EQUINOX EQUINOX	2014	2016-09-08	WAS INVOLVED IN ACCIDENT 9/8/2016. IT WAS A TOTAL LOSS. FRONT END HEAVILY DAMAGED. AIRBAGS DID NOT WORK OR THE PASSENGER SIDE SEATBELT. DRIVING STRAIGHT AT INTERSECTION AND OTHER PARTY RAN RED LIGHT STRIKING THE LEFT FRONT AND CAUSING FRAME TO CRACK. I HIT A DEER ON SEPT. 1, 2018 AND MY AIRBAGS DIDN'T DEPLOY.
11186171	CHEVROLET	EQUINOX	2014	2019-03-05	VEHICLE WAS IN MOTION TRAVELING STRAIGHT GOING APPROXIMATELY 50MPH WHEN IT STRUCK ANOTHER VEHICLE THAT FAILED TO YIELD THE RIGHT OF WAY. THE EQUINOX SUFFERED EXTENSIVE FRONT END DAMAGE ON THE DRIVERS SIDE BUT NO AIRBAGS DEPLOYED.
11376003	CHEVROLET	EQUINOX	2014	2020-11-16	I WAS INVOLVED IN A CAR ACCIDENT ON NOVEMBER 16, 2020 AND NEITHER OF MY AIRBAGS DEPLOYED. MY WIFE & SISTER WERE RUN OFF THE ROAD . THEY WENT UP A DITCH & HIT A COLVURT . THE SEATBELTS DID NOT LOCK IN PLACE & AIR BAGS DID NOT INFLATE . THIS WAS A LOANER TRUCK
10599029	CHEVROLET	SILVERADO	2014	2014-06-10	FROM DEALER . IT WAS A 2014 4 DOOR CHEVY SILVERADO FROM LUCAS CHEVY IN COLUMBIA TN. 38401 . I THINK THE WAS SOME SORT OF TROUBLE WITH THIS HAPPENING . PLEAS CALL FOR COMPLETE INFO ON THIS . *TR
10695408	CHEVROLET	SILVERADO	2014	2015-02-18	TL* THE CONTACT OWNED A 2014 CHEVROLET SILVERADO. WHILE DRIVING APPROXIMATELY 60 MPH, THE CONTACT REACHED OVER TO TURN THE HEAT OFF AND THE VEHICLE WENT OFF THE ROAD, DOWN A HILL, AND INTO A DITCH. THE VEHICLE CONTINUED ON UNTIL IT CRASHED INTO A CABLE THAT WAS CONNECTED TO A TELEPHONE POLE. THE TELEPHONE POLE SPLIT IN HALF. THE SEAT BELT FAILED TO RESTRAIN THE CONTACT AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO HIS BACK, KNEE, AND HIP THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED AND TOWED TO A LOT. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 7,956.

10712235	CHEVROLET	SILVERADO	2014	2015-03-21	TL* THE CONTACT OWNS A 2014 CHEVROLET SILVERADO. WHILE DRIVING AT APPROXIMATELY 70 MPH, THE VEHICLE STRUCK A DEER ON THE HIGHWAY. THE FRONT AND REAR AIR BAGS FAILED TO DEPLOY. THERE WERE NO INJURIES AND A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS TAKEN TO A DEALER, BUT WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 8,000.
					TL* THE CONTACT OWNS A 2014 CHEVROLET TRAVERSE. WHILE DRIVING 45 MPH, THE CONTACT CRASHED INTO THE REAR PASSENGER QUARTER PANEL OF A HONDA ACCORD. THERE WERE NO WARNING INDICATORS ILLUMINATED. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED NECK AND BACK INJURIES, WHICH DID NOT REQUIRE MEDICAL ATTENTION. THE TWO OCCUPANTS OF THE HONDA SUSTAINED UNKNOWN INJURIES, WHICH REQUIRED MEDICAL ATTENTION AT THE SCENE. A POLICE REPORT WAS FILED. THE VEHICLE WAS TAKEN TO AN INDEPENDENT MECHANIC, BUT WAS NOT DIAGNOSED OR REPAIRED. THE LOCAL DEALER AND MANUFACTURER WERE NOT
11129851	CHEVROLET	TRAVERSE	2014	2018-09-15	CONTACTED. THE FAILURE MILEAGE WAS APPROXIMATELY 62,000. THE VIN WAS NOT AVAILABLE. TL* THE CONTACT OWNED A 2014 GMC TERRAIN. THE CONTACT STATED THAT WHILE DRIVING AT APPROXIMATELY 10 MPH AND MAKING A LEFT TURN, ANOTHER VEHICLE CRASHED INTO THE VEHICLE HEAD ON. THE FRONTAL AIR BAGS DID NOT DEPLOY. THE POLICE AND FIRE DEPARTMENT
10909600	GMC	TERRAIN	2014	2016-09-18	WERE PRESENT. NO INJURIES WERE REPORTED. THE VEHICLE WAS DESTROYED AND TOWED TO A COLLISION LOT. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 27,448.
10608599	GMC	YUKON	2014	2014-07-04	I HAD A FRONT END COLLISION AT 25 MPH WITH A PARKED CAR. MY AIRBAG(S) DID NOT DEPLOY. THE ENTIRE FRONT END OF MY CAR WAS DESTROYED. THE HOOD WAS CRUMPLED AND BOTH FRONT QUARTER PANELS DAMAGED. THE FRONT DOORS ARE NOT EASILY OPENED DUE TO THE QUARTER PANEL DAMAGE. IT IS HARD FOR ME TO UNDERSTAND HOW AN IMPACT AT THE SPEED I WAS TRAVELING AND THE LOCATION OF IMPACT DID NOT CAUSE THE AIRBAG(S) TO DEPLOY. I HAD TO BE TRANSPORTED VIA AMBULANCE FROM THE SCENE AND SUFFERED A CONCUSSION FROM MY HEAD SLAMMING DOWN ON THE STEERING WHEEL. *JS
					TL* THE CONTACT OWNS A 2013 BUICK ENCLAVE. THE CONTACT STATED THAT WHILE TRAVELING 5 MPH, THE VEHICLE CRASHED HEAD-ON INTO ANOTHER VEHICLE AND THE AIR BAGS DID NOT DEPLOY. THE CONTACT WAS INJURED AND REQUIRED IMMEDIATE MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE
10595132	BUICK	ENCLAVE	2013	2014-05-29	AND CURRENT MILEAGE WAS 11,500. HEAD ON COLLISION AT 40 MPH ON A CITY STREET. AIR BAGS DID NOT DEPLOY AND SEAT MOVED
11352287 10575764	CADILLAC	EQUINOX	2013	2013-11-11	FORWARD. RESULTING IN ER VISIT AND HEAD LACERATION AND LOSS OF CONSCIOUSNESS. HIT A DEER WITH FRONT END OF VEHICLE CAUSING APPROXIMATELY \$6,000 IN DAMAGES. AIRBAGS DID NOT DEPLOY CAUSING CONCUSSION RECEIVED BY DRIVER. DRIVER IS STILL EXPERIENCING MEDICAL PROBLEMS DUE TO THIS ACCIDENT. *TR
10667442	CHEVROLET	EQUINOX	2013	2014-12-14	I WAS INVOLVED IN AN ACCIDENT THAT RESULTED IN DAMAGES OVER \$14,000 TO THE FRONT END OF THE VEHICLE. THE AIR BAGS DID NOT DEPLOY. I HAVE CONTACTED GM TWICE THIS WEEK AND HAVE NOT YET SPOKEN TO ANYONE IN THEIR PRODUCT ASSISTANCE DEPARTMENT. *DT
10958946	CHEVROLET	EQUINOX	2013	2016-11-23	TL* THE CONTACT OWNED A 2013 CHEVROLET EQUINOX. WHILE DRIVING APPROXIMATELY 60 MPH, THE CONTACT'S VEHICLE CRASHED INTO A SECOND VEHICLE. THE FRONT END OF THE VEHICLE SUSTAINED SIGNIFICANT DAMAGE. THE AIR BAGS DID NOT DEPLOY. THE REAR PASSENGER SEAT OCCUPANT SUSTAINED A HEAD INJURY, WHICH REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED. A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS 50,000.
10993565	CHEVROLET	EQUINOX	2013	2017-05-09	"TAMARA RECALL" I'M WRITING REGUARDING AN ACCIDENT THAT TOTALED OUT MY VEHICLE BUT NONE OF MY AIR BAGS DEPLOYED? I HIT A DEER AT 75-80 MPH ON A HWY IT HIT MY DRIVERS SIDE HEADLIGHT AND CONTINUED UP OVER MY HOOD AND ACTUALLY DENTED PART OF MY PASSENGER SIDE FENDER I COULDN'T EVEN OPEN THE DOOR ALL THE WAY! NONE OF MY AIR BAGS WENT OFF. LUCKILY I HAD MY SEAT BELT ON WHICH SOMETHING IN THE SEAT BELT BLEW WHEN IT LOCKED ME IN PLACE DUE TO THE IMPACT OF THE DEER HITTING JUMPING OUT AT ME A WARNING POPPED UP ON MY DASH BELIEVE SAID "LOCKED" BUT ALL HAPPENED SO FAST, IT PUSHED & CRACKED JUST ABOUT EVERYTHING UNDER MY HOOD. I HAD SMOKE COMING FROM MY VEHICLE, FLUIDS ON THE GROUND NO FIRE THANKFULLY! MY SUV WAS TOTALED AND MANY HAVE QUESTIONED ME ABOUT THE AIR BAGS. I'M NOW WONDERING THE SAME THING. WHY IN THE WORLD DID NONE OF THESE GO OFF? IF I WOULDN'T HAVE HAD MY SEAT BELT ON WHO KNOWS WHAT WOULD HAVE HAPPENED WITH THE AIR BAGS NOT GOING OFF! I'VE DONE RESEARCH! HAVEN'T SEEN ANY RECALLS, BUT! AM A LITTLE CONFUSED BY THIS!

				ON TUESDAY MARCH 18, 2014 I WAS DRIVING A 2013 CHEVY SILVERADO AND REAR ENDED A CHEVY TAHAO AT APPROXIMATELY 20 MPH WITHOUT HITTING MY BRAKES. CONDITIONS AT THE TIME WERE CLEAR AND DRY ALTHOUGH VERY WINDY. I WAS THE ONLY PASSENGER IN MY TRUCK. I WAS WEARING MY SEATBELT. I HIT THE STEERING WHEEL WITH MY CHEST. THE ONSTAR SYSTEM CALLED TO SAY THEY COULD SEE I WAS IN AN ACCIDENT AND HELP WAS ON THE WAY. I EXCHANGED INFO WITH THE OTHER DRIVER AND RETURNED TO MY VEHICLE. THE SEATBELT WAS IN THE EXTENDED POSITION AND WOULD NOT EXTEND FURTHER OR RETRACT. ON THE DISPLAY PANEL IT HAD AN 'AIRBAG DEPLOYED' ICON AND MESSAGE 'SERVICE AIRBAG'. MY INSURANCE COMPANY GAVE ME A AUTO REPAIR SHOP TO GO TO FOR AN ESTIMATE, HOWEVER, THE SHOP TOLD ME THEY WOULD NOT TOUCH THE VEHICLE UNTIL A GM REPRESENTATIVE INVESTIGATED THE SYSTEM FIRST AS THEY FELT THE SEATBELT SHOULD HAVE PREVENTED ME FROM HITTING THE STEERING WHEEL. I CALLED GM AND SPOKE WITH WALTER IN CUSTOMER SERVICE. HE ARRANGED TO HAVE A 'THIRD PARTY' INVESTIGATOR COME AND DO A INTERROGATION OF THE SYSTEM AND ARRANGED FOR A LOANER VEHICLE. RAYTHEON REPRESENTATIVE 'JEFF" CALLED ME SUNDAY MARCH 20 AND STATED HE WAS TO INTERROGATE THE SYSTEM AND WOULD CONTACT ME FROM THE AIRPORT WHEN HE GOT TO TOWN ON WEDNESDAY MARCH 23. ON WEDNESDAY MARCH 23 I CALLED JEFF TO SEE IF HE WAS IN TOWN AND HE STATED HE WAS AT THE AIRPORT 'LEAVING' TOWN, HE HAD DONE HIS INVESTIGATION AND DETERMINED EVERYTHING WORKED LIKE IT SHOULD. I ASKED HIM IF I WAS SUPPOSED TO HIT THE STEERING WHEEL AND HE STATED HE DID
CHEVROLET	SILVERADO	2013	2014-03-18	NOT AGREE OR DISAGREE. *TR TL* THE CONTACT OWNS A 2013 CHEVROLET SILVERADO. THE CONTACT STATED WHILE DRIVING
CHEVROLET	SILVERADO	2013	2014-06-08	APPROXIMATELY 35 MPH A DRUNK DRIVER CRASHED INTO THE CONTACT STATED WHILE BRIVING APPROXIMATELY 35 MPH A DRUNK DRIVER CRASHED INTO THE CONTACTS VEHICLE. THE AIR BAGS DID NOT DEPLOY. THE PASSENGER SUSTAINED A BROKEN FOOT AND WAS TAKEN TO THE HOSPITAL. THE APPROXIMATE FAILURE MILEAGE WAS 22,000.
CHEVROLET	TRAVERSE	2013	2016-10-25	ON OCT 25 OF LAST YEAR WE WERE INVOLVED IN A ACCIDENT WHERE WE HIT A CAR BROADSIDED DOING ABOUT 30 MPH CAUSING CONSIDERABLE DAMAGE TO OUR CAR, BOTH MY WIFE AND MYSELF HAD TERRIBLE WHIPLASHES. AND I BELIEVE THAT SOME OF OUR PAIN COULD HAVE BEEN PREVENTED IF THE AIR BAGS WOULD HAVE DEPLOYED WHICH THEY DID NOT DO. WE WERE ON 4 LANE DIVIDED ROAD GOING THROUGH THE TOWN OF CHIEFLAND FL. WE WERE PASSING A SEMI TRUCK WHICH WAS SLOWING DOWN TO MAKE A TURN WHEN A VEHICLE CAME ACROSS THE FRONT OF THE TRUCK AND CONTINUED TO COME INTO OUR LANE WITH NO REGARDS TO STOPPING AND WE HAD NO CHOICE OR TIME TO STOP.
CHEVROLET	TRAVERSE	2013	2017-09-18	HAVE HAD MY VEHICLE IN DEALER TO FIX AIR BAG LIGHT SEVERAL TIMES AND IT IS STILL ON. MY WIFE WAS INVOLVED IN AN ACCIDENT WHERE AIRBAGS SHOULD OF DEPLOYED AND DIDN'T. LUCKILY SHE WAS NOT INJURED.
GMC	TERRAIN	2013	2013-12-13	VEHICLE WAS INVOLVED IN A SEVERE ACCIDENT WHERE THE OTHER DRIVER RAN A STOP SIGN AND HIT TERRAIN CAUSING SEVERE FRONT END AND ENGINE DAMAGE. AIR BAGS FAILED TO DEPLOY. INJURES INCLUDED WERE NECK AND BACK. DAMAGE WAS SEVERE ENOUGH TO CAUSE AIRBAGS TO DEPLOY BUT NEVER DID. HAVING AN INDEPT INSPECTION CONDUCTED AS TO WHY THEY NEVER DEPLOYED. *TR
				WAS DRIVING DOWN HIGHWAY US19 AND COLLIDED WITH ANOTHER VEHICLE AT AT LEAST 40MPH
GMC	TERRAIN	2013	2016-08-15	AND AIRBAGS DID NOT DEPLOY I WAS IN A COLLISION ON 6/21/2019 THAT HAD SEVERE FRONT END OBSTRUCTIONS AND WITH A
				STRONG TOTAL LOSS AS A RESULT. MY AIRBAGS NEVER DEPLOYED. THE VEHICLE WAS IN MOTION
BUICK	ENCLAVE	2012	2019-06-21	ON ASSEMBLY STREET, COLUMBIA SC. I FELL ASLEEP WHILE DRIVING, JUMPED A LEVEE, RAN THROUGH A FENCE, AND WRECKED IN A
CADILLAC	SRX	2012	2014-03-23	GRASSY WATERY AREA. MY ENGINE WAS SMASHED, THE MOTOR MOUNT BROKE, AND MY TIRES ARE PUSHED BACK. MY AIR BAGS DID NOT DEPLOY. MY FACE HIT THE STEERING WHEEL AND MY NOSE IS BROKEN. I WOULD LIKE TO FIND OUT IF THERE IS ANY RECALLS ON THIS CAR. *TR VEHICLE DRIVER AIR BAG DID NOT DEPLOY, NOR ANY OTHER AIR BAG, UPON COLLISION TO REAR
				OF A STOPPED PICK UP TRUCK. SPEED OF OFFENDING VEHICLE WAS APPROXIMATELY 45 MPH. DRIVER SUFFERED CHEST INJURY FROM SEAT BELT. DAMAGE ESTIMATED TO FRONT END EXCEEDS
CADILLAC	SRX	2012	2014-03-27	\$10,000. *TR
CADILLAC	SRX	2012	2014-12-14	MVA WITH TWO IMPACTS; FRONT DRIVER SIDE (SIGNIFICANT IMPACT) AND FRONT OF VEHICLE NO AIRBAGS DEPLOYED. *TR
CADILLAC	SRX	2012	2017-05-31	TWO CARS AHEAD OF ME WAS GOING STRAIGHT AND ALL OF A SUDDEN TURNED INTO A STRIP MALL WITHOUT INDICATOR, THE CAR IN FRONT OF ME SLAMMED ON THEIR BRAKES AND SO DID I, BUT I STILL ENDED UP REAR ENDING THE VEHICLE IN FRONT. I THINK MY SPEED WAS AROUND 30 AT THE TIME OF IMPACT. I HIT MY CHIN TO THE STEERING WHEEL. GOT MULTIPLE CUTS INSIDE OF MY MOUTH. AND COUPLE OF THEM ON MY FACE WHICH REQUIRED STITCHES. MY AIR BAG DID NOT DEPLOY AND NEITHER THE SEATBELT PREVENTED IT, WHICH I THOUGHT WAS ODD. CHECKED WITH CADILLAC IF HEY WERE AWARE OF ANY PROBLEM WITH THE CAR. THEY DENIED THE EXISTENCE OF SUCH AN ISSUE. SO I WANT TO GET THE VEHICLE INVESTIGATED, SO THAT NOBODY ELSE SHOULD GET HURT THE WAY I DID; ALSO I HAVE ANOTHER CADILLAC AND NEED TO KNOW. WILL REALLY APPRECIATE IT. THANKS
	CHEVROLET CHEVROLET CHEVROLET GMC GMC BUICK CADILLAC CADILLAC CADILLAC	CHEVROLET TRAVERSE GMC TERRAIN BUICK ENCLAVE CADILLAC SRX CADILLAC SRX CADILLAC SRX	CHEVROLET TRAVERSE 2013 CHEVROLET TRAVERSE 2013 CHEVROLET TRAVERSE 2013 GMC TERRAIN 2013 BUICK ENCLAVE 2012 CADILLAC SRX 2012 CADILLAC SRX 2012	CHEVROLET TRAVERSE 2013 2016-10-25 CHEVROLET TRAVERSE 2013 2017-09-18 GMC TERRAIN 2013 2013-12-13 GMC TERRAIN 2013 2016-08-15 BUICK ENCLAVE 2012 2019-06-21 CADILLAC SRX 2012 2014-03-23 CADILLAC SRX 2012 2014-03-27 CADILLAC SRX 2012 2014-12-14

			1		
11138938	CADILLAC	SRX	2012	2018-06-25	ON 6/25/18, MY WIFE WAS TRAVELING 45 MPH., IN OUR 2012 CADILLAC SRX. THE VEHICLE IN FRONT OF HER WENT TO MAKE A LEFT TURN INTO A SUBDIVISION. BUT, THEN DECIDED NOT TO DO THAT AND PULLED BACK INTO THE LANE OF MY WIFE. SHE SLAMMED ON HER BRAKES, TO AVOID HITTING THE VEHICLE. HOWEVER, SHE COULDN?T ANTICIPATE THEIR MOVE. SHE HIT THEM FROM BEHIND, GOING 45MPH. SHE HIT HER FOREHEAD ON THE VISOR BAR TWICE, CAUSING A SKULL FRACTURE, BRAIN BLEED, SEVER CONCUSSION, DEEP LACERATIONS, A BURST ARTERY IN HER FOREHEAD TO WHERE SHE WAS BLEEDING HEAVILY AND UNCONSCIOUS. HER CHEST HIT THE STEERING WHEEL, WHICH BADLY BRUISED HER RIBS, CAUSING A HIATAL HERNIA, DUE TO THE IMPACT. SHE SUFFERED LACERATIONS TO HER LEFT ARM, KNEE AND HAS RUPTURED DISCS IN HER CERVICAL SPINE. SHE WAS ICU FOR SEVERAL DAYS DUE TO THE BRAIN BLEED AND HEAD INJURIES SHE SUSTAINED. OUR AIR BAG NEVER DEPLOYED AND THE DRIVER SEAT BELT DIDN?T LOCK ON IMPACT, ALLOWING HER TO BOUNCE UPWARD TWICE AND SUSTAINED THE HEAD INJURIES. THE CADILLAC AIR BAGS AND SEAT LOCKING MECHANISMS FAILED TO PROTECT HER FROM INJURIES SHE SHOULD HAD NEVER HAD. SOMEONE NEEDS TO RESEARCH FURTHER THESE ISSUES FOR THE 2012 SRX SO OTHER CONSUMERS DON?T FEEL SAFE IN A VEHICLE, WHERE THE SAFETY MECHANISMS FAIL. CADILLAC SHOULD NOT BE ABLE TO GET AWAY WITH THIS. SHOULD THE 2012 SRX HAVE A RECALL ON AIR BAGS AND SEAT BELT LOCKING MECHANISMS FAILING? MORE THAN ONE COMPLAINT HAS BEEN POSTED, SO I HOPE THE NHTSA INVESTIGATES THIS FOR US ALL. PLEASE CONSIDER THIS A FORMAL COMPLAINT! THANK YOU, AND PLEASE FOLLOW UP! *TR
11136936	CADILLAC	SILX	2012	2018-00-23	I WAS TRAVELING SOUTH AS ANOTHER CAR WAS TRAVELING NORTH. THE CAR TRAVELING NORTH
10546238	CHEVROLET	EQUINOX	2012	2013-09-20	MADE A RAPID LEFT TURN DIRECTLY IN MY TRAVELING PATH. WE COLLIDED AND MY CAR WAS TOTALED. I HIT THE STEERING WHEEL PRETTY HARD BECAUSE THE AIRBAG DID NOT DEPLOY. HOW SHOULD I PROCEED? *TR
10979985	CHEVROLET	EQUINOX	2012	2017-03-31	I WAS INVOLVED IN AN ACCIDENT WHERE I REAR ENDED A STOPPED VEHICLE. MY CRUISE WAS SET AT 57 MPH AND I DID NOT APPLY BRAKES. BECAUSE CRUISE WAS SET, I HIT ONCE, BOUNCED BACK AND HIT AGAIN. MY AIRBAGS DID NOT DEPLOY AT ALL. THE VEHICLE HAS EXTENSIVE DAMAGE TO THE FRAME BUT NO AIRBAG DEPLOYMENT.
11329614	CHEVROLET	EQUINOX	2012	2020-05-31	TL* THE CONTACT OWNED A 2012 CHEVROLET EQUINOX. THE CONTACT STATED THAT WHILE HER HUSBAND WAS DRIVING ABOUT 25 MPH, HE SUFFERED A MEDICAL CONDITION AND LOST CONTROL OF THE VEHICLE, CRASHING INTO A THREE FEET HIGH CEMENT BOULDER. THE AIR BAGS DID NOT DEPLOY. BOTH THE DRIVER AND THE FRONT PASSENGER SUSTAINED INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE DRIVER AND THE PASSENGER HAD THEIR SEAT BELTS LATCHED AT THE TIME OF THE CRASH. THE VEHICLE WAS TOTALED AND WAS TOWED TO A TOW YARD. THE DEALER AND THE MANUFACTURER WERE NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS APPROXIMATELY 133,000.
10700202	CHEVROLET	SHIVEDADO	2012	2015-09-30	RECENTLY I WAS INVOLVED IN AN ACCIDENT THAT WAS A DIRECT IMPACT. AT THE TIME OF THIS ACCIDENT THE SEAT BELT DID NOT LOCK NOR DID THE AIR BAGS DEPLOY. THE SPEED FROM THIS ACCIDENT WAS BETWEEN 50-55 MPH ON THE HIGHWAY. AT THE RATE OF SPEED I WAS GOING BEFORE THE ACCIDENT AND THE FACT THAT I HAD TO SLAM ON THE BREAKS TO BEGIN SLOWING DOWN ONE WOULD HAVE THOUGHT THE SEAT BELT WOULD HAVE LOCKED BUT IT DID NOT AND AT THE POINT OF IMPACT I WAS VERY SURPRISED THAT THE AIRBAGS DID NOT DEPLOY BUT YET THE SYSTEM INDICATED THAT IT DID AND NEEDED TO BE RESET. HOWEVER NOW THAT THE VEHICLE IS IN PROCESS OF BEING REPAIRED I AM BEING TOLD THAT THE ENTIRE AIRBAG SYSTEM
10790202	CHEVROLET	SILVERADO	2012	2015-09-30	HAS TO BE REPLACED ALONG WITH THE DRIVER SEAT BELT.
					WHILE TURNING LEFT (TAHOE) WITH A PROTECTED GREEN ARROW AT AN X-SHAPED INTERSECTION, VEHICLE (KIA SEDAN) AT FAULT FAILED TO YIELD AND ENTERED THE INTERSECTION AT SPEEDS UPWARDS OF 40 MPH FROM THE LEFT OF THE TAHOE. FRONT-IMPACT COLLISION OCCURRED; DUE TO THE SHAPE OF THE INTERSECTION AND THE VELOCITY OF THE IMPACT, TAHOE STRUCK PASSENGER SIDE OF KIA SEDAN. TRAJECTORY OF IMPACT CAUSED DIRECTIONAL CHANGES IN UPWARDS OF 90* FOR BOTH VEHICLES; THE FORCE OF THE PRIMARY ACCIDENT DESCRIBED ABOVE ALSO CAUSED MENTIONED VEHICLES; TO COLLIDE WITH LEFT REAR OF ANOTHER VEHICLE (HONDA SEDAN), CAUSING NEAR 360* ROTATION OF THE HONDA SEDAN. DUE TO THE FORCE OF IMPACT, FRONT & SIDE AIRBAGS DEPLOYED ON BOTH THE KIA SEDAN AND THE HONDA SEDAN, BUT FAILED TO DEPLOY ON THE TAHOE. SCENE INDICATED THAT THE KIA SEDAN MADE NO ATTEMPT TO BRAKE OR DECREASE SPEED PRIOR TO COLLISION; POSTED SPEED LIMIT AT INTERSECTION IS 40 MPH. FORCE WAS SUCH THAT AFTER THE COLLISION, TAHOE TRANSMISSION WAS IN DRIVE, BUT REMAINED AT A COMPLETE STOP. DAMAGE SUSTAINED ON THE TAHOE INCLUDE FRONT-END BODY DAMAGE, ENGINE DAMAGE (VEHICLE REQUIRED TOWING AND WAS INOPERABLE), AND FRAME DAMAGE, AT A MINIMUM. IN ADDITION, ENGINE SERVICE LIGHTS AS WELL AS ONSTAR VEHICLE DIAGNOSTIC REPORTS INDICATE THAT THE AIRBAG SYSTEM, ANTILOCK BRAKING SYSTEM, AND THE STABILITRAK STABILITY CONTROL SYSTEM ALSO SUSTAINED DAMAGE AND REQUIRE ATTENTION. MULTIPLE FIRST-RESPONDERS COMMENTED ON THE ODDITY THAT, GIVEN THE DAMAGE SUSTAINED BY THE TAHOE AND THE VELOCITY AT IMPACT, THE AIRBAGS
10622016	CHEVROLET	TAHOE	2012	2014-08-09	DEPLOYED ON ALL VEHICLES BUT THE TAHOE. *TR

			1		THE PROPERTY OF THE POLICE OF STATE OF AND ACLARDS OF THE FIGURE FOR THE POLICE OF THE
					I WAS DRIVING WEST BOUND ON 176TH ST AND AS I APPROACHED THE LIGHT I COULD NOT BRAKE OR TURN MY CAR TO THE RIGHT IN WHICH I HAD A HEAD ON COLLISION WITH ANOTHER VEHICLE.
					ON IN PACKED MY AIRBAGS DID NOT DEPLOY! THE DRIVER OF THE OTHER VEHICLE EVEN TOLD THE
					OFFICER HE WAS TRYING TO TURN , HIS EYES WERE AS BIG AS A COWS CLEARLY HE WAS IN
11194940	CHEVROLET	TAHOE	2012	2018-03-19	DISTRESS. LUCKILY NEITHER OF US WERE INJURED.
					AS I WAS DRIVING ON 176TH GETTING READY TO TURN ON SPANAWAY LOOP MY WOULDN'T
11278797	CHEVROLET	TAHOE	2012	2018-08-24	COMPLETE THE RIGHT TURN OR STOP SO I HAD A HEAD ON COLLISION WITH ANOTHER TRUCK AND MY AIR BAGS DIDN'T DEPLOY.
112/6/9/	CHEVROLET	TARUE	2012	2016-06-24	THE DRIVER STEERING WHEEL FRONT AIRBAG DID NOT DEPLOY WHEN I HIT ANOTHER VEHICLE
					FROM BEHIND. WHEN WE RECEIVED THE LETTER ABOUT RECALL WE BROUGHT THE VEHICLE INTO
10885565	CHEVROLET	TRAVERSE	2012	2016-06-30	SERVICE CHEVROLET IN LAFAYETTE, LA.
					MY WIFE AND THREE DAUGHTERS, AGES 11, 9, AND 6, WERE INVOLVED IN A MAJOR CRASH. AN
					ELDERLY MALE TRAVELED THRU A STEADY RED TRAFFIC SIGNAL AND STRUCK THE PASSENGER SIDE
					OF MY WIFE'S VEHICLE AS SHE WAS CROSSING THE INTERSECTION WITH A GREEN TRAFFIC SIGNAL.
					AFTER IMPACT, THEY WERE PUSHED HEAD ON INTO A TRAFFIC STANDARD (WHICH WAS TAKEN OUT COMPLETELY) AND THEN INTO A TELEPHONE POLE, ALSO HEAD ON. NOT ONE AIRBAG
					DEPLOYED. THE VEHICLE IS SUPPOSEDLY EQUIPPED WITH FRONT AND SIDE AIRBAGS. IN MARCH
					OF 2014 THERE WAS A RECALL CONCERNING THE AIRBAGS NOT DEPLOYING IN THESE VEHICLES (#
					14V118000). I HAVE OWNED THIS VEHICLE SINCE NEW AND DID RETURN IT TO THE DEALERSHIP IN
					MAY OF 2014 FOR THE RECALL SHORTLY AFTER RECEIVING NOTIFICATION. I WAS ADVISED THAT IT
10882239	GMC	ACADIA	2012	2016-06-14	WAS TAKEN CARE OF.
					THE VEHICLE WAS IN MOTION NEAR AN INTERSECTION AND APPROACHING THE LIGHT TO TURN.
					NEAR AIRPORT IN RALEIGH NC) THE FRONT AND SIDE AIRBAGS FAILED TO DEPLOY DURING THE
					CRASH. THE OTHER VEHICLE HAS BEEN DECLARED TOTAL LOSS AND MINE HAS SIGNIFICANT
10925628	GMC	ACADIA	2012	2016-09-27	DAMAGE AND COULD BE CLASSIFIED AS TOTAL LOSS. THERE ARE PERSONAL INJURIES. I AM ATTACHING PICTURES OF THE VEHICLE AND ACCIDENT REPORT.
10323020	GIVIC	ACADIA	2012	2010 03 27	ATTACHING TICTORES OF THE VEHICLE AND ACCIDENT REPORT.
					ON APRIL 16TH OUR SON WAS DRIVING ON FAIRVIEW RD. AND TRAVELING THROUGH A GREEN
					LIGHT WHEN A CAR THAT RAN A RED LIGHT HIT HIM. PHIS CAR ? A GMC 2012 TERRAIN WAS HIT
					MULTIPLE TIMES ? DRIVER'S FRONT END, FRONT END AND SPUN AROUND FROM THE FORCE AND
					HIT ON THE PASSENGER SIDE. NO AIRBAGS DEPLOYED ?[XXX] WAS IMMEDIATELY CONTACTED BY
					ON STAR, THEY CALLED POLICE, HIS CAR WAS TOTALED ?ON 4/21 I EMAILED GMC AND ASKED
					WHAT DEPARTMENT I WOULD CONTACT TO FILE A COMPLAINT ABOUT THE FRONT AND SIDE AIRBAGS NOT DEPLOYING CALL FROM GMC 866-790-5700 EXT. 22745 SAID ON VOICE MAIL? THE
					AIRBAG DID NOT DEPLOY AS IT SHOULD HAVE? HE MADE A CASE NUMBER [XXX] GMC HAS SINCE
					DECLARED THIS WAS A LOW THRESHOLD EVENT - NO NEED FOR AIRBAG DEPLOYMENT - YET THE
					CAR WAS TOTALED AND OUR SON HAS WHIPLASH AND CONTUSIONS INFORMATION REDACTED
10466384	GMC	TERRAIN	2012	2012-04-16	PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6). *TR
					TL* THE CONTACT OWNS A 2012 GMC TERRAIN. THE CONTACT STATED THAT HE FELL ASLEEP
					WHILE DRIVING AN UNKNOWN SPEED. THE VEHICLE TRAVELED TO THE RIGHT SIDE OF THE ROAD AND WENT AIRBORNE APPROXIMATELY 20 FEET, LANDING ON ALL FOUR TIRES. THE VEHICLE THEN
					TRAVELED APPROXIMATELY 200 FEET AND CRASHED INTO AN EMBANKMENT. THE AIR BAGS FAILED
					TO DEPLOY. THE CONTACT SUSTAINED A FRACTURED BACK AS A RESULT. A POLICE OFFICER
					WITNESSED THE INCIDENT AND FILED A REPORT. THE VEHICLE WAS DESTROYED AND TOWED TO A
					COLLISION CENTER. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAULTY AIR BAGS. THE
10477166	GMC	TERRAIN	2012	2012-09-04	APPROXIMATE FAILURE MILEAGE WAS 7,000. UPDATED 10/16/12*LJ
					VEHICLE WAS INVOLVED IN A CAR ACCIDENT AND CRASHED INTO A BRIDGE IRON BEAM HEAD-ON.
					VEHICLE'S AIR BAGS FAILED TO DEPLOY. HOOD AND FRONT OF CAR SMASHED AS VEHICLE WAS
10516265	GMC	TEDDAIN	2012	2013-06-08	WRAPPED AROUND BEAM. ONLY MINOR INJURIES TO DRIVER, AS DRIVER WAS WEARING A
10516265	GMC	TERRAIN	2012	2013-00-08	SEATBELT. *TR
				1	I INADVERTENTLY VEERED OFF SIDE ROADWAY, (VA HIGHWAY 220) COLLIDING WITH A
					TREE/ROADSIDE SHRUBS, ETC (WAS KNOCKED UNCONSCIOUS AS FOREHEAD HIT STEERING WHEEL
					ON INITIAL IMPACT). AIRBAGS DID NOT DEPLOY ALLOWING ME TO SUSTAIN A HEAD INJURY THAT
					KNOCKED ME UNCONSCIOUS FOREHEAD WAS GASHED WITH SIGNIFICANT BLEEDING. I WAS
					TRANSPORTED BY AMBULANCE IN UNCONSCIOUS STATE. DAMAGE TO VEHICLE IS IN EXCESS OF
					\$8,000 SO FAR AS VEHICLE STILL IN REPAIR SHOP WITH MASSIVE FRONT END DAMAGE THAT
					AFFECTS STEERING LINKAGE, ETC. THE IMPACT OF VEHICLE AGAINST FOLIAGE, TREES SHRUBS,
				1	SHOULD HAVE FORCED AIR BAGS TO DEPLOY AND I BELIEVE THAT I WOULD NOT HAVE SUSTAINED A HEAD INJURY THAT RENDERED ME UNCONSCIOUS WITH MILD CONCUSSION AND COULD NOT
10583703	GMC	TERRAIN	2012	2014-03-13	CONTROL VEHICLE LEAVING ROADWAY. *TR
_0000,00	510	. =	-012		The state of the s

10588334	GMC	TERRAIN	2012	2014-03-13	VEERED OFF SIDE OF HIGHWAY, STRUCK SOMETHING HEAD-ON AND WAS RENDERED UNCONSCIOUS AS HEAD HIT STEERING WHEEL. I WAS TRANSPORTED UNCONSCIOUS IN AMBULANCE FROM CRASH SCENE TO LOCAL HOSPITAL, WHERE I WAS AN INPATIENT FOR TWO DAYS. EXTENSIVE DAMAGE TO FRONT OF VEHICLE INDICATED THE SEVERITY OF IMPACT YET AIR BAGS DID NOT DEPLOY. I BELIEVE AIR BAGS SHOULD HAVE DEPLOYED ON IMPACT AND I WOULD NOT HAVE BEEN RENDERED UNCONSCIOUS, AND COULD HAVE CONTROLLED VEHICLE TO AVOID STRIKING TREE, BRUSH, ETC. I CONTACTED GMC CORPORATE TO ADVISE MY CONCERNS FOR SAFETY RECEIVED A FOLLOW UP TELEPHONE CALL FROM GMC REPRESENTATIVE (HE) EXPRESSED NO INTEREST IN MY COMPLAINT REFUSED TO COMMENT ON MY STATEMENT THAT AIR BAG FAILED TO DEPLOY RESULTING IN EXTENSIVE DAMAGE TO FRONT OF VEHICLE AND SUSTAINING A HEAD INJURY AS NO BAG DEPLOYED. NO MATTER THAT I AM LEASING THE VEHICLE AND FEAR FOR MY SAFETY I WAS ADVISED THAT GMC HAD NO FURTHER INTEREST IN THIS MATTER AND WOULD NOT EVALUATE MY SAFETY CONCERNS. *TR
10722057	GMC	TERRAIN	2012	2015-05-19	CAR CRASH AT 45 MPH. FRONT IN DAMAGE AND AIR BAG DID NOT DEPLOY. SEATBELTS DID NOT LOCK UP.
10924918	GMC	TERRAIN	2012	2016-11-06	I WAS TRAVELING ABOUT 75MPH WHEN A DEER RAN INFRONT OF ME, I WASN'T ABLE TO STOP COMPLETELY AND HIT THE DEER ON MY RIGHT FRONT SIDE OF MY VEHICLE THE SMELL OF SMOKE CAME FROM MY VEHICLE AND MY "SERVICE AIRBAGS" INDICATOR CAME ON NO AIRBAGS DEPLOYED I HAD MY 6 YEAR OLD SON IN THE CAR WITH ME!! MY CAR ISN'T DRIVABLE DUE TO THE SIGNAL BEING ON EVEN THOUGH THE AIRBAGS DIDN'T DEPLOY.
11088412	GMC	TERRAIN	2012	2016-04-21	TL* THE CONTACT OWNED A 2012 GMC TERRAIN. WHILE DRIVING AT AN UNKNOWN SPEED, THE DRIVER CRASHED INTO A LANDSCAPING TRUCK. THE AIR BAGS FAILED TO DEPLOY. THERE WERE NO INJURIES. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A TOW LOT AND DEEMED DESTROYED. THE DEALER WAS NOT CONTACTED TO DETERMINE THE CAUSE OF THE AIR BAG FAILURE. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNKNOWN.
11219747	GMC	TERRAIN	2012	2019-06-12	TL* THE CONTACT OWNS A 2012 GMC TERRAIN. THE CONTACT STATED THAT WHILE HER GRANDSON WAS DRIVING APPROXIMATELY 40-45 MPH, A DEER JUMPED INTO THE FRONT OF THE VEHICLE CAUSING SEVERE DAMAGE TO THE FRONT END OF THE VEHICLE BUT THE AIR BAGS DID NOT DEPLOY. THE CONTACT MENTIONED THAT THE RADIATOR WAS PUSHED INTO THE ENGINE. THE CONTACT SUSTAINED WHIPLASH INJURIES THAT DID NOT REQUIRE MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS TOWED. THE CAUSE OF THE FAILURE WAS NOT DETERMINED BY THE INDEPENDENT MECHANIC. THE LOCAL DEALER WAS NOT NOTIFIED OF THE FAILURE. THE MANUFACTURER WAS CONTACTED AND A CASE WAS OPENED BUT NO ASSISTANCE WAS OFFERED. THE FAILURE MILEAGE WAS 103,000. *AS *AS
					TURNED CORNER ON IRONWOOD46615 AND REAR ENDED CAR THAT STOPPED SUDDENLY. CRUSHED MY FRONT END BACK TO PUNCTURING THE RADIATOR. NO AIR BAG DEPLOYED AND NO SEAT BELT ON IMPACT. MY KNEES HIT THE DASH UNDER THE STEERING WHEEL. NO ONSTAR AS NO AIRBAG DEPLOYED. HOLDING STEERING WHEEL WAS MY ONLY DETERRENT TO HITTING FORWARD. REPAIRS COST \$5000.+ AND GM DEALER INSISTED AIRBAG AND SEAT BELT WERE FUNCTIONING. KNEES STILL HURT. AND SEEN DOCTOR ABOUT KNEES AND GOING AGAIN SOON. I AM REPORTING THIS AFTER HEARING THAT THERE ARE RECALLED ON SEAT BELTS AND AIRBAGS ON DRIVER SIDE.
10608978	BUICK	ENCLAVE	2011	2012-10-10	*TR TL - THE CONTACT OWNS A 2011 BUICK ENCLAVE. THE CONTACT STATED WHILE DRIVING AT UNKNOWN SPEED, THE VEHICLE CRASHED INTO A DEER CAUSING THE VEHICLE TO CATCH ON FIRE AND THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE AND CURRENT MILEAGE WAS 56,000. PAM UPDATED 11/24/14*LJ UPDATED 8/17/2015*JS
10732977	BUICK	ENCLAVE	2011	2015-07-04	DRIVING DOWN THE ROAD ON A 50MPH ZONE AND A VEHICLE PULLED OUT IN FRONT OF US. OUR CAR T-BONED THE CAR THAT PULLED IN FRONT OF US. EVERYONE HAD THERE SEATBELTS ON BUT THE FRONT AIRBAGS NEVER DEPLOYED. I DON'T UNDERSTAND WHY THEY WOULDN'T HAVE DEPLOYED WHEN WE HIT THE OTHER CAR AT AT LEAST 40MPH AFTER SLAMMING ON THE BREAKS.
10654934	CADILLAC	SRX	2011	2014-10-23	I WAS TURNING SOUTH WITH A GREEN ARROW WHEN THE SECOND DRIVER RAN A RED LIGHT TRAVELING EAST AND WE COLLIDED. HE WAS TRAVELING AT APPROXIMATELY 40-45 MILES PER HOUR AND I WAS TRAVELING AT APPROXIMATELY 30 MILES AN HOUR. OUR IMPACT WAS SOMEWHAT OF A T-INCIDENT WITH THE FRONT END OF MY CAR DAMAGED AND HIS CAR ON THE DRIVER'S SIDE DAMAGED. MY AIR BAGS DID NOT INFLATE, EVEN THOUGH WE BELIEVE THE IMPACT WAS AT THE ANGLE AND THE REQUIRED SPEED OF VEHICLES TO INFLATE THEM. THE AIR BAGS IN THE SECOND DRIVER'S CAR (FORD FOCUS) DID INFLATE. *TR
10679589	CADILLAC	SRX	2011	2015-01-08	TL* THE CONTACT OWNED A 2011 CADILLAC SRX. WHILE DRIVING 35 MPH, THE CONTACT CRASHED INTO ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY AND THE FRONT PASSENGERS SIDE SEAT BELT WAS LOOSE. A POLICE REPORT WAS FILED AND THREE UNKNOWN INJURIES WERE REPORTED. THE CONTACT DID NOT DISCLOSE IF MEDICAL ATTENTION WAS REQUIRED OR NOT. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 60,000.
_					

					I WAS INVOLVED IN AN ACCIDENT, I RAN INTO A VEHICLE THE DAMAGE WAS TO THE FRONT OF THE
					CAR . THE AIRBAGS DIDNT DEPLOY OR THE SENSORS OF THE FRONT OF MY CAR DID NOT GO OFF
11192908	CADILLAC	SRX	2011	2018-12-19	EITHER.
					I WAS RECENTLY IN A PRETTY BAD FRONT END VEHICLE ACCIDENT GOING ABOUT 45 MPH WHEN I
					REAR ENDED SOMEONE. MY CAR HAS BEEN TOTALED DO TO THE DAMAGE TO THE FRONT END OF
					THE VEHICLE. MY AIR BAGS DID NOT DEPLOY IN THIS ACCIDENT, EVERYONE ONE I HAVE TALKED TO
					FROM THE TOWING COMPANY TO THE PARAMEDIC ON SEEN SAID THAT IT SHOULD HAVE
10391449	CHEVROLET	EQUINOX	2011	2011-03-10	DEPLOYED.
					2011 CHEVROLET EQUINOX. CONSUMER STATES AIRBAGS DID NOT DEPLOY DURING CRASH *TGW
					THE CONSUMER STATED ANOTHER VEHICLE PULLED OUT IN FRONT OF HIM FROM A SIDE STREET,
					ON HIS RIGHT SIDE, WHICH RESULTED IN THE CONSUMER HITTING THE OTHER VEHICLE, WHEN
					THAT VEHICLE FAILED TO STOP AT A STOP SIGN. THE CONSUMER STATED THE ENTIRE FRONT END
10449809	CHEVROLET	EQUINOX	2011	2012-01-23	OF THE VEHICLE WAS DESTROYED. *JB
					AIR BAGS DID NOT DEPLOY AT OR ABOVE THE MFG. THRESHOLDS.WHICH CAUSED FOR NO AIR BAG
					DEPLOYMENT AND SIGNIFICANT FACIAL TRAUMA ON THE STEERING WHEEL. SEAT BELT
					PRETENSTIONERS ALSO DID PRETENSION CAUSING THE UPPER TORSO TO GO FORWARD AND
10552442	CHEVROLET	EQUINOX	2011	2013-07-31	CAUSE THE FACIAL TRAUMA ON THE STEERING WHEEL. *TR
					WHILE CHANGING LANES DURING AN ICE STORM, THE VEHICLE'S BACK END LET LOSE AND THE
					DRIVER LOST CONTROL AND SLIDE INTO THE MEDIA AT WHICH TIME THE VEHICLE WAS PROJECTED
					INTO THE GUARDRAIL HEAD ON. NEITHER FRONT AIRBAGS DEPLOYED NOR DID ANY OF THE
10682338	CHEVROLET	EQUINOX	2011	2015-01-29	AIRBAGS DEPLOY. *TR
					TL* THE CONTACT OWNS A 2011 CHEVROLET EQUINOX. THE CONTACT WAS INVOLVED IN A
					FRONTAL CRASH. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS NOT FILED AND NO
					INJURIES WERE SUSTAINED. THE VEHICLE WAS DECLARED DESTROYED BY THE INSURANCE
					COMPANY. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE
10721958	CHEVROLET	EQUINOX	2011	2015-05-09	WAS 58,000.
					INVOLVED IN AN ACCIDENT WHERE I COLLIDED WITH ANOTHER CAR. THE FRONT END OF MY CAR
					WAS COMPLETED DAMAGED TO THE POINT WHERE THE CAR WAS TOTALED. THE PROBLEM WITH
					THIS ACCIDENT WAS THE AIR BAGS DID NOT GO OFF CAUSING INJURY TO MYSELF AND MY WIFE. I
					ESTIMATE THE SPEED AT COLLISION TO BE AROUND 30MPH. I WAS TRAVELING WEST BOUND AT
					ABOUT 630PM IN THE EVENING, ON A FOUR LANE CITY ROAD WITH A CENTER TURN LANE. I WAS
					IN MY LANE AND FAILED TO STOP BEFORE HITTING THE CAR IN FRONT OF ME. MY WIFE SPOKE
					WITH THE REPAIR SHOP CLERK WHO INFORMED THAT THIS WAS A COMMON ISSUE WITH MANY
					EQUINOX'S UNDER THE SAME CONDITIONS. I BELIEVE THE AIR BAGS SHOULD HAVE GONE OFF AND
10949808	CHEVROLET	EQUINOX	2011	2017-01-31	THEREFORE I
					JUNE 9, 2017 AT 10:00 PM I HIT A DEER ON SOUTH DAKOTA HWY 11 IN LINCOLN COUNTY. THE
					SPEED LIMIT WAS 65 MPH AND I WAS GOING 68 MPH WHEN I HIT THE DEER HEAD ON. I DROVE
					OVER TO THE SIDE OF THE ROAD AND THE VEHICLE STOPPED. AFTER A FEW MINUTES MY WIFE
					AND I SMELLED BURNING ELECTRICAL WIRE. WE GOT OUT OF THE CAR AND STARTED TO WALK
					AWAY AND WITHIN 10 MINUTES THE WHOLE THING WENT UP IN FLAMES. THE CAR WAS TOTALED
					AND THE AIRBAGS DID NOT GO OFF. IF WE WOULD HAVE WENT IN THE DITCH AND BEEN
					UNCONSCIOUS WE WOULD HAVE BURNT UP WITH THE VEHICLE. THERE IS NO REASON THAT
					VEHICLE SHOULD HAVE STARTED ON FIRE. GMC WILL NOT ACKNOWLEDGE THAT THERE WAS
11010876	CHEVROLET	EQUINOX	2011	2017-06-09	ANYTHING WRONG WITH THE VEHICLE.
					VECHICAL WAS INVOLVED IN A CRASH, REAR ENDED ANOTHER VEHICLE, VECHICAL WAS TOTALED.
11189908	CHEVROLET	EQUINOX	2011	2019-03-08	AIRBAGS NEVER WENT OFF. ON A HIGHWAY ABOUT 50-60 MPH.
					MY VEHICLE WAS FORCED OFF THE ROAD BY ANOTHER VEHICLE CAUSING MY VEHICLE TO HIT A
10607261	CHEVROLET	SILVERADO	2011	2014-02-14	LIGHT POLE HEAD ON. NO AIR BAGS DEPLOYED. DRIVER AND PASSENGER SUFFERED INJURY. *TR

10487443	CHEVROLET	ТАНОЕ	2011	2012-12-02	I WAS DRIVING WEST ON RIO RD. IN CHARLOTTESVILLE, VA, AT ROUGHLY 35 MPH. AT APPROXIMATELY 6:00 PM, A DEER EMERGED FROM THE PASSENGER SIDE OF THE VEHICLE. IT HAPPENED INSTANTANEOUSLY AND AVOIDING THE DEER WAS NOT AN OPTION. IMMEDIATELY AFTER STRIKING THE DEER AT THE FRONT RIGHT BUMPER (UNDERNEATH HEADLIGHT), THE SIDE AIRBAGS DEPLOYED IN MY 2011 CHEVY TAHOE. HOWEVER, THE AIRBAG THAT WAS SUPPOSE TO DEPLOY FROM THE DRIVERS SEAT (ON THE SIDE NEAR SEATBELT) DID NOT DEPLOY. ADDITIONALLY, THE FRONT TWO AIRBAGS (FROM STEERING WHEEL AND DASHBOARD) DID NOT DEPLOY AS WELL. MOREOVER, APPROXIMATELY THREE MONTHS BACK, ANOTHER FAMILY MEMBER ALSO HIT A DEER WITH THE SAME VEHICLE (2011 CHEVY TAHOE) AND AT THAT TIME NO AIRBAGS DEPLOYED. IN THIS INCIDENT THE VEHICLE WAS TRAVELING 70 MPH AND THE DEER STRUCK THE LEFT SIDE OF THE FRONT BUMPER AND NO AIRBAGS DEPLOYED. AT THE TIME, WE DIDN'T EVEN THINK ABOUT DEFECTIVE AIRBAGS, BUT NOW, WE ARE VERY, VERY CONCERNED THAT THERE'S A DEFECT. WE SIMPLY DO NOT KNOW WHAT TO DO. I HAVE CONTACTED CHEVROLET DIRECTLY AND THEY ASSURE ME SOMEONE WILL COME OUT AND LOOK AT THE VEHICLE THIS WEEK SOMETIME. I WOULD BE RELIEVED IF SOMEONE FROM THE NHTSA ALSO INVESTIGATES THESE TWO SCENARIOS. WHAT IS CHEVROLET'S RESPONSIBILITY TO ME AND MY FAMILY IN THESE TWO CASES? AND WHAT IS THE BEST COURSE OF ACTION? FURTHERMORE, I CAN ARRANGE FOR MY INSURANCE ADJUSTOR TO GATHER ANY DOCUMENTATION FROM THE FIRST INCIDENT (WHERE AIRBAGS DID NOT DEPLOY) SUCH AS PHOTOS, REPORTS AND PROVIDE THEM TO YOU. THE VEHICLE IS SITTING IN MY DRIVEWAY BECAUSE I AM WAITING FOR A CHEVROLET REPRESENTATIVE TO COME AND INSPECT IT.
10586298	CHEVROLET	TRAVERSE	2011	2011-05-31	I WAS GOING STRAIGHT AT 40 MPH (CONFIRMED BY GM ENGINEER). ANOTHER VEHICLE TURNED IN FRONT OF ME AND THERE WAS A T-BONE STYLE OF ACCIDENT. THE OTHER CAR WAS TOTALED AND MINE TOOK ABOUT \$18000 OF DAMAGE. NONE OF MY AIRBAGS DEPLOYED. I COMPLAINED TO GM, THEY SENT AN ENGINEER OUT TO LOOK AT THE VEHICLE BEFORE IT WAS REPAIRED TO ASSESS AND THEY SAID THAT THE AIRBAGS NOT DEPLOYING MEANT THAT THEY FUNCTIONED CORRECTLY. THE ENGINEERS REPORT SAID AT THE MOMENT OF IMPACT, MY CAR WAS TRAVELING 40MPH, AND I HAVE A HARD TIME BELIEVING THAT THE AIRBAGS WOULDN'T DEPLOY UNDER ANY CIRCUMSTANCES WHILE THE VEHICLE IS TRAVELING 40MPH. *TR
11113909	CHEVROLET	TRAVERSE	2011	2018-07-16	AIR BAGS DO NOT COME OUT IN HIGHWAY IMPACT OF 70 MILES PER HOUR.
10794590	GMC	TERRAIN	2011	2015-11-12	TL* THE CONTACT OWNS A 2011 GMC TERRAIN. WHILE DRIVING APPROXIMATELY 55 MPH, THE CONTACT CRASHED INTO THE SIDE OF ANOTHER VEHICLE THAT VEERED INTO THE CONTACT'S LANE. THE AIR BAGS FAILED TO DEPLOY. THERE WERE MINOR INJURIES THAT DID NOT REQUIRE MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A TOW YARD. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 70,000UPDATED 04/01/16 *BF *CN
10851422	GMC	TERRAIN	2011	2016-01-15	TL* THE CONTACT OWNS A 2011 GMC TERRAIN. WHILE DRIVING 55 MPH, THE CONTACT FELL ASLEEP CRASHED INTO THE REAR OF ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED INJURIES TO THE SPINE, WHICH REQUIRED MEDICAL ATTENTION. THERE WERE NO INJURIES SUSTAINED TO THE DRIVER OF THE OTHER VEHICLE. THE VEHICLE WAS TOWED TO AN INDEPENDENT MECHANIC. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 62,000.
11166326	GMC	TERRAIN	2011	2019-01-04	MY 2011 GMC TERRAIN HIT A VEHICLE IN FRONT, CAUSING MAJOR DAMAGE (THE VEHICLE IS TOTALED OUT) AND NO AIR BAGS DEPLOYED. MY VEHICLE WAS TRAVELING AT APPROXIMATELY 55 MPH NORTHBOUND IN THE #3 LANE OF THE 41 FREEWAY, SOUTH OF THE SHAW EXIT. IMPACT WAS ESTIMATED TO BE BETWEEN 20 TO 30 MPH. THE DRIVER, MY 18 YEAR GRAND-DAUGHTER HIT HER HEAD ON THE STEERING WHEEL AND HER LEFT WRIST WAS INJURED HOLDING ON TO THE STEERING WHEEL. THE 18 YEAR OLD FEMALE RIGHT FRONT SEAT PASSENGER SUFFERED AN ANKLE INJURY. WHY DID THE AIR BAGS FAIL TO DEPLOY, WITH A STRAIGHT ON FRONT END COLLISION WITH THE VEHICLE IN FRONT?! UNACCEPTABLE!!!
10732291	CADILLAC	SRX	2010	2015-06-22	HIT HEAD ON BY TRUCK GOING APPROX. 45 MPH THAT SWERVED INTO MY CENTER TURN LANE. FRONT END DEMOLISHED - CAR WAS TOTALED - BUT AIR BAGS DID NOT DEPLOY. SEAT BELT DID NOT LOCK ON IMPACT. SIDE OF MY HEAD HIT DRIVER'S WINDOW OR FRAME - WAS CATAPULTED FORWARD AND CAUGHT IN SEAT BELT WHEN IT PULLED OUT ALL THE WAY, RESULTING IN HORRIFIC AND PAINFUL CHEST, ABDOMEN AND LEFT LEG INJURIES (SOFT TISSUE).
10927215	CADILLAC	SRX	2010	2016-11-16	I WAS IN A MINOR COLLISION. RAN INTO THE BACK OF SOMEONE. MY AIRBAGS DIDN'T DEPLOY AND MY ENGINE IMMEDIATELY CAUGHT ON FIRE AND IN A FEW MINUTES MY WHOLE CARE WAS ON FIRE AND DESTROYED. THERE WAS NO KNOWN REASON HOW OR WHY THE FIRE STARTED.
11053454	CADILLAC	SRX	2010	2017-12-02	I WAS IN A CAR ACCIDENT ALONG WITH TWO OTHER PASSENGERS AND NONE OF THE AIR BAGS DEPLOYED

				1	
					ON JAN 17TH,2011 MY VEHICLE WAS WRECKED BY THE DEALER ON SITE OF DEALERSHIP. THE WHOLE FRONT END WAS CAVED IN ON CENTER. THE DRIVER A MECHANIC AT DON WOODS CHEVROLET WAS DRIVING AT A HIGHER THEN NORMAL SPEED. HE HIT A POLE DEAD CENTER AND THE AIR BAG DID NOT DEPLOY. THE DRIVER WAS INJURED TO WHAT EXTENT I AM NOT SURE, BUT I AM NOT WANTING THIS CAR BACK FEELING THE AIRBAG MAY DEPLOY AT ANYTIME DUE TO THE HIT
10383428	CHEVROLET	EQUINOX	2010	2011-01-17	IT TOOK OR IT ISN'T SAFE AND WILL NOT DEPLOY UPON AN ACCIDENT. *TR
					AS I APPROACHED AN INTERSECTION, I HIT THE REAR END OF A FORD 150 PICK UP TRUCK THAT WAS IN THE INTERSECTION WAITING TO MAKE A LEFT TURN. MY APPROX SPEED WAS 15 MILES PER HOUR. I HAD MY SEATBELT ON, I WAS TAKEN BY AMBULANCE TO THE HOSPITAL - MY EVALUATION REVEALED SPRAIN/STRAIN TO MY NECK, FRACTURED RIGHT ANKLE, AND CHEST WALL
10460416	CHEVROLET	EOUINOX	2010	2012-05-18	DISCOMFORT RELATED TO THE SEAT BELT. THE CAR WAS TOTALED THE AIRBAG DID NOT DEPLOY. *TR
10400410	CHEVNOLET	Egginox	2010	2012 03 10	TL* THE CONTACT OWNS A 2010 CHEVROLET EQUINOX. THE CONTACT STATED THAT WHILE TRAVELING 15 MPH, ANOTHER DRIVER CRASHED INTO THE FRONT DRIVER'S SIDE CORNER OF THE VEHICLE. THE COLLISION CAUSED THE CONTACT TO THEN CRASH INTO A UTILITY POLE. THE AIR BAGS FAILED TO DEPLOY. THE POLICE ARRIVED AND A REPORT WAS FILED. THE CONTACTS INSURANCE COMPANY INSPECTED THE VEHICLE AND ADVISED THE CONTACT THAT THE AIR BAGS SHOULD HAVE DEPLOYED UPON IMPACT. THE CONTACT SUSTAINED A FRACTURED RIB AND INJURY
					TO THE HEAD. THE VEHICLE WAS DESTROYED. THE FAILURE AND THE CURRENT MILEAGE WAS
10508670	CHEVROLET	EQUINOX	2010	2013-03-25	42,000. *TR I WAS DRIVING IN TRAFFIC WHEN THE CAR IN FRONT OF ME STOPPED ABRUPTLY IN FRONT OF ME. I READ ENDED HIM GOING ABOUT 40 MILES PER HOUR. MY AIR BAGS DID NOT INFLATE. I EXITED THE CAR AND BEGAN SPEAKING WITH THE OTHER DRIVER WHEN WE HEARD A POP IN MY CAR. SMOKE STARTING COMING OUT OF THE ENGINE COMPARTMENT AND THEN ALMOST
10746722	CHEVROLET	EQUINOX	2010	2015-07-08	IMMEDIATELY MY CAR ENGINE CAUGHT ON FIRE. THE CAR WAS NOT RUNNING. I INJURED MY KNEE AND SHOULDER IN THE INCIDENT.
10740722	CHEVNOLET	Egginox	2010	2013 07 00	TL* THE CONTACT OWNED A 2010 CHEVROLET EQUINOX. WHILE DRIVING 35 MPH, THE CONTACT ATTEMPTED TO AVOID HITTING A DEER AND STRUCK THE GUARDRAIL. THE AIR BAGS FAILED TO DEPLOY. THE EMERGENCY ONSTAR SYSTEM RESPONDED AND CALLED THE POLICE AND AMBULANCE. THE VEHICLE WAS TOWED TO A COLLISON CENTER WHERE THE VEHICLE WAS DIAGNOSED AS DESTROYED. THE CONTACT SUSTAINED INJURIES TO THE HEAD, NECK, BACK, AND HANDS. A POLICE REPORT WAS FILED. THE MANUFACTURER WAS NOTIFIED. THE APPROXIMATE
10809547	CHEVROLET	EQUINOX	2010	2015-12-08	FAILURE MILEAGE WAS 57,000.
10928817	CHEVROLET	EQUINOX	2010	2016-11-25	AIRBAGS DID NOT DEPLOY WHEN INVOLVED IN CAR ACCIDENT ON 11/25/2016
10649152	CHEVROLET	SILVERADO	2010	2013-11-14	LETTER FROM CONGRESSMAN WITTMAN ON BEHALF OF CONSTITUENT RE AIRBAGS THAT DID NOT DEPLOY. *SMD 2010 CHEVROLET SILVERADO. THE CONSUMER WAS INVOLVED IN AN ACCIDENT. AS A RESULT, SHE SUSTAINED A BRAIN INJURY.*JB
10215712	CHEVPOLET	TDAVEDSE	2010	2010 02 25	1. STOPPED AT RED LIGHT IN 2010 CHEVROLET TRAVERSE SUV AND REAR ENDED BY A NISSAN FRONTIER PICK UP TRUCK TRAVELING AT A HIGH RATE OF SPEED. DRIVER'S SEAT BELT ON BUT DRIVER'S HEAD THROWN AGAINST WINDSHIELD AND THEN DRIVER'S BODY SLAMMED AGAINST THE BACK OF THE DRIVER'S SEAT WHICH WAS FORCED BACK TO A RECLINING POSITION. AIRBAG DID NOT DEPLOY. 2. SEAT BELT FAILED TO PREVENT DRIVER'S HEAD FROM HITTING WINDSHIELD IF IT IS SUPPOSED TO IN THIS TYPE OF COLLISION. DID THE SEAT BACK ACT PROPERLY IN SUCH A COLLISION? WAS THE AIRBAG SUPPOSED TO DEPLOY IN THIS TYPE OF COLLISION. 3. IN BODY SHOP TO REPAIR TO PRE-ACCIDENT CONDITION *TR
10315713	CHEVROLET	IKAVEKSE	2010	2010-02-25	WAS GETTING READY TO PARK ON THE STREET WHEN A CAR HIT ME,I HIT A CAR IN FRONT OF
10637484	CHEVROLET	TRAVERSE	2010	2010-07-19	ME,MY CAR WAS THROWN ON THE SIDE WALK,I WAS PASS OUT FOR A FEW SECONDS,BUMP MY HEAD,MY CAR WAS TOTAL, FRONT AND REAR,SURPRISINGLY MY AIR BAG DID NOT DEPLOY TO HELP PROTECT ME FROM MY INJURIES I GOT. *TR
10037404	CHEVILOLET	TRAVERSE	2010	2010 07 13	TL* THE CONTACT OWNS A 2010 CHEVROLET TRAVERSE. WHILE DRIVING AT AN UNKNOWN SPEED
					ATTEMPTING TO MAKE A LEFT TURN, ANOTHER VEHICLE CRASHED INTO THE CONTACTS VEHICLE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED UNKNOWN INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A SALVAGE YARD. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE APPROXIMATE FAILURE MILEAGE
10749869	CHEVROLET	TRAVERSE	2010	2015-08-06	WAS 75,000.
11210243	CHEVROLET	TRAVERSE	2010	2018-12-01	TL* THE CONTACT OWNS A 2010 CHEVROLET TRAVERSE. WHILE DRIVING 30 MPH, THE VEHICLE WAS HIT BY ANOTHER VEHICLE COMING FROM THE OPPOSITE DIRECTION AS IT WAS MAKING A TURN INTO A PARKING LOT. THE CONTACT WAS INJURED BUT NOT TRANSPORTED BY AMBULANCE TO A HOSPITAL SHE WENT TO THE DOCTOR THE SAME DAY DAY. A POLICE REPORT WAS FILED THE VEHICLE WAS TOTALED AND TOWED AWAY TO A SALVAGE LOT. THE FRONTAL AIR BAGS DID NOT DEPLOY DURING THE CRASH.THE FAILURE MILEAGE WAS 103,000. TF
10574205	GMC	TERRAIN	2010	2014 02 24	INVOLVED IN A 21 CAR PILE UP IN THE UPPER PENINSULA DURING A COMPLETE WHITE OUT. WE WERE ONLY TRAVELING APPROXIMATELY 25 MILES PER HOUR BUT, WE DID HAVE SERIOUS IMPACT IN THE FRONT, AFTER HITTING A TRAILER AND ALSO SERIOUS IMPACT FROM BEHIND WHEN HIT BY A TRUCK AND TRAILER. NO AIRBAGS DEPLOYED. THE TRUCK TRAVELING AHEAD OF US, THAT WE HIT, THE AIRBAGS DID DEPLOY. MY FATHER AND BROTHER, WHO WERE ALSO BOTH DRIVING CHEVY TRUCKS, AND ALSO HAD SERIOUS FRONT END DAMAGE DURING THE SAME ACCIDENT, THEIR AIRBAGS DID NOT DEPLOY EITHER. *TR
10574295	GMC	TERRAIN	2010	2014-02-21	AMERICA DID HOT DELECT ETHIER. IN

			l		
					TL* THE CONTACT OWNED A 2010 GMC TERRAIN. WHILE DRIVING 45 MPH, THE CONTACT CRASHED INTO THE REAR OF ANOTHER VEHICLE AND THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED FACIAL INJURIES THAT REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE VIN
10810541	GMC	TERRAIN	2010	2015-12-05	WAS INVALID. THE APPROXIMATE FAILURE MILEAGE WAS 51,000. GOT INTO A MAJOR ACCIDENT TWO CARS RAN INTO MY VEHICLE AND EVERYONE WAS INJURED
					AND THE AIR BAGS DID NOT COME ON TO PREVENT THAT. I HAVE INSURANCE AND POLICE REPORT
10547172	BUICK	ENCLAVE	2009	2009-08-16	THAT STATES THIS. *TR
					I HAD PASSED OUT WHILE DRIVING TO WORK DUE TO LOW BLOOD SUGAR. THE FRONT OF MY
10572633	CHEVROLET	FOLINOX	2009	2014-03-11	VEHICLE CRASHED INTO A STRUCTURE AT APPROXIMATELY 55/60 MPH. NONE OF MY AIRBAGS EVER DEPLOYED. I WAS TRANSPORTED TO THE HOSPITAL. *TR
10331539	CHEVROLET		2009	2010-04-19	TL* THE CONTACT OWNS A 2009 CHEVROLET SILVERADO. THE CONTACT STATED THAT WHILE TRAVELING APPROXIMATELY 35 MPH AND APPROACHING AN INTERSECTION, THE VEHICLE ABNORMALLY VEERED OFF THE ROAD. THE VEHICLE PROCEED TO TRAVEL OFF THE ROADWAY AND WENT AIRBORNE OVER AND EMBANKMENT BEFORE CRASHING INTO A DITCH. THE AIR BAGS DID NOT DEPLOY UPON IMPACT AND THE CONTACT SUSTAINED MODERATE TO SEVER INJURIES. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE AND A POLICE REPORT WAS FILED ACCORDINGLY. THE VEHICLE WAS TOWED TO A CHEVROLET DEALER FOR REPAIRS. THE FAILURE WAS 13,800 UPDATED 7/16/10 *CN UPDATED 08/18/10
10447821	CHEVROLET	SILVERADO	2009	2011-10-13	TL* THE CONTACT OWNS A 2009 CHEVROLET SILVERADO. THE CONTACT STATED THAT WHILE DRIVING 55 MPH, HE FELL ASLEEP AND LOST CONTROL OF THE VEHICLE. THE VEHICLE CRASHED INTO A CEMENT WALL AND THE FRONT DRIVERS AIR BAG DID NOT DEPLOY. THE CONTACT SUFFERED HEAD INJURIES DURING THE CRASH. THE VEHICLE WAS REPAIRED. THE MANUFACTURER INVESTIGATED THE FAILURE AND CONCLUDED THAT THE AIR BAG PERFORMED AS DESIGNED. THE FAILURE MILEAGE WAS 46,000 AND THE CURRENT MILEAGE WAS 55,000.
10496236	CHEVROLET	SILVERADO	2009	2013-02-01	2009 CHEVY SILVERADO LOST TRACTION ON HIGHWAY DURING SLIPPERY ROAD CONDITIONS, VEHICLE SPUN OUT AND HIT A METAL ROPED FENCE HEAD ON AND ALSO WENT ACROSS THE MEDIAN AND SLAMMED THE FRONT END OF VEHICLE INTO A GUARD RAIL STOPPING IT INSTANTLY FROM GOING INTO ON COMING TRAFFIC. THE VEHICLES DAMAGE WAS ON THE FRONT END DIRECTLY IN THE CENTER CAUSING A WEDGE INTO THE RADIATOR, ENGINE AND BENT THE FRONT OF THE FRAME. THE IMPACT WAS VERY LOUD AND SOLID. THE IMPACT CAUSED THE TRUCK TO STAND ON THE FRONT OF VEHICLE, SLAMMING THE BACK END OF THE VEHICLE ON THE GROUND WITH GREAT FORCE. THE AIRBAG DIDN'T DEPLOY WHICH AT THE SPEED OF AROUND 60 MPH AND THE PLACE THE VEHICLE WAS HIT IN, MAKES ME VERY CONCERNED ON THE SAFETY OF THIS VEHICLE. MY 5 YEAR OLD SON SAID HIS RIGHT ARM WAS HURTING AFTER THE ACCIDENT AND WITH IN THE HOUR OF HAVING THE ACCIDENT MYSELF ENDED UP IN THE HOSPITAL WITH A STIFF NECK AND A VERY SOAR AND BRUISED BACK, I WAS RELEASED WITH MINOR INJURIES AND I CONSIDER MYSELF LUCKY. PLEASE LET ME KNOW IF ANYTHING CAN BE DONE ABOUT THIS SITUATION AND THE SAFETY OF MYSELF AND MY SON. *TR
11340458	CHEVROLET	SUBURBAN	2009	2020-02-17	TL* THE CONTACT OWNS A 2009 CHEVROLET SUBURBAN. THE CONTACT STATED THAT WHILE HIS WIFE WAS DRIVING AT A LOW RATE OF SPEED, SHE ATTEMPTED TO MAKE A LEFT TURN AND WAS HIT BY A CAR COMING FROM THE OPPOSITE SIDE. THE AIR BAGS DID NOT DEPLOY UPON IMPACT. THE DRIVER WAS TREATED FOR WHIPLASH AND MULTIPLE BULGED DISKS IN RER BACK WHICH WOULD REQUIRE SURGERY. A POLICE REPORT WAS NOT FILED. THE DRIVER WAS ABLE TO DRIVE THE VEHICLE HOME AFTER THE ACCIDENT. THE CONTACT STATED THAT THE VEHICLE HAD BEEN INCLUDED IN NHTSA CAMPAIGN NUMBER: 16V381000 (AIR BAGS); HOWEVER, THE PARTS TO DO THE REPAIR WERE UNAVAILABLE. THE DEALER NOR THE MANUFACTURER HAD BEEN NOTIFIED OF THE FAILURE. THE VEHICLE HAD YET TO BE REPAIRED. THE FAILURE MILEAGE WAS APPROXIMATELY 167,000.
10944639	CHEVROLET	TRAILBLAZER	2009	2017-01-06	TL* THE CONTACT OWNED A 2009 CHEVROLET TRAILBLAZER. WHILE DRIVING 70 MPH, THE CONTACT'S VEHICLE REAR ENDED ANOTHER VEHICLE. IN TURN, THE CONTACT'S VEHICLE WAS STRUCK BY A SEMI-TRUCK. THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED INJURIES TO THE HEAD, KNEES, AND ARMS, WHICH REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED AND TOWED. THE MANUFACTURER WAS NOT MADE AWARE OF THE CRASH. THE FAILURE MILEAGE WAS 135,000.
		TDAH B: 4355	2000		
11184731	CHEVROLET	TRAILBLAZER	2009	2019-02-22	TRAVELING ON HIGHWAY APPLIED BRAKES AND HIT CAR IN REAR. AIR BAGS NOT DEPLOYED.
					TL*THE CONTACT OWNS A 2009 CHEVROLET TRAVERSE. THE CONTACT APPLIED THE BRAKES WHILE DRIVING 35 MPH AND THE VEHICLE CRASH INTO THE REAR END OF THE VEHICLE IN FRONT. THE AIR BAG DID NOT DEPLOY. THE CONTACT SUFFERED A FRACTURED STERNUM BY HITTING THE STEERING WHEEL. THE CONTACT STATED THAT THE SEAT BELT DID NOT LOCK DURING THE CRASH. THE CONTACT WAS TAKEN TO THE HOSPITAL. THE MANUFACTURER STATED THAT THEY WILL
10375125	CHEVROLET	TRAVERSE	2009	2010-12-17	PERFORM AN INVESTIGATION REGARDING THE SEAT BELT. THE FAILURE MILEAGE WAS 30,000.
	•				

		1	1	1	1
10501339	CHEVROLET	TRAVERSE	2009	2013-02-22	TL* THE CONTACT OWNS A 2009 CHEVROLET TRAVERSE. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 55 MPH, CRASHED INTO A HIGHWAY BARRIER WHILE ATTEMPTING TO AVOID CRASHING INTO ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. THE VEHICLE WAS TOWED TO A SALVAGE YARD. THE POLICE REPORTED TO THE SCENE AND A REPORT WAS FILED. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF INJURIES TO THE BACK. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE VEHICLE WAS NOT REPAIRED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE MILEAGE WAS 48,000.
10620828	GMC	ACADIA	2009	2014-07-12	TL* THE CONTACT OWNS A 2009 GMC ACADIA. THE CONTACT STATED WHILE DRIVING 20 MPH THE FRONT PASSENGER SIDE TIRE BLEW AND THE CONTACT LOST CONTROL OF THE VEHICLE, CRASHING INTO A TWO FOOT DITCH. THE VEHICLE THEN WENT THROUGH A ROW OF HEDGES AND CRASHED INTO A TREE ON THE DRIVER'S SIDE. THE SEAT BELT DID NOT RESTRAIN THE CONTACT AND THE AIR BAGS DID NOT DEPLOY. THE REAR SEATS COLLAPSED AS WELL. THE CONTACT SUSTAINED A SEVERE CONCUSSION FROM HITTING HER HEAD ON THE WINDSHIELD, BRUISED LEGS, ARM, FRACTURED NOSE, AND BRUISING TO THE FACE. THE CONTACT WAS FOUND LYING OVER THE CONSOLE AND WAS TAKEN TO THE EMERGENCY ROOM. A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS TOWED TO A COLLISION SHOP. THE CONTACT LATER RECEIVED NOTIFICATION OF NHTSA RECALL CAMPAIGN NUMBER 14V266000 (SEAT BELT) HOWEVER, THE PART NEEDED FOR THE REPAIR WAS NOT AVAILABLE. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 120,000.
11308898	GMC	ACADIA	2009	2020-02-07	I WAS DRIVING ON THE MAIN HIGHWAY GOING 35MPH AND ANOTHER VEHICLE PULLED OUT I FRONT OF ME CAUSING ME TO HIT HER WITH MY FRONT END. MY AIRBAGS NEVER DEPLOYED BUT MY SERVICE AIRBAGS LIGHT IS ON AS WELL AS THE MESSAGE ON MY BOARD.
10966352	GMC	YUKON	2009	2017-03-13	TL* THE CONTACT OWNS A 2009 GMC YUKON. WHILE DRIVING 35 MPH, THE CONTACT CRASHED INTO THE DRIVER'S SIDE DOOR OF ANOTHER VEHICLE, WHICH THEN ROLLED OVER. THE AIR BAGS FAILED TO DEPLOY. THERE WERE NO WARNING INDICATORS ILLUMINATED. THE CONTACT SUSTAINED INJURIES TO THE LEFT FOOT, LEFT KNEE, A CONCUSION, CHEST PAINS, AND A BLACK EYE. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A DEALER WHERE THE FAILURE WAS DIAGNOSED. THE DRIVER OF THE OTHER VEHICLE ALSO SUSTAINED MINOR INJURIES. THE CONTACT HAD NOT RECEIVED NOTIFICATION OF NHTSA CAMPAIGN NUMBER: 16V381000 (AIR BAGS), WHICH WAS ASSOCIATED WITH THE VIN. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 69,000.
11055457	BUICK	ENCLAVE	2008	2017-12-13	TL* THE CONTACT OWNS A 2008 BUICK ENCLAVE. WHILE DRIVING APPROXIMATELY 20 MPH, THE CONTACT LOST CONTROL AND CRASHED HEAD ON INTO ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED INJURIES TO THE HEAD, WHICH REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS TOWED TO THE CONTACT'S RESIDENCE. THE CONTACT WAS NOT SURE IF THE VEHICLE WAS DESTROYED. A LOCAL DEALER AND MANUFACTURER WERE NOT CONTACTED. THE VIN AND FAILURE MILEAGE WERE NOT AVAILABLE.
10632511	CHEVROLET	EQUINOX	2008	2014-05-14	TL* THE CONTACT OWNS A 2008 CHEVROLET EQUINOX. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, THE VEHICLE HYDRO-PLANED AND CRASHED. THE CONTACT MENTIONED THAT NONE OF THE AIR BAGS DEPLOYED. A POLICE REPORT WAS FILED AND INJURIES WERE SUSTAINED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE VEHICLE WAS INSPECTED AND THE TECHNICIAN STATED THAT THE AIR BAGS WERE NOT EXPECTED TO DEPLOY. THE FAILURE MILEAGE WAS 91,000. PAMUPDATED 09/25/14 *BF UPDATED 10/23/2014*LJ THE CONSUMER STATED THE KEY WAS STUCK IN THE IGNITION. UPDATED 12/08/14. *JB UPDATED 12/28/15.*JB THE CONSUMER STATED GM CLAIMED TO HAVE INVESTIGATED THE CRASH AND STATED THE AIR BAG WAS NOT DESIGNED TO DEPLOY IN THE TYPE OF CRASH THE CONSUMER WAS INVOLVED IN. UPDATED 01/05/16.*JB UPDATED 06/02/16.*JB *JS TL* THE CONTACT OWNS A 2008 CHEVROLET SILVERADO. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO A TREE. NEITHER THE DRIVER NOR THE PASSENGER SIDE AIR BAGS DEPLOYED. THE VEHICLE WAS DESTROYED AND THE CONTACT SUSTAINED HEAD AND BACK
10442223	CHEVROLET	SILVERADO	2008	2011-12-30	INJURIES. THE CONTACT DID CALL THE MANUFACTURER. THE FAILURE MILEAGE WAS 66,000. UPDATED 02/15/12*LJ UPDATED 02/24/12 7:10 A.M. TUESDAY MORNING, I HIT BLACK ICE AND LOST CONTROL OF MY VEHICLE. I PROCEEDED TO SLIDE UNCONTROLLABLY ACROSS THE ROAD. I THEN HIT A CLIFF WITH THE FRONT END OF MY VEHICLE, ONCE I HIT THE THE CLIFF MY VEHICLE THEN FLIPPED IN THE AIR AND LANDED ON THE DRIVER SIDE OF THE VEHICLE. ONCE I HAD LANDED ON THE PAVEMENT, ANOTHER VEHICLE CAME ALONG PROCEEDING AT AROUND 45 MPH. THE VEHICLE PROCEEDED TO HIT THE HOOD OF MY VEHICLE. THE DRIVER HIT MY HOOD DIRECTLY WITH THE FRONT END OF HIS VEHICLE. DURING THE WHOLE INCIDENT, I HAD MY SEATBELT ON. ALSO IT WAS INDICATED THAT MY AIR BAGS WERE ONE AND FUNCTIONING CORRECTLY. THE VEHICLE ITSELF WAS TOTALED AND I SUSTAINED WHIPLASH, A
10565014	CHEVROLET	SILVERADO	2008	2014-02-18	SLIGHT CONCUSSION, SEVERE BRUISES AND CUTS, AND ALSO RECEIVED A CHIPPED TOOTH FROM HITTING THE STEERING WHEEL WITH MY FACE. *TR

					I WAS ON MY WAY HOME FROM WORK AFTER WORKING A VERY LONG DAY AND I FELL ASLEEP AT THE WHEEL AND WENT OFF THE SIDE OF 225. ALL I REMEMBER WAS WAKING UP IN BETWEEN TREES ABOUT TWO FEET AWAY FROM SIMS BAYOU. MY VEHICLE WAS TOTALED. NO AIR BAGS
10672875	CHEVROLET	SILVERADO	2008	2015-01-07	DEPLOYED. *TR
					2008 CHEVY SILVERADO 4X4 WT. DRIVER SIDE AIRBAG DID NOT DEPLOY DURING CRASH. VEHICLE IMPACT WAS ON THE FRONT. A FATALITY OCCURRED DURING THIS CRASH. (PASSENGER IN OTHER VEHICLE) POINT OF IMPACT WAS FRONT OF SILVERADO INTO PASSENGER SIDE OF OTHER VEHICLE.
10678613	CHEVROLET	SILVERADO	2008	2015-01-16	*TR
					TL* THE CONTACT OWNS A 2008 CHEVROLET SILVERADO. THE CONTACT STATED THAT THE AIR BAGS FAILED TO DEPLOY AFTER BEING INVOLVED IN A CRASH. THE SPECIFICS OF THE CRASH WERE NOT AVAILABLE. A POLICE REPORT WAS FILED AND THE DRIVER SUSTAINED INJURIES TO THE HEAD, THE NECK, AND THE BACK THAT DID NOT REQUIRE MEDICAL ATTENTION. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE
10681040	CHEVROLET	SILVERADO	2008	2015-01-21	FAILURE MILEAGE WAS 111,687.
10761080	CHEVROLET	SILVERADO	2008	2015-08-25	TL* THE CONTACT OWNED A 2008 CHEVROLET SILVERADO. WHILE DRIVING 65 MPH, THE CONTACT FELL ASLEEP BEHIND THE WHEEL AND THE VEHICLE DROVE OFF THE ROAD. THE CONTACT CRASHED INTO THE SUPPORT CABLES ON THE SIDE OF THE ROAD. THE CONTACT STATED THAT THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THERE WERE NO INJURIES. THE VEHICLE WAS TOWED TO AN INDEPENDENT MECHANIC WHERE IT WAS DEEMED DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 127,000.
					TL*THE CONTACT OWNS A 2008 CHEVROLET TRAILBLAZER. WHILE DRIVING 35 MPH, THE CONTACT WAS INVOLVED IN A HEAD-ON CRASH. THE ENTIRE FRONT END OF HIS VEHICLE WAS CRUSHED AND THE INSURANCE COMPANY DECLARED THE VEHICLE AS DESTROYED. THE SEAT BELTS PROPERLY RESTRAINED THE CONTACT, BUT THE AIR BAGS FAILED TO DEPLOY. THERE WERE NO
10261711	CHEVROLET	TRAILBLAZER	2008	2009-03-07	INJURIES, BUT A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS 6,500. THE VEHICLE LOST CONTROL ON BLACK ICE, THE STEERING WHEEL AND BRAKES LOCKED UP AND THE TRAILBLAZER HIT A TREE. THE AIRBAG NEVER DEPLOYED. THE VEHICLE'S FRAME WAS BENT.
10679071	CHEVROLET	TRAILBLAZER	2008	2015-01-18	THE SUV WAS CONSIDERED A TOTAL LOSS. THE VEHICLE PICKED UP A LITTLE MORE SPEED WHILE ON THE ICE, BUT NO MORE THAN 30 MPH. *TR
11143666	CHEVROLET	TRAILBLAZER	2008	2018-10-19	WAS TRAVELING 40 MPH AND WAS HIT HEAD ON BY ANOTHER VEHICLE. NONE OF THE AIR BAGS DEPLOYED. WAS ON A CITY STREET WITH A 40 MPH SPEED LIMIT. GOING STRAIGHT.
11324166	CHEVROLET	TRAILBLAZER	2008	2020-05-05	TL* THE CONTACT OWNED A 2008 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT HE CRASHED AND REAR ENDED INTO ANOTHER VEHICLE STOPPED AT A STOP LIGHT AT 53 MPH. THE CONTACT STATED THAT THE AIR BAGS FAILED TO DEPLOY AS WELL AS THE SEAT BELT PRETENSIONER FAILED TO ENGAGE. THE CONTACT SUSTAINED A SEVERE CONCUSSION & ALMOST BIT HIS TONGUE OFF WITH HIS HEAD SMASHING INTO THE WINDSHIELD. HE ALSO SUSTAINED CUTS AND BRUISES ON HIS LOWER BODY AND LEGS AND A BRUISED NECK. THERE WAS A PASSENGER IN THE OTHER VEHICLE THAT HAD TO BE TRANSPORTED TO THE HOSPITAL WITH INJURIES AS WELL. THE VEHICLE WAS TOTALED WITH THE WHOLE FRONT SMASHED IN UP TO THE WINDSHIELD. THE DEALER AND MANUFACTURER HAD NOT BEEN CONTACTED YET. THE FAILURE MILEAGE WAS 220,000. THE VIN WAS NOT AVAILABLE. *LN*JB
10615043	GMC	ACADIA	2008	2013-04-30	TL* THE CONTACT OWNS A 2008 GMC ACADIA. THE CONTACT STATED THAT WHILE DRIVING 50 MPH, THE VEHICLE WAS INVOLVED IN A FRONT END CRASH IN WHICH NO AIR BAGS DEPLOYED. A POLICE REPORT WAS FILED AND NO INJURIES WERE SUSTAINED. THE VEHICLE WAS TAKEN TO A DEALER. THE FAILURE MILEAGE WAS 113,000 AND THE CURRENT MILEAGE WAS 132,653.
					MY WIFE FELL ASLEEP RAN OFF THE ROAD STRUCK A UTILITY POLE AND A LARGE DIRT EMBANKMENT. THE AIR BAGS DID NOT DEPLOY NOR DID THE BELT TENSIONERS, SHE HIT THE STEERING COLUMN SO HARD SHE IT BROKE THE COLUMN AND BROKE HER STERNUM. OUR GRANDDAUGHTER WAS IN THE FRONT PASSENGER SEAT THE AIR BAG NOR THE TENNSIONERS DEPLOYED RESULTING HER BACK BEING BROKEN IN TWO PLACES AND ALSO HER FOOT WAS BROKEN. I CONTACTED GENERAL MOTORS AND THEY SENT A MAN TO DOWNLOAD THE COMPUTER INFORMATION THEY SENT ME A COPY OF THE INFO AND LATER CONTACTED ME SAYING THE INFO SHOWED EVERYTHING WAS WORKING PROPERLY. PRYOR TO THE ACCIDENT I HAD THE AUTO IN FOR THE RECALL ON THIS PROBLEM. I ALSO HAD IT IN FOR ANOTHER RECALL FOR THE HEADLIGHTS AND THEY HAD TO REMOVE A LARGE PART OF THE FRONT TO DO THE REPAIR AND DONE A POOR JOB OF PUTTING IT BACK TOGETHER I RETURNED IT AND THEY FINALLY GOT IT RIGHT, IN THE MEAN TIME THE SERVICE AIR BAG LIGHT CAME ON AND THEY REPAIRED THAT. LATER AFTER THE ACCIDENT I WENT BACK TO THE DEALER AND QUESTIONED THE BODY SHOP MANAGER ABOUT PUTTING IT BACK TOGETHER PROPERLY AND THEN TOLD HIM ABOUT THE ACCIDENT THEN HE HAD NOTHING ELSE TO SAY. THE AUTO WAS A TOTAL LOSS AFTER A LENGTH OF TIME WIFE AND GRANDDAUGHTER GOT OUT OF HOSPITAL. THIS CAR WAS RECALLED FOR THIS VERY REASON. MY INSURANCE COMPANY PAID MY GRANDDAUGHTER \$95,000 FOR HER INJURIES AND COMMENTED
11066850	GMC	ACADIA	2008	2015-08-21	THAT THEY WOULD PROBABLY SUE GM TO GET THAT BACK.

INTERSECTION, WHEN THE CARS TRUCK THE SOUTH EMBANAMENT OF THE TIMITESE DISPOSED WAS DURBED TO PHICE CHASH. AND ALSO UNSURE IT THE STATE REST HAD ON OF THE STORE OF THE STATE THE STATE THE OF THE CRASH. THE STATE THE OF THE CRASH. THE STATE THE OF THE CRASH. THE STATE THE STAT	Г						
11143613 GMC ENVOY 2008 2018-10-24 ON 10/34/2018 WHILE DRIVING MY 2008 GMC ENVOY SLT, I WAS INVOIUVED IN A HEA 11143613 GMC ENVOY 2008 2018-10-24 ON 10/34/2018 WHILE DRIVING MY 2008 GMC ENVOY SLT, I WAS INVOIUVED IN A HEA 11143613 GMC ENVOY 2008 2018-10-24 ON 10/34/2018 WHILE DRIVING MY 2008 GMC ENVOY SLT, I WAS INVOIUVED IN A HEA 1114 THE CONTACT OWNS A 2008 GMC YUKON SL, WHILE DRIVING 65 MPH, THE CONT 1114 THAT ANOTHER VEHICLE WAS SWERVING TOWARDS HER VEHICLE. THE REPORT FR PASSINGER SIDE, AND REAR PRAME OF THE CONTACT SHELLE. THE REPORT FR PASSINGER SIDE, AND REAR PRAME OF THE CONTACT WAS KNOCKED UNCONSCIOUS AND REQUIRED MEDICAL 1118 THE CONTACT OWNS A 2008 GMC YUKON SLOW SHOULED BROM HER SHELLE THE REPORT FR PASSINGER SIDE, AND REAR PRAME OF THE CONTACT SHELLE. THE REPORT FR PASSINGER SIDE, AND REAR PRAME OF THE CONTACT SHELLE THE REPORT FR PASSINGER SIDE, AND THE CONTACT WAS KNOCKED UNCONSCIOUS AND REQUIRED MEDICAL 1118 THE CONTACT OWNS AND REAR PRAME OF THE CONTACT SHELLE THE REPORT FROM THE PROMEMENT OF THE AND A CASE WAS 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILLED 1118 CONTACT STATED 1118 CONTACT STATED THAT THE CASE HAD CLOSED. THE CONTACT	11310375	GMC	AC	CADIA 2	2008	2015-11-26	VEHICLE WAS SOUTHBOUND ON COUNTY ROAD AND ATTEMPTED TO MAKE A RIGHT TURN AT THE INTERSECTION, WHEN THE CAR STRUCK THE SOUTH EMBANKMENT OF THE T INTERSECTION, AS DRIVER WAS UNABLE TO NAVIGATE THE TURN. NONE OF THE SIDE OR FRONT AIRBAGS IN THE CAR DEPLOYED AS A RESULT OF THE CRASH. I AM ALSO UNSURE IF THE SEAT BELT HAD OPERATED CORRECTLY (SEAT BELT WAS BEING WORN AT THE TIME OF THE CRASH). THE DRIVER'S HEAD HIT THE SIDE WINDOW AND AS A RESULT HE SUSTAINED A HEAD INJURY AND AN EYE INJURY RESULTING IN OPTIC NERVE DAMAGE AND COMPLETE LOSS OF VISION IN THE EYE. I UNDERSTAND THERE WERE PROBLEMS WITH THE AIRBAGS ON THESE VEHICLES WITH A POSSIBLE RECALL ISSUED. I DO HAVE ALL THE CORRESPONDING ACCIDENT REPORTS, MEDICAL REPORTS, ETC.
ON 10/24/2018 WHILE DRIVING MY 2008 GMC ENVOY SLT, I WAS INVOLVED IN A HEA COLLISION WHICH RESULTED IN MY CAR BEING TOTALED. NONE OF MY AIR BAGS DEP THE THE CONTACT WAS A 2008 GMC YUKON IL WHILE DRIVING 65 MPH, THE CONTACT MAY THAN ADMITTER YELLER WAS SWERNING TOWARDS HER SET THE CONTACT WAS THAN ADMITTER YELLER WAS SWERNING TOWARDS HER SET THE CONTACT WAS THAN ADMITTER YELLER WAS SWERNING TOWARDS HER SET THE CONTACT WAS THAN ADMITTER YELLER WAS SWERNING TOWARDS HER SET THE CONTACT WAS THAN ADMITTER YELLER WAS THAN ADMITTER WAS WERE ADMITTED TO DEPLOY. THE CONTACT WAS KNOCKED WAS COLUMN THE WERE DAMAGED. THE PASSENGER SIDE, AND REAR FRAME OF THE CONTACT SY PHICLE WERE DAMAGED. THE PASSENGER SIDE, AND REAR FRAME OF THE CONTACT SY PHICLE WERE DAMAGED. THE PASSENGER SIDE, AND REAR FRAME OF THE CONTACT SY PHICLE WAS NOT REPAIRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD COSED. THE PAPPORT REPAIRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD COSED. THE PAPPORT REPAIRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD COSED. THE PAPPORT REPAIRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD COSED. THE PAPPORT REPAIRED. THE PAUL FROM THE CONTACT STATED THAT THE CASE HAD COSED. THE PAPPORT REPAIRED THE PAUL FROM THE PAPPORT AND ADDITION THE CONTACT STATED THAT THE CASE HAD COSED. THE PAPPORT AND ADDITION THE PAPPORT	10007110					201112	I WAS IN AN AUTO ACCIDENT ON A MAJOR HIGHWAY AND UPON CRASHING MY AIRBAG DIDN'T
114.3613 GMC ENVOY 2008 2018-10-24 COLLISION WHICH RESULTED IN MY CAR BEING TOTALED. NONE OF MY AIR BAGS DEP IL "THE CONTACT OWNS A 2008 GMC YUKON XL. WHILE DRIVING SO SPIPL, THE CONTACT HAD THE ACCELERATOR PEDAL TO INCREASE SPEED AND AVOID A COLLISION, HOWEVER, I VEHICLE LOYS CONTROL AND CREAKED INTO THE CONTACT WHICH E PROVE PROMOTED THE PROVE PROSENOER SIDE, AND REAR FRAME OF THE CONTACT WHICH E WERE PROMOTED THE PROVE PROVIDED THE PROVE PROVIDED THE PROVIDE AND REAR FRAME OF THE CONTACT WHICH E WERE PROMOTED THE PROVIDE AND REAR FRAME OF THE CONTACT WHICH E WAS TOWNED FROM THE SCHE ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWNED FROM THE SCHE ATTENTION. A POLICE REPORT WAS SHED. THE VEHICLE WAS TOWNED FROM THE SCHE CONTACT STATED THAT THE VEHICLE WAS NOT REPARRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILEDAGE INTERIOR OF THE VEHICLE STRUCK A DITCH, WENT ARRANGE MILEDAGE MILEDAGE AT AN UNKNOWN SPEED. THE VEHICLE STRUCK A DITCH, WENT ARRANGE MILEDAGE AND THE SCHE AT AN UNKNOWN SPEED. THE VEHICLE STRUCK A DITCH, WENT ARRANGE SAME THAT THE CONTACT OWNED A 2007 CADILLAC ESCALADE. THE CONTACT FIELD SHAPE AND THE SCHE VEHICLE AND EACH WINDOW WAS BROKEN AND SMASHED. MONE OF THE EIGHT ARRANGE PROVIDE AND THE VEHICLE STRUCK A DITCH, WENT ARRANGE SOME SHOULDER SONE, AND A BROKEN HAND IN TWO PLACES. THE INSURANCE COMPANY STATED THAT THE DEPLOYED. THE CONTACT SONTACT SHAPE AND THE SCHE VEHICLE HYDROPOLITED AND CONTACT SHAPE AND THE SCHE VEHICLE HYDROPOLITED AND CONTACT SHAPE AND THE SCHE SHAPE AND THE SCH	10667413	JIVIC	EN	NVOY	2008	2014-12-19	DEPLOY AND MY FACE SMASHED INTO THE STEEKING WHEEL.
11.* THE CONTACT OWNS A 2008 GMC YUKON XI. WHILE DRIVING 65 MPH, THE CONT THAT AND THER VEHICLE WAS SWERVING TOWARDS HER VEHICLE. THE CONTACT AND THE ACCESSEADOR PEDAL TO INCRESSE SEED AND ADDITION OF THE CONTACT SWENCE. THE CONTACT SHE CONTACT SWENCE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE. THE FRONT FR. PASSENGER SIDE, AND REAR FRAME OF THE CONTACT SHEED. THE CONTACT SHEED WHO CONTACT SHEED THE THE VEHICLE WAS TOWER OWN THE PASSEN OF THE PASSEN OWN THE PASSE							ON 10/24/2018 WHILE DRIVING MY 2008 GMC ENVOY SLT, I WAS INVOLVED IN A HEAD-ON
THAT ANDTHEN VEHICLE WAS SWERNING TOWARDS HER VEHICLE. THE CONTACT TAKE THE ACCELERATOR PEDAL TO INCREASE SPEED AND AVOID COURSION, HOWEVER, T VEHICLE LOST CONTROL AND CRASHED INTO THE CONTACT'S VEHICLE THE FRONT RE PASSENDERS RIGH, AND FRAM FRAME OF THE CONTACT'S VEHICLE THE FRONT RE PASSENDERS RIGH, AND FRAME FRAME OF THE CONTACT WAS RINDECKED UNCONSCIOUS AND REQUIRED MEE ATTENTION, A POLICE REPORT WAS RINDECKED UNCONSCIOUS AND REQUIRED MEE ATTENTION, A POLICE REPORT WAS RINDECKED WAS TOWED FROM THE SCEN CONTACT STATED THAT THE VEHICLE WAS NOT REPAIRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILEAGE 130,000. THE AIR BAGS FAILED TO DEFLOY, THE VEHICLE WAS NOT REPAIRED. THE DEALER WAS CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILEAGE 130,000. THE AIR AND NAME OF THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILEAGE 130,000. THE THE CONTACT SUPPORT WAS RIFLED. ALL FOUR WHELES AND THE SCAELE AND	11143613	GMC	EN	NVOY 2	2008	2018-10-24	COLLISION WHICH RESULTED IN MY CAR BEING TOTALED. NONE OF MY AIR BAGS DEPLOYED.
AT AN UNKNOWN SPED. THE VEHICLE STRUCK A DITCH, WENT AIRBORNE, AND ROLL SEVERAL TIMES. A POLICE REPORT WAS FILED. ALL FOUN WHELE AND TIMES CAME. VEHICLE AND EACH WINDOW WAS BROKEN AND SMASHED. NONE OF THE EIGHT ARD DEPLOYED. THE CONTACT SUSTAINED A BROKEN COLLAR BONE, SHOULDER BONE, RAD AND ABBOKEN HAND IN TWO PLACES. THE INSURANCE COMPANY STATED THAT THE WAS DESTROYED. CADILLAC HAS BEEN NOTIFIED AND WILL INSPECT THE VEHICLE. THE AND FAILURE MILEAGES WERE 28,000. 10226642 CADILLAC ESCALADE 2007 2008-04-26 TIL*THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING 35 MPH IN THE VEHICLE HYDROPLANED AND CRASHED INTO SEVERAL TREES. THE VEHICLE SPUN ARD ENDED UP FACING THE OPPOSITE DIRECTION. THE AIR BAGS FAILED TO DEPLOY AND WAS INJURED. A POLICE REPORT WAS FILED. THE FAILURE MILEAGES WAS UNKNOWN. TIL*THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING 95 MPH IN THE VEHICLE HYDROPLANED AND CRASHED INTO SEVERAL TREES. THE VEHICLE SPUN ARD ENDED UP FACING THE OPPOSITE DIRECTION. THE AIR BAGS FAILED TO DEPLOY AND WAS INJURED. A POLICE REPORT WAS FILED. THE FAILURE MILEAGES WAS UNKNOWN. TIL*THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING 96 CRASHED THE CONTECT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING 96 CRASHED THE FAILURE MILEAGE WAS UNKNOWN THE FRONT BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE FROM THE FRONT BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE FROM THE FRONT BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE FROM THE FRONT BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE FROM THE MILEAGES WERE SR,000. I WAS IN AN ACCIDENT WERE ISTRUCK TWO HORSES THAT RUN OUT INTO THE HIGHWOOD FROM THE MILEAGES WERE SR,000. I WAS IN AN ACCIDENT WERE ISTRUCK TWO HORSES THAT RUN OUT INTO THE HIGHWOOD FROM THE AIR BAGS AREAS PREMOVED. I WAS WERNING MYS AND TO CHEVROLET EQUINOX. WHEN ADDITION TO PEPLOY. THE AIR BAGS AREAS PREMOVED. I WAS WERNING MYS AND TO PEPLOY. THE AIR BAGS AREAS PREMOVED. I WAS WERNING MYS AND TO PEPLOY. THE AIR BAGS AND TO THE FROM THE AIR BAG	11080754	SMC	YU	UKON XL	2008	2017-01-08	TL* THE CONTACT OWNS A 2008 GMC YUKON XL. WHILE DRIVING 65 MPH, THE CONTACT NOTICED THAT ANOTHER VEHICLE WAS SWERVING TOWARDS HER VEHICLE. THE CONTACT HAD TO DEPRESS THE ACCELERATOR PEDAL TO INCREASE SPEED AND AVOID A COLLISION; HOWEVER, THE OTHER VEHICLE LOST CONTROL AND CRASHED INTO THE CONTACT'S VEHICLE. THE FRONT FRAME, FRONT PASSENGER SIDE, AND REAR FRAME OF THE CONTACT'S VEHICLE WERE DAMAGED. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS KNOCKED UNCONSCIOUS AND REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED FROM THE SCENE. THE CONTACT STATED THAT THE VEHICLE WAS INSPECTED BY A MECHANIC FRIEND WHO CONFIRMED THE AIR BAGS FAILED TO DEPLOY. THE VEHICLE WAS NOT REPAIRED. THE DEALER WAS NOT CONTACTED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE AND A CASE WAS OPENED. THE CONTACT STATED THAT THE CASE HAD CLOSED. THE APPROXIMATE FAILURE MILEAGE WAS 150,000.
10207326 CADILLAC ESCALADE 2007 2007-10-06 AND FAILURE MILEAGES WERE 28,000. TL*THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING 35 MPH IN THE VEHICLE HYDROPLANED AND CRASHED INTO SEVERAL TREES. THE VEHICLE SPUN ARC ENDED UP FACING THE OPPOSITE DIRECTION. THE AIR BAGS FAILED TO DEPLOY AND TWO MAS INJURED. A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS UNKNOWN TI.* THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING SHE CRASHED TREE. THE ENTIRE RENOT-END OF THE VEHICLE WAS DAMAGED, AND NONE OF THE AIR DEPLOYED. CONSEQUENTLY SHE RECEIVED INJURIES TO HER NECK. A POLICE REPORT ALSO THE FRONT END OF THE VEHICLE WAS DAMAGED, AND NONE OF THE AIR DEPLOYED. CONSEQUENTLY SHE RECEIVED INJURIES TO HER NECK. A POLICE REPORT ALSO THE FRONT BRAKE PADS FRACTURED WITHIN THE FIRST TWO MONTHS OF PURC VEHICLE. THE BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE F. CURRENT MILEAGES WERE S8,000. I WAS IN AN ACCIDENT WERE I STRUCK TWO HORSES THAT RUN OUT INTO THE HIGHWOOF ME IN MY 2007 CHEVROLET EQUINOX LIST. THE FIRST HORSE STRUCK MY PASSENGE QUARTER PANEL AND THIS CAUSED ME TO SWERVE INTO ANOTHER HORSE ON THE DI WAS TRAVELING AT APPROXIMATELY 50 MPH AND THE DAMAGE TO THE FRONT OF NEW YER SERVICE AND AND THE PROPEDITE DIST. HE HE AIRBAGS NEVER DEPLOYED DURING KNOW THAT THE AIRBAGS ARE SET OF BY SPECIFIC SPEEDS AND DAMAGE BUT MY WHO FMY 2007 CHEVROLET EQUINOX LSWA SHEATIY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS WEARING MY 54 AND IT OFFERED LITTLE HELP SINCE I WAS NEARLY REMOVED. I WAS THE DIT AND IT AND IT OFFER THE TOTAL TO AND IT OFFER THE THIS HOLD LITTLE HELP AND IT AND IT OFFER THE TA							TL*THE CONTACT OWNED A 2007 CADILLAC ESCALADE. THE CONTACT FELL ASLEEP WHILE DRIVING AT AN UNKNOWN SPEED. THE VEHICLE STRUCK A DITCH, WENT AIRBORNE, AND ROLLED OVER SEVERAL TIMES. A POLICE REPORT WAS FILED. ALL FOUR WHEELS AND TIRES CAME OFF THE VEHICLE AND EACH WINDOW WAS BROKEN AND SMASHED. NONE OF THE EIGHT AIR BAGS DEPLOYED. THE CONTACT SUSTAINED A BROKEN COLLAR BONE, SHOULDER BONE, ROTARY CUP, AND A BROKEN HAND IN TWO PLACES. THE INSURANCE COMPANY STATED THAT THE VEHICLE WAS DESTROYED. CADILLAC HAS BEEN NOTIFIED AND WILL INSPECT THE VEHICLE. THE CURRENT
VEHICLE HYDROPLANED AND CRASHED INTO SEVERAL TREES. THE VEHICLE SPUN ARC ENDED UP FACING THE OPPOSITE DIRECTION. THE AIR BAGS FAILED TO DEPLOY AND TO WAS INJURED. A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS UNKNOWN TI.* THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING SHE CRASHET TREE. THE ENTIRE FRONT-END OF THE VEHICLE WAS DAMAGED, AND NONE OF THE AID DEPLOYED. CONSEQUENTLY SHE RECEIVED INJURIES TO HER NECK. A POLICE REPORT ALSO THE FRONT BRAKE PADS FRACTURED WITHIN THE FIRST TWO MONTHS OF PURC VEHICLE. THE BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE F. CURRENT MILEAGES WERE 58,000. I WAS IN AN ACCIDENT WERE I STRUCK TWO HORSES THAT RUN OUT INTO THE HIGHWOF ME IN MY 2007 CHEVROLET EQUINOX LIS. THE FIRST HORSE STRUCK MY PASSENGE QUARTER PANEL AND THIS CAUSED ME TO SWERVE INTO ANOTHER HORSE ON THE DI WAS TRAVELING AT APPROXIMATELY 50 MPH AND THE DAMAGE TO THE FRONT OF NETW YEARY SERIOUS AND MY COMPLAINT IS THAT THE AIRBAGS NEVER DEPLOYED DURING KNOW THAT THE AIRBAGS MUST HAVE BEEN FAULTY SINCE I DEPLOY. **TR 10317216 CHEVROLET EQUINOX 2007 2010-03-03 DEPLOY. **TR AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRO DAMAGE SUSTAINED. **TR AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRO DAMAGE SUSTAINED. **TR AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRO DAMAGE SUSTAINED. **TR AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRO DAMAGE SUSTAINED. **TR AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT	10207326 C	CADILLAC	LLAC ES	SCALADE 2	2007	2007-10-06	
I WAS IN AN ACCIDENT WERE I STRUCK TWO HORSES THAT RUN OUT INTO THE HIGHWOF ME IN MY 2007 CHEVROLET EQUINOX LSI. THE FIRST HORSE STRUCK MY PASSENGE QUARTER PANEL AND THIS CAUSED ME TO SWERVE INTO ANOTHER HORSE ON THE DI WAS TRAVELING AT APPROXIMATELY 50 MPH AND THE DAMAGE TO THE FRONT OF VERY SERIOUS AND MY COMPLAINT IS THAT THE AIRBAGS NEVER DEPLOYED DURING KNOW THAT THE AIRBAGS ARE SET OF BY SPECIFIC SPEEDS AND DAMAGE BUT MY WHOF MY 2007 CHEVROLET EQUINOX LS WAS NEARLY REMOVED. I WAS WEARING MY SA AND IT OFFERED LITTLE HELP SINCE I WAS HIT TWICE FROM OPPOSITE SIDES. I WAS TO RESPONDING EMERGENCY CREW THAT THE AIRBAG MUST HAVE BEEN FAULTY SINCE I RESPONDING EMERGENCY CREW THAT THE AIRBAG MUST HAVE BEEN FAULTY SINCE I WAS HIT TWICE FROM OPPOSITE SIDES. I WAS TO DEPLOY. *TR AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRO DAMAGE SUSTAINED. *TR THE THE CONTACT OWNED A 2007 CHEVROLET EQUINOX. WHILE DRIVING 20 MPH, TH CRASHED INTO A CONCRETE EMBANKMENT TO AVOID COLLIDING WITH ANOTHER VEIL AIR BAG FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SHOUL LEFT ARM THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. TWAS DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AND DESTROYED AND	10226642 C	CADILLAC	LLAC ES	SCALADE ;	2007	2008-04-26	TL*THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING 35 MPH IN THE RAIN, THE VEHICLE HYDROPLANED AND CRASHED INTO SEVERAL TREES. THE VEHICLE SPUN AROUND AND ENDED UP FACING THE OPPOSITE DIRECTION. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT WAS INJURED. A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS UNKNOWN. TL* THE CONTACT OWNS A 2007 CADILLAC ESCALADE. WHILE DRIVING SHE CRASHED INTO A TREE. THE ENTIRE FRONT-END OF THE VEHICLE WAS DAMAGED, AND NONE OF THE AIR BAGS DEPLOYED. CONSEQUENTLY SHE RECEIVED INJURIES TO HER NECK. A POLICE REPORT WAS FILED. ALSO THE FRONT BRAKE PADS FRACTURED WITHIN THE FIRST TWO MONTHS OF PURCHASING THE VEHICLE. THE BRAKE PADS WERE REPLACED UNDER THE SERVICE WARRANTY. THE FAILURE AND
FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRO DAMAGE SUSTAINED. *TR TL* THE CONTACT OWNED A 2007 CHEVROLET EQUINOX. WHILE DRIVING 20 MPH, TH CRASHED INTO A CONCRETE EMBANKMENT TO AVOID COLLIDING WITH ANOTHER VEI AIR BAG FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SHOUL LEFT ARM THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. T WAS DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY A							I WAS IN AN ACCIDENT WERE I STRUCK TWO HORSES THAT RUN OUT INTO THE HIGHWAY IN FRONT OF ME IN MY 2007 CHEVROLET EQUINOX LSI. THE FIRST HORSE STRUCK MY PASSENGERSIDE FRONT QUARTER PANEL AND THIS CAUSED ME TO SWERVE INTO ANOTHER HORSE ON THE DRIVER SIDE. I WAS TRAVELING AT APPROXIMATELY 50 MPH AND THE DAMAGE TO THE FRONT OF MY CAR WAS VERY SERIOUS AND MY COMPLAINT IS THAT THE AIRBAGS NEVER DEPLOYED DURING THE CRASH. I KNOW THAT THE AIRBAGS ARE SET OF BY SPECIFIC SPEEDS AND DAMAGE BUT MY WHOLE FRONT OF MY 2007 CHEVROLET EQUINOX LS WAS NEARLY REMOVED. I WAS WEARING MY SAFETY BELT AND IT OFFERED LITTLE HELP SINCE I WAS HIT TWICE FROM OPPOSITE SIDES. I WAS TOLD BY RESPONDING EMERGENCY CREW THAT THE AIRBAG MUST HAVE BEEN FAULTY SINCE IT DID NOT
10370521 CHEVROLET EQUINOX 2007 2010-12-13 DAMAGE SUSTAINED. *TR TL* THE CONTACT OWNED A 2007 CHEVROLET EQUINOX. WHILE DRIVING 20 MPH, TH CRASHED INTO A CONCRETE EMBANKMENT TO AVOID COLLIDING WITH ANOTHER VEI AIR BAG FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SHOUL LEFT ARM THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. T WAS DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY A						-	AUTOMOBILE ACCIDENT AT ROUGHLY 20 MILES AN HOUR IN A 2007 CHEVY EQUINOX MOSTLY
TL* THE CONTACT OWNED A 2007 CHEVROLET EQUINOX. WHILE DRIVING 20 MPH, TH CRASHED INTO A CONCRETE EMBANKMENT TO AVOID COLLIDING WITH ANOTHER VEI AIR BAG FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SHOUL LEFT ARM THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. T WAS DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY A	10370521	CHEVROLET	ROLET FO	OUINOX	2007	2010-12-13	FRONT END AND DRIVER SIDE DAMAGE. THE AIR BAGS DID NOT DEPLOY. MAJOR FRONT END DAMAGE SUSTAINED. *TR
THAT THE AIR BAG SHOULD HAVE DEPLOYED SINCE IT WAS JUST INSTALLED. THE MAN							TL* THE CONTACT OWNED A 2007 CHEVROLET EQUINOX. WHILE DRIVING 20 MPH, THE CONTACT CRASHED INTO A CONCRETE EMBANKMENT TO AVOID COLLIDING WITH ANOTHER VEHICLE. THE AIR BAG FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SHOULDER AND LEFT ARM THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS DESTROYED AND TOWED TO A TOW LOT. THE CONTACT CALLED ALLEN TILLERY AUTO (LOCATED AT 4573 CENTRAL AVE, HOT SPRING, AR 71913, (501) 881-4160) AND WAS INFORMED THAT THE AIR BAG SHOULD HAVE DEPLOYED SINCE IT WAS JUST INSTALLED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE AND DID NOT ASSIST. THE APPROXIMATE FAILURE MILEAGE WAS

	1	1			
					TL* THE CONTACT OWNS A 2007 CHEVROLET SILVERADO. THE CONTACT STATED THAT WHILE TRAVELING APPROXIMATELY 35 MPH, A VEHICLE AHEAD OF HIM MADE AN UNEXPECTED LEFT TURN. THE CONTACT CRASHED INTO THE THE PRECEDING VEHICLE AND THE AIR BAGS DID NOT DEPLOY UPON IMPACT. THE CONTACT WAS INJURED AND A POLICE REPORT WAS FILED ACCORDINGLY. THE VEHICLE WAS TOWED TO A LOCAL DEALER WHERE UNKNOWN REPAIRS WERE MADE THE VEHICLE WAS TRADED IN. THE VIN WAS NOT AVAILABLE AND THE FAILURE MILEAGE
10331536	CHEVROLET	SILVERADO	2007	2007-09-07	WAS APPROXIMATELY 28,000. UPDATED 07/19/10 *BF UPDATED 07/21/10
					TL* THE CONTACT OWNS A 2007 CHEVROLET SILVERADO. THE CONTACT STATED THAT WHILE DRIVING 45 MPH, THE VEHICLE HYDRO PLANED AND THE CONTACT CRASHED INTO THE ROAD BARRIER. NO AIR BAGS DEPLOYED UPON IMPACT. THERE WERE FOUR INJURIES AND A POLICE REPORT WAS FILED. INJURY DETAILS WERE NOT AVAILABLE. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE AND CURRENT MILEAGE
10585572	CHEVROLET	SILVERADO	2007	2014-04-22	WAS 102,000.
10606814	CHEVROLET	SILVERADO	2007	2014-06-12	ON IMPACT TO FRONT END OF MY VEHICLE THE AIR BAGS DID NOT DEPLOY. THE AIR BAGS ON THE OTHER VEHICLE DID DEPLOY. HOW CAN I BE SURE MY AIRBAGS ARE FUNCTIONING PROPERLY. THERE IS ABOUT \$9,000 DAMAGE TO MY VEHICLE. I AM SENDINGAGAIN BECAUSE I AM NOT CERTAIN THE FIRST ONE WENT THROUGH. *TR
10608220	CHEVROLET	SILVERADO	2007	2012-08-17	VEHICLE WAS INVOLVED IN HEAD ON COLLISION THAT TOTALED IT. OTHER VEHICLE WAS AN OLDER MODEL VAN, DO NOT KNOW EXTENT OF DAMAGES TO IT. MY CONCERN IS THE AIR BAGS DID NOT DEPLOY WAS TOLD BY GM THAT CRASH DID NOT MEET CRITERIA FOR DEPLOYMENT!!!!! A HEAD ON COLLISION AT 50 MPH THAT TOTALED 2500 SERIES CHEVY TRUCK. HARD FOR ME TO BELIEVE I NOW OWN A 2008 CHEVY 1500 SERIES, DO I NEED TO CONCERNED? *TR
10649638	CHEVROLET	SILVERADO	2007	2014-09-29	TL* THE CONTACT OWNS A 2007 CHEVROLET SILVERADO 1500. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 15 MPH, THE VEHICLE CRASHED INTO A TREE CAUSING EXTENSIVE DAMAGE TO THE FRONT END. THE CONTACT INDICATED THAT DURING THE CRASH THE FRONT AIR BAGS DID NOT DEPLOY AND THE DRIVER SUFFERED INJURIES TO THE RIGHT KNEE, WHILE THE FRONT PASSENGER SUFFERED INJURIES TO BOTH KNEES AND HEAD. A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 95,000.
10512756	CHEVROLET	SUBURBAN	2007	2013-05-19	WE WERE DRIVING HOME WHEN A PERSON RAN A RED LIGHT AND HIT US. WE WERE CROSSING AN INTERSECTION ABOUT 15 MILES AN HOUR AND THEY HIT THE FRONT PART OF OUR SUBURBAN. EVERYTHING WAS DAMAGED THE HOOD, AND EVERYTHING INSIDE THE HOOD SUSTAINED DAMAGE. THERE WAS A LIQUID THAT WAS LEAKING BUT I AM UNAWARE OF THE SUBSTANCE. THE PERSON THAT HIT US MUST HAVE BEEN GOING ABOUT 40-60 MILES AN HOUR. AFTER THEY FLED THE SEEN POLICE MENTIONED THAT THEIR AIR BAGS WERE DEPLOYED. MY CONCERN WAS WHY OUR AIR BAGS DID NOT DEPLOY AS WELL. MY DAUGHTER AND I BOTH HIT OUR HEADS ON OUR SIDE WINDOWS. MY SON HAD SLIGHT INJURY MOSTLY FROM THE SEATBELT. MY SONS DOOR HAD TO BE OPENED FROM THE POLICE OFFICER ON THE SCREEN. MY BIGGEST CONCERN WAS ABOUT THE AIRBAGS AND ALSO THE ONSTAR DID NOT WORK AS WELL. *TR
10400538	CHEVROLET	ТАНОЕ	2007	2010-03-19	TL* THE CONTACT OWNS A 2007 CHEVROLET TAHOE. THE CONTACT STATED THAT THE VEHICLE WAS INVOLVED IN A FRONTAL CRASH WITH ANOTHER VEHICLE AT APPROXIMATELY 30 MPH BUT THE AIR BAGS DID NOT DEPLOY. THE DRIVER OF THE CONTACT'S VEHICLE AND A PASSENGER SUFFERED MINOR INJURIES. THE VEHICLE WAS DESTROYED AND A POLICE REPORT WAS FILED. THE CONTACT CALLED THE MANUFACTURER WHO TOOK A COMPLAINT BUT PROVIDED NO FURTHER ASSISTANCE. THE CURRENT AND FAILURE MILEAGES WERE UNKNOWN. THE VIN WAS UNAVAILABLE.
10659540	CHEVROLET	TAHOE	2007	2014-03-16	2007 CHEVROLET TAHOE. AIRBAG DEPLOYMENT FAILURE DURING AN ACCIDENT. *TA
10811111	CHEVROLET	ТАНОЕ	2007	2014-04-17	TL* THE CONTACT OWNS A 2007 CHEVROLET TAHOE. THE CONTACT STATED THAT WHILE DRIVING 50 MPH, THE CONTACT BLACKED OUT AND CRASHED INTO THE GUARDRAIL. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED HEAD INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. ON ANOTHER OCCASIONS, WHILE MAKING A LEFT TURN AT 15 MPH, THE CONTACT CRASHED INTO ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED AND THERE WERE NO INJURIES REPORTED. THE CONTACT ALSO STATED THAT THERE WERE TWO LARGE CRACKS IN THE DASHBOARD AND A THIRD CRACK DEVELOPED AS A RESULT OF THE FIRST CRASH. THE VEHICLE WAS TAKEN TO A DEALER HOWEVER, THE DIAGNOSIS WAS UNKNOWN. THE VEHICLE WAS REPAIRED AFTER BOTH FAILURES. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 120,000.
10821342	CHEVROLET	TAHOE	2007	2015-11-16	CRACKED DASH, POTENT HAZARD OF PLASTIC DASH PIECES BECOMING AIRBORNE SHRAPNEL IN THE EVENT OF CRASH WITH AIR BAGS DEPLOY. 2007 TAHOE DASH HAD SMALL 6 INCH CRACK AT THE 2 O CLOCK POSITION ON DRIVERS SIDE INSTRUMENT CLUSTER AND SMALL 1 INCH CRACK ON RIGHT SIDE OF PASSENGER SIDE AIRBAG. AFTER 25 MPH HEAD ON CRASH AIR BAGS DIDN'T DEPLOY BUT ADDITIONAL CRACKS HAVE APPEARED. NOW 10 X WORST. PICS WILL SHOW. DEALER DOESN'T WANT TO REPLACE NOR INSURANCE COMPANY.
	1				TAHOE WAS INVOLVED IN FRONT COLISION WITH ANOTHER VEHICLE AND BAGS DID NOT DEPLOY.
10854032	CHEVROLET	TAHOE	2007	2016-03-31	BUMPER, HOOD DAMAGED. BUMPER METAL BRACKET PUSHED IN.TAHOE WAS TURNING LEFT ON LIGHT WHEN STRUCK BE ANOTHER VEHICLE LIKE HEAD ON.

					TL* THE CONTACT OWNS A 2007 CHEVROLET TAHOE. WHILE DRIVING APPROXIMATELY 60 MPH, THE CONTACT'S VEHICLE CRASHED INTO THE REAR OF A SECOND VEHICLE. DURING THE CRASH, THE FRONT END OF THE VEHICLE SUSTAINED SIGNIFICANT DAMAGE. THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED INJURIES TO THE BACK, SHOULDERS, ARMS, LEFT LEG, AND KNEE. THE PASSENGER SUFFERED INJURIES TO BOTH KNEES. MEDICAL ATTENTION WAS RECEIVED. A POLICE REPORT WAS FILED. THE CAUSE OF THE FAILURE WAS NOT DIAGNOSED. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE VIN WAS NOT
10959039	CHEVROLET	TAHOE	2007	2017-02-01	AVAILABLE. THE FAILURE MILEAGE WAS 100,000.
11265920	CHEVROLET	ТАНОЕ	2007	2019-07-16	TL* THE CONTACT OWNED A 2007 CHEVROLET TAHOE. WHILE DRIVING 35 MPH, A 2012 NISSAN FRONTIER SIDESWIPED THE CONTACT'S VEHICLE. THE CONTACT VEERED OFF THE ROAD AND CRASHED INTO A LIGHT POLE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED HEAD, BACK, NECK, HAND, AND KNEE INJURIES. MEDICAL ATTENTION WAS RECEIVED. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO AN INDEPENDENT LOT. THE CONTACT CALLED PATTERSON HYUNDAI TYLER (3120 S SW LP, TYLER, TX 75701, (903) 561-2404) AND INFORMED THEM OF THE FAILURE. THE VEHICLE WAS NOT DIAGNOSED. THE MANUFACTURER WAS NOT CONTACTED. THE VEHICLE WAS DEEMED A TOTAL LOSS BY THE INSURANCE COMPANY. THE FAILURE MILEAGE WAS 128,122.
10252163	CHEVROLET	TRAILBLAZER	2007	2008-09-24	ON 9/24/08 I WAS INVOLVED IN AN AUTO ACCIDENT WHERE MY 2007 CHEVROLET TRAILBLAZER'S AIRBAGS FAILED TO DEPLOY. MY VEHICLE IMPACTED ANOTHER WITH MY ENTIRE FRONT END AT APPROXIMATELY 45 MPH. MY TRAILBLAZER WAS TOTALED. NOT ONLY DID MY AIRBAGS FAIL TO DEPLOY, THE ONSTAR SYSTEM DID NOT AUTOMATICALLY GO OFF. I HAD TO HIT THE BUTTON TO SUMMON ASSISTANCE. WHEN WE ASKED THE DEALER ABOUT IT, THEIR RESPONSE WAS "SOMETIMES THEY GO OFF, SOMETIMES THEY DON'T" I SUSTAINED A BROKEN LEFT ARM, NUMEROUS BRUISES, A CUT ON MY ANKLE AND AN ANKLE SPRAIN. I ALSO INJURED MY BACK AND NECK WHICH IS REQUIRING ONGOING CARE. *TR
10289962	CHEVROLET	TRAILBLAZER	2007	2009-10-18	THAT DID NOT DEPLOY WAS A FRONTAL CRASH. T-BONED ANOTHER VEHICLE THAT PULLED OUT IN FRONT OF MENTIONED VEHICLE. *TR
10478475	CHEVROLET	TRAILBLAZER TRAILBLAZER	2007	2012-05-14	TL* THE CONTACT OWNS A 2007 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING 40 MPH, THE CONTACT CRASHED HEAD ON INTO ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS TAKEN TO THE HOSPITAL FOR TREATMENT OF WHIPLASH AND EYE INJURIES. THE ENTIRE FRONT END OF THE VEHICLE WAS SEVERELY DAMAGED. THE POLICE WERE NOTIFIED AND A REPORT WAS FILED. THE MANUFACTURER WAS NOTIFIED AND A REPRESENTATIVE WAS SENT TO INSPECT THE VEHICLE, STATING THAT THE VEHICLE PERFORMED AS DESIGNED. THE VIN WAS UNKNOWN. THE FAILURE MILEAGE WAS 64,056. TL* THE CONTACT OWNS A 2007 CHEVROLET TRAILBLAZER. THE CONTACT STATED HE WAS GETTING SICK WHILE DRIVING AND CRASH INTO ANOTHER VEHICLE. THE CONTACT STATED THAT THE AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS NOT DESTROYED AND THERE WAS A POLICE REPORT FILED. THE CONTACT SUSTAINED A WHIPLASH INJURY AND SEVERE HEADACHE. THE MANUFACTURER WAS NOTIFIED WHO SENT A TECHNICIAN TO LOOK AT THE VEHICLE AND THEY STATED THAT THE AIR BAGS FUNCTIONED PROPERLY. THE FAILURE MILEAGE WAS 65,000. UPDATED 01/10/13*LJ UPDATED 1/11/13 *JS
10661436	CHEVROLET	TRAILBLAZER		2014-12-01	TL* THE CONTACT OWNED A 2007 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 20 MPH, ANOTHER VEHICLE CRASHED INTO THE CONTACTS VEHICLE WHILE CROSSING AN INTERSECTION. THE AIR BAGS FAILED TO DEPLOY. THE VEHICLE WAS DESTROYED. IT WAS UNKNOWN IF ANY INJURIES WERE SUSTAINED OR IF A POLICE REPORT WAS FILED. THE MANUFACTURER WAS NOT NOTIFIED. THE FAILURE MILEAGE WAS 140,000. THE VIN WAS UNAVAILABLE.
10661920	CHEVROLET	TRAILBLAZER	2007	2014-11-12	TL* THE CONTACT OWNS A 2007 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT APPROXIMATELY 20 MPH CROSSING AN INTERSECTION, ANOTHER VEHICLE CRASHED INTO THE CONTACTS VEHICLE AND THE AIR BAGS FAILED TO DEPLOY. THE VEHICLE WAS DESTROYED. NO INJURIES WERE REPORTED. THE MANUFACTURER WAS NOT NOTIFIED OF THE ISSUE. THE FAILURE MILEAGE WAS 140,000. THE VIN WAS UNAVAILABLE.
10664216		TRAILBLAZER		2014-05-17	IT WAS RAINING AND WE WERE ON OUR WAY HOME DRIVING DOWN THE HIGHWAY AND HIT A WATER PUDDLE AND HYDROPLANED OF THE SIDE OF THE ROAD THE TRUCK CUT OFF AND SPENT AROUND HIT A TREE HEAD ON AND THE AIRBAGS DIDN'T DEPLOY. I WAS HOSPITALIZED WITH MULTIPLE INJURIES AND IM STILL SUFFERING. *TR
10715742	CHEVROLET	TRAILBLAZER	2007	2015-04-27	A VEHICLE WAS STOPPED IN FRONT OF ME AND I REAR ENDED THEM. I WAS GOING AROUND 44-55 MPH. AFTER I HIT THE OTHER CAR FROM BEHIND I CROSSED 2 LANES OF TRAFFIC AND WENT THRU A PRETTY DEEP DITCH. THE AIR BAGS DID NOT DEPLOY AT ALL. I SUSTAINED A CONCUSSION., SEVERAL HEAD LACERATIONS AND A FRACTURED LUMBAR SPINE.
					SWERVED TO AVOID HITTING A DEER ALMOST HIT MAILBOXES SO SWERVED TO AVOID THEM. I SWERVED TO MUCH THAN IN MY CORRECTION HIT THE GAS INSTEAD OF THE BRAKE. I THAN HIT A
10733714	CHEVROLET	TRAILBLAZER	2007	2015-07-04	TREE BETWEEN 45 - 50 MPH. MY AIRBAGS NEVER DEPLOYED.

10934884	CHEVROLET	TRAILBLAZER	2007	2016-12-07	I HAD MY CRUISE SET ON 55 MPH AND WAS HIT HEAD ON BY VW JETTA PULLING OUT TOWARD MY VEHICLE, THEN FORCED TO LEFT INTO A TELEPHONE POLE. AIRBAGS DIDN'T DEPLOY, AND RECEIVED BROKEN STERNUM. DON'T KNOW IF SEATBELT INJURED ME, OR IF THE SEATBELT DIDN'T LOCK ON 2ND IMPACT AND POSSIBLY HIT THE STEERING WHEEL.
10208661	GMC	ACADIA	2007	2007-10-12	INVOLVED IN FRONTAL COLLISION WITH CONSIDERABLE DAMAGE, BUT AIR BAG DID NOT DEPLOY. *TR
10498046	GMC	ACADIA	2007	2013-02-09	TL* THE CONTACT OWNS A 2007 GMC ACADIA. THE CONTACT STATED THAT WHILE DRIVING 20 MPH, ANOTHER VEHICLE CRASHED INTO HIS VEHICLE IN THE MIDDLE OF THE INTERSECTION. UPON IMPACT, THE AIR BAGS FAILED TO DEPLOY. THE CONTACT STATED THAT HE WAS PINNED IN THE VEHICLE AND COULD NOT GET OUT. THE VEHICLE HAD SEVERE DAMAGES TO THE DRIVER SIDE AND WAS COMPLETELY DESTROYED. THE CONTACT SUSTAINED INJURIES TO HIS HEAD AND CHEST. THE CONTACT WAS TAKEN TO THE EMERGENCY ROOM BY FAMILY. THE POLICE WERE NOTIFIED AND A REPORT WAS AVAILABLE IF NEEDED. THE MANUFACTURER WAS NOTIFIED WHO STATED THAT A REPRESENTATIVE WILL GIVE HIM A RETURN CALL. THE FAILURE MILEAGE WAS 91,000. UPDATED 3/10/13 *CN
10959190	GMC	ACADIA	2007	2017-03-02	TL* THE CONTACT OWNED A 2007 GMC ACADIA. WHILE MAKING A LEFT TURN AT APPROXIMATELY 5 MPH FROM A STOP SIGN, A SPEEDING VEHICLE CRASHED HEAD-ON INTO THE FRONT CENTER OF THE CONTACT'S VEHICLE. THE AIR BAGS DID NOT DEPLOY. BOTH THE CONTACT AND A MINOR PASSENGER, SEATED IN THE REAR BEHIND THE DRIVER, SUSTAINED INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE CONTACT'S VEHICLE WAS TOTALED AND WAS TOWED TO A TOW YARD. THE FAILURE MILEAGE WAS APPROXIMATELY 140,000.
					MY WIFE WAS DRIVING HOME FROM THE DOCTOR AND A FULL SIZE CHEVY CAME ACROSS ON HER SIDE AND HIT HER HEAD ON NEITHER AIR BAG DEPLOYED ON THE ENVOY BOTH VEHICLES WAS
10639641	GMC	ENVOY	2007	2014-06-20	TOTALED WHAT SHOULD WE DO THANKS. *TR A GUY HIT ME ON THE DRIVERS SIDE THEN IT PUSHED ME INTO A DRIVEWAY OF A BUSINESS WHICH HAD A BRICK WALL WHICH I HIT &BOUNCED OFF IT .POPPED BOTH TIRES ON THE DRIVERS SIDE. THEN I HIT A TELEPHONE POLE STRAIGHT ON &SMASHED IN MY FRONT ON MY CARI MOVED THE TELEPHONE POLE IN THE CONCRETE ABOUT 2 INI WAS THE SECOND OWNER. THE OTHER OWNER WAS THE DEALERSHIP &THY HAD IT JUST FOR THERE CAR TO RUN FROM 1 DEALERSHIP TO THE OTHERI HAD TO GO TO THE HOSPITAL &I AM STILL HAVING TREATMENT ON MY NECK BACK &SHOULDERNOT 1 OF THE AIR BAGS WENT OFFIT WAS TOWED AWAY &THEN WAS TOTALEDI HAVE HIRED AN ATTORNEY. *TR
10915508	GMC	ENVOY	2007	2016-08-10	I HIT A GUARD RAIL AT 67 MPHSPIKE WITH GMC AND SHE NOTIFY ME THAT MY THRESHOLD (SPEED AND IMPACT) WERE NOT ENOUGH TO SET AIRBAGS OFFREALLY67 MPHI WAS ON A HIGHWAY SWEATED TO MISS SEMIKICKED IT AND IT FLEW ME IN A CIRCLE AND HIT GAURDRAILIMPACT HIT HARD THAT THEY HAD TO PRY BUMPER OFF RAIL AND CARFRAME WENT THROUGH RADIATOR BUT NO AIRBAGS DEPLOEYED??? TRYING TO FIND LAWYER NO ONE WILL TAKE XASE????
10290508	GMC	YUKON	2007	2009-09-14	TRAVELING AT NIGHT, AT 65 MILES AN HOUR IN A 2007 YUKON SLE2 4 DR WAGON, I HIT A STEER (APPROXIMATELY 880LBS). UPON IMPACT, THE BOTTOM OF MY POWER DRIVER'S SEAT MOVED FORWARD AND THE BACK OF THE SEAT TILTED FORWARD, CAUSING ME TO HIT THE STEERING WHEEL. I HAD TO MOVE THE SEAT BACK TO GET OUT OF THE VEHICLE. THE AIRBAGS DID NOT DEPLOY. I REPORTED THE INCIDENT TO THE DEALER, AND MY INSURANCE AGENT BOTH VERBALLY AND IN WRITING. THE VEHICLE HAD OVER \$11,000.00 WORTH OF DAMAGE, BUT THE REPAIR CENTER STATED THEY WERE UNABLE TO FIND ANY DAMAGE TO THE SEAT. I TRADED THE VEHICLE IN, AS I DID NOT FEEL SAFE DRIVING IT WITH THE SEAT NOT BEING REPLACED OR REPAIRED. THE VEHICLE IS NOW FOR SALE AGAIN, AND I AM FEARFUL THAT SOMEONE ELSE WILL BE IN A WRECK AND THE SEAT WILL MALFUNCTION AGAIN. *TR
					TL* THE CONTACT OWNS A 2007 GMC YUKON. WHILE DRIVING APPROXIMATELY 60 MPH, THE CONTACT CRASHED INTO ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. THERE WERE NO INJURIES AND A POLICE REPORT WAS FILED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 180,000. THE
11034703	GMC	YUKON	2007	2015-03-06	VIN WAS NOT AVAILABLE. I HAVE TRIED TO SUBMIT MY YUKON FOR TANAKA RECALL REMEDY SEVERAL TIMES BY CONTACTING MY LOCAL GMC DEALERSHIP. THEIR SERVICE DEPT CONTINUES TO TELL ME THAT THEY DO NOT HAVE PARTS AVAILABLE TO MODIFY MY VEHICLE. A FEW YEARS AGO I BROADSIDED A LEXUS SUV WHICH 'RAN A TRAFFIC LIGHT'. MY AIRBAGS DID NOT DEPLOY, WHILE SEVERAL OF THE AIRBAGS DEPLOYED IN THE LEXUS. I FELT THAT MY LIFE MIGHT HAVE BEEN AT RISK SINCE THE AIRBAGS DID NOT DEPLOY, OR ALTERNATELY, AT EVEN WORST RISK IF THEY DID EXPLODE UPON DEPLOYMENT. WHO IS RESPONSIBLE FOR ADDRESSING THIS ISSUE? THE GMC DEALER SAYS THEY ARE NOT! I HAVE PHOTOS OF THE ACCIDENT AND A POLICE REPORT STATING THAT THE LADY WAS RESPONSIBLE FOR
10907149	CADILLAC	SRX	2006	2016-09-01	TL* THE CONTACT OWNED A 2006 CADILLAC SRX. WHILE DRIVING VARIOUS SPEEDS, THE VEHICLE HIT A CURB AND DROVE INTO A BUILDING. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO AN INDEPENDENT MECHANIC WHERE IT WAS DEEMED DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 77,814. UPDATED 10/26/16*LJ *TR

					FOUR CAR PILEUP ON HWY 41 NB. WE WERE VEH.#3 AND HIT FORWARD AND WERE HIT FROM BEHIND. OUR SEAT BELTS DID NOT RESTRAIN US AND THE AIR BAGS DID NOT DEPLOY. MY
10223015	CHEVROLET	EQUINOX	2006	2008-02-28	HUSBAND , ERNST, FLEW INTO THE DASHBOARD AND I SLAMMED INTO THE STEERING WHEEL. *TR
10241948	CHEVROLET	EQUINOX	2006	2008-09-10	THE VEHICLE WAS INVOLVED IN A FRONTAL CRASH. THE DRIVER NOR THE PASSENGER AIRBAG DEPLOYED. THE WHOLE FRONT END OF THE VEHICLE WAS PUSHED IN. *TR
10279951	CHEVROLET	EQUINOX	2006	2009-08-04	VEHICLE INVOLVED IN A ONE-AUTO ACCIDENT - 2006 CHEVROLET EQUINOX - HYDROPLANED AND HIT AN EMBANKMENT WITH THE FRONT END AND FLIPPED OVER. THE AIR BAG DID NOT DEPLOY. THIS IS NOT THE FIRST TIME THIS VEHICLE HAS HAD AN IMPACT TO THE FRONT BUMPER AND THE AIR BAG HAS NEVER DEPLOYED. EACH TIME THE FRONT BUMPER HAD DAMAGE SUSTAINED WHICH SHOULD HAVE CAUSED THE IMPACT THE SET THE AIR BAG OFF. *TR 2006 CHEVY EQUINOX AIR BAGS DID NOT DEPLOY IN MY DAUGHTER'S FRONT CRASH ACCIDENT. HER CAR WAS TOTALED. SHE HIT A MAILBOX AND IN A SPIN ON THE DRIVER'S FRONT SIDE HIT A TELEPHONE POLE. SHE HIT HER HEAD ON THE STEERING WHEEL AND HURT HER BACK. THE REAR
10342436	CHEVROLET	FOLUNOX	2006	2010-07-07	WINDSHIELD WAS ALSO SHATTERED AND ALSO HAD A BACK FLAT TIRE. I CALLED OUR LOCAL GM DEALER AND THEY TOLD ME TO CALL GM. SHE CALLED GM BUT THEY GOT HER UPSET AND SHE IN OTHER WORDS SAID THERE WAS NOTHING THEY COULD DO ABOUT THE AIR BAGS NOT DEPLOYING. IN OTHER WORDS THIS IS A DEFECT OF THIS MODEL AND THEY AREN'T GOING TO DO ANYTHING ABOUT IT. *TR
10342430	CHEVROLET	EQUINOX	2006	2010-07-07	ANTITING ABOUTTI. TR
10503970	CHEVROLET	EQUINOX	2006	2013-03-19	I RAN OFF THE SIDE OF THE ROAD INTO A GUARDRAIL AND COULD NOT STOP UNTIL I WAS ON TOP OF THE GUARDRAIL INTO AN EMBANKMENT. MY ENTIRE FRONT END WAS DESTROYED AS WELL AS MOST OF THE UNDERNEATH OF THE CAR. MY FACE HIT THE STEERING WHEEL CAUSING ME TO LOSE CONSCIOUSNESS AS WELL AS GIVING ME A BLACK EYE, CROOKED TEETH, CUTS, BROKEN DENTAL APPLIANCES, AND MY TEETH WENT THROUGH MY LIP. I STRONGLY BELIEVE MY AIRBAGS SHOULD HAVE DEPLOYED AND PREVENTED THE IMPACT OF MY FACE TO THE STEERING WHEEL SINCE I THOUGHT THAT IS WHAT AIRBAGS ARE FOR. MY CAR WAS TOTALED. *TR
10560310	CHEVROLET	EQUINOX	2006	2013-11-14	HIT A ONE TON LOW BED DUMP TRUCK, THE WHOLE FRONT END OF MY SUV WAS DEMOLISHED, MY AIRBAGS DIDN'T DEPLOY AND I ENDED UP WITH REALLY BAD WHIPLASH FROM THE ACCIDENT, TO WHERE I'M STILL IN MAJOR PAIN! WONDERING IF THERE WAS A LAWSUIT AGAINST THIS? NEVER DEALT WITH A WRECK THIS BAD, I WAS JUST CURIOUS! *TR
					MY AIRBAG DID NOT DEPLOY WHEN THE CAR HIT THE TREE. IT HIT SO HARD THE BACK TIRES CAME
10586081	CHEVROLET	EQUINOX EQUINOX	2006	2014-05-01	COMPLETELY OFF THE GROUND. *TR MY GRANDDAUGHTER WAS INVOLVED IN AN ACCIDENT WHERE AS ANOTHER VEHICLE FAILED TO STOP AT A STOP SIGN AND PULLED INTO HER PATH. SHE AND THE OTHER VEHICLE WERE BOTH AT A SPEED OF 25 MPH. THE FRONT CLIP WAS TORN FROM HER CAR AND NO DRIVERS AIRBAG DEPLOYED. SHE DID HAVE HER SEATBELT ON WHICH DID PREVENT SERIOUS INJURY. THE ACCIDENT OCCURRED 30 DEC 2016. THIS HAPPENED ON CITY STREETS.
10343112	CHEVROLET	SILVERADO	2006	2010-03-22	TL* THE CONTACT OWNS A 2006 CHEVROLET SILVERADO. THE CONTACT STATED WHILE TRAVELING AT 40 MPH WHEN AN 18-WHEELER DROVE IN FRONT OF THE CONTACT SUDDENLY. THE CONTACT DID NOT HAVE ENOUGH TIME TO STOP THE VEHICLE BEFORE CRASHING INTO THE TRUCK. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED MINOR BRUISING. THE VEHICLE WAS TOWED TO A LOCAL REPAIR FACILITY WHERE THE CONTACT WAS AWAITING REPAIRS. THE POLICE ADVISED THAT THE AIR BAGS SHOULD HAVE DEPLOYED UPON IMPACT. THE FAILURE MILEAGE AND CURRENT MILEAGES WERE 88,508.
10411579	CHEVROLET	SILVERADO	2006	2010-07-28	MY 2006 SILVERADO 2500 HD AIR BAG DID NOT DEPLOY DURING MY ACCIDENT ON JULY 28, 2010. I TRIED SENDING ALL INFORMATION IN THE MAIL BUT, YOU JUST SENT IT BACK TO ME. COPING THAT WAS SENT TO ME FROM GENERAL MOTORS OF THEIR EXPLANATION OF THEY ARE NOT THE ONES RESPONSIBLE FOR THIS BECAUSE THEY DIDN'T MAKE THIS PRODUCT. NOT TO MENTION THAT ONSTAR DIDN'T COME ON AS THEY SHOW ON THEIR TV ADS'. IF I HAD NOT REGAIN CONSCIENCE. DON'T KNOW WHEN THEY WOULD HAVE FOUND ME THERE WHERE I WENT OFF THE ROAD JUST 4 MILES FROM MY HOME. DON'T KNOW IF ANYONE WOULD HAVE THOUGHT OF CALLING ONSTAR ABOUT LOOKING FOR MY TRUCK. IF GM VEHICLES ARE SO SAFE AND LEAD US TO BELIEVE HOW? SAFE AND RELIABLE THEIR VEHICLES ARE. THEN WHY? THEY ARE NOT STANDING BEHIND THEIR PARTS NOW. THE VEHICLE WAS TOTAL AND THE ONLY THING THAT SAVED ME WAS MY SEAT BELT. EVEN DOE I WAS STILL BADLY INJURED FROM MY NECK TO MY TAIL BONE. GM DOESN'T CARE TO OWN UP TO NO KIND OF RESPONSIBILITY FOR ANYTHING. I'M STILL AFRAID TO DRIVE MY 2010 CAMARO BECAUSE IT HAS THE SAME EQUIPMENT AS THE 2006 PICKUP THAT I TOTALED. I DRIVE IT WHENEVER I HAVE NO CHOICE. WHEN THE DODGE TRUCK ISN'T HERE. EVERY OTHER WEEK WHEN MY HUSBAND NEEDS IT. I'VE SENT YOU ALL THE PICTURES AND SOME OF THE LETTERS THAT GM'S [XXX] HAS SENT TO ME BUT, YOU DIDN'T EVEN OPEN IT ALL YOU DID WAS SEND IT BACK UNOPENED. WHAT'S UP WITH THIS???????????? MY NAME IS: [XXX], MY ADDRESS IS:[XXX]; [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6). *TR

DAY 1971/14/29 CHEVROLET FAHOE 2006 2015-05-09 AWAS ATOTAL LOSS. AMADEM STATE CLEAR SHEEP AND INTO THE RACK OF A SEMI-TRUCK, ARRAGIO IN OIT PREVIOUS PRIVATE ADDRESS.			1			
19717429	10775393	CHEVROLET	SILVERADO	2006	2010-03-22	VEHICLE FAILED TO YIELD. AS A RESULT, THE CONTACT CRASHED INTO THE PASSENGER SIDE OF ANOTHER VEHICLE AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED HIP AND PELVIC INJURIES ON THE RIGHT SIDE THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED
ACOUND 11.459PM A 2006 CHEVY TRABIBLAZER TRAVELING OVER THE SERED LIMIT ON MY STREET CACHS-FIDE MOVE THE AND THE APPROXISE CACK, AND THEN CONTINUED IT OR DOWN CAROSS MY FRONT LAWN, LANDING SIDEWAYS AFTER FLIPPING SEVERAL TIMES. THE OCCUPANTS WERE SEVERLY NUMBER. DO A DRIRKOS DEVELOPED DURING THE LOKASH. THE DRIVEN OF WHELE IS IN ICU. 10277418 CHEVROLET TRABIBLAZER 2006 2008 02 07 NEEDING FACIAL RECONSTRUCTIVE SURGERY. "TR WHILE DRIVING ON A DIRT SOAD THAT ONLY STETS ON CAR, I WAS INVOICED IN A HEAD ON COLLISION INVOLVING A LEFT CHEROMES. THERE WAS EXTRINSIVE FRONT DAMAGE HOWEVER, THE ARRAGE ON DOT THE OTHER THE LINE WAS EXTRINSIVE FRONT DAMAGE HOWEVER, THE ARRAGE ON DOT THE OTHER THE LINE WAS EXTRINSIVE FRONT DAMAGE HOWEVER, THE ARRAGE ON DOT THE OTHER CAN HAVE ARRAGE HOWEVER, THE ARRAGE ON DOT THE OTHER CHEMPERS. THE RE WAS EXTRINSIVE FRONT DAMAGE HOWEVER, THE ARRAGE HOWEVER, AND THE CHERCISH AND THE SHEERING HOWEVER, THE ARRAGE HOWEVER, AND THE CHERCISH HOWEVER, AND THE SHEERING HOWEVER, AND CONTINUED TO HAVE BEEN AND ARRAGE HOWEVER, AND CONTINUED TO HAVE BEEN AND ARRAGE HOWEVER, AND CONTINUED TO HAVE BEEN AND ARRAGE HOWEVER, AND CONTINUED TO HAVE BEEN ARRAGE HOWEVER, AND THE SHEED ARRAGE HOWEVER, AND THE ARR						·
CRESHED INTO A TREE, A PARKED CAR, AND THEN CONTINUED TO ROLL OVER ACROSS MY FRONT LAWN, LANDING SIDEWAYS AFTER FURPING SENTER, THISS. THE OCCURRY TO AND ARRASCS DEPLOYED DURING THE CRASH. THE BRIVET OF THE VEHICLE IS IN ICU NEEDING FACILITY REVIEW SURPER. "YELLOW STATE THE PROPER SENTER THE STATE OF THE VEHICLE IS IN ICU NEEDING FACILITY SURPER." "YELLOW SETTINGS FRONT AND ARRASCS DEPLOYED DURING THE CRASH. THE BRIVET OF THE VEHICLE IS IN ICU NEEDING FACILITY SURPER." "YELLOW SETTINGS FRONT DAMAGE HOWEVER, THE ARRASC DID NOT DEPLOY NOR DID ONSTAR CONTRACT ME. HAVE VERY PARHEUN INCC. HEAD, SINULIDER, AND RIGHT ARMY BARN. "TR WE WERE INVOICED IN A HEAD ON COLLISION WITH ANOTHER VEHICLE. BOTH WERE TRAVELING AT SPROGMANTIVE AS MAY IT HE ARRASCS DID NOT DEPLOY. IN SURPERD A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE STEERING WHEEL. MY WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE STEERING WHEEL WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE STEERING WHEEL WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE STEERING WHEEL WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE STEERING WHEEL WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE STEERING WHEEL WIRE SUFFERED A BROKEN WIRST, UNCONSCIOUS AND HITTING THE ARRASC SOLD NOT DEPLOY. SUFFERED MAJOR TRADING THE WHILE WAS SONNO TO MAN HITTING THE ARRASC SOLD ON THE STEERING WHEEL WIRE AND SOLD ON THE STEERING WHEEL WIRE AND SOLD ON THE STEERING WHEEL WIRE AND SOLD ON THE STEERING WHEEL WIRE A	10717429	CHEVROLET	TAHOE	2006	2015-05-09	
10217799 CHEVROLET TRAILBLAZER 2006 2008-02-07 NEEDING FACAL RECONSTRUCTIVE SURGERY. "TRE COLUPANTS WERE STYRETLY NUMBER ON A DRABAGS DEPLOY DO JOINT NOT THE SCARS. "THE DRIVEN PETILIC IS NICL) 10227418 CHEVROLET TRAILBLAZER 2006 2008-02-07 NEEDING FACAL RECONSTRUCTIVE SURGERY. "TRE VIEWE DRIVING ON A DIET ROOD THAT ON IN 1715 SIN CAR, I WAS INVOICIVED IN A HEAD ON THE OFFICE AND THAT ONLY IT SIN CAR, I WAS INVOICIVED IN A HEAD ON THE OFFICE AND THAT ONLY IT SIN CAR, I WAS INVOICIVED IN A HEAD ON THE OFFICE AND THAT ONLY INVOICING A LEFT CHERROWS EXTENSIVE FRONT DAMAGE HOWEVER, THE ARBAGS DID NOT DEPLOY NOT THE ONLY INVOICING A LEFT CHERROWS EXTENSIVE FRONT DAMAGE HOWEVER, THE ARBAGS DID NOT DEPLOY NOT THE ARBAGS DID NOT DEPLOY. INVOICING HAMP AND IN "TREAT ARBAGS DID NOT DEPLOY." INVOICING HAMP AND IN "TREAT ARBAGS DID NOT DEPLOY." INVOICING HAMP AND IN "TREAT ARBAGS DID NOT DEPLOY." INVOICING AND RIGHT HAMP AND ARBAGE HOWEVER, AND RIGHT SHORT HAMP AND HAME. HAMP AND						
COLUSION INVOLVING A JEP CHEROKEE. THERE WAS SETRISINE FRONT DAMAGE HOWEVER, THE ARRADA ON TO DELOTAR CITE. HAVE APPRILED IN CONTROLLED AND TO PERFORM DELOTAR CITE. HAVE APPRILED IN CONTROLLED AND TO PERFORM PAIN. TR. SHOULDER, AND RIGHT ARM PAIN. "TR. WE WERE INVOICED IN A HEAD ON COLUSION WITH ANOTHER VEHICLE. BOTH WERE TRAVELING AT APPROXIMATELY 45 MPH. THE ARM BASS DIO NOT DEPOLY. I WAS DRIVING THE VEHICLE AND HAVE A BROKEN RIGHT LEG, BOKOTH LETH THE AND ANKEL. I WAS DRIVING THE VEHICLE AND HAVE A BROKEN RIGHT LEG, BOKOTH LETH THE AND ANKEL. I WAS DRIVING THE VEHICLE AND HAVE A BROKEN RIGHT LEG. BOKOTH LETH THE AND ANKEL. I WAS DRIVING THE VEHICLE AND HAVE A BROKEN RIGHT LEG. BOKOTH LETH THE AND ANKEL. I WAS DEFINED A BROKEN RIGHT. THE AND ANKEL I WAS DEFINED AND ANKEL AND ANKEL AND ANKEL I WAS DEFINED AND ANKEL AND	10217793	CHEVROLET	TRAILBLAZER	2006	2008-02-07	LAWN, LANDING SIDEWAYS AFTER FLIPPING SEVERAL TIMES. THE OCCUPANTS WERE SEVERELY INJURED. NO AIRBAGS DEPLOYED DURING THE CRASH. THE DRIVER OF THE VEHICLE IS IN ICU NEEDING FACIAL RECONSTRUCTIVE SURGERY. *TR
WE WERE INVOIVED IN A HEAD ON COLLISION WITH ANOTHER YEMICLE. BOTH WERE TRAVELING AT APPROXIMATELY 8 MPH. THE ARR BASED BION TO TEPLOY. AS PRIVATE HELE AND ANKLE. I MAS TEMPORARILY KNOCKED UNCONCIOUS FROM HITTISTS THE STETRING WHELE. ANY MAS PRIVATE HELE AND ANKLE. I MAS TEMPORARILY KNOCKED UNCONCIOUS FROM HITTISTS THE STETRING WHELE MAY MAS PERFORD ARROWS THE STATE OF THE HELE AND ANKLE. I MAS TEMPORARILY KNOCKED UNCONCIOUS FROM HITTISTS THE STETRING WHELE MAY WELFERD A BROKEN WRIST, FRACTURED PELVIS, AND FRACTURED TIBULA. "TR. PART WAS NO LONGER UNDER WARRANTY AT SAK MILES. VERY DAMGEROUS WHEN TRAVELING 400 MILES WITH LEDREY JAUNT AND SMALL CHILD ZX A WEEK. ON COTTOBER 1, 2010 I MAS INVOIVED IN A HIGH SPEED COLLISION WHEN A CAR PULLED IN FRONT OF MIL, WHILE I WAS GOING 70MPH. THE ARRAGS IDD NOT DEPLOY, SUFFERED MAJOR TRALIBLAZER DUIT WORKEN. THE PART WAS NO LONGER UNDER WARRANTY AT SAK MILES. VERY DAMGEROUS WHEN TRAVELING 400 MILES WITH LEDREY JAUNT AND SMALL CHILD ZX A WEEK. ON COTTOBER 1, 2010 I MAS INVOIVED IN A HIGH SPEED COLLISION WHEN A CAR PULLED IN FRONT OF MIL, WHILE I WAS GOING 70MPH. THE ARRAGS IDD NOT DEPLOY, SUFFERED MAJOR TRALIBLAZER AND SILL HELE 10364174 CHEVROLET TRAILBLAZER 2006 2010-10-01 INFORT ARRAGS IND NOT DEPLOY ON THE ADD THE STETEMEN WHEE AND CONTINUE TO HAVE PAIN. MY ELDREY AUTH AND SHORE STEWARD WHICH A PROVIDED HELD 1054151 CHEVROLET TRAILBLAZER 2006 2011-02-02 2010-10-01 INFORT ARRAGS IND NOT DEPLOY ON THE ADD THAN THE STEM UNLESS ON THE MAJOR THE STEM OF THE VEHICLE OWNER AND DRIVER. THIS CHEVY TRAILBLAZER STRUCK THE DISTRICATION TO YELD CHEM 1054151 CHEVROLET TRAILBLAZER 2006 2013-05-30 201						COLLISION INVOLVING A JEEP CHEROKEE. THERE WAS EXTENSIVE FRONT DAMAGE HOWEVER, THE
AT APPROXIMATELY 45 MPH. THE AIR BAGS DID NOT DEPLOY. I WAS DRIVING THE VEHICLE AND HAVE ARE READ ROAD REST THE CARRON THE VEHICLE AND HAVE ARE READ ROAD REST THE CARRON THE VEHICLE AND HAVE ARE READ ROAD REST THE CARRON THE VEHICLE AND HAVE ARE READ ROAD READ READ READ READ READ READ READ RE	10227418	CHEVROLET	TRAILBLAZER	2006	2008-05-09	· ·
PART WAS NO LONGER UNDER WARRANTY AT 8M MILES. VERY DANGEROUS WHEN TRAVELING 400 MILES WITH LEDREY JAURT AND SMALL CHILD VERY CON OCTORED 1, 2010 I WAS MYOLVED IN A HIGH SPEED COLLSION WHEN A CAR PULLED IN FRONT OF ME, WHILE I WAS GOING 70MPH. THE ARRAGS DID NOT DEPLOY, I SUFFERD MAJOR TRAUMAT OM Y NAVELS AND AM UNABLE TO WALK WELL OR DRIVE. I HIT MY HEAD ON THE STEERING WHELE AND CONTINUE TO HAVE PAIN. MY ELDERLY JAUNT BROKE 3 CERVICAL VERTEBREA AND STILL HAS A TRACHITOMY OVER A MONTH LATER. SHE IS STILL IN THE HOSPITAL, AND IT IS DINKNOWN HIS SHE WILL COME HOME. "TR INSTRIA REEL ON SEATBELT FAILED. NO AIR BAG DEPLOYMENT. 2006 TRAILBLAZER, FULL STRAIGHT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON CRASH. "TR THIS COMPLANT HEAD ON CRASH." TR THIS COMPLANT HEAD ON THE TRAILBLAZER BAD ON COLUMN THE TRAILBLAZER THE CRONN TO THE CRANT HEAD ON THE TRAILBLAZER. THE COMPLANT HEAD ON CRASH." THE CAPALER, PORCING TO THE LEFT THAILBLAZER." THE CAPALER, PORCING TO THE LEFT THAILBLAZER." THE CAPALER, PORCING TO THE CENTED TO THE CONTACT STATED THAT WHILE DRIVING A PROXIMATED AND THE TRAI	10244652	CHEVROLET	TRAILBLAZER	2006	2008-08-28	AT APPROXIMATELY 45 MPH. THE AIR BAGS DID NOT DEPLOY. I WAS DRIVING THE VEHICLE AND HAVE A BROKEN RIGHT LEG, BROKEN LEFT HEEL AND ANKLE. I WAS TEMPORARILY KNOCKED UNCONSCIOUS FROM HITTING THE STEERING WHEEL. MY WIFE SUFFERED A BROKEN WRIST, FRACTURED PELVIS, AND FRACTURED TIBULA. *TR
10389988 CHEVROLET TRAILBLAZER 2006 2011-02-24 STRAIGHT HEAD ON CRASH. *TR THIS COMPLAINT IS BEING FILED ON BEHALF OF THE VEHICLE OWNER AND DRIVER. THIS CHEVY TRAILBLAZER AWAS INVOLVED IN A TWO VEHICLE, DOUBLE FATAL CRASH. THE FRONT OF THE TRAILBLAZER STRUCK THE DRIVER'S ISD GOO PF A CAVALIER THAT FAILED TO YELD FROM A STOP SIGN. THE TRAILBLAZER STRUCK THE DRIVER'S ISD GOO PF A CAVALIER, FORCING IT OFF THE LEFT SIDE OF THE ROLADWAY AND INTO A LARGE TIERE. BOTH OCCUPANTS IN THE CAVALIER WERE FATALLY INJURED. THE FRONT AIRBAGS DID NOT DEPLOY ON THE TRAILBLAZER AND NO EVENT WAS RECORDED ON THE HIGHWAY AND HAD GOT CUT OFF BY A CAR. ISWERVED AND AVOIDED HITTING THE CAR BUT ENDED UP HITTING THE MEDIAN ALMOST DIRECTLY HEAD ON. THE WHOLE FRONT OF THE VEHICLE WAS SMASHED IN AND THE VEHICLE WAS TOTALED. THE AIRBAGS NEVER WENT OFF, ME AND MY PASSENGER WERE BOTH WEARING OUR SEAT BELT AND IENDED UP HITTING MY HEAD ON THE STERRING WHEEL LEAVING ME UNCONSCIOUS. AN AMBULANCE FOR THE STERRING WHEEL LEAVING ME UNCONSCIOUS. AN AMBULANCE AND HITTING MY HEAD ON THE HOSPITAL AND I RECEIVED 10 STITCHES ABOVE MY LEFT EVE. *TR TL* THE CONTACT OWNS A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE WAS DOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A BOULDER. THE AIR BAGS SHALED TO DEPLOY. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR THE FAILURE. THE APPROXIMATE FAILURE MILEGGE WAS 102,000. TL* THE CONTACT OWNED A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT 33 MMP, IT HE DRIVE ARBITRED OFF THE ROAD AND CRASHED THE WHILE DRIVING AT 33 MMP, IT HE DRIVE A DRIVE AND ADD CRASHED THE WHILE DRIVING AT 33 MMP, IT HE DRIVE A DRIVE AND ADD CRASHED THE WHILE DRIVING AT 33 MMP, IT HE DRIVE A STRUCK A HOUSE, COMING TO FEAT THE BAGS DID NOT DEPLOY. THE CONTACT SUSTAINE	10364174	CHEVROLET	TRAILBLAZER	2006	2010-10-01	PART WAS NO LONGER UNDER WARRANTY AT 84K MILES. VERY DANGEROUS WHEN TRAVELING 400 MILES WITH ELDERLY AUNT AND SMALL CHILD 2X A WEEK. ON OCTOBER 1, 2010 I WAS INVOLVED IN A HIGH SPEED COLLISION WHEN A CAR PULLED IN FRONT OF ME, WHILE I WAS GOING 70MPH. THE AIRBAGS DID NOT DEPLOY, I SUFFERED MAJOR TRAUMA TO MY KNEES AND AM UNABLE TO WALK WELL OR DRIVE. I HIT MY HEAD ON THE STEERING WHEEL AND CONTINUE TO HAVE PAIN. MY ELDERLY AUNT BROKE 3 CERVICAL VERTEBRAE AND STILL HAS A TRACHIOTOMY OVER A MONTH LATER. SHE IS STILL IN THE HOSPITAL, AND IT IS UNKNOWN IF SHE WILL COME
THIS COMPLAINT IS BEING FILED ON BEHALF OF THE VEHICLE OWNER AND DRIVER. THIS CHEVY TRAILBLAZER WAS INVOLVED IN A TWO VEHICLE, DOUBLE FATAL CRASH. THE FRONT OF THE TRAILBLAZER STRUCK THE DRIVER'S SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM A STOP SIGN. THE TRAILBLAZER STRUCK THE DRIVER'S SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM A STOP SIGN. THE TRAILBLAZER STRUCK THE DRIVER'S SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM A STOP SIGN. THE TRAILBLAZER STRUCK THE DRIVER'S SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM A STOP SIGN. THE TRAILBLAZER SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM THE LET THE CAVALIER OF THE LEFT SIDE OF THE ROADWAY AND INTO A LARGE TREE. BOTH OCCUPANTS IN THE CAVALIER WERE FATALLY INJURED. THE FRONT AIRBAGS DID NOT DEPLOY ON THE TRAILBLAZER AND NO EVENT WAS BRECORDED ON THE HERBOAC CONTROL MODULE. "TR I WAS DRIVING DOWN THE HIGHWAY AND HAD GOT CUT OFF BY A CAR. I SWERVED AND AVOIDED HITTING THE CAR BUT ENDED UP HITTING THE MEDIAN ALMOST DIRECTLY HEAD ON. THE WHOLE FRONT OF THE VEHICLE WAS SMASHED IN AND THE VEHICLE WAS TOTALED. THE AIRBAGS NEVER WENT OFF, ME AND MY PASSENGER WEB OTH WEARING OUR SEAT BELT AND I ENDED UP HITTING MY HEAD ON THE STEERING WHEEL LEAVING ME UNCONSCIOUS. AN AMBULANCE RUSHED ME TO THE HOSPITAL AND I RECEIVED 10 STITCHES ABOVE MY LEFT EYE. "TR TL* THE CONTACT OWNS A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 35 MPH, SHE LOST CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONCUSSION AND BRUISING. THE FRONT PASSENGER WAS ALSO INJURED AND SUSTAINED BRUISING. THE VEHICLE WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE NOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A BOULDER. THE WEHLCE NOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A SOULDER. THE WEHLCE NOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A SOULDER. THE WEHLCE HOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A SOULDER. THE WEHLCE HOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A MADEL AND AND AND AW						INERTIA REEL ON SEATBELT FAILED. NO AIR BAG DEPLOYMENT. 2006 TRAILBLAZER, FULL
TRAILBLAZER WAS INVOLVED IN A TWO VEHICLE, DOUBLE FATAL CRASH. THE FRONT OF THE TRAILBLAZER STRUCK THE DRIVER'S SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM A STOP SIGN. THE TRAILBLAZER STAYED CONNECTED WITH THE CAVALIER, FORCING 10F THE LETE SIDE OF THE ROADWAY AND INTO A LARGE TREE. BOTH OCCUPANTS IN THE CAVALIER WERE FATALLY INJURED. THE FRONT AIRBAGS DID NOT DEPLOY ON THE TRAILBLAZER AND NO EVENT WAS RECORDED ON THE AIRBAGS CONTROL MODULE. *TR I WAS DRIVING DOWN THE HIGHWAY AND HAD GOT CUT OFF BY A CAR. I SWERVED AND AVOIDED HITTING THE CAB BUT ENDED UP HITTING THE MEDIAN ALMOST DIRECTLY HEAD ON. THE WHOLE FRONT OF THE VEHICLE WAS SMASHED IN AND THE VEHICLE WAS TOTALED. THE AIRBAGS NEVER WENT OFF, ME AND MY PASSENGER WERE BOTH WEARING OUR SEAT BELT AND I ENDED UP HITTING MY HEAD ON THE STEERING WHEEL LEAVING ME UNCONSCIOUS. AN AMBULANCE RUSHED ME TO THE HOSPITAL AND I RECEIVED 10 STITCHES ABOVE MY LEFT EYE. *TR TL* THE CONTACT OWNS A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 35 MPH, SHE LOST CONTROL OF THE VEHICLE WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE NOS DEDIVING AND BRUISING. THE FRONT PASSENGER WAS ALSO INJURIED AND SUSTAINED BRUISING. THE VEHICLE WAS DESTROYED. HIT MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONCUSSION AND BRUISING. THE FRONT PASSENGER WAS ALSO INJURED AND SUSTAINED BRUISING. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 102,000. TL* THE CONTACT OWNED A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT 35 MPH, THE DRIVER DRIFTED OFF THE ROAD AND CRASHED THE VEHICLE INTO A TREE. THE AIR BAGS SID NOT DEPLOY. THE CONTACT SESSIONCE. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 102,000. THE THE CONTACT OWNED BACK TO THE FAILURE MILEAGE WAS 199,000. VEHICLE WAS TRAVELING ON CITY STREET AT 30MPH WHEN IT STRUCK A U	10389988	CHEVROLET	TRAILBLAZER	2006	2011-02-24	STRAIGHT HEAD ON CRASH. *TR
HITTING THE CAR BUT ENDED UP HITTING THE MEDIAN ALMOST DIRECTLY HEAD ON. THE WHOLE FRONT OF THE VEHICLE WAS SMASHED IN AND THE VEHICLE WAS TOTALED. THE AIRBAGS NEVER WENT OFF, ME AND MY PASSENGER WERE BOTH WEARING OUR SEAT BELT AND I ENDED UP HITTING MY HEAD ON THE STEERING WHEEL LEAVING ME UNCONSCIOUS. AN AMBULANCE RUSHED ME TO THE HOSPITAL AND I RECEIVED 10 STITCHES ABOVE MY LEFT EYE. *TR TL* THE CONTACT OWNS A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 35 MPH, SHE LOST CONTROL OF THE VEHICLE WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE NOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A BOULDER. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONCUSSION AND BRUISING. THE FRONT PASSENGER WAS ALSO INJURED AND SUSTAINED BRUISING. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 102,000. TL* THE CONTACT OWNED A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT 35 MPH, THE DRIVER DRIFTED OFF THE ROAD AND CRASHED THE VEHICLE INTO A TREE. THE AIR BAGS DID NOT DEPLOY. THE CONTACTS STATED THAT WHILE DRIVING AT 35 MPH, THE DRIVER DRIFTED OFF THE ROAD AND CRASHED THE VEHICLE INTO A TREE. THE AIR BAGS DID NOT DEPLOY. THE CONTACTS RESIDENCE. THE MANUFACTURER WAS DESTROYED AND TOWNED THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED AND TOWNED AND TOWNED BACK TO THE CONTACTS RESIDENCE. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 199,000. VEHICLE WAS TRAVELING ON CITY STREET AT 30MPH WHEN IT STRUCK A UTILITY POLE, SHEARING IT OFF AT THE AIR BAGS. DEPLOYED. NEWS STORY AT HTTP://WWW.WEMCEM.COM/CATEGORY/133158/VIDEO-LANDING-	10524151	CHEVROLET	TRAILBLAZER	2006	2013-05-30	TRAILBLAZER WAS INVOLVED IN A TWO VEHICLE, DOUBLE FATAL CRASH. THE FRONT OF THE TRAILBLAZER STRUCK THE DRIVER'S SIDE DOOR OF A CAVALIER THAT FAILED TO YIELD FROM A STOP SIGN. THE TRAILBLAZER STAYED CONNECTED WITH THE CAVALIER, FORCING IT OFF THE LEFT SIDE OF THE ROADWAY AND INTO A LARGE TREE. BOTH OCCUPANTS IN THE CAVALIER WERE FATALLY INJURED. THE FRONT AIRBAGS DID NOT DEPLOY ON THE TRAILBLAZER AND NO EVENT
DRIVING APPROXIMATELY 35 MPH, SHE LOST CONTROL OF THE VEHICLE WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE NOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A BOULDER. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONCUSSION AND BRUISING. THE FRONT PASSENGER WAS ALSO INJURED AND SUSTAINED BRUISING. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 102,000. TL* THE CONTACT OWNED A 2006 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT 35 MPH, THE DRIVER DRIFTED OFF THE ROAD AND CRASHED THE VEHICLE INTO A TREE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED A FRACTURED NOSE AND LEFT CHEEKBONE THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED AND TOWED BACK TO THE CONTACTS RESIDENCE. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 199,000. VEHICLE WAS TRAVELING ON CITY STREET AT 30MPH WHEN IT STRUCK A UTILITY POLE, SHEARING IT OFF AT THE BASE. VEHICLE THEN TRAVELED STRAIGHT UP A HILL AND STRUCK A HOUSE, COMING TO REST THERE. NONE OF THE AIR BAGS DEPLOYED. NEWS STORY AT HTTP://WWW.WGEM.COM/CATEGORY/133158/VIDEO-LANDING-	10548331	CHEVROLET	TRAILBLAZER	2006	2013-10-10	HITTING THE CAR BUT ENDED UP HITTING THE MEDIAN ALMOST DIRECTLY HEAD ON. THE WHOLE FRONT OF THE VEHICLE WAS SMASHED IN AND THE VEHICLE WAS TOTALED. THE AIRBAGS NEVER WENT OFF, ME AND MY PASSENGER WERE BOTH WEARING OUR SEAT BELT AND I ENDED UP HITTING MY HEAD ON THE STEERING WHEEL LEAVING ME UNCONSCIOUS. AN AMBULANCE
DRIVING AT 35 MPH, THE DRIVER DRIFTED OFF THE ROAD AND CRASHED THE VEHICLE INTO A TREE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED A FRACTURED NOSE AND LEFT CHEEKBONE THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED AND TOWED BACK TO THE CONTACTS RESIDENCE. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 199,000. VEHICLE WAS TRAVELING ON CITY STREET AT 30MPH WHEN IT STRUCK A UTILITY POLE, SHEARING IT OFF AT THE BASE. VEHICLE THEN TRAVELED STRAIGHT UP A HILL AND STRUCK A HOUSE, COMING TO REST THERE. NONE OF THE AIR BAGS DEPLOYED. NEWS STORY AT HTTP://WWW.WGEM.COM/CATEGORY/133158/VIDEO-LANDING-	10550276	CHEVROLET	TRAILBLAZER	2006	2013-10-28	DRIVING APPROXIMATELY 35 MPH, SHE LOST CONTROL OF THE VEHICLE WHILE DRIVING IN SNOWY WEATHER. THE VEHICLE NOSE DIVED INTO AN EMBANKMENT AND THEN CRASHED INTO A BOULDER. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL VIA AMBULANCE FOR TREATMENT OF A CONCUSSION AND BRUISING. THE FRONT PASSENGER WAS ALSO INJURED AND SUSTAINED BRUISING. THE VEHICLE WAS DESTROYED. THE MANUFACTURER
IT OFF AT THE BASE. VEHICLE THEN TRAVELED STRAIGHT UP A HILL AND STRUCK A HOUSE, COMING TO REST THERE. NONE OF THE AIR BAGS DEPLOYED. NEWS STORY AT HTTP://WWW.WGEM.COM/CATEGORY/133158/VIDEO-LANDING-	10679561	CHEVROLET	TRAILBLAZER	2006	2014-10-06	DRIVING AT 35 MPH, THE DRIVER DRIFTED OFF THE ROAD AND CRASHED THE VEHICLE INTO A TREE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED A FRACTURED NOSE AND LEFT CHEEKBONE THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED AND TOWED BACK TO THE CONTACTS RESIDENCE. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 199,000.
10888990 CHEVROLET TRAILBLAZER 2006 2016-07-21 PAGE?&CLIPID=12610200&AUTOSTART=TRUE						IT OFF AT THE BASE. VEHICLE THEN TRAVELED STRAIGHT UP A HILL AND STRUCK A HOUSE, COMING TO REST THERE. NONE OF THE AIR BAGS DEPLOYED. NEWS STORY AT
	10888990	CHEVROLET	TRAILBLAZER	2006	2016-07-21	PAGE?&CLIPID=12610200&AUTOSTART=TRUE

	_			1	
					LETTER FROM SENATOR NELSON ON BEHALF OF CONSTITUENT REGARDING GENERAL MOTOR SAFETY DEFECTS. *LD THE CONSUMER SUGGESTED THERE WAS A DEFECT WITH THE GM AIR BAGS IN 2006 CHEVROLET TRAILBLAZER, IN WHICH THE DRIVER SUSTAINED A BRAIN INJURY AND HIS WIFE WAS INJURED, WHEN IT WAS IMPACTED ON THE DRIVER'S SIDE, RESULTING IN LEFT A-PILLAR
					CONTACT WHEN THE AIR BAG FAILED TO DEPLOY AND HIS SEAT BELT RESTRAINTS FAILED. THE
10955948	CHEVROLET	TRAILBLAZER	2006	2016-09-08	CRASH WAS OF ENORMOUS SEVERITY, WITH A SPEED CHANGE OF 38 MPH WITH A LINE FORCE IN THE DIRECTION OF THE A PILLAR. *JB
10955946	CHEVROLET	TRAILBLAZER	2006	2010-09-08	THE DIRECTION OF THE A FILLAN. JB
					I WAS IN A CRASH AND NEITHER FRONT AIRBAG DEPLOYED, MY INSURANCE ADJUSTER
					QUESTIONED IF THE AIR BAG SYSTEM EVEN WORKS. I HAVE COPY OF THE ESTIMATE TO REPAIR AS WELL. DUE TO THE FORCE OF IMPACT EVEN LOCAL REPAIR SHOP STATED THAT MY AIR BAGS
					SHOULD HAVE GONE OFF AS WELL. IS THERE A RECALL ON THIS MODEL FOR AIR BAGS NOT
10966507	CHEVROLET	TRAILBLAZER	2006	2017-02-27	DEPLOYING? I WAS IN A SECOND WRECK ON 3/7/17 AND NEITHER AIR BAG DEPLOYED AT THAT TIME EITHER AND THERE WAS NO BUMPER SO AIR BAGS SHOULD HAVE DEFINITELY GONE OFF.
10900307	CHEVROLET	TRAILBLAZER	2000	2017 02 27	I HAD A CRASH AT 45 MPH INTO A LARGE TREE \$9000+ DAMAGE TO THE FRONT END OF MY CAR
10403445	GMC	ENVOY	2006	2011-05-20	AND THE AIRBAG NEVER WENT OFF. ONSTAR WAS CALLED AND HELPED ME.
					I WAS INVOLVED IN A HEAD ON COLLISION, WHERE A CAR CAME AROUND A BUS INTO MY LANE . IT WAS A CLEAR CUT CASE OF WHO WAS AT FAULT. MY CONCERN IS THAT MY AIR BAG NEVER DEPLOYED. THERE IS A DRIVER AND PASSENGER AIRBAG IN THAT MODEL. IF NOT FOR MY SEAT
					BELT , I WOULD HAVE GONE THROUGH THE WINDSHIELD AND THE VEHICLE WAS TOTALED FROM
10704170	GMC	ENVOY	2006	2015-03-22	THE FORCE. THERE ARE PICTURES I COULD FORWARD OF THE ACCIDENT. I WANTED TO KNOW IF THERE WAS ANY THING ELSE I COULD DO TO ADDRESS THIS ISSUE. THANK YOU *TR
	516	2			THE SECTION OF THE SE
					MY FATHER WAS DRIVING FROM DIALYSIS ON THE DECLINE OF A BRIDGE WHEN HE PASSED OUT BEHIND THE WHEEL. HE WAS WEARING HIS SEATBELT, AND THE VEHICLE RESTED AFTER HITING A
					TREE. THE AIRBAGS DID NOT DEPLOY. I HAVE CONTACTED GMC AND THERE IS AN INVESTIGATION
					PENDING, THEY HAVE SENT A REPRESENTAIVE TO INSPECT THE VEHICLE AND I AM AWAITING THE OUTCOME. I HAVE CONTACTED COPART AND HAD THE VEHICLE PLACED ON HOLD TO ALLOW
					NHTSA THE OPPORTUNITY TO DO THE SAME, IF YOU CHOOSE. 5017 DUNCAN ROAD, PUNTA
10780171	GMC	YUKON	2006	2015-08-21	GORDA, FL (941) 505-9700. PLEASE FEEL FREE TO CONTACT ME WITH ANY QUESTIONS.
					AIRBAG FAILED FUNCTION DUE TO LACK OF INFLATOR PERFORMANCE DURING MY HUSBANDS
					HEAD-ON CRASH AND HE SUFFERED COLLAR BONE AND RIB FRACTURES, MASSIVE HEAD TRAUMA
11377560	GMC	YUKON	2006	2011-06-07	RESULTING IN A CRAINIOTOMY,BRAIN DAMAGE AND DEATH ONE MONTH LATER. THE VEHICLE WAS TRAVELLING AT 45MPH ON A PAVED TWO LANE STREET.
					2005 BUILD DAINIED WAS IN A USAD ON COULSION WITH A SURVEYED TOWN D. COUNTDY VAN IN
					2005 BUICK RAINIER WAS IN A HEAD ON COLLISION WITH A CHRYSLER TOWN & COUNTRY VAN IN COMING TRAFFIC. MY WIFE DRIVING THE RAINIER HIT HER HEAD ON THE STEERING WHEEL AND
					BENT IT. SHE RECEIVE A LARGE LACERATION REQUIRING ABOUT 30 STITCHES, CLAVICLE STRAIN,
					BROKEN COLLAR BONE AND MULTIPLE BRUISES. SHE WAS WEARING THE SEAT BELT. COLLISION WAS STRONG ENOUGH TO LIFT THE REAR OF THE CAR OFF THE GROUND AND TURN IT FACING THE
10275950	BUICK	RAINIER	2005	2009-06-30	SAME DIRECTION AS THE VAN SHE HIT. THE AIRBAGS DID NOT DEPLOY! *TR
					HAD A FRONT END COLLISION WITH ANOTHER VEHICLE AND NONE OF MY AIRBAGS DEPLOYED.
					THE VEHICLE WAS 4 WEEKS OLD AND HAD 1850 MILES AT THE TIME OF THE ACCIDENT. CALLED
					CADILLAC CUSTOMER SERVICE AND WAS GIVEN AN AIRBAG HISTORY LESSON VIA TELEPHONE FROM SOMEONE THAT HAD NEVER SEEN MY VEHICLE OR INSPECTED IT FOR DAMAGE AFTER THE
					ACCIDENT. AT THE END OF OUR CONVERSATION I WAS TOLD ALL WAS OK, NONE OF MY AIRBAGS
					SHOULD HAVE DEPLOYED AND NOT TO WORRY ABOUT IT. THE ENTIRE FRONT END OF MY VEHICLE WAS KNOCKED OFF, THE FRAME HAS MULTIPLE CRACKS AND IS BENT AS A RESULT OF THE
10152376	CADILLAC	ESCALADE	2005	2006-03-01	COLLISION AND THE COLLISION CENTER IS 90% CERTAIN THE VEHICLE IS NOT REPAIRABLE. *JB
10005443	CADILLAC	CDV	2005	2016 00 11	AIRBAG DIDN'T DEPLOY IN AN ACCIDENT ON AUGUST 11 2016. AIRBAG IS FAULTY AND CONCERN
10895442	CADILLAC	SRX	2005	2016-08-11	ABOUT THE SAFETY OF THE 2005 SRC
					TL* THE CONTACT'S DAUGHTER OWNED A 2005 CADILLAC SRX. WHILE DRIVING APPROXIMATELY
					40 MPH ON AN ICY, SNOWY ROAD, THE VEHICLE STARTED TO SKID AND THE DRIVER LOST CONTROL OF THE VEHICLE. THE DRIVER CRASHED INTO A CEMENT WALL. ALL THE AIR BAGS FAILED TO
					DEPLOY. THE DRIVER SUSTAINED HEAD INJURIES THAT REQUIRED MEDICAL ATTENTION ALONG
					WITH BRUISES TO THE CHEST, RIGHT ARM, AND LEG. A POLICE REPORT WAS FAILED. THE VEHICLE WAS TOWED AND DEEMED DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE
10968319	CADILLAC	SRX	2005	2017-03-14	FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 110,000. THE VIN WAS UNAVAILABLE.
					2005 CHEVROLET EQUINOX REAR ENDED ANOTHER VEHICLE AFTER BEING HIT IN THE REAR WHILE STOPPED. THE AIR BAGS DID NOT DEPLOY AND THE SEAT BELTS DID NOT ENGAGE.*MR THE
					DRIVER SUSTAINED SOME INJURIES WHEN HE WAS PUSHED FORWARD INTO THE STEERING WHEEL
10120423	CHEVROLET	EQUINOX	2005	2005-05-01	AND DASH. *NM 2005 CHEVY EQUINOX AIR BAGS DID NOT DEPLOY. CONSUMER STATES THAT HE WAS INVOLVED IN
					A FRONTAL CRASH AND AIR BAGS FAILED TO DEPLOY. HE STATES THAT HE WAS INVOLVED IN
10221708	CHEVROLET	EQUINOX	2005	1901-01-01	ABOUT 35 MPH. *KB

10221964	CHEVROLET	EQUINOX	2005	2007-12-15	I HAD A HEAD ON COLLISION WITH A CONCRETE WALL IN MY 2005 CHEVROLET EQUINOX ON DECEMBER 15, 2007. I WAS TRAVELING ABOUT 55-60 MPH WHEN THE HEAD ON COLLISION OCCURRED. MY AIRBAGS DID NOT DEPLOY. HOWEVER THE TALC POWER AND THE SMELL CAME OUT. I HAD AN INVESTIGATION DONE ON THE AIRBAGS. I WAS TOLD BY A GM INVESTIGATION REP THAT THE VEHICLE HAS TO SLOW DOWN 10-15 MPH FOR THE AIRBAGS TO DEPLOY. THE INVESTIGATION SHOWED THAT THE VEHICLE SLOWED DOWN 11.85 MPH WHICH FALLS WITHIN THE RANGE FOR THE AIRBAGS TO DEPLOY. I NEED A SECOND OPINION BECAUSE GM STATED THAT DESPITE WHAT THE REPORT SAYS, THEY ARE NOT AT FAULT FOR THE AIRBAGS. *TR
10266217	CHEVROLET	EQUINOX	2005	2009-04-14	TL*THE CONTACT OWNS A 2005 CHEVROLET EQUINOX. WHILE DRIVING 40 MPH, ANOTHER DRIVER PULLED OUT IN FRONT OF THE CONTACT'S VEHICLE. AS A RESULT, THE CONTACT CRASHED INTO THE OTHER VEHICLE. THE FRONT DRIVER'S SIDE AIR BAG FAILED TO DEPLOY AND THE CONTACT SUSTAINED MINOR NECK INJURIES. A POLICE REPORT WAS FILED. THE VEHICLE WAS INSPECTED BY HER INSURANCE AGENCY AND THEY STATED THAT IT WAS DESTROYED. THE ADJUSTER WAS UNABLE TO DETERMINE WHY THE AIR BAGS DID NOT DEPLOY. THE CONTACT CALLED THE MANUFACTURER AND WAS INFORMED THAT SHE WOULD RECEIVE A CALL BACK REGARDING THE CRASH. THE FAILURE MILEAGE WAS 30,000.
40440033	CHENDOLET	FOLUNION	2005	2011 12 12	TL* THE CONTACT OWNS A 2005 CHEVROLET EQUINOX. THE CONTACT WAS DRIVING 30 MPH WHEN A DEER JUMPED A FENCE AND LANDED ON THE HOOD OF THE VEHICLE WITH EXTREME FORCE. THE CONTACT STATED THE ENGINE CONTINUED TO RUN BUT THE INTERIOR AND EXTERIOR LIGHTNING FAILED. THE AIR BAGS ALSO FAILED TO DEPLOY. THE POLICE WERE NOT CONTACTED AND THERE WERE NO INJURIES. THE VEHICLE WAS TAKEN TO A LOCAL REPAIR SHOP AND THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE VEHICLE WAS NOT REPAIRED. THE VIN WAS UNAVAILABLE. THE FAILURE AND THE CURRENT MILEAGES WERE 73,000. UPDATED 01/10/12*LJ
10449315	CHEVROLET		2005	2011-12-13	I WAS DRIVING, HIT ICE, FISH TAILED, STARTED TO SPIN, WENT HEAD FIRST INTO THE MEDIAN, PROBABLY GOING 30-45 MPH. AFTER THAT WE CAME TO A STOP, AND WERE HIT BY A SEMI TRAILER TRAVELING AT APPROXIMATELY 45-60 MPH. NEITHER IMPACT SET THE AIR BAGS OFF AND WE BELIEVE THAT IT SHOULD HAVE. *TR
10597676	CHEVROLET	EQUINOX	2005	2004-10-31	TL* THE CONTACT OWNS A 2005 CHEVROLET EQUINOX. WHILE DRIVING APPROXIMATELY 70 MPH ON THE HIGHWAY, THE CONTACT NOTICED THE KEY WAS DETACHING FROM THE IGNITION. THE DEALER STATED THAT THE VIN WAS NOT INCLUDED IN NHTSA CAMPAIGN NUMBER: 04V302000 (POWER TRAIN). WHILE DRIVING 35 MPH, THE CONTACT WAS INVOLVED IN A CRASH AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS INJURED AND RECEIVED MEDICAL ATTENTION. THE VEHICLE WAS REPAIRED BY THE DEALER. THE MANUFACTURER WAS NOT NOTIFIED. THE APPROXIMATE FAILURE MILEAGE WAS 70.
10597688	CHEVROLET	EQUINOX	2005	2005-10-31	DRIVING DOWN STREET CUT OFF BY SEMI RAN INTO FLASHING SIGN WITH NOWHERE ELSE TO GO. OVER HALF PASSENGER FRONT BUMPER WAS CRUSHED RADIATOR SMASHED, WHOLE FRONT PASSENGER QUARTER SMASHED. CAR WAS UNDRIVEABLE BUT AIR BAGS DID NOT GO OFF. *TR
10936302	CHEVROLET	EQUINOX	2005	2013-12-13	I WAS IN AN ACCIDENT ON 12/15/2016 WHERE I HIT SOMEONE FROM BEHIND. I WAS DRIVING STRAIGHT DOWN THE HIGHWAY AND DIDN'T NOTICE THE PEOPLE IN FRONT OF ME STOPPING. WHEN I HIT THE BRAKES, IT WAS TOO LATE AND MY CHEST WENT FLYING AGAINST THE STEERING WHEEL. WHEN MY EQUINOX HIT THEM, MY SEAT BELT DID NOT LOCK AND MY CHEST HIT THE STEERING WHEEL. I HAD TO GO TO THE HOSPITAL BECAUSE OF THE FORCE OF THE IMPACT. THE FORCE WAS SO HARD THAT THE AIR BAG DID NOT COME OUT. I DON'T KNOW IF THERE IS AN AIR BAG INSIDE THE VEHICLE. I COULD NOT CATCH MY BREATH AND I TESTED OUT MY SEAT BELT AND REALIZED IT DOES NOT LOCK WHEN BREAKING. IT IS ACTUALLY LOSE THE WHOLE TIME I AM DRIVING. THIS IS NOT SAFE FOR ME OR A PASSAGE THAT I HAVE IN THE CAR. TESTED OUT THE PASSAGE SIDE AS WELL AND IT IS THE SAME THING. *TR
11023592	CHEVROLET	EQUINOX	2005	2017-09-06	TL* THE CONTACT OWNS A 2005 CHEVROLET EQUINOX. WHILE DRIVING 45 MPH, THE CONTACT CRASHED INTO ANOTHER VEHICLE. ALL THE AIR BAGS FAILED TO DEPLOY. THE CONTACT NOTICED SMOKE COMING FROM THE RADIATOR. THE VEHICLE WAS TOWED TO XTREME COLOR INC. IN KANSAS CITY, KS 66102; 913-281-0830. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED A NECK AND BACK INJURY THAT REQUIRED MEDICAL ATTENTION. THE MANUFACTURER WAS NOT CONTACTED. THE APPROXIMATE FAILURE MILEAGE WAS 146,500.
11127938	CHEVROLET	EQUINOX	2005	2018-07-20	TL* THE CONTACT OWNS A 2005 CHEVROLET EQUINOX. WHILE DRIVING 24 MPH ON AN EXIT RAMP, THE VEHICLE INADVERTENTLY DROVE OFF THE SIDE OF THE RAMP AND CRASHED. THE AIR BAGS FAILED TO DEPLOY AND THE SEAT BELT FAILED TO RESTRAIN THE CONTACT. THERE WERE NO WARNING INDICATORS ILLUMINATED. THE CONTACT SUSTAINED MINOR INJURIES TO THE HEAD AND HIPS THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A TOW LOT. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE AND A FIELD INSPECTOR WAS SENT TO INSPECT THE VEHICLE. THE CONTACT WAS AWAITING THE INSPECTION RESULTS. THE VEHICLE WAS NOT TAKEN TO A DEALER FOR DIAGNOSTIC TESTING. THE FAILURE MILEAGE WAS 140,000.

		1		1	
11191960	CHEVROLET	EQUINOX	2005	2019-03-27	TL* THE CONTACT OWNS A 2005 CHEVROLET EQUINOX. WHILE DRIVING 35 MPH AND DRIVING STRAIGHT PREPARING TO MAKE A RIGHT TURN, THE CONTACT CRASHED INTO THE FRONT QUARTER PANEL OF ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE HEAD AND ANKLE, WHICH REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO AN INDEPENDENT LOT. THE DEALER AND MANUFACTURER WERE NOT CONTACTED. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE FAILURE MILEAGE WAS 65,000. *DT *TR
					TL* THE CONTACT OWNED A 2005 CHEVROLET EQUINOX. THE CONTACT STATED THAT WHILE
11297402	CHEVROLET	EQUINOX	2005	2020-01-05	DRIVING 55 MPH AND TURNING ON CURVE TOO FAST, CONTROL OF THE VEHICLE WAS LOST. THE VEHICLE SWERVED LEFT AND RIGHT ULTIMATELY COMING TO A STOP AFTER CRASHING INTO A TREE. THE AIR BAGS FAILED TO DEPLOY. DURING THE IMPACT THE CONTACT HEAD WAS HIT ON THE WINDSHIELD AND ABRASION TO THE KNEE WERE SUSTAINED. MEDICAL ATTENTION WAS NOT SOUGHT. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A TOW YARD. THE VEHICLE WAS DESTROYED. THE DEALER AND MANUFACTURER WERE NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS APPROXIMATELY 165,000.
11237402	CHEVILOLET	EQUITOX	2003	2020 01 03	WHILE DRIVING 40 MPH VEHICLE CRASHED INTO A STORE FRONT. UPON IMPACT, DUAL AIRBAGS
10117624	CHEVROLET	SILVERADO	2005	2005-03-29	DID NOT DEPLOY. NO INJURIES REPORTED. *AK
10137371	CHEVROLET	SILVERADO	2005	2005-09-20	I HAD AN ACCIDENT ON TUESDAY SEPT. 20, 2005 DRIVING MY 2005 CHEVY PICKUP K2500 HD 4 WHEEL DRIVE. I LOST CONTROL AND WENT OFF HIGHWAY STRIKING A CITY DUMPSTER HEADON AND MOVING THE DUMPSTER APPROXIMATELY 50-60 FT. BY POLICE REPORT AND THAN GOING BACK ON HIGHWAY AND CROSSING ALL 4 LANES BEFORE THE TRUCK STOPPED. MY TRUCK WAS TOTALED BUT MY AIRBAG NEVER DEPLOYED. I WAS UNCONSCIOUS AND WAS AIRLIFTED TO VANDERBILT HOSPITAL IN NASHVILLE TN. WHY DIDN'T MY AIRBAG DEPLOY WITH A HEADON CRASH OF THIS FORCE? THIS SEEMS TO BE A DEFECT IN THE PRODUCT. I RECEIVED A 4 INCH CUT ACROSS THE BOTTOM OF MY CHIN THAT REQUIRED SEVERAL STITCHES AND VERY SORE FROM MY HEAD DOWN MY RIGHT LEG. STILL FOLLOWING UP WITH DOCTORS *NM
10153906	CHEVROLET	SILVERADO	2005	2006-03-27	DT*: THE CONTACT STATED THE VEHICLE WAS INVOLVED IN AN ACCIDENT ON DRY ROADS. TWO VEHICLES COLLIDED IN FRONT OF THE CONTACT, CAUSING AN EMERGENCY BRAKING SITUATION. THE CONTACT COLLIDED WITH THE REAR OF THE SECOND VEHICLE, AND THE AIR BAGS DID NOT DEPLOY. THE CONTACT WAS INJURED IN THE ACCIDENT. AN INDEPENDENT REPAIR SHOP WAS CONSULTED AND THEY WERE UNABLE TO DUPLICATE THE PROBLEM.
10201747	CHEVROLET	SILVERADO	2005	2007-08-27	AIRBAG FAILURE IN HEAD-ON COLLISION, TOTALING 2 TRUCKS. *JB
10455110	CHEVROLET	SUBURBAN	2005	2011-12-06	TL* THE CONTACT OWNS A 2005 CHEVROLET SUBURBAN. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 30 MPH, SHE CRASHED INTO THE REAR OF A TRASH TRUCK. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED INJURIES TO THE LEFT ARM AND LEFT LEG. THE POLICE WERE CONTACTED AND A REPORT WAS FILED. THE VEHICLE WAS TOWED TO AN INDEPENDENT MECHANIC WHERE THEY DEEMED THE VEHICLE AS BEING DESTROYED. THE MANUFACTURER WAS CONTACTED AND AFTER DIAGNOSING THE VEHICLE, THEY ADVISED HER THAT THE VEHICLE WAS NOT TRAVELING FAST ENOUGH AT THE TIME OF IMPACT FOR THE AIRBAGS TO DEPLOY. THE FAILURE MILEAGE WAS APPROXIMATELY 80,000.
					DT: ON JULY 16, 2005 WHILE TRAVELING AT 55 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION WITH ANOTHER VEHICLE. TOTALED THE OTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. VEHICLE HAS NOT BEEN INSPECTED TO SEE WHY THEAIR BAGS DID NOT DEPLOY. AIR BAG LIGHT CAME ON. CONSUMER CALLED THE DEALERSHIP, AND THEY ADVISED CONSUMER NOT DRIVE THE VEHICLE TO THE DEALERSHIP BECAUSE THE AIRBAGS MIGHT DEPLOY. THE VEHICLE WAS TAKEN TO THE BODY SHOP YESTERDAY TO BE FIXED. THE CONSUMER SPRAINED
10130316	CHEVROLET	TAHOE	2005	2005-07-16	BACK AND NECK. A POLICE REPORT WAS ISSUED.*AK
10200191	CHEVROLET	ТАНОЕ	2005	2007-06-18	AIR BAGS FAILED TO DEPLOY IN A CRASH. THE FRAME OF OUR 2005 CHEVROLET TAHOE WAS BUCKLED IN THE CRASH. CRASH TEST DATA WAS RETRIEVED FROM THE VEHICLE, ALTHOUGH GENERAL MOTORS DOES NOT FEEL THAT THEY ARE IN A POSITION TO HONOR OUR REQUEST FOR DAMAGES AGAINST THEM. MY HUSBAND AND I BOTH RECEIVED BACK AND NECK INJURIES DURING THE ACCIDENT. *TR
10335468	CHEVROLET	ТАНОЕ	2005	2009-06-12	TL*THE CONTACT OWNS A 2005 CHEVROLET TAHOE. THE CONTACT STATED THAT WHILE DRIVING AT APPROXIMATELY 55 MPH, THE VEHICLE CRASHED INTO A DEER BUT THE AIR BAGS DID NOT DEPLOY. THERE WAS EXTENSIVE DAMAGE TO THE VEHICLE. A POLICE REPORT WAS FILED. THE DEALER STATED THAT THE VEHICLE COULD BE INSPECTED AT THE CONTACT'S EXPENSE. THE BODY DAMAGE HAD BEEN REPAIRED. THE FAILURE MILEAGE WAS APPROXIMATELY 75,000. THE CURRENT MILEAGE WAS APPROXIMATELY 100,000.
					2005 CHEVY TAHOE WAS IN AN ACCIDENT AND HIT FRONT DRIVERS SIDE INTO DIRT EMBANKMENT
10494771	CHEVROLET	ТАНОЕ	2005	2013-01-24	AT 35-40 MPH PUSH DRIVERS SIDE TIRE BACK ABOUT 3" AND BUCKLED HOOD AND FENDER AND THE AIRBAGS DIDN'T GO OFF. *TR

			1		1
10748242	CHEVROLET	ТАНОЕ	2005	2015-08-11	TL* THE CONTACT OWNED A 2005 CHEVROLET TAHOE. WHILE DRIVING APPROXIMATELY 50 MPH, THE REAR DRIVER SIDE WHEEL BECAME DETACHED FROM THE VEHICLE AND CAUSED THE CONTACT TO LOSE CONTROL OF THE VEHICLE. THE CONTACT CRASHED INTO A WOODEN POLE, WHICH CRASHED THROUGH THE FRONT WINDOW. THE VEHICLE FLIPPED OVER THREE TIMES AND LANDED UPSIDE DOWN. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED BROKEN BONES AND INJURIES THAT REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS TOWED TO THE TOWING COMPANY. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 131,000.
10748242	CHEVROLLI	TAHOL	2003	2013-08-11	I WAS INVOLVE IN AN ACCIDENT WHERE I HAVE LOST CONTROL OF A CHEVROLET TRAILBLAZER
					AND HIT A CENTER DIVIDER ON THE FREEWAY. WITH THE FRONT BUMPER SMASHED ONTO THE
10134099	CHEVROLET	TRAILBLAZER	2005	2005-05-12	CENTER DIVIDER, THE AIR BAG FAILED TO DELPLOY. CHEVY TRAILBLAZER ('05 OR '06) REAR ENDED ANOTHER VEHICLE AT A SPEED FAST ENOUGH TO
					TOTAL THE TRAILBLAZER, THE AIRBAG DID NOT DEPLOY AND THE DRIVER SUSTAINED CHEST AND
10141221	CHEVROLET	TRAILBLAZER	2005	2005-10-19	HEART INJURIES. *NM
					DT: THE CONTACT'S BOY FRIEND WAS TRAVELING AT 78 MPH WHEN HE LOST CONTROL OF THE
					VEHICLE, AND IT WAS INVOLVED IN A FRONTAL IMPACT. THE VEHICLE ROLLED OVER SIX TIMES. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONTACT AND PASSENGER SUSTAINED
10143976	CHEVROLET	TRAILBLAZER	2005	2005-11-20	INJURIES. MANUFACTURER WAS NOT CONTACTED. *AK
					7/8/06, WHILE TRAVELING HIGHWAY 31 IN NILES, MICHIGAN, SPEED LIMIT OF 70 MPH, WE HIT A DEER HEAD ON WITH OUR 2005 CHEVY TRAILBLAZER LS, S/N. WE HAD NO TIME TO EVEN BRAKE PRIOR TO THE IMPACT. THE IMPACT TOOK OUT THE FRONT END OF THE CAR, PUSHING THE RADIATOR BACK INTO THE ENGINE COMPARTMENT. NEITHER AIR BAG DEPLOYED. THERE WERE 4
10161963	CHEVROLET	TRAILBLAZER	2005	2006-07-08	PASSENGERS IN THE VEHICLE, INCLUDING AN 11-YEAR OLD BOY, AND A 14-YEAR OLD BOY. *JB DT*: THE CONTACT STATED WHILE DRIVING 40 MPH ENTERING THE FREEWAY, THE VEHICLE REAR
10173065	CHEVROLET	TRAILBLAZER	2005	2006-11-08	ENDED ANOTHER VEHICLE AND NONE OF THE AIR BAGS DEPLOYED. THE AIRBAG WARNING LIGHT DID NOT ILLUMINATE PRIOR TO THE CRASH. A POLICE REPORT WAS FILED IN THE STATE OF CALIFORNIA. THERE WERE TWO PEOPLE INJURED; THE NOSE OF THE CHILD WAS BLEEDING AND THE CONTACT SUFFERED A NECK INJURY. THE CHILD WAS 6 YEARS OLD AND THE CONTACT WAS 22 YEARS OLD. BOTH OF THE PASSENGERS WERE WEARING SEAT BELT. THE WEATHER WAS CLOUDY. A POLICE REPORT WAS PROCESS. THE SERVICE DEALER AND THE MANUFACTURER WERE NOT NOTIFIED.
					TIX THE CONTACTIC 2005 CHENY TRAILED ATER MAS PURCHASED HISER ON ALICHET 42, 2005
10178482	CHEVROLET	TRAILBLAZER	2005	2007-01-08	TL* - THE CONTACT'S 2005 CHEVY TRAILBLAZER WAS PURCHASED USED ON AUGUST 13, 2005 FROM BERGLUND CHEVROLET OF VIRGINIA, WITH 13000 MILES. THE VEHICLE WAS INVOLVED IN AN ACCIDENT ON JANUARY 8TH, 2007 WERE THERE WAS ONE FATALITY AND FIVE PEOPLE WERE INJURED. A SECOND VEHICLE, A BUICK LASABRE, FAILED TO STOP AT STOP SIGN WHILE MAKING A LEFT HAND TURN. THE CONTACTS VEHICLE STRUCK THE SECOND VEHICLE DIRECTLY ON THE DRIVERS SIDE. THE CONTACTS VEHICLE WAS TRAVELING AT 50 MPH. THE DRIVER OF THE SECOND VEHICLE WAS PRONOUNCED DEAD AT THE SCENE. THE CONTACTS VEHICLE PASSENGER AND DRIVER SIDE AIR BAGS NEVER DEPLOYED, EVEN THOUGH THERE WERE PASSENGERS IN ALL SEATS. SIX STATE TROOPERS WERE ON THE SCENE AND NO ONE WAS SITED.
10205154	CHEVROLET	TDAILDI AZED	2005	2007 10 06	I WAS DRIVING ON AN ELEVATED INTERSTATE AND LOST CONTROL OF THE VEHICLE. I HIT THE GUARDRAIL IN A DIRECT FRONTAL IMPACT. THE ENTIRE FRONT OF THE CAR WAS CRUSHED ABOUT 40 INCHES. THE CAR IS TOTALED BUT THE AIRBAGS DID NOT DEPLOY. I SUFFERED SOME INJURIES ON MY HEAD EVEN THOUGH I HAD MY SEATBELT ON. *JB
10205154	CHEVROLET	TRAILBLAZER	2003	2007-10-00	I WAS DRIVING ON A 2 LANE ROAD GOING 45MPH. A CAR WAS FOLLOWING CLOSE BEHIND ME SO I WENT TO GET INTO RIGHT LANE AND MY TRUCK DID 5 360 AND HIT 3 TREES HEAD ON AND AIR BAG
10221319	CHEVROLET	TRAILBLAZER	2005	2008-02-21	NEVER DEPLOYED. *TR
10239994	CHEVROLET	TRAILBLAZER	2005	2008-08-25	TL*THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. WHILE DRIVING 60 MPH, THE CONTACT STRUCK THE GUARDRAIL. THE VEHICLE WAS DESTROYED AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT HAS PICTURES OF THE VEHICLE. SHE WAS TRANSPORTED TO THE HOSPITAL AND IS CURRENTLY IN PAIN. A POLICE REPORT WAS FILED. THE AIR BAGS WERE NOT SERVICED PRIOR TO THE CRASH. THE VIN WAS UNKNOWN. THE FAILURE MILEAGE WAS 44,000.
10241433	CHEVROLET	TRAILBLAZER	2005	2005-09-07	TL*THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 45 MPH, THE CONTACT CRASHED INTO ANOTHER VEHICLE, WHICH RESULTED IN A THREE CAR PILE UP. THE FRONT END OF HER VEHICLE WENT UNDERNEATH THE PRECEDING VEHICLE. THE AIR BAGS FAILED TO DEPLOY. SHE WAS UNABLE TO RECEIVE ASSISTANCE FROM ON STAR DUE TO THE AIR BAG FAILURE. THERE WERE NO PRIOR FAILURES WITH HER VEHICLE. THE CONTACT AND THREE CHILDREN IN SAFETY SEATS SUSTAINED MINOR INJURIES. A POLICE REPORT WAS FILED. THE CURRENT AND FAILURE MILEAGES WERE 76,000.

10254382	CHEVROLET	TRAILBLAZER	2005	2008-12-16	MY DAUGHTER HAD AN ACCIDENT ON 12/16/2008. SHE HAS(HAD) A 2005 CHEVROLET TRAILBLAZER LS, 2 WHEEL DRIVE SUV. WHILE DRIVING ON THE OHIO TURNPIKE DURING A SNOW STORM SHE LOST CONTROL AND HAD A HEAD ON CRASH WITH A CEMENT RETAINING WALL WHILE TRAVELING BETWEEN 25 TO 35 MILES PER HOUR. THE AIR BAG DID NOT DEPLOY DURING THE ACCIDENT AND SHE SLAMMED HARD INTO THE STEERING WHEEL RESULTING IN A CONCUSSION, CHEST INJURIES, SORE WRIST, DIZZINESS, AND STILL HAS RINGING IN ONE EAR. SHE DID HAVE HER SAFETY BELT ON AT THE TIME OF THE ACCIDENT AND ALWAYS WEARS IT. WE ARE BAFFLED AS TO WHY THE AIR BAG DID NOT COME OUT AS IT WOULD HAVE SAVE HER MUCH PAIN. THE CAR IS A TOTAL WRECK AS DESCRIBED BY THE PONTIAC DEALER THAT HER INSURANCE COMPANY TOWED THE SUV TO FOR REPAIRS. THE TRAILBLAZER SUSTAINED MUCH DAMAGE SUCH AS A BENT FRAME, BROKEN TRANSMISSION, ALL OF THE MOTOR MOUNTS AND THE TRANSMISSION MOUNTS BROKE LOOSE FROM THE FRAME, BENT STEERING WHEEL, AND ALL PARTS FROM THE ENGINE FORWARD ARE EITHER GONE OR BENT BEYOND REPAIR. WITH THIS VIOLENT OF A CRASH NO ONE HAS BEEN ABLE TO TELL US WHY THE AIR BAGS DID NOT DEPLOY. WE BOUGHT THIS SUV USED FROM A CHEVY DEALER IN JULY OF 2005 AND IT HAD AROUND 8000 MILES ON IT AT THAT TIME. I WOULD LIKE TO KNOW IF THERE IS SOME WAY OF CHECKING THE FUNCTIONALLY OF THIS AIR BAG TO SEE IF THERE MAY BE A POSSIBLE PROBLEM WITH IT. HER CRASH WAS HEAD ON AND IN MY OPINION VIOLENT ENOUGH TO ACTIVATE THE DRIVER SIDE AIR BAG. ANY SUGGESTIONS AS TO WHAT WE SHOULD DO? *TR
10256371	CHEVROLET	TRAILBLAZER	2005	2009-01-12	TL*THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. THE CONTACT WAS THE PASSENGER IN A VEHICLE TRAVELING 35 MPH ON ICY ROAD CONDITIONS. ANOTHER VEHICLE PULLED OUT IN FRONT OF THEM AND CRASHED INTO THE VEHICLE. THE VEHICLE WAS DESTROYED AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL BY AMBULANCE. HER NECK WAS SNAPPED BACKWARDS. THE SEAT BELT PROPERLY RESTRAINED HER AT THE TIME OF THE CRASH. A POLICE REPORT WAS FILED AND THE OTHER DRIVER RECEIVED A CITATION. THE DEALER WAS UNABLE TO DETERMINE WHY THE AIR BAGS FAILED. THE FAILURE MILEAGE WAS 80,000.
					AIRBAGS DID NOT DEPLOY. A DRIVER PULLED OUT IN FRONT OF MY WIFE. SHE WAS TRAVELING AT NEARLY 40MPH. SHE STRUCK ANOTHER VEHICLE BROAD SIDE. THE AIRBAGS DID NOT DEPLOY. THE FRONT BUMPER FROM OUR TRAILBLAZER WAS ABOUT 30 YARDS BEHIND OUR VEHICLE. MY WIFE
10266680	CHEVROLET	TRAILBLAZER	2005	2009-04-20	EXPERIENCED SEVERE BRUISING TO ABD AND CHEST. HER SEATBELT WAS IN USE. *TR LOST CONTROL OF CAR ON NARROW ROAD UNDER NORMAL DRIVING CONDITIONS. COLLISION
10328284	CHEVROLET	TRAILBLAZER TRAILBLAZER	2005	2010-04-29	INTO TWO TREES HEAD ON. DRIVER SIDE AIRBAG NEVER DEPLOYED. *TR I WAS IN AN ACCIDENT WHERE ANOTHER DRIVER PULLED OUT IN FRONT OF ME CROSSING ONCOMING TRAFFIC. I HIT HIM BROADSIDE DOING APPROXIMATELY 30-35 MILES PER HOUR. MY FRONT END WAS NEARLY SHOVED ALL THE WAY UP TO THE WINDSHIELD. MY 2005 TRAILBLAZER WAS TOTALED. MY AIRBAG DID NOT DEPLOY AND IF IT WASN'T FOR MY SEATBELT I WOULD HAVE WENT THROUGH THE WINDSHIELD THE IMPACT WAS SO HARD. I SUSTAINED A HURT SHOULDER AND ARM AND PROBABLY WOULDN'T HAD SUCH A PAINFUL INJURY IF THE AIRBAG HAD OF DEPLOYED. *TR
10357310	CHEVROLET	TRAILBLAZER	2005	2010-07-09	TL* THE CONTACT OWNS A 2005 CHEVROLET TRAIL BLAZER. THE CONTACT WAS DRIVING 50 MPH ON A SLICK MOUNTAIN ROAD WHEN THE VEHICLE HYDROPLANED AND CRASHED INTO THE SIDE OF A MOUNTAIN BEFORE FALLING INTO A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT AND TWO PASSENGERS SUSTAINED INJURIES. THE VEHICLE WAS DESTROYED. THE VEHICLE WAS NOT INSPECTED FOR THE FAILURE OF THE AIR BAGS. THE CONTACT WAS ADVISED BY HIS INSURANCE ADJUSTER THAT THE AIR BAGS SHOULD HAVE DEPLOYED. A POLICE REPORT WAS AVAILABLE. THE VIN WAS NOT AVAILABLE. THE FAILURE AND CURRENT MILEAGE WAS APPROXIMATELY 100,000.
10398899	CHEVROLET	TRAILBLAZER	2005	2011-04-28	AIR BAG DID NOT DEPLOY IN HEAD-ON COLLISION. *TR
10470760	CHEVROLET	TRAILBLAZER	2005	2012-07-27	TL* THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT THE DRIVER WAS TRAVELING BETWEEN 30 AND 40 MPH WHEN THE VEHICLE CRASHED INTO ANOTHER VEHICLE HEAD ON AND THE AIR BAGS FAILED TO DEPLOY. THE DRIVER SUSTAINED INJURIES TO THE HEAD, MOUTH, CHEST, LEG, AND WRIST. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VEHICLE WAS NOT TAKEN TO THE DEALER. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE AND CURRENT MILEAGE WAS 40,000.
10475331	CHEVROLET	TRAILBLAZER	2005	2012-06-27	TL* THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. THE CONTACT WAS TRAVELING 45 MPH WHEN HE CRASHED AGAINST THE STREET MEDIAN, A UTILITY POLE AND THEN INTO A BUILDING. THE CONTACT STATED THAT NONE OF THE AIR BAGS IN THE VEHICLE DEPLOYED. THE CONTACT SUSTAINED LESIONS TO THE FACE, A CONTUSION TO THE RIGHT EYE AND CONTUSIONS TO THE CHEST AND LOWER ABDOMEN AREA. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE, VEHICLE WAS INSPECTED HOWEVER, THE FINDINGS WERE NOT DISCLOSED TO CONTACT. THE FAILURE AND CURRENT MILEAGE WAS 118,000.

			1		1
10477042	CHEMBOLET	TRAUDI AZER	2005	2012 00 17	TL* THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. THE CONTACT WAS DRIVING IN RAINY WEATHER AT VARIOUS SPEEDS WHEN HE UNEXPECTEDLY CRASHED INTO ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED FOR THE INCIDENT. THE CONTACT SUSTAINED SEVERE HEAD TRAUMA AND WAS TRANSPORTED BY AN AMBULANCE TO THE HOSPITAL. THE VEHICLE WAS DESTROYED AND TOWED TO A SAVAGE FACILITY. THE MANUFACTURER WAS NOT NOTIFIED OF THE PROBLEM. THE APPROXIMATE FAILURE MILEAGE
10477042	CHEVROLET	TRAILBLAZER	2005	2012-09-17	WAS 122,000. UPDATED 10/31/12 *BF UPDATED 11/02/12 TL* THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE
10477257	CHEVROLET	TRAILBLAZER	2005	2012-05-20	DRIVING 30 MPH ATTEMPTING TO AVOID IMPACTING A DEER ON THE ROAD, HE CRASHED OFF A 9 FOOT EMBANKMENT AND NONE OF THE AIR BAGS DEPLOYED. THE CONTACT BECAME UNCONSCIOUS AFTER HIS HEAD CRASHED INTO THE STEERING WHEEL. ALSO, THE CONTACT SUFFERED SEVERE NECK INJURIES. THE VEHICLE WAS INSPECTED BY THE DEALER BUT THE RESULTS WERE INCONCLUSIVE. THE MANUFACTURER WAS NOTIFIED BUT OFFERED NO ASSISTANCE. THE FAILURE AND CURRENT MILEAGE WAS 108,429. THE VIN WAS UNAVAILABLE. UPDATED 10/31/12 *CN UPDATED 11/9/2012 *JS
10669444	CHEVROLET	TRAILBLAZER	2005	2014-11-18	HIT BLACK ICE. TRUCK SLID OFF THE ROAD AND FRONT END IMPACTED THE DITCH CAUSING HEAVY DAMAGE TO THE FRONT END. AIR BAG FAILED TO DEPLOY CAUSING INJURY. *JS
10678235	CHEVROLET	TRAILBLAZER	2005	2015-01-21	TL*THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT 25 MPH, ANOTHER VEHICLE CRASHED INTO THE FRONT PASSENGER SIDE OF THE CONTACT'S VEHICLE. AS A RESULT, THE CONTACT CRASHED INTO A SIGN AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED BACK INJURIES AND THE PASSENGER SUSTAINED NECK AND BACK INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE CONTACT WAS UNABLE TO CONFIRM IF THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 122,000. THE VIN WAS UNAVAILABLE.
10689540	CHEVROLET	TRAILBLAZER	2005	2015-02-16	TL* THE CONTACT OWNED A 2005 CHEVROLET TRAILBLAZER. WHILE DRIVING VARIOUS SPEEDS, THE VEHICLE SLID AND CRASHED. THE DRIVER SIDE AIR BAG FAILED TO DEPLOY. THE VEHICLE WAS NOT INCLUDED IN NHTSA CAMPAIGN NUMBER: 06V417000 (AIR BAGS). THE CONTACT SUSTAINED LACERATIONS TO THE FACE, STITCHES UNDER THE EYEBROWS ON BOTH EYES, AND AN INJURED NECK THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS NOT AVAILABLE.
10721128	CHEVROLET	TRAILBLAZER	2005	2015-04-27	2005 CHEVY TRAILBLAZER WAS DRIVEN BY MY GRANDDAUGHTER. SHE WAS TRYING TO ENTER ONTO I-10 INTERSTATE AND WAS GOING TOO FAST ON THE ENTRANCE RAMP. ROAD CONDITIONS WERE HAZARDOUS AS IT WAS A SEVERE RAIN STORM. SHE HYDROPLANED AND HIT A VEHICLE IN FRONT OF HER WHICH CAUSED HER TO SPIN INTO ONCOMING TRAFFIC. SHE WAS HIT ON THE DRIVER'S SIDE AND THE TRUCK SPUN AROUND SEVERAL TIMES BEFORE IT STOPPPED. THE AIRBAG DID NOT DEPLOY!!! THE POLICE OFFICER AND THE TOW COMPANY DRIVER SAID SHE WAS LUCKY TO BE ALIVE. MY CONCERN IS THIS COULD HAVE BEEN A FATAL ACCIDENT AND THE AIRBAG FAILED TO DEPLOY. THE TRAILBLAZER WAS TOTALED AS THE AXLE AND THE ENGINE WERE ON THE GROUND. THE DRIVER'S SIDE FRONT WHEEL CAME OFF. I HAVE ALWAYS LIKE CHEVY VEHICLES BUT AM NOW HESITANT TO PURCHASE ANOTHER ONE B/C OF THIS ISSUE WITH THE AIR BAG.
					HEAD ON COLLISION BOTH VEHICLES TRAVELING ABOUT 30MPH ON IMPACT AND TRAILBLAZER AIR
10885198	CHEVROLET	TRAILBLAZER	2005	2016-06-20	BAGS DID NOT DEPLOY. I HAD MY SEATBELT ON AND WAS NOT INJURED.
10983668	CHEVROLET	TRAILBLAZER	2005	2017-05-02	TL* THE CONTACT OWNS A 2005 CHEVROLET TRAILBLAZER. WHILE DRIVING 35 MPH, THE CONTACT CRASHED INTO THE REAR OF ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THE DRIVER SUSTAINED VARIOUS INJURIES TO THE FACE, WHICH REQUIRED MEDICAL ATTENTION. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE VEHICLE WAS TOWED TO A TOW YARD AND WAS NOT DIAGNOSED FOR THE AIR BAG FAILURE. THE FAILURE MILEAGE WAS 140,000.
11011530	CHEVROLET	TRAILBLAZER	2005	2017-07-27	AIRBAG DID NOT WORK
10111298	GMC	ENVOY	2005	2005-01-25	COMPLAINT RECEIVED VIA E-MAIL. MY WIFE WAS IN HER 2005 GMC ENVOY WHEN IT WAS HIT ON THE DRIVER'S TIRE, AND WAS DRIVEN INTO A CONCRETE POWER POLE AT 40 MPH HEAD ON. THE POWER LINES WERE KNOCKED DOWN. DRIVER'S SIDE AIR BAG NEVER DEPLOYED, AND HER HEAD HIT THE STEERING, CAUSING A BUMP ON THE HEAD, A BLACK EYE AND A CUT LIP.*AK
10119967	GMC	ENVOY	2005	2005-04-22	SEVERE CAR CRASH WITH MY LEASED 2005 GMC ENVOY. MUCH SIDE AND FRONT DAMAGE OCCURED, BUT AIR BAGS DID NOT DEPLOY. GMC WILL BE SENDING SOMEONE FROM THE PROTECTION ALLEGATION DEPARTMENT TO PERFORM A DIAGNOSTIC TEST ON THE AIR BAGS WITHIN THE NEXT 14 DAYS. THE ACCIDENT OCCURED ON 4/22/05. I DO NOT WANT THE VEHICLE REPAIRED AND GIVEN BACK TO ME FOR THE FOLLOWING 2 REASONS: THE VEHICLE INCURRED (IN MY OPINION, POLICE REPORT, ALLSTATE INSURANCE CO., STERLING AUTO BODY REPAI SHOP) ETC EXTENSIVE DAMAGE. THE 2ND REASON IS THE AIRBAGS, AS STATED, DID NOT DEPLOY. IF ANYONE WERE TO BE SEATED IN THE PASSENGER SEAT, THEY WOULD HAVE BEEN SERIOUSLY HURT. I HAVE READILY AT MY DISPOSAL ANY AND ALL ADDITIONAL INFO. WHICH I WILL GLADLY SUBMIT WHEN NECESSARY.

10183935	GMC	ENVOY	2005	2007-02-13	TL* - THE CONTACT OWNS A 2005 GMS ENVOY. IN MID FEBRUARY 2007 THE CONTACT'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION WHILE DRIVING AT 35 MPH. THE CONTACT DROVE INTO A TREE DUE TO ICY ROAD CONDITIONS. NONE OF THE AIR BAGS DEPLOYED. THERE WERE NO PASSENGERS IN THE VEHICLE. THE CONTACT WAS WEARING A SEAT BELT. THERE WERE NO WARNING INDICATOR LIGHTS ON THE DASHBOARD BEFORE OR AFTER THE CRASH. THE VEHICLE WAS TOWED TO A THE DEALER, AND THE INSURANCE COMPANY ADVISED THE CONTACT THAT THE VEHICLE WAS TOTALED. THE CONTACT HAD REQUESTED THAT THE MANUFACTURER ISSUE A COMPUTER READ OUT INDICATING WHY THE AIR BAGS DIDN'T DEPLOY. THE DEALER SENT THE CONTACT PRIOR TO THE COLLISION A DIAGNOSTIC EMAIL STATING THE VEHICLE WAS OPERATING NORMALLY. A POLICE REPORT WAS TAKEN. THE CURRENT AND FAILURE MILEAGE WERE BOTH 25000.*AK
10257735	GMC	ENVOY	2005	2009-01-28	TL*THE CONTACT OWNS A 2005 GMC ENVOY. THE CONTACT WAS INVOLVED IN A HEAD-ON CRASH. THE CONTACT WAS SEVERELY INJURED AND THE ENTIRE FRONT END OF THE VEHICLE WAS CRUSHED. ALL FOUR TIRES BLEW OUT AND THE FRONTAL AIR BAGS FAILED TO DEPLOY. THERE WERE NO OTHER PASSENGERS IN THE VEHICLE AND NO MAINTENANCE WAS PERFORMED ON THE VEHICLE PRIOR TO THE CRASH. THE VEHICLE WAS DESTROYED AND TOWED FROM THE SCENE. A POLICE REPORT WAS FILED. THE MILEAGES, SPEED, AND VIN WERE UNKNOWN.
10463248	GMC	ENVOY	2005	2011-07-15	TL* THE CONTACT OWNED A 2005 GMC ENVOY. THE CONTACT STATED WHILE DRIVING 55 MPH, HE CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED MINOR TISSUE DAMAGE ON THE UPPER BODY FROM THE IMPACT. THE VEHICLE WAS TOWED TO A REPAIR SHOP, WHERE IT WAS DECLARED DESTROYED. A POLICE REPORT WAS FILED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE; HOWEVER, THEY PROVIDED NO ASSISTANCE. THE CURRENT AND FAILURE MILEAGE WERE UNAVAILABLE. UPDATED 09/24/2012 *JS THE CONSUMER STATED THE ACCIDENT WAS INITIATED BY A VEHICLE GOING WEST BOUND THAT CROSSED THE SOLID DOUBLE LINES, ULTIMATELY CAUSING A DOMINO EFFECT. THE CONSUMER'S VEHICLE WAS DAMAGED WHEN HE TRIED TO AVOID HITTING THE VEHICLE BY SWERVING SIDEWAYS AND SLIDING INTO THE GRASS. HE TRIED STOPPING THE VEHICLE WHILE IT WAS STILL ON THE PAVEMENT BUT HE INEVITABLY RAN INTO THE DITCH AND FLEW AIRBORNE INTO A TREE, AND THE TRUCK OVERTURNED. UPDATED 03/25/14 UPDATED 01//22/15. *JBUPDATED 03/17/16 *BF UPDATED 09/06/16.*JB UPDATED 09/18/2017*JS *JS
10503799	GMC	ENVOY	2005	2013-03-15	THE ACCIDENT HAPPENED ON 2-15-2013 ON PENNSYLVANIA AVENUE SE DURING RUSH HOUR THE OTHER CAR DID NOT YIELD TO ONGOING TRAFFIC ON PENNSYLVANIA AVENUE AND DODGED OUT FROM A SIDE STREET AND HIT MY VEHICLE ON THE FRONT SIDE AND MY SON WHO IS 13 HEAD HIT THE DASHBOARD AND MY DAUGHTERS DOG FLEW FROM THE BACK SEAT UP TO THE FRONT. THE OTHER VEHICLE AIRBAG DID DEPLOY BUT MINES DID NOT. *TR
10607728	GMC	ENVOY	2005	2008-03-16	SINGLE CAR ACCIDENT WITH CAR RUNNING OFF ROAD RAN INTO DITCH, OVERTURNED AND HITTING PHONE POLE. AIRBAG DID NOT DEPLOY. QUESTIONABLE SEAT BELT ISSUES. *TR
10632374	GMC	ENVOY	2005	2011-09-16	CRASH. THE AIR BAGS NEVER DEPLOYED AND I SUSTAINED BACK INJURIES. ON SITE OF THE ACCIDENT MY BACK WAS HURTING SOME BUT DID NOT GO TO HOSPITAL UNTIL LATER THAT EVENING, AFTER THE ADRENALIN AND THE SHOCK WORE OFF. I NOW HAVE SEVER BACK PROBLEMS WITH A LOT OF PAIN AND WAS DECLARED DISABLED IN 2012. AT THE TIME OF DOING RESEARCH I WAS TOLD BY ON-STAR, WHICH NEVER CAME ON, THAT IF MY AIR BAGS DIDN'T DEPLOY THEY WOULDN'T COME ON BUT, THE FRAME WAS BENT SO BAD THAT THEY TOTALED THE VEHICLE, WITH A LOT OF OTHER DAMAGE. THE WHOLE FRONT WAS DAMAGED, THE BUMPER WAS DESTROYED ALONG WITH DAMAGE TO THE MOTOR. AND WE COULD NOT UNDERSTAND WHY THE AIR BAGS DID NOT DEPLOY. *TR
10908300	GMC	ENVOY	2005	2016-08-22	I HAD THREE CARS IN FRONT OF ME STOPPED. I DID NOT SEE ANY BREAKL LIGHTS AND I HIT THE CAR IN FRONT OF ME PUSHING THE OTHER CARS TO HIT EACH OTHER. MY FRONT END OF MY CAR WAS SEVERELY DAMAGED BAD ENOUGH TO DAMAGE THE RADIATOR AND DESTROY MY AC UNIT. I'M NOT SURE WHAT ELSE WAS DAMAGED. IT SENT THE PERSON IN FRONT OF ME AND MYSELF TO THE EMERGENCY ROOM. " MY AIR BAGS DID NOT DEPLOY ". MY VEHICLE WAS MOVING ON A CITY STREET.

				1	<u> </u>
10370915	ISUZU	ASCENDER	2005	2010-12-10	I WAS DRIVING EAST ON INTERSTATE 10 IN PENSACOLA, FLORIDA. A VEHICLE TRAVELING WEST LOST CONTROL AND CAME ACROSS THE SLOPED GRASSY MEDIAN, OVERTURNED AN SLID ACROSS MY TRAFFIC LANE, CAUSING ME TO CRASH INTO THEIR ROOF. MY ODOMETER SAYS AT THE POINT OF IMPACT I WAS ONLY TRAVELING 48 MPH. ONCE I REALIZED I WAS ALIVE, I WAS IN AWE THAT THE AIRBAG DID NOT DEPLOY. I SPOKE TO A MANAGER AT ISUZU IN CALIFORNIA. HE REQUESTED THE VIN NUMBER AND SOME OTHER PERSONAL INFORMATION AND SAID IF THE INSURANCE COMPANY ADJUSTER SAW ANY MANUFACTURER DEFECTS, THEN THE INSURANCE COMPANY WOULD CONTACT ISUZU. I ALSO CONTACTED MY INSURANCE PROVIDER, THEY SAID SINCE I WAS NOT KILLED IN THE ACCIDENT, THEY WOULD NOT PURSUE ANYTHING WITH ISUZU. I THOUGHT SOMEONE SHOULD KNOW BECAUSE I WAS PINNED IN THE VEHICLE AND HAD TO BE CUT OUT. THE TOW TRUCK DRIVER ALSO MENTIONED SOMETHING ABOUT THE STEERING COLUMN HAD MALFUNCTIONED, NOT SURE WHAT THE MALFUNCTION WAS, BUT IT DID NOT DO WHAT IT WAS DESIGNED TO DO FOR SAFETY PURPOSES. I SUSTAINED A FRACTURED RIGHT FOOT, BRUISED LUNGS/RIBS, NUMEROUS LACERATIONS, BRUISED LEFT KNEE AND LEFT ELBOW. *TR
					WE HAD A CAR ACCIDENT AND THE AIRBAGS DIDN'T ACTIVATETHE IMPACT WAS VERY HARD
10449350	ISUZU	ASCENDER	2005	2012-02-20	THAT THE INSURANCE COMPANY DECIDED TO TOTAL THE CAR BECAUSE THE DAMAGE WAS TO BIGI AM PREGNANT AND I HAVE 2 MORE KIDS, AND I'M SO DISAPPOINTED WITH THIS EXPERIENCE THAT SOMETHING COULD HAPPENED TO ME OR MY KIDS IF WE WERE IN THE ACCIDENT. *TR
					MY FIANCE WAS IN ACCIDENT WITH MY SUV AND THE AIR BAG DIDN'T DEPLOY CAN I SUE THE
10228093	BUICK	RAINIER	2004	2008-03-20	COMPANY WHO SOLD ME THE VEHICLE? *TR
10266690	BUICK	RAINIER	2004	2009-04-05	AUTO, MY AUTO WAS STRUCK THEN SHOVELED INTO A CEMENT WALL BLOCK AND THEN BOUNCED INTO ON COMING TRAFFIC TO THE OTHER CEMENT WALL BLOCK ON THE OPPOSITE SITE WHILE TRYING TO STOP, I WAS WEARING A SEAT BELT, THE VEHICLE'S AIR BAGS DIDN'T GO OFF AT ALL IN THE VEHICLE. A HEAD INJURY OCCURRED, NECK AND SHOULDER INJURIES OCCURRED. THE AUTO WAS A TOTAL LOSS! *TR
10638828	BUICK	RAINIER	2004	2012-11-17	A PERSON RAN TWO STOP SIGNS AND ENTERED VEHICLE PATH. THE TWO VEHICLES HIT HEAD ON AND THIS VEHICLE MADE IMPACT AT 40 MPH AFTER IT DECELERATED FROM 43 MPH. THE TWO VEHICLE HIT HEAD ON WITH NEAR PERFECT EVEN IMPACT, BASED UPON THIRD PARTY VISUAL DESCRIPTION OF THE FRONT END OF THE VEHICLES DAMAGE. THE VEHICLE DECELERATED AT A MAX SDM RECORDED VELOCITY CHANGE RATE OF -14.07 (MPH) AND A ALGORITHM ENABLED TO MAXIMUM SDM RECORDED VELOCITY CHANGE OF 127.5 MSEC. DRIVER OF THE VEHICLE HIT THE STEERING WHEEL WITH HEAD KNOCKING THE PERSON OUT. AIRBAGS DID NOT DEPLOY. ONSTAR WAS NOT NOTIFIED THAT THERE WAS AN ACCIDENT. COMPUTER SHOWS THE SEATBELT WAS WORN BY DRIVER. WHEN THE ONSTAR WAS MANUALLY ACTIVATED BY THE DRIVER WHEN HE CAME TOO, THE GPS SHOWED THE VEHICLE FURTHER NORTH UP THE ROAD CAUSING INCORRECT POLICE DIVISION BEING CALLED. VEHICLE WAS GOING UP HILL WHEN THE ACCIDENT OCCURRED. OTHER VEHICLE WAS GOING DOWNHILL. THE OTHER VEHICLE WAS A SUBARU. VEHICLE COMPUTER DATA WAS RETRIEVED BY A BOSCH CRASH DATA RETRIEVAL TOOL USING VERSION 8.0 SOFTWARE. I HAVE A COPY OF THIS DATA. GM REPORTS THAT THE COMPUTER WAS CORRECT NOT TO DEPLOY AIRBAGS AND NOT CALL FOR HELP USING ONSTAR. THE VEHICLE HAD A SOFTWARE MODIFICATION DUE TO A FAULT WITH THE FAN SPEED CALIBRATION SETTING OFF A WARNING LIGHT. WE HAD COMPLAINED THAT THINGS WERE NEVER CORRECT AFTER THIS MODIFICATION OF THE SOFTWARE AND TOOK THE VEHICLE TO TWO DIFFERENT DEALERSHIPS COMPLAINING THAT COMPUTERS WERE DOING STRANGE THINGS AFTER THIS FIRMWARE MODIFICATION. VEHICLE VIN: [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6). *TR

10638830	BUICK	RAINIER	2004	2012-11-17	A PERSON RAN TWO STOP SIGNS AND ENTERED VEHICLE PATH. THE TWO VEHICLES HIT HEAD ON AND THIS VEHICLE MADE IMPACT AT 40 MPH AFTER IT DECELERATED FROM 43 MPH. THE TWO VEHICLE HIT HEAD ON WITH NEAR PERFECT EVEN IMPACT, BASED UPON THIRD PARTY VISUAL DESCRIPTION OF THE FRONT END OF THE VEHICLES DAMAGE. THE VEHICLE DECELERATED AT A MAX SDM RECORDED VELOCITY CHANGE RATE OF -14.07 (MPH) AND A ALGORITHM ENABLED TO MAXIMUM SDM RECORDED VELOCITY CHANGE OF 127.5 MSEC. DRIVER OF THE VEHICLE HIT THE STEERING WHEEL WITH HEAD KNOCKING THE PERSON OUT. AIRBAGS DID NOT DEPLOY. ONSTAR WAS NOT NOTIFIED THAT THERE WAS AN ACCIDENT. COMPUTER SHOWS THE SEATBELT WAS WORN BY DRIVER. WHEN THE ONSTAR WAS MANUALLY ACTIVATED BY THE DRIVER WHEN HE CAME TOO, THE GPS SHOWED THE VEHICLE FURTHER NORTH UP THE ROAD CAUSING INCORRECT POLICE DIVISION BEING CALLED. VEHICLE WAS GOING UP HILL WHEN THE ACCIDENT OCCURRED. OTHER VEHICLE WAS GOING DOWNHILL. THE OTHER VEHICLE WAS A SUBARU. VEHICLE COMPUTER DATA WAS RETRIEVED BY A BOSCH CRASH DATA RETRIEVAL TOOL USING VERSION 8.0 SOFTWARE. I HAVE A COPY OF THIS DATA. GM REPORTS THAT THE COMPUTER WAS CORRECT NOT TO DEPLOY AIRBAGS AND NOT CALL FOR HELP USING ONSTAR. THE VEHICLE HAD A SOFTWARE MODIFICATION DUE TO A FAULT WITH THE FAN SPEED CALIBRATION SETTING OFF A WARNING LIGHT. WE HAD COMPLAINED THAT THINGS WERE NEVER CORRECT AFTER THIS MODIFICATION OF THE SOFTWARE AND TOOK THE VEHICLE TO TWO DIFFERENT DEALERSHIPS COMPLAINING THAT COMPUTERS WERE DOING STRANGE THINGS AFTER THIS FIRMWARE MODIFICATION. VEHICLE VIN: [XXX] INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6). *TR
10038830	DUICK	KAINIEK	2004	2012-11-1/	
11099015	виіск	RAINIER	2004	2016-04-29	TL* THE CONTACT OWNED A 2004 BUICK RAINIER. WHILE DRIVING APPROXIMATELY 30 MPH IN THE RAIN, THE VEHICLE HYDROPLANED. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO A WALL. AS A RESULT, THE CONTACT WAS RENDERED UNCONSCIOUS AND TRANSPORTED TO THE HOSPITAL VIA AMBULANCE. THE CONTACTS HEAD STRUCK THE DRIVER'S SIDE WINDOW AND THE CONTACT REMAINED IN A COMA FOR SEVERAL MONTHS. THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SIDE OF THE HEAD, WHICH CAUSED WALKING COMPLICATIONS AND A LOSS OF FEELING IN THE RIGHT SIDE OF THE BODY. IN ADDITION, THE CONTACT SUFFERED A LOSS OF SIGHT IN THE RIGHT EYE DUE TO A CRUSHED SKULL. THE VEHICLE WAS TOWED TO A TOW LOT AND DEEMED DESTROYED. A DEALER WAS NOT MADE AWARE OF THE AIR BAG FAILURE. THE VEHICLE WAS NOT DIAGNOSED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNKNOWN.
					INVOLVED IN A HORRIFIC AUTO ACCIDENT WITH OTHER VEHICLE. HIT IN FRONT PASSENGER & FRONT PART OF VEHICLE (BY RADIATOR AREA) AT HIGH SPEED. EST.SPEED APPROX. 45-55 MPH WITH NO SKID MARKS, OTHER VEHICLE STOPPED WHEN IT HIT US. NEW GM/ESCALADE-SUV/"04-WITH 11,000 MILES, BOUGHT NEW DECLARED TOTAL LOSS, WITH APPARENT SERIOUS FRAME DAMAGE/BENT 12 IN. AND FOUND STRESS CRK. SHOULD GIVE AN IDEA HIGH SPEED OTHER VEHICLE TRAVELING. 8-10 SECONDS FROM IMPACT, ONSTAR CAME ON AUTOMATICALLY, THEY RECD. EMERGENCY MESSAGE VIA SATELLITE, VEHICLE HAD BEEN IN A SERIOUS MVA AND AIR BAGS DEPLOYED. WE DIDN'T CALL ONSTAR THEY CALLED US. NEXT DAY WE CALLED ASKED HOW THEY KNEW WE WERE ACCIDENT. TOLD US DEPENDING ON THE SEVERITY, THEY GET CERTAIN SIGNALS, WHICH OURS HAD ADVISED OF SERIOUSNESS & AIRBAG DEPLOYMENT. UNBELIEVABLY, NONE OF OUR 4 AIRBAGS DEPLOYED. WE & HUNDREDS OF OUR FRIENDS ARE IN TOTAL DISBELIEF WHEN YOU SEE THE CONDITION VEHICLE WAS LEFT IN & THAT 4 AIR BAGS DIDN'T DEPLOY. WE WERE INJURED BUT BY GRACE OF GOD INJURIES WERE NOT LIFE THREATENING. HEAD, UPPERANDLOWERBACK, NECK, LEGS, SHOULDER, HIPSAND ARMS EXTREMLEY SORE. HAS BEEN 33 DAYS SINCE THE ACCIDENT AND AM STILL FEELING PAINS & SERIOUS HEADACHES BUT ALIVE. HAVE DECIDED TO BECOME ADVOCATES AND REPORT ACCIDENT/INCIDENT TO POSSIBLY SAFE A PERSON(S) LIFE AND MAKE GENERAL MOTORS AWARE THAT THEY HAVE A POSSIBLE DEFECT IN THEIR AIR BAGS, LEADING TO MASSIVE RECALL AND POSSIBLY A CLASS ACTION LAW SUIT IF NOT FIXED. THIS IS A VERY SERIOUS MATTER. ANYTIME ANYONE IS HIT AT RATE OF SPEED THAT WE
					WERE, TO LEAVE BRAND NEW SUV ESCALADE A TOTAL LOSS/ 12 IN. BENT FRAME & STRESS CRACK & 4 AIR BAGS NOT DEPLOY - LEADS US TO BELIEVE OF A SERIOUS PROBLEM AND A SERIOUS ONE FOR GM/CADILLAC. CALL FOR FURTHER DETAILS (956) 533-0811 (956)358-5272. THANK YOU &
10125145	CADILLAC	ESCALADE	2004	2005-05-11	GOD BLESS.
10127916	CADILLAC	ESCALADE	2004	2005-05-11	THE CONSUMER WAS INVOLVED IN AN A SERIOUS ACCIDENT AND THE AIR BAGS DID NOT DEPLOY. THERE WERE 2 INJURIES. *JB *SC

10152700	CADILLAC	ESCALADE	2004	2005 07 46	ON JULY 16TH, 2005; I WAS INVOLVED IN A LIFE CHANGING, SINGLE VEHICLE AUTO ACCIDENT. I STRUCK A HILL WITH THE FRONT RIGHT SIDE OF THE VEHICLE WITH ENOUGH EXCESSIVE FORCE TO FLIP THIS CADILLAC ESCALADE HEAD FIRST. THE ESCALADE FLIPPED TWICE, IMPACTING THE FRONT OF THE VEHICLE AND LANDING UP SIDE DOWN. ASTONISHINGLY, OUT OF THE FOUR AIR BAGS IN THIS VEHICLE, NOT ONE OF THEM DEPLOYED. I PURCHASED THIS 2004 ESCALADE BRAND NEW AND AT THE TIME OF THE ACCIDENT IT ONLY HAD 15,000 MILES. THE VEHICLE IS A TOTAL LOSS AND IT IS UTTERLY UNBELIEVABLE THAT THE AIR BAGS DID NOT DEPLOY. I WAS SO IMPRESSED WITH THE RAVED REVIEWS, CONSUMER REPORTS INCLUDING SAFETY FEATURES, AND STYLISH BODY THAT THIS CADILLAC ESCALADE BECAME THE VEHICLE OF MY DREAMS. NEEDLESS TO SAY, I AM VERY DISAPPOINTED WITH MY CADILLAC EXPERIENCE. I DO NOT TRUST THIS VEHICLE ENOUGH TO GET INTO ANOTHER ONE. I KNOW THAT I AM ONLY HERE BECAUSE GOD DECIDED THE SPARE MY LIFE. AS A DIRECT RESULT OF THIS ACCIDENT I FREQUENTLY SUFFER SEVERE MIGRAINES, DIZZY SPELLS, BLURRED VISION, MEMORY LOSS, AND ANXIETY/PANIC ATTACKS ALL WHICH KEEP ME FROM SLEEPING. IT IS EXTREMELY DIFFICULT TO COMMUTE FROM DOCTORS APPOINTMENTS AND WORK FOR FEAR OF ANOTHER ACCIDENT. THE NEXT WEEK I HAD SEVERE CHEST, SHOULDER AND LOWER BACK PAINS; ALL OF WHICH I AM BEING TREATED FOR ON A REGULAR BASIS. I ALSO SEEK TREATMENT FROM A NEUROLOGIST FOR THE HEAD INJURY. I BELIEVE THAT THIS VEHICLE HAS A SERIOUS PROBLEM WITH THE AIR BAGS AND GM SHOULD STRONGLY CONSIDER INVESTIGATING
10152700	CADILLAC	ESCALADE	2004	2005-07-16	THIS MATTER. *NM
10386829	CADILLAC	ESCALADE	2004	2010-02-10	TL* THE CONTACT OWNS A 2004 CADILLAC ESCALADE. WHILE DRIVING APPROXIMATELY 65-75 MPH, THE CONTACT FELL ASLEEP. THE VEHICLE DRIFTED OFF THE ROAD AND CRASHED INTO A BRIDGE BARRIER. THE CONTACT SUSTAINED A BROKEN WRIST AND FACIAL LACERATIONS. THE FRONT SEAT PASSENGER WAS AIR-LIFTED TO THE HOSPITAL AND SUSTAINED A BROKEN RIGHT LEG AND SEVERE FACIAL INJURIES. THE REAR SEAT PASSENGER SUSTAINED INJURIES TO THE SPINE. THE AIRBAGS FAILED TO DEPLOY WITH THE MASSIVE IMPACT. A POLICE REPORT WAS FILED AND THE VEHICLE WAS TOWED TO A COLLISION CENTER. UPDATED 10/14/11
10436436	CADILLAC	ESCALADE	2004	2011-11-01	I WAS IN AN MVA ON NOV. 1, 2011 THAT TOTALED MY 2004 ESCALADE. NONE OF THE AIRBAGS DEPLOYED, DESPITE DAMAGE TO ALL SIDES OF THE AUTOMOBILE, INCLUDING FRONT END IMPACT. THE CAR ACTUALLY ROLLED. THE FRAME WAS BENT AND THE FRONT HIT AN EMBANKMENT NOSE FIRST WITH GREAT IMPACT. I SUFFERED SEVERAL INJURIES, INCLUDING HEAD TRAUMA. *TR
10430430	CADILLAC	LOCALADE	2004	2011 11 01	2004 CADILLAC SRX INVOLVED IN A FRONT END RASH ON JAN 19, 2010. SEVERE FRONT END CRASH
10324984	CADILLAC	SRX	2004	2010-01-19	HOWEVER AIRBAGS DID NOT DEPLOY. *TR
10638570	CADILLAC	SRX	2004	2014-09-17	TL* THE CONTACT OWNS A 2004 CADILLAC SRX. THE CONTACT STATED THAT A TIRE BLEW OUT CAUSING THE VEHICLE TO SPIN OUT OF CONTROL AND CRASH. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED AND ONE INJURY WAS REPORTED THAT DID NOT REQUIRE MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 120,000.
10245434	CHEVROLET	ASTRO	2004	2008-10-10	MY WIFE WAS DRIVING A 2004 CHEVY ASTRO VAN APPROX. 35-40 MPH ON A TWO-WAY STREET. ANOTHER DRIVER FROM THE OPPOSITE DIRECTION CUT ACROSS INTO HER LANE AND HAD A HEAD-ON COLLISION. SHE SUFFERED A BROKEN WRIST & BRUISED RIBS. SHE HAD THREE OF OUR CHILDREN IN THEIR SEATS. THEY WERE SHAKEN AND HAD SEATBELT BRUISES. THE VAN WAS NOT DRIVABLE AND WAS TOWED AWAY. THE POLICE & THE TOW DRIVER REPORTED THAT THE AIRBAGS DID NOT DEPLOY. WE HAVE SOME EXPECTATION THAT THE AIRBAGS WOULD HAVE SECONDARY ROLE TO MINIMIZE INJURIES. MY COMPLIANT THAT THE HARD COLLISION WAS SUFFICIENT TO DEPLOY SAFETY EQUIPMENT BUT DID NOT WORK AS DESIGNED. WAS THERE A RECALL FOR AIRBAG FAILURES FOR THIS MODEL OF VEHICLE? *TR
10057529	CHEVROLET	SILVERADO	2004	2004-01-27	WHILE DRIVING 40 MPH VEHICLE WAS INVOLVED IN A HEAD ON COLLISION. UPON IMPACT, DUAL AIR BAGS DID NOT DEPLOY. PASSENGER SUSTAINED INJURIES TO NECK, JAW, AND A BROKEN ARM. *AK *JB
10065268	CHEVROLET	SILVERADO	2004	2004-03-30	WHILE DRIVING 60 MPH DRIVER APPLIED THE BRAKES AND PEDAL WENT TO THE FLOOR. THIS CAUSED THE DRIVER TO LOSE CONTROL OF THE VEHICLE, AND HIT ANOTHER VEHICLE ON THE PASSENGER SIDE. UPON IMPACT, BOTH AIR BAGS DID NOT DEPLOY. THERE WERE NO INJURIES. *AK
10073357	CHEVROLET	SILVERADO	2004	2004-05-10	THE CONSUMER STATED THE FRONTAL AIR BAGS DID NOT DEPLOY DURING AN ACCIDENT. THERE WERE NO INJURIES. THE DRIVER HAD THE VEHICLE TOWED TO A BODY SHOP. *JB WHILE TRAVELING AT 30 MPH AND APPROACHING AN INTERSECTION, A SECOND VEHICLE ENTERED ON THE CONSUMER'S LEFT HAND SIDE, THERE WAS NO TIME TO REACT, THE CONSUMER STRUCK THE SECOND VEHICLE ON IT'S RIGHT SIDE. THE DRIVERS SIDE AIR BAG DID NOT DEPLOY. *SC *JB
10083968	CHEVROLET	SILVERADO	2004	2004-06-19	WHILE DRIVING AT 35 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A FRONTAL COLLISION. UPON IMPACT, NONE OF THE FRONTAL AIRBAGS DEPLOYED. DRIVER SUSTAINED MINOR BRUISES TO THEIR CHEST FROM THE SEAT BELT, AND THE FRONT PASSENGER SUSTAINED A BRUISED KNEE. THIS COLLISION RESULTED IN \$800.00 FRONTAL DAMAGE. *AK

CHEVROLET	SILVERADO	2004	2004-08-06	2001 CHEVROLET PICKUP INVOLVED IN A CRASH WITH A TREE AND AIR BAG DID NOT DEPLOY. DRIVE SUSTAINED SEVERE INJURY TO MOUTH BY HITTING STEERING WHEEL, DISPLACING FIVE LOWER FRONT TEETH CAUSING EXTENSIVE PAIN HAVING TEETH REPOSITIONED. *JB
CHEVROLET	SILVERADO	2004	2004-12-10	WHILE DRIVING 60 MPH VEHICLE HYDROPLANED, LOST CONTROL, AND CRASHED INTO A BUILDING HEAD ON . UPON IMPACT, DRIVER'S SIDE AIR BAG DID NOT DEPLOY, AND PASSENGER'S SIDE AIR BAG WAS DEACTIVATED. NO INJURIES REPORTED. *AK
				CONSUMER'S VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WITH AN OAK TREE AT 5 MPH. UPON IMPACT, NEITHER FRONTAL AIR BAG DEPLOYED. ALTHOUGH CONSUMER WAS PROPERLY RESTRAINED THE CRASH PUSHED THE ENGINE THROUGH THE FIREWALL AGAINST THE PASSENGER'S SEAT. DRIVER SUSTAINED INJURIES, AND AN AMBULANCE TRANSPORTED THE
CHEVROLET	SILVERADO	2004	2005-04-01	DRIVER TO THE LOCAL HOSPITAL. *AK
CHEVROLET	SILVERADO	2004	2005-08-23	DT: 2004 CHEVROLET SILVERADO. THE CONSUMER WAS IN AN ACCIDENT ON AUGUST 23, 2005. WHILE DRIVING 40 MPH. A DEER CAME ONTO THE ROAD, CONSUMER'S VEHICLE SWERVED TO AVOID IT, AND WENT INTO RAVINE. TOOK OUT TWO TREES. THIS DAMAGED THE FRONT END OF THE VEHICLE. UPON IMPACT, THE AIRBAGS DID NOT DEPLOY. THE VEHICLE WAS DRIVEN HOME, AND IS CURRENTLY AT THE AUTO BODY SHOP. THERE HAS BEEN NO DETERMINATION AS TO WHY THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT TAKEN. THE CONSUMER SUSTAINED INJURIES. SHE BRUISED THE CHEST, AND SHE HAD A BULGING DISC I NECK NEAR SPINAL CORD. *AK
CHEVROLET	SILVERADO	2004	2005-08-28	DT: THE CONTAC OWNS A 2004 CHEVROLET SILVERADO. THE CONTACT'S VEHICLE WAS INVOLVED IN A FRONT END COLLISION WHILE TRAVELING 65 MPH ON AUGUST 28, 2005. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THERE WERE NO WARNING LIGHTS ON INDICATING THERE WAS A PROBLEM WITH THE AIR BAG SYSTEM. THE CONTACT STATED ANOTHER VEHICLE LOST CONTROL OF AND HIT THE SIDE OF CONTACT'S VEHICLE, CAUSING IT TO HIT THE CENTER MEDIAN. THE CONSUMER CONTACTED THE DEALERSHIP AND THE MANUFACTURER. *AK
				DT: THE CONTACT STATED THE COMPANY TRUCK THAT HE DROVE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, THE AIRBAGS DID NOT DEPLOY. THE ENTIRE FRONT END OF THE VEHICLE WAS DESTROYED. THE CONTACT SUSTAINED INJURIES. HE BRUISED HIS CHEST, SHIN AND TORE THE TENDON IN HIS ANKLE. THERE HAD BEEN NO ACCIDENTS IN THIS VEHICLE PRIOR TO
CHEVROLET	SILVERADO	2004	2005-10-25	THIS. A POLICE REPORT WAS TAKEN AT THE SCENE. *AK
CHEVROLET	SILVERADO	2004	2006-01-10	ON JAN. 10 OF 2006 I LOST CONTROL OF MY 2004 CHEVY SILVERADO WHILE I WAS DRIVING ON ICY ROAD. I HIT A CONCRETE DIVIDER HEAD ON. MY CONCERN IS THAT THE AIR BAG NEVER DEPLOYED EVEN THOUGH THE DAMAGE TO THE TRUCK WAS QUITE BIG. I WAS GIVEN A ESTIMATE OF \$9820 OF DAMAGE BECAUSE THEY HAVE TO REPLACE THE BODY FRAME. EVEN WITH ALL THIS DAMAGE MY AIRBAG NEVER DEPLOYED. *NM
CHEVROLET	SILVERADO	2004	2006-03-20	WHILE DRIVING ON SLICK ROADS MY TRUCK WENT OFF THE ROAD, DOWN A HILL AND CRASHED INTO AN EMBANKMENT. THE ENTIRE FRONT END WAS SEVERELY DAMAGED. THE FRAME WAS BENT, THE BUMPER WAS WRAPPED UP UNDER THE FENDER, GRILL GUARD PUSHED INTO THE RADIATOR. UPON IMPACT NEITHER OF THE AIRBAGS DEPLOYED. MY FACE SLAMMED INTO THE STEERING WHEEL BREAKING MY NOSE. TRUCK SALVAGED. *JB
CHEVROLET	SILVERADO	2004	2006-02-19	I HAD AN ACCIDENT IN MY 2004 CHEVY TRUCK AT A SPEED OF APPROX 80 MPH HEAD ON IMPACT. THE TRUCK WAS TOTALED BUT MY AIR BAGS DIDN'T WORK. I MADE A COMPLAINT TO GMAC, THEY HAD AN INVESTIGATION AND ACCORDING TO THEM THERE WAS NOTHING WRONG WITH THE AIR BAGS. I FIND THAT HARD TO BELIEVE WITH THAT KIND OF IMPACT, THIS IS A SAFETY ISSUE AND I HAVE 2001 CHEVY SUBURBAN THAT MY WIFE DRIVES WITH MY CHILDREN. CAN YOU PLEASE LOOK INTO THIS BECAUSE I WOULD LIKE TO KNOW GMAC IS NOT TAKEN RESPONSIBILITY FOR THE AIR BAG FAILURE. THANK GOD I WAS WEARING MY SEAT BELT, BECAUSE IT WAS THE ONLY THING THAT SAVED MY LIFE. *NM
CHEVROLET	SILVERADO	2004	2004-09-04	DT*: THE CONTACT STATED WHILE STOPPED AT A STOP SIGN, THE VEHICLE WAS HIT ON THE DRIVER'S SIDE FRONT END. THE AIR BAGS DID NOT DEPLOY. SEAT BELTS WERE IN USE HOWEVER BACK AND NECK INJURIES WERE SUSTAINED. THE IMPACT WAS SO SEVERE; BOTH PASSENGER TIRES CAME OFF THE RIMS AND DUG INTO THE PAVEMENT. THE POLICE WERE ON SCENE AND A REPORT WAS FILED. THE VEHICLE WAS TOWED TO DEALER, UPON INSPECTION NO DETERMINATION COULD BE MADE WHY THE AIR BAGS DID NOT DEPLOY. THE MANUFACTURER WAS ALERTED. UPDATED 05/16/06. *JB
		2004	2006-02-08	I WAS DRIVING UP TP A STOP LIGHT WHEN THE LIGHT TURNED RED THERE WAS A CAR IN FRONT OF ME THAT HAD STOPPED, I REALIZED I DIDN'T HAVE A LOT OF ROOM BUT THOUGHT IT WOULD BE ENOUGH TO STOP. I PUT THE PEDAL TO THE FLOOR AND STILL HIT THEM TWO PEOPLE WERE INJURED. *TR THEN ON 9/8/07 AND A DEER RAN OUT IIN FRONT OF ME, AGAIN MY FOOT TO THE FLOOR I HIT THE DEER. 1ST I WAS SUPRISED THAT MY AIR BAGS DIDN'T DEPLOY (REALLY TORE UP THE FRONT OF THE TRUCK) AND 2ND I SHOULD OF BEEN ABLE TO SLOW DOWN IN TIME. AFTER READING ALL OF THE ISSUES WITH THE BRAKES ON CHEVYS AND NO ONE IS DOING ANYTHING ABOUT IT, I THINK ITS TIME TO LOOK FOR A DIFFERENT CAR COMPANY.
	CHEVROLET CHEVROLET CHEVROLET CHEVROLET CHEVROLET CHEVROLET CHEVROLET	CHEVROLET SILVERADO CHEVROLET SILVERADO	CHEVROLET SILVERADO 2004 CHEVROLET SILVERADO 2004	CHEVROLET SILVERADO 2004 2004-12-10 CHEVROLET SILVERADO 2004 2005-04-01 CHEVROLET SILVERADO 2004 2005-08-23 CHEVROLET SILVERADO 2004 2005-08-28 CHEVROLET SILVERADO 2004 2005-10-25 CHEVROLET SILVERADO 2004 2006-01-10 CHEVROLET SILVERADO 2004 2006-03-20 CHEVROLET SILVERADO 2004 2006-03-20 CHEVROLET SILVERADO 2004 2006-02-19 CHEVROLET SILVERADO 2004 2006-02-19

			I		
10238395	CHEVROLET	SILVERADO	2004	2008-01-22	TL*THE CONTACT OWNS A 2004 CHEVROLET SILVERADO. WHILE DRIVING APPROXIMATELY 58 MPH, THE CONTACT SLID ON A PATCH OF ICE AND LOST CONTROL OF THE VEHICLE. THE VEHICLE RAN OFF THE ROAD AND CRASHED INTO A TELEPHONE POLL ON THE PASSENGER SIDE. THE VEHICLE STOPPED WHEN IT CRASHED INTO A FROZEN EMBANKMENT. UPON IMPACT, THE FRONT AIR BAGS FAILED TO DEPLOY EVEN THOUGH THE CONTACT MADE IMPACT WITH THE STEERING WHEEL. THE CONTACT WAS INJURED. THE VEHICLE WAS COMPLETELY DESTROYED AND A POLICE REPORT WAS FILED. THE CONTACT FILED A COMPLAINT WITH THE MANUFACTURER, BUT THE COMPLAINT WAS DENIED. THE MANUFACTURER WAS UNABLE TO DIAGNOSE THE VEHICLE; HOWEVER, AFTER INSPECTION OF THE VEHICLE, THE MANUFACTURER CONFIRMED THAT THE AIR BAGS WERE ENABLED AT THE TIME OF IMPACT. THEY DID NOT GIVE AN EXPLANATION FOR THE DEPLOYMENT FAILURE. THE VIN WAS UNKNOWN. THE FAILURE AND CURRENT MILEAGES WERE 180,000. UPDATED 09/03/08 *BF UPDATED 09/04/08.*JB THE CONSUMER WAS INVOLVED IN AN ACCIDENT IN HIS 2004 CHEVROLET SUBURBAN IN WHICH THE AIR BAGS DID NOT DEPLOY. AN OCCUPANT IN THE VEHICLE WAS INJURED WHEN THE AIR BAGS DID NOT DEPLOY. *NM *SC*JB
10125146	CHEVROLET	SUBURBAN	2004	2005-06-10	DT: VEHICLE WAS GOING ABOUT 35-40 MPH AND THE SIDE AND FRONT AIR BAGS DID NOT DEPLOY DURING AN ACCIDENT. *AK
10200729	CHEVROLET	TAHOE	2004	2007-08-09	I WAS INVOLVED IN A HEAD ON COLLISION WITH 2 OTHER VEHICLES, AT 45 TO 50 MPH, AND MY AIR BAGS FAILED TO DEPLOY. *TR
10409000	CHEVROLET	TAHOE	2004	2011-06-16	2004 CHEVROLET TAHOE, AFTER BEING INVOLVED IN AN ACCIDENT WITH SEVERE IMPACT TO BOTH FRONT CORNERS AND BUMPER, HARD IMPACT COLLISION, AND AFTER FLIPPING THREE TIMES, BOTH FRONT AIR BAGS DID NOT DEPLOY. SEVERE DRIVER INJURY AS A RESULT OF THE AIRBAG FAILURE. *TR MY HUSBAND AND I WAS INVOLVED IN AN ACCIDENT AND THE AIR BAGS DID NOT DEPLOY WE
10836861	CHEVROLET	TAHOE	2004	2015-02-09	WERE HIT AT 55 MPH
10314549	CHEVROLET	TRACKER	2004	2010-02-04	MYSELF AND 2 DAUGHTERS WERE IN A HEAD ON WRECK 2/04/2010 WHEN A GUY PULLED OUT IN FRONT OF US, NEITHER OF THE AIRBAGS DEPLOYED. MY DAUGHTER HIT THE WINDSHIELD AND I HIT THE STEERING WHEEL AND DASH. THE PREGNANT ONE WAS THANKFULLY IN THE BACK SEAT. *TR
10567426	CHEVROLET	TRACKER	2004	2014-02-23	TL* THE CONTACT OWNS A 2004 CHEVROLET TRACKER. THE CONTACT STATED THAT WHILE DRIVING IN THE SNOW, SHE LOST CONTROL OF THE VEHICLE AND CRASHED THE FRONT OF END INTO AN EMBANKMENT. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUFFERED CONTUSIONS AND BRUISING TO THE TORSO REGION. A POLICE REPORT WAS TAKEN. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED. THE FAILURE MILEAGE WAS APPROXIMATELY 20,000. UPDATED 04/22/14*LJ THE CONSUMER STATED SHE HIT A PATCH OF ICE WHILE DRIVING, SHE VEERED OFF THE HIGHWAY LOST CONTROL OF THE VEHICLE, AND FLIPPED OVER 3 TIMES. UPDATE 04/24/14
10083860	CHEVROLET	TRAILBLAZER	2004	2004-07-16	WHILE DRIVING AT 70 MPH DRIVER SWERVED TO LEFT TO AVOID HITTING A MOTORIST. WHEN THE DRIVER ATTEMPTED TO STRAIGHTEN BACK THE STEERING WHEEL BY TURNING IT TO THE RIGHT IT OVERCORRECTED SEVERELY. THIS RESULTED IN THE DRIVER LOSING CONTROL OF THE VEHICLE AND CRASHING INTO A TREE. UPONIMPACT, AIR BAGS DID NOT DEPLOY. DRIVER DIED, AND FRONT PASSENGER SUSTAINED A BROKEN NECK, SEVERE LACERATION TO THEIR SCULL, AND BRUISES. THE PASSENGER IN THE REAR SUSTAINED A BROKEN ANGLE, A DISLOCATED HIP, AND TWO BROKEN RIBS. *AK
10087212		TRAILBLAZER	2004	2004-08-03	WHILE DRIVING 45 MPH CONSUMER'S VEHICLE COLLIDED INTO ANOTHER VEHICLE. UPON IMPACT, BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. VEHICLE WAS TOWED TO A GARAGE. *AK THE CONSUMER SUSTAINED A HAIR LINE FRACTURE IN THE CHEST AREA. *NM
10094926	CHEVROLET	TRAILBLAZER	2004	2004-10-03	AT APPROXIMATELY 45 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A COLLISION, STRIKING A BARRIER HEAD ON. UPON IMPACT, AIR BAGS DID NOT DEPLOY.*AK
10100282	CHEVROLET	TRAILBLAZER	2004	2004-10-29	I WAS GOING BETWEEN 25 AND 35 MPH I SWRIVED TO AVOID A VEHICLE BACKING UP THAT HAD MISSED A TURN. I TRIED TO STREER BACK AND LOST CONTROL HITTING A TELEPHONE POLE HEAD ON. AIRBAGS DID NOT DEPLOY NEITHER DID ONSTAR. TO THIS POINT NOTHING HAS BEEN DONE TO REPAIR THE FAILURE AS FOR MY DAD'S TRAILBLAZER THATS A WORK IN PROGRESS. *AK
					CONSUMER WAS DRIVING 60 MPH AND LOST CONTROL, HITTING A UTILITY POLE. UPON IMPACT,
10103148	CHEVROLET	TRAILBLAZER	2004	2004-11-24	I WAS DRIVING A CHEVY TRAILBLAZER RENTED FROM HERTZ ON DECEMBER 29, 2004. ON HIGHWAY 285 NEAR MILE MARKER 189.5, I ENCOUNTERED BLACK ICE ON A CURVE. THE VEHICLE STARTED A 4-WHEEL DRIFT INTO THE ONCOMING LANE. I ATTEMPTED TO AVOID COLLIDING WITH ANOTHER VEHICLE THAT HAD SPUN OUT. THE ABS DID NOT WORK. THERE WAS NO STABILITY CONTROL. I STRUCK AN EMBANKMENT AND THE VEHICLE FLIPPED OVER. ALTHOUGH THERE WAS BOTH FRONTAL AND SIDE IMPACT, NO AIRBAGS DEPLOYED. IT IS MY BELIEF THAT THE CHEVY TRAILBLAZER IS INHERENTLY UNSAFE. THERE IS NO WAY THIS VEHICLE SHOULD HAVE ROLLED OVER AT THE SPEED AT WHICH I WAS DRIVING. *NM
10123920	CHEVROLET	TRAILBLAZER	2004	2005-05-30	OTHER VEHICLE FAILED TO YIELD FROM A YIELD SIGN. FRONT OF TRAILBLAZER STRUCK RIGHT SIDE REAR OF OTHER VEHICLE. IMPACT DAMAGED CROSS BAR ON FRAME PUSHING RADIATOR INTO MOTOR. DRIVER AND PASSENGER AIR BAG FAILED TO DEPLOY. ESTIMATED IMPACT SPEED 45-50

10135169	CHEVROLET	TRAILBLAZER	2004	2005-01-19	MY DAUGHTER WAS DRIVING MY 2004 TRAILBLAZER ON AN ICY, SLIPPERY ROAD AT 25 -30 MILES PER HOUR, (THE SPEED LIMIT IS 30, IT WAS THE STREET WE LIVE ON) WHEN SHE LOST CONTROL, HIT A TREE AND TOTALED (\$22,000.00) THE VEHICLE. THE OFFICER AND I WALKED THE PATH IN THE STREET AND COULD NOT FIND ANY SIGNS OF SKIDDING OR BRAKING, THERE FORE LEADING ME TO BELIEVE NOW THAT THERE WAS A BRAKING FAILURE. UP UNTIL NOW, WHEN I HEARD ABOUT THE BRAKES FAILING DO TO CORROSION FROM ROAD SALT, I ALWAYS THOUGHT IT WAS JUST AN ACCIDENT IN POOR ROAD CONDITIONS. WHEN I FIRST READ THE REPORT OF THE INVESTIGATION I COULDN'T BELIVE IT WAS THE SAME SCENARIO AS HER ACCIDENT. POOR ROAD CONDITIONS, THEREFORE POSSIBLE SALT BUILDUP, A SLOW SPEED AND INABILITY TO STOP. I AM SO GRATEFULL THAT SHE WALKED AWAY WITHOUT A SCRATCH, ALSO CONSIDERING THE AIR BAGS DID NOT DEPLOY, EVEN THOUGH THE FRONT END WAS TOTALED. I AM SURE THIS IS A PROBLEM THAT MUST BE IDENTIFIED FOR THOSE LIVING IN COLDER, NORTHERN STATES.
10154051	CHEVROLET	TRAILBLAZER	2004	2005-10-23	FOIA REQUEST ALL DOCUMENTS/INFO RELATIVE TO ANY RECALLS OR KNOWN DEFECTS OF THE AIR BAG SYSTEM IN THE 2004 CHEVROLET TRAILBLAZER. *TS ATTORNEY'S CLIENTS WERE SERIOUSLY INJURED WHEN THE VEHICLE THEY WERE OPERATING WAS INVOLVED IN A HIGH SPEED, FRONT END COLLISION. THE AIR BAG SYSTEM DID NOT DEPLOY AT THE TIME OF IMPACT AND AS A RESULT THE THREE OCCUPANTS WERE INJURED. *NM ***NAR***
10158090	CHEVROLET	TRAILBLAZER	2004	2006-02-26	DT*: THE CONTACT STATED WHILE DRIVING 50 MPH THE VEHICLE WAS INVOLVED IN A HEAD ON COLLISION WITH ANOTHER VEHICLE. THE VEHICLE CONTINUED MOVING AND STOPPED BY COLLIDING WITH A STORE SIGN. THE AIR BAGS DID NOT DEPLOY AND SEAT BELTS WERE WORN. THERE WERE NO WARNING LIGHTS TO INDICATE THE AIR BAGS WOULD FAIL. THE CONTACT SUFFERED A KNEE INJURY. A POLICE REPORT WAS FILED AT THE SCENE. THE INSURANCE COMPANY DETERMINED THE VEHICLE WAS TOTALED DUE TO THE ACCIDENT. THE DEALER DOES NOT HAVE THE MEANS TO TEST FOR AIR BAG NON-DEPLOYMENT. UPDATED 1/24/2007 - *NM TL* - THE CONTACT OWNS A 2005 CHEVROLET TRAIL BLAZER. DURING A SNOW STORM THE
10177618	CHEVROLET	TRAILBLAZER	2004	2006-12-01	CONTACT'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION. THE CONTACT WAS DRIVING ON THE HIGHWAY AT 55 MPH, AND THE AIR BAGS DID NOT DEPLOY. THERE WERE NO WARNING INDICATOR LIGHTS. THE MANUFACTURER SENT AN INVESTIGATOR TO ACCESS THE DAMAGE, AND STATED THAT THERE WAS \$10,000 WORTH OF DAMAGE, AND THAT THE VEHICLE WAS ONLY TRAVELING 8 MPH. *AK
10178863	CHEVROLET	TRAILBLAZER	2004	2007-01-13	TL* - THE CONTACT STATED THAT ON 1/13/07 HE CRASHED INTO ANOTHER VEHICLE WITH HIS 2004 CHEVROLET TRAILBLAZER. THE ODOMETER READ 33,000 MILES AT THE TIME OF THE CRASH. HE WAS DRIVING AT 45 MPH AND COLLIDED WITH THE SECOND VEHICLE IN A PERPENDICULAR ANGLE "T-BONE" STRIKING IT ON THE SIDE AS IT CROSSED IN FRONT OF HIM. THE DRIVER WAS THE ONLY OCCUPANT IN THE VEHICLE AND THE DRIVER'S SIDE AIRBAG NEVER DEPLOYED. THERE WERE 5 PEOPLE INJURED IN THE SECOND VEHICLE. *NM
10218896	CHEVROLET	TRAILBLAZER	2004	2008-02-22	TL*THE CONTACT OWNS A 2004 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 35 MPH, THE CONTACT REAR ENDED A SCHOOL BUS. THE VEHICLE WAS COMPLETELY DESTROYED AND NONE OF THE AIR BAGS DEPLOYED. TWO PASSENGERS WERE INJURED AND A POLICE REPORT WAS FILED. PRIOR TO THE FAILURE, SHE NEVER EXPERIENCED ANY AIR BAG FAILURE. THE DEALER AND MANUFACTURER HAVE NOT BEEN NOTIFIED. THE CONTACT HAS PICTURES. THE VIN AND ENGINE SIZE WERE UNKNOWN. THE CURRENT AND FAILURE MILEAGES WERE 44,000.
10228023	CHEVROLET	TRAILBLAZER	2004	2006-11-06	I WAS SIDE SWIPED BY ANOTHER CAR THAT WENT THROUGH A RED LIGHT. MY TRUCK THEN PROCEEDED TO HIT ANOTHER CAR AND FINALLY THE FRONT END OF THE TRUCK GOT AIRBORNE AND LANDED WITH THE TIRES IN THE FRONT WINDSHIELD OF ANOTHER CAR. THE TRUCK SUSTAINED OVER \$6,000 IN DAMAGE AS WELL AS THE FRONT FRAME WHERE THE MOTOR SITS WAS DAMAGED. INSURANCE COMPANY SAID IT COULD BE REPLACED. NOT SURE HOW BECAUSE IT WAS WELDED IN PLACE. AND MY AIRBAGS NEVER DEPLOYED. *TR
					I WAS REAR ENDED BY A GUY DOING 40 MPH. MY TRUCK WAS LIFTED IN THE AIR AND PUSHED INTO THE REAR END OF ANOTHER VEHICLE. MY AIRBAGS NEVER DEPLOYED AND MY SEAT BROKE!!
10228026	CHEVROLET	TRAILBLAZER		2007-03-07	POSSIBLE DEFECT IN THE SEAT? I WAS STOPPED AT A RED LIGHT WHEN THE ACCIDENT HAPPENED. THE SPARE TIRE HOLDER WAS RIPPED OFF MY TRUCK. *TR SLIGHTLY TURNED STEERING WHEEL TO LEFT TO AVOID ANOTHER MOTORIST IN FRONT OF ME. ATTEMPTED TO STRAIGHTEN OUT THE VEHICLE, VEHICLE OVER-CORRECTED SEVERELY, UNABLE TO BRAKE, VEHICLE SLAMMED HEAD-ON INTO CONCRETE HIGHWAY BARRIER 45-60MPH, AIR BAGS FAILED TO DEPLOY. DRIVER WAS WEARING SEATBELT, SUBSTANTIAL BRUISING & NECK/BACK INJURY. *TR
10313103		TRAILBLAZER		2009-10-02	TI*THE CONTACT OWNS A 2004 CHEVROLET TRAILBLAZER. WHILE THE CONTACT WAS DRIVING 35 MPH HE CRASHED INTO ANOTHER VEHICLE AND THEN INTO A LIGHT POLE WHICH DESTROYED THE VEHICLE; HOWEVER, DURING THE CRASH NONE OF THE AIR BAGS DEPLOYED. THE DRIVER AND PASSENGER WERE INJURED. NO ONE WAS INJURED IN THE OTHER VEHICLE. THE VEHICLE WAS DIAGNOSED BY THE DEALERSHIP WHO STATED THAT NO FAILURES COULD BE FOUND. THERE WERE NO PRIOR WARNINGS. THE CURRENT AND FAILURE MILEAGES WERE 95,272 UPDATED 03/30/10. *LJ ACCORDING TO GM, THE NOTICE ON THE DASH READOUT STATED THE AIR BAGS DEPLOYED. UPDATED 06/30/10.*JB

40007766					TL* THE CONTACT OWNS A 2004 CHEVROLET TRAILBLAZER. WHILE DRIVING 35 MPH, THE CONTACT ATTEMPTED TO MANEUVER THE STEERING WHEEL TO AVOID CRASHING INTO A DEER AND LOST CONTROL OF THE VEHICLE. THE VEHICLE CRASHED INTO A TREE. THE AIR BAGS DID NOT DEPLOY UPON IMPACT. THE CONTACTS FACE HIT THE STEERING WHEEL UPON IMPACT AND SUSTAINED A BROKEN NOSE. THE CONTACT WAS TAKEN TO THE HOSPITAL. THE VEHICLE WAS DESTROYED AND WAS TOWED BY HER INSURANCE COMPANY TO AN UNKNOWN LOCATION. A POLICE REPORT WAS AVAILABLE, IF NEEDED. THE MANUFACTURER WAS NOT CONTACTED. THE
10327766	CHEVROLET	TRAILBLAZER	2004	2010-04-21	FAILURE MILEAGE WAS 80,700.
10356973	CHEVROLET	TRAILBLAZER	2004	2010-09-19	TL* THE CONTACT OWNED A 2004 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT THE AIRBAGS DID NOT DEPLOY WHEN HIS WIFE CRASHED INTO A DEER AT APPROXIMATELY 35 MPH. THE DRIVER WAS ALSO INVOLVED IN ANOTHER CRASH WHEN TRAVELING APPROXIMATELY 55 MPH. SHE LOOKED DOWN TO CHECK ON A NOISE SHE HEARD AND WHEN SHE LOOKED UP THE THE VEHICLE LOST CONTROL AND CRASHED HEAD ON INTO A TREE. THE DRIVER AND THREE OTHER OCCUPANTS WERE INURED. THE GEORGIA HIGHWAY PATROL RESPONDED AND FILED A REPORT. THE PARAMEDICS ALSO RESPONDED AND TRANSPORTED THE FOUR OCCUPANTS TO THE HOSPITAL. THE VEHICLE WAS DESTROYED AND TOWED TO A STORAGE LOT. THE FAILURE MILEAGE WAS APPROXIMATELY 107,000.
					I HIT A DEER AT APPROXIMATELY 65 MPH AND THE AIR BAG DID NOT DEPLOY. MY SON THAT WAS
10419650	CHEVROLET	TRAILBLAZER	2004	2011-08-13	RIDING IN THE PASSENGER SEAT ALSO WAS WEARING HIS SEAT BELT BUT THE SEAT BELT DID NOT CATCH AND HE WAS SLAMMED INTO THE DASH. I REFUSE TO BELIEVE THAT THIS IS NORMAL BEHAVIOR FOR THOSE SAFETY DEVICES. *KB
10551484	CHEVROLET	TRAILBLAZER	2004	2013-10-29	TL* THE CONTACT OWNS A 2004 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING 35 MPH, THE DRIVER BECAME DISTRACTED AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE SEAT BELT FAILED TO RESTRAIN, CAUSING THE DRIVER TO BE THROWN FORWARD. THE DRIVER'S HEAD IMPACTED THE WINDSHIELD AND AS A RESULT, HE SUSTAINED BLEEDING FROM THE BRAIN. A POLICE REPORT WAS FILED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE FAILURE AND CURRENT MILEAGE WAS UNKNOWN. THE VIN WAS NOT AVAILABLE.
10576838	CHEVROLET	TRAILBLAZER	2004	2008-06-16	ON THE AFTERNOON OF 6/16/08, ME IN MY FAMILY WAS TRAVELING NORTH ON 195 IN NORTH CAROLINA GOING TOWARD OUR DESTINATION IN BALTIMORE MD., WHEN ANOTHER VEHICLE CLICK US AND CAUSE MY SISTER TO LOSE CONTROL OF THE VEHICLE CRASHING INTO THE GUARDRAIL. MY TWO AUNTS AND MYSELF WERE EJECTED FROM THE VEHICLE, BOTH MY AUNTS DIE INSTANTLY. MY MOTHER, SISTERS AND MYSELF SURVIVED BUT HAD SEVERAL INJURIES. THE AIRBAGS DID NOT DEPLOY, AND THE DOORS THAT WERE INITIALLY LOCKED; BUT SOMEHOW THE REAR DOORS (MIDDLE) OPEN DURING IMPACT CAUSING MY AUNTS IN MYSELF TO BE THROWN FROM THE VEHICLE. BE ADVISED THE VEHICLE WAS A GREEN TRAILBLAZER (EXTENDED CAB). *TR
10626582	CHEVROLET	TRAILBLAZER	2004	2014-08-18	I WAS ON A 4 LANE HIGHWAY TRAVELING EASTBOUND GOING 50 MPH POSTED SPEED 55 MPH WEARING OUR SEAT BELTS, WHEN ANOTHER VEHICLE WAITING TO U - TURN IN THE CENTER MEDIAN DECIDED TO TURN RIGHT INTO ME-ONCOMING TRAFFIC. THIS PERSON COLLIDED WITH ME, WHICH THAT IMPACT SENT ME INTO A HEAD ON COLLISION WITH THE GUARD RAIL. THE CHEVROLET TRAILBLAZER IS COMPLETELY TOTALED. THERE WERE 2 INCIDENTS IN THAT SEQUENCE OF EVENTS THAT THE AIRBAGS SHOULD HAVE DEPLOYED, BUT DID NOT! THIS ACCIDENT CAUSED SEVERAL INJURIES TO MYSELF AND MY PASSENGER. WE DEFINITELY COULD HAVE BEEN KILLED AND NO AIRBAGS TO HELP SAVE OUR LIVESUPDATED 09-03-14 *BF UPDATED 11/7/2014 *JS *TR
					ON SATURDAY, AUGUST 1, 2015 AT APPROXIMATELY 8:55PM MY MOTHER WAS INVOLVED IN A 1 CAR ACCIDENT ON BAUM RD LOCATED IN TALLAHASSEE, FL. SHE WAS THE ONLY PASSENGER DETERMINED TO BE IN THE VEHICLE AT THE TIME OF THE ACCIDENT. ACCORDING TO THE CRASH REPORT, D1 (DRIVER ONE) WAS TRAVELING WESTBOUND ON BAUM RD GOING THE NORMAL POSTED SPEED OF 55MPH, WHEN SHE VEERED TOWARDS THE CENTER OF THE RD AND SUDDENLY TURNED RIGHT VEERING OF THE RIGHT SHOULDER OF THE RD AND STRIKING SEVERAL TREES ON THE DRIVERS SIDE AND FRONT END. D1 WAS WEARING HER SEATBELT AND MANAGED TO EXIT OUT THE DRIVERS SIDE WINDOW BEFORE COMING TO HER FINAL RESTING PLACE ON THE SHOULDER OF THE RD. WHEN I WENT TO RETRIEVE MY MOTHERS THINGS FROM HER TRAILBLAZER, I NOTICED THAT NO AIR BAGS HAD DEPLOYED. AND AS FAST AS MY MOM WAS GOING AND THE TYPE OF IMPACT & DAMAGE HER SUV SUSTAINED, I WOULD THINK AND HOPE THE AIRBAGS WOULD DEPLOY IN THIS TYPE OF ACCIDENT, THUS PREVENTING SERIOUS INJURY OR DEATH. MY MOM WAS NOT SO LUCKY, AND MYSELF AND MY FAMILY HAVE ENDURED GREAT PAIN FROM LOOSING HER SO
10767586	CHEVROLET	TRAILBLAZER	2004	2015-08-01	SUDDENLY. I WAS RECENTLY IN A CAR ACCIDENT DUE TO BAD WEATHER AND ROAD CONDITIONS. LEAVING WORK DRIVING INTERSTATE 189 9STATE NORTHBOUND. CAME UPON BLACK ICE MY CAR FISHTAILED OUT OF CONTROL; TRYING TO GAIN CONTROL BACK BEFORE I KNEW IT I WAS HEADING
					TORDS A GUARD RAIL. I WAS ONLY DRIVING 50 TO 55MPH. BEYOND THE GUARD RAIL I DO NOT REMEMBER. I SUFFERED UPPERBODY AND HEAD INJURY AND MY FRONT AIR BAG FAILED TO
10022507	CHEVROLET	TRAILBLAZER	2004	2016-01-19	DEPLOY. OTHERS ARE TELLING ME AND MY HUSBAND TO LOOK INTO THIS AS MY AIRBAG FAILED TO DEPLOY. CAN YOU HELP
10823597 11265285	CHEVROLET	TRAILBLAZER	2004	2016-01-19	WELL I HIT A TREE AN THE AIRBAGS DIDNT DEPLOYED BUT THE AIRBAG LIGHT IS ON

	1			1	T 1
10128270	GMC	ENVOY	2004	2005-07-08	DT: CONSUMER STATES THAT SHE WAS IN A HEAD ON COLLISION ON JULY 8, 2005 AND THE AIR BAGS DID NOT DEPLOY. SHE WAS GOING 55 MPH WHEN HIT. THERE WAS DAMAGE TO THE VEHICLE AND A POLICE REPORT WAS TAKEN. CONSUMER STATES SHE HAS NECK AND BACK INJURIES, SHE IS GOING TO THE DOCTOR FOR A FOLLOW UP VISIT TODAY. HER DAUGHTER HAS SEAT BELT BURNS ON HER NECK. THE VEHICLE IS CURRENTLY BEING INSPECTED BY THE INSURANCE COMPANY; IT HAD TO BE TOWED TO A BODY SHOP. SHE HAS NOT CONTACTED THE DEALERSHIP OR MANUFACTURER, THE ATTORNEY GENERAL ADVISED HER TO CALL US FIRST. *NM
10152802	GMC	ENVOY	2004	2006-03-13	AVOIDING TO HIT AN UPCOMING VEHICLE IN A CURVE, I LOST CONTROL OF MY GMC ENVOY SUV 2004 AND HIT A CONCRETE DRIVEWAY AND STOPPED WITH AN ELECTRICAL UTILITY POST FRONT SIDE. THE AIRBAGS DID NOT DEPLOY CAUSING MYSELF TO HIT THE STEERING WHEEL AND INJURED MY NECK, MY HEAD, LOWER BACK, KNEES AND LEFT ARM. THE INSURANCE COMPANY TOLD ME THAT IF THE AIR BAGS WOULD DEPLOYED THEY WOULD DECLARED MY VEHICLE TOTAL LOSS DUE TO THE EXTENSIVE DAMAGE. I TOLD THEM I DON'T WANT MY VEHICLE REPAIRED IF THE AIR BAGS ARE NOT CHANGED. I INTEND TO GO AGAINST GMC LEGALLY. *JB
10182098	GMC	ENVOY	2004	2007-01-03	IN ROUTE TO WORK DRIVING MY 2004 GMC ENVOY I WAS INVOLVED IN WHAT I WOULD CONSIDERED A HEAD ON COLLISION WITH A TELEPHONE POLE. THE IMPACT WAS GREAT ENOUGH TO SPILT THE POLE IN TWO, TOP HALF JUST MISSING THE ROOF OF THE VEHICLE. UPON IMPACT THE AIRBAGS DID NOT DEPLOY NOR DID MY SEAT BELTS LOCK ME IN CAUSING ME TO FLY FORWARD HITTING MY HEAD ON THE STEERING WHEEL, I HAD TO BE EXTRACTED FROM VEHICLE BY FIRE DEPARTMENT AND TRANSPORTED TO ER. I NOW HAVE PERMANENT SCAR APPROXIMATELY 5 INCHES IN LENGTH ACROSS MY FOREHEAD. I FILED A COMPLAINT WITH GMC LATER TO BE INFORMED THAT AFTER THEIR INVESTIGATION THEY CONCLUDED THAT SINCE THE PASSENGER SIDE TOOK THE GREATER OF THE IMPACT THE IMPACT WAS NOT GREAT ENOUGH TO WARRANT AIRBAG DEPLOYMENT. PLEASE NOTE THAT DRIVERS NOR PASSENGER SIDE AIRBAG DEPLOYED. *JB
					TL*THE CONTACT OWNS A 2004 GMC ENVOY. WHILE DRIVING APPROXIMATELY 55 MPH, THE VEHICLE STRUCK A GATE, WENT AIRBORNE, DROPPED APPROXIMATELY 35 FEET DOWN AN EMBANKMENT, STRUCK SOME TREES, BOULDERS, AND LANDED IN A SWAMP. THE AIR BAGS FAILED TO DEPLOY AND THE VEHICLE SUSTAINED MAJOR DAMAGE. BOTH THE DRIVER AND PASSENGER SUSTAINED MULTIPLE INJURIES. THE VEHICLE HAD TO BE LIFTED FROM THE EMBANKMENT WITH A CRANE AND WAS TOWED AWAY. A POLICE REPORT WAS FILED. THE
10237647	GMC	ENVOY	2004	2008-08-10	CURRENT AND FAILURE MILEAGES WERE 51,000. I WAS TRAVELING NORTHBOUND ON RT 251 FROM PERU TO MENDOTA IL WHEN IT BEGAN
10266307	GMC	ENVOY	2004	2009-04-20	RAINING AND HAILING VERY HARD. 251 IS FULL OF POT HOLES. I WAS TRAVELING ABOUT 40 M.P.H. I HIT A POT HOLE AND MY CAR STARTED TO HYDROPLAN. I WENT INTO THE SOUTHBOUND LANE AND THEN INTO DITCH HEAD ONI HIT THE DITCHES WALL ALMOST HEAD ON AND MY AIRBAGS DID NOT COME OUT. *TR
10272370	GMC	ENVOY	2004	2009-05-02	TL*THE CONTACT OWNS A 2004 GMC ENVOY. WHILE DRIVING 60 MPH WITH THE CRUISE CONTROL ACTIVATED, THE CONTACT PASSED OUT DUE TO A SEVERE MEDICAL ISSUE. HE LOST CONTROL OF THE VEHICLE AND CRASHED INTO A TREE. UPON IMPACT, BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. THE CONTACT AND PASSENGER WERE SEVERELY INJURED. THE DRIVER SUSTAINED A BROKEN CLAVICLE AND HIS TEETH WERE KNOCKED OUT OF HIS MOUTH. THE PASSENGER SUSTAINED A LACERATION TO THE HEAD AND ABDOMINAL INJURIES. THE VEHICLE WAS INSPECTED BY AN INSURANCE ADJUSTER, WHO WAS UNABLE TO DETERMINE WHY THE AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS DESTROYED. THE CONTACT CALLED THE MANUFACTURER AND WAS INFORMED THAT AN INVESTIGATION WAS IMPLEMENTED AND A REPRESENTATIVE WILL CALL HIM BACK IN FIVE BUSINESS DAYS. THE FAILURE MILEAGE WAS 42,600. UPDATED 6/5/09 *CN UPDATED 06/09/09.*JB
					TL*THE CONTACT OWNS A 2004 GMC ENVOY. WHILE DRIVING 35 MPH, THE CONTACT REAR ENDED ANOTHER VEHICLE. HIS VEHICLE WAS DESTROYED. THE AIR BAGS FAILED TO DEPLOY AND THE SEAT BELTS DID NOT RETRACT FOR BOTH OCCUPANTS SEATED IN THE FRONT. THE CONTACT AND THE PASSENGER STRUCK THE STEERING WHEEL WITH THEIR CHESTS AND SHOULDERS. BOTH WERE SEVERELY INJURED. THE CONTACT, PASSENGER, AND OTHER DRIVER WERE TRANSPORTED
10275464	GMC	ENVOY	2004	2009-06-29	TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A REPAIR SHOP AND IS AWAITING AN INVESTIGATION. A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS 60,000.
10286793	GMC	ENVOY	2004	2009-10-07	WHILE TRAVELING DOWN I-95 AT APPX. 60MPH THE CAR IN FRONT OF ME STOPPED SHORT. I SLAMMED INTO THE BACK OF IT. MY AIRBAGS DID NOT DEPLOY, NOR DID ONSTAR CALL TO CHECK ON ME (SO MUCH FOR BELIEVING IN THOSE ADS!) THE ENTIRE FRONT END NEEDS TO BE REPLACED. FLUIDS WERE SPILLING FROM THE VEHICLE. 2 WITNESSES ARE CAPITOL HILL POLICE OFFICERS WHO WERE SHOCKED THAT THE AIRBAGS DID NOT DEPLOY. THE SEATBELT DID RESTRAIN ME CAUSING IRRITATION AT THAT SITE. MY BACK, NECK AND HEAD WERE ACHING. I WAS CHECKED OUT BY THE ER. *TR
10302345	GMC	ENVOY	2004	2010-01-26	TL*THE CONTACT OWNS A 2004 GMC ENVOY. WHILE DRIVING 65 MPH IN SNOWY CONDITIONS, HE ATTEMPTED TO PASS A VEHICLE AND WHILE RETURNING BACK INTO THE LANE THE VEHICLE SLID AND HE CRASHED INTO A CONCRETE BARRIER FRONT-END FIRST. THE FRONTAL AIR BAGS DID NOT DEPLOY AT THE TIME OF THE CRASH. THE CONTACT DID NOT SUFFER ANY INJURIES. THE POLICE ARRIVED SHORTLY AFTER AND A POLICE REPORT WAS FILED. THE FAILURE AND CURRENT MILEAGES WERE UNDER 97,000.
					·

10504270	CNC	ENIVOV	2004	2014 02 12	CAR SLID INTO RIGHT GUARDRAIL AND THEN SLID TO LEFT IN DITCH ON EXPRESSWAY. THE AIRBAGS DID NOT DEPLOY. IMPACT WAS SIGNIFICANT ENOUGH TO BEND THE FRONT PASSENGER CORNER OF FRAME. THE FRAME IS ALSO CRACKED UNDERNEATH THE MIDDLE OF VEHICLE AS RESULT OF
10594270	GMC	ENVOY	2004	2014-03-12	CRASH. CAR IS NO LONGER DRIVEABLE. DRIVER SUFFERED WHIPLASH. *TR I HAD AN ACCIDENT ON A MAJOR HIGHWAY DUE TO WEATHER CONDITIONS. I ENDED UP SPINNING
10596479	GMC	ENVOY	2004	2014-03-31	THE VEHICLE AROUND WHILE IN THE TRAVEL LANE AND HIT THE CAR IN THE PASSING LANE. MY AIRBAGS NEVER DEPLOYED. ALTHOUGH NO ONE WAS INJURED THANKFULLY. I WONDERED WHY THE AIRBAGS DIDN'T GO OFF. SHOULD I BE WORRIED? HAS ANYONE MADE THIS SAME COMPLAINT? THANK YOU. *TR
10631914	GMC	ENVOY	2004	2009-08-25	MY WIFE WAS IN THE CAR ALONE. VEHICLE RAN OFF ROAD, CRASHED INTO PARKED TRUCK, AIR BAG DID NOT DEPLOY. WIFE DIED OF "CLOSED CHEST TRAUMA", *TR
					TL-THE CONTACT OWNS A 2004 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT 50 MPH HE HAD THE SWERVE TO AVOID A HEADON COLLISION FROM A VEHICLE THAT WAS IN HIS LANE. THE VEHICLE WENT OFF THE ROAD AND CRASHED INTO A CONCRETE BARRIER. THE CONTACT HAD A FRACTURED STERNUM AND A BRUISED RIGHT ANKLE, KNEE AND ELBOW. THE CONTACT VISITED THE EMERGENCY ROOM ON HIS OWN WITHOUT BEING TRANSPORTED BY AN AMBULANCE. THE CONTACT STATED THAT NONE OF THE AIR BAGS IN THE FRONT DEPLOYED. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOTALED BY THE INSURANCE COMPANY AND TOWED FROM THE CRASH SITE. THE ENTIRE FRONT OF THE VEHICLE WAS SMASHED IN INCLUDING THE FRAME. THE BACK AXEL DROPPED AFTER THE COLLISION AND BOTH RIMS ON THE BACK TIRES WERE SHATTERED. THE FRONT RIMS WERE ALSO CRACKED. THE DEALER AND MANUFACTURER
11378518	GMC	ENVOY	2004	2020-12-03	HAD NOT BEEN CONTACTED YET. THE FAILURE MILEAGE WAS 180,000. TF
10067417	GMC	YUKON	2004	2004-04-16	WHILE DRIVING CONSUMER APPLIED THE BRAKES AND WITHOUT WARNING CONSUMER'S VEHICLE COLLIDED WITH THE VEHICLE IN FRONT. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DRIVER SUSTAINED MINOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL FOR EXAMINATION. VEHICLE WAS TOWED TO THE DEALER FOR INSPECTION, AND DEALER WAS UNABLE TO DUPLICATE OR RESOLVE THE PROBLEM. *AK
					TL* THE CONTACT OWNS A 2004 GMC YUKON. THE CONTACT WAS DRIVING APPROXIMATELY 40 MPH WHEN THE VEHICLE WAS INVOLVED IN A HEAD ON CRASH IN WHICH THE AIR BAGS DID NOT DEPLOY. THE POLICE APPEARED ON THE SCENE AND A REPORT WAS AVAILABLE. THE DRIVER AS WELL AS THE FRONT PASSENGER WAS INJURED AND TRANSPORTED VIA AMBULANCE TO THE HOSPITAL TO TREAT INJURIES. THE VEHICLE WAS TOWED TO AN INSURANCE COMPANY LOT BUT DID NOT HAVE THE FAILURE DIAGNOSED. THE VEHICLE WAS NOT REPAIRED. THE FAILURE AND
10372063	GMC	YUKON	2004	2010-11-12	CURRENT MILEAGE WAS 134,000.
					WHILE TRAVELING AT 40 MPH, CONSUMER STATES ANOTHER VEHICLE TRAVELING IN FRONT CAME TO A SUDDEN STOP. CONSUMER REAR ENDED THAT VEHICLE, AND NONE OF CONSUMER AIRBAGS
8023949	CHEVROLET	BLAZER	2003	2002-11-19	DEPLOYED. PLEASE PROVIDE ANY FURTHER INFORMATION. PH
					TWO EMPLOYEES WERE INVOLVED IN A CRASH WHERE THEY WERE THE ONES THAT STRUCK A STOPPED CAR AT 50 MPH. THE AIR BAGS DID NOT DEPLOYIS THIS A PROBLEM. IS THIS A POSSIBLE RECALL SITUATION. WHO DO I CONTACT ABOUT THIS A CHEVROLET??? DOES YOUR AGENCY GET
10023373	CHEVROLET		2003	2003-06-11	INVOLVED. *NLM CONSUMER STATED WHILE TRAVELING 45 MPH OR OVER ON WET PAVEMENT VEHICLE LOST CONTROL, AND TRAVELED OFF THE ROAD. REAR HATCH GLASS EXPLODED, BUT AIR BAGS DID NOT
10040503	CHEVROLET	BLAZEK	2003		DEPLOY AT ANY TIME. *AK WHILE TRYING TO AVOID HITTING A PEDESTRIAN VEHICLE WENT OF THE ROAD AND HIT A TREE.
10044264	CHEVROLET	BLAZER	2003	2003-08-30	UPON IMPACT, FRONT AIR BAGS DID NOT DEPLOY. VEHICLE COULD NO LONGER BE DRIVEN DUE TO THE EXTENSIVE DAMAGE DONE TO THE FRONT END. *AK
10160753	CHEVROLET	BLAZER	2003	2006-06-19	DT*: THE CONTACT STATED THAT BOTH FRONT AIRBAGS OF THE VEHICLE DID NOT DEPLOY DURING A CRASH WHICH OCCURRED WHILE TRAVELING 45 MPH. THE VEHICLE WAS HEADED EAST ON A NARROW, ROUGH, BUMPY ROAD WHEN IT APPROACHED AN INTERSECTION AND STRUCK ANOTHER VEHICLE HEADING NORTH. THE OTHER VEHICLE BRIEFLY STOPPED AT THE STOP SIGN AND PULLED OUT INTO THE INTERSECTION 15 FEET BEFORE THE CONTACT'S VEHICLE REACHED THE INTERSECTION. THIS RESULTED IN THE CONTACT'S VEHICLE CRASHING INTO THE FRONT DRIVER SIDE DOOR OF THE OTHER VEHICLE. BOTH OCCUPANTS WERE WEARING THEIR SEAT BELTS. THE AIRBAG WARNING LIGHT WAS NOT ON PRIOR TO THE CRASH. THE POLICE TOOK PICTURES AND A REPORT WAS FILED. THE VEHICLE WAS TAKEN TO THE DEALER FOR INSPECTION.

			1		
10537593	CHEVROLET	BLAZER	2003	2013-08-13	I WAS TRAVELING SOUTHBOUND WHEN I EXPERIENCED A SEIZURE AND LOST CONTROL OF MY VEHICLE. I PROCEEDED TO VEER TO THE LEFT WHERE I CLIPPED SEVERAL CARS THAT WERE HEADED NORTHBOUND AND HAD STOPPED DUE TO THE REALIZATION THAT MY VEHICLE WAS NOT UNDER CONTROL. I THEN PROCEEDED OVER A TREE LAWN AND INTO A PARKING LOT. I HIT A DODGE RAM PICKUP WITH THE RIGHT FRONT CORNER OF MY VEHICLE AND PUSHED THAT VEHICLE INTO ANOTHER PARKED CAR THAT WAS NEXT TO IT. BOTH VEHICLES ENDED UP SIDEWAYS AND MY VEHICLE ENDED UP SPUN AROUND 180 DEGREES. AT THIS TIME MY VEHICLE CAME TO A STOP. POLICE WERE CALLED AN PARAMEDICS ARRIVED. THE JAWS OF LIFE WERE USED TO EXTRACT ME FROM MY VEHICLE. I WAS TAKEN TO A LOCAL HOSPITAL WHERE IT WAS DETERMINED THAT I SUFFERED BURST FRACTURES OF L1, L2, AND L3. I ALSO SUFFERED AN EVULSION FRACTURE OF MY LEFT ANKLE. THE POLICE REPORT STATES THAT I WAS TRAVELLING AT A HIGH RATE OF SPEED AND THAT THE VEHICLES WHICH WERE NORTHBOUND WERE JUST CLIPPED. THE AIRBAGS ARE BOTH STILL WITHIN THEIR CASES AS NEITHER DEPLOYED. I WOULD EXPECT THIS OF THE PASSENGER AIRBAG AS THAT SEAT WAS UNOCCUPIED BUT THE DRIVER BAG SHOULD HAVE DEPLOYED. THE INSURANCE INVESTIGATOR EVEN EXPRESSED TO MY WIFE THAT HE WAS SURPRISED THAT THE AIR BAG DID NOT DEPLOY. I WAS HAVING A SEIZURE AND WAS NOT CONSCIOUS SO I CANNOT PROVIDE ANY INFORMATION OTHER THAN WHAT IS IN THE POLICE REPORT. THE REPORT IS #370763 ISSUED BY THE TOWNSHIP OF CLINTON, MICHIGAN. THE VEHICLE IS CURRENTLY LOCATED AT COPARD AUTO SALVAGE, 21000 HAYDEN, WOODHAVEN, MI 48183. THE PHONE NUMBER IS 734-365-0070. IT WILL BE HELD THERE FOR BETWEEN 7 AND 10 DAYS FROM 8/26/2013. THANK YOU *TR
10337333	CHEVILOLET	DE VEEN	2003	2013 00 13	REAR ENDED A STOPPED PICK UP AT 45 MPH AND AIR BAGS DID NOT DEPLOY. IT WAS ON A HIGHWAY WHERE THE SPEED LIMIT IS 55. THE WHOLE FRONT END WAS DAMAGED BUT MOST WAS
11075512	CHEVROLET	BLAZER	2003	2016-02-16	ON DRIVER SIDE.
8017964	CHEVROLET	SILVERADO	2003		THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT HIGHWAY SPEED. UPON IMPACT THE PASSENGER SIDE AIR BAG DID NOT DEPLOYED. MANUFACTURER HAS BEEN CONTACTED. PLEASE PROVIDE FURTHER INFORMATION.*JB
10030725	CHEVROLET	SILVERADO	2003	2003-07-31	2003 CHEVROLET SILVERADO EXT. CAB 4X4 WITH ONSTAR, WRECKED. HIT TREES. TRUCK TOTALLED, FRONT-END DAMAGE, SIDE AND REAR END DAMAGE. AIR BAG DID NOT INFLATE. ONSTAR DID NOT WORK. *AK
10032581	CHEVROLET	SILVERADO	2003	2003-08-01	AIR BAGS FAILED TO OPEN ON HEAD END COLLISION. SPEED APPROX. 40 MPH. 2003 CHEVY SILVERADO - NEW CONDITION
10050872	CHEVROLET	SILVERADO	2003	2003-10-18	INVOLVED IN A 45 MPH COLLISION WITH ANOTHER VEHICLE. AIRBAGS IN MY 2003 CHEVROLET SILVERADO DID NOT DEPLOY.*AK
10055994	CHEVROLET	SILVERADO	2003	2004-01-24	WHILE DRIVING 25 MPH THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION. UPON IMPACT, THE FRONT AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED NECK AND BACK INJURIES. *AK *SC
10056087	CHEVROLET	SILVERADO	2003	2004-01-24	WHILE DRIVING AT 65 MPH ON THE HIGHWAY, THE DRIVER LOST CONTROL OF THE VEHICLE, RESULTING IN A FRONTAL COLLISION. THE VEHICLE WENT INTO AN EMBANKMENT. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED INJURIES. *AK BROKEN STERNUM, SPINE AND RIBS. THE CONSUMER WAS WEARING HIS SEAT BELT. THE SDM CRASH DOWN LOAD FROM THE CRASH WAS SENT TO ODI WITH PICTURES OF THE VEHICLE. CW *MR *JB
10066690	CHEVROLET	SILVERADO	2003		WHIEL DRIVING AT 40 MPH VEHICLE WAS HIT HEAD ON AND THE AIR BAGS FAILED TO DEPLOY.*MR

					AIR BAGS NOT DEPLOYING ON A NEW CHEVY SILVERADO PICK-UP/ FOLLOWING A VEHICLE CRASH. DRIVER WAS INJURED, AND SCARRED. WAS HOSPITLIZED AND STILL HAVING PROBLEMS AND WILL HAVE A LIFETIME SCAR ON FACE AREA. ALSO LEGS AND THIGHS ARE SCARRED. OUR SON WAS TRAVELING AT A HIGH RATE OF SPEED PASSING, LOST CONTROL WENT OFF HIGHWAY HEAD ON INTO DEEP DITCH, FLIPPED OVER, WENT SIDE TO SIDE COMING TO REST SIDEWAYS ON TIRES THAT WERE NOW FLAT AND STILL NO AIRBAG DEPLOYMENT. SENT A COMPLAINT AND PICTURES, POLICE REPORT AND MEDICAL RECORDS TO GM, NO SATISFACTION FROM THERE. WHAT DOES A VEHICLE HAVE TO HAVE DONE TO HAVE AN AIRBAG DEPLOY???? VEHICLE WAS TOTALED. SON IS PERMANTLY SCARRED, AND PARENTS HAVE LOST FAITH IN CHEVY TRUCKS, AND AIRBAGS. HIS OLDER BROTHER CO-SIGNED SO HE WOULD HAVE A "NEW, SAFER" VEHICLE AND AM NOW SO VERY UPSET WITH GM AS TO AN EXPLANATION AS TO WHY THESE AIR BAGS DID NOT DEPLOY TO PROTECT OUR SON. THIS VEHICLE (HE WAS SPEEDING PASSING) WENT OFF THE ROAD HEAD ON INTO A DEEP DITCH, OVERTURNED SEVERAL TIMES, HIT SIDE TO SIDE IN DITCH, FLATTENED TIRES AND CAME TO REST ON SHOULDER OF ROAD. NOW HOW MUCH MORE DOES IT TAKE TO DEPLOY AN AIR BAG????? I THINK IF WE WERE WEALTHY AND COULD AFFORD A LAWYER THEY MAYBE WOULD OF LISTENED AND CHECKED THIS MORE, BUT AS WE ARE JUST "COMMON" HARD WORKING US CITIZENS, WE DON'T REALLY COUNT. ALSO OUR SON WAS DRINKING AT THE TIME OF THE INCIDENT, (SHOULD NOT MATTER TO SAFETY OF VEHICLE EQUIPMENT) I WAS TOLD IT WAS NOT "CATASTROPIC ENOUGH" OF AN ACCIDENT TO WARRENT ANY DAMAGES. ?? THEN THEY TRIED TO SAY THE "ACCIDENT" (MEANING VEHICLE) WASN'T. I THINK WE ALL KNOW WHAT THEY MEANT. WE WERE NOT LOOKING FOR "MILLIONS" (STRETCHING IT), JUST HIS MEDICAL BILLS AND THE PROBLEM CORRECTED IN OTHER CHEVY'S SO THIS WOULD NOT HAPPEN TO SOMEONE ELSE. AS USUAL THE HONEST PEOPLE, AND HARD WORKING MIDDLE CLASS CAN GET NO HELP. PRAYERS GO OUT TO ANYONE ELSE THIS HAS HAPPENED TO AND THAT IT WON'T HAPPEN TO SOMEONE ELSE'S
10072429	CHEVROLET	SILVERADO	2003	2003-05-25	CHILD.
10000011	CUEVADOLET	CILVEDADO	2002	2004 00 44	WHILE DRIVING 55 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION. UPON IMPACT, DUAL AIR BAGS DID NOT DEPLOY. DRIVER SUSTAINED HEAD INJURIES DUE TO HIS HEAD HITTING THE STEERING WHEEL.*AK THE CHEVROLET TESTERS CAME TO INSPECT THE VEHICLE. THEY CONCLUDED THAT THE IMPACT WAS NOT HARD ENOUGH NOR WAS THE VEHICLE GOING
10089611	CHEVROLET	SILVERADO	2003	2004-08-14	FAST ENOUGH FOR THE AIR BAG TO DEPLOY. *NM AIR BAGS DID NOT INFLATE WITH A FRONT END CRASH THAT PUSHED THE MOTOR IN THE DASH.
10137033	CHEVROLET	SILVERADO	2003	2005-08-14	SON RECEIVED HEAD INJURIES WOULD LIKE TO KNOW WHAT YOU ARE GOING TO DO ABOUT THIS. PICKUP WAS A TOTAL LOSS. FRAME WAS BENT. OUR ATTORNEY WOULD LIKE TO PUSH THIS BUT I WOULD LIKE TO KNOW WHAT YOU WILL DO FOR US FIRST. I HAVE PICTURES IF YOU WOULD LIKE TO SEE THEM. *JB
10154224	CHEVROLET	SILVERADO	2003	2006-03-23	DIRECT FRONTAL IMPACT WITH SIDE OF CAR THAT RAN RED LIGHT. AIR BAG DID NOT DEPLOY. SPEED WAS APPROXIMATELY 40-50 MPH. *JB
					I HIT A DEER HEAD ON AND TOTALED MY SILVERADO. I HIT IT AT 55 MPH AND NEITHER OF THE
10577089	CHEVROLET	SILVERADO	2003	2013-11-14	AIRBAGS DEPLOYED. *TR TRUCK COLIDED WITH GUARD RAIL. BOUNCED OFF, HIT VEHICLE 1, THEN INTO VEHICLE 2 THEN STOPPED AFTER HITTING VEHICLE 3 A SEMI TRUCK. ALL DAMAGE WAS DONE TO FRONT OF THE CHEVY SILVERADO. AT NO TIME DID THE AIRBAGS DEPLOY. SILVERADO WAS DETERMINED TO BE TOTALED DUE TO THE EXCESSIVE DAMAGE ON THE FRONT. AIRBAGS SHOULD HAVE DEPLOYED DURING ONE OF THE IMPACTS. *JS
10082050	CHEVROLET	SUBURBAN	2003	2004-07-14	THE CONSUMER WAS INVOLVED IN AN ACCIDENT WHERE IT WAS HIT FROM THE FRONT DRIVER SIDE, THE IMPACT CAUSED THE VEHICLE TO HIT A TELEPHONE POLE HEAD ON. THE AIR BAGS DID NOT DEPLOY. *JB
11360703		SUBURBAN	2003	2020-08-07	TL* THE CONTACT OWNED A 2003 CHEVROLET SUBURBAN. THE CONTACT STATED THAT WHILE TOWING HIS DAUGHTERS VEHICLE AT ABOUT 60 MPH, ANOTHER VEHICLE CRASHED INTO THE VEHICLE BEING TOWED. THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED A HEAD AND LOWER BACK INJURY. THE FRONT PASSENGER (HIS DAUGHTER) SUSTAINED A BACK INJURY. THE TWO WENT TO THE DOCTOR THREE DAYS LATER. THERE WAS NO POLICE REPORT. THE VEHICLE BEING TOWED WAS DAMAGED AND WAS DRIVEN TO THE DAUGHTERS DORM WHERE IT WAS TOTALED BY THE INSURANCE COMPANY. THE DEALER AND THE MANUFACTURER WERE NOT CONTACTED. THE CONTACT STATED THAT THE OTHER DRIVERS INSURANCE DENIED ANY COMPENSATION TO THE CONTACT, STATING THAT THE CONTACTS VEHICLE (THE VEHICLE TOWING THE DAMAGED VEHICLE) WAS NOT HIT. THE CONTACT STATED THAT AFTER THE ACCIDENT, A LOUD NOISE WAS HEARD WHENEVER THE VEHICLE WAS TURNED ON. THE CONTACT ALSO STATED THAT THE DASHBOARD WAS CRACKED. THE VEHICLE WAS NOT REPAIRED. THE FAILURE MILEAGE WAS APPROXIMATELY 173,000.
					TL* THE CONTACT OWNED A 2003 CHEVROLET TAHOE. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 45 MPH, THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO A GUARD RAIL. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE FRONT SEAT PASSENGER SUSTAINED 12 BROKEN RIBS AND 2 COLLAPSED LUNGS THAT REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS TOWED TO AN INDEPENDENT TOWING FACILITY. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE
10899484	CHEVROLET	TAHOE	2003	2016-04-14	WAS UNKNOWN. THE VIN WAS UNAVAILABLE.

					I RENTED A CHEVROLET TRACKER 2003 AND WAS HIT HEAD ON BY ANOTHER DRIVER AND
10008283	CHEVROLET	TRACKER	2003	2003-02-28	EVERYONE THERE NOTICE THAT THE AIRBAG DID NOT OPEN. THIS WAS A HEAD ON ACCIDENT. I WILL BE FILING THIS TO A LAWYER SHORT AS I WAS HURT. *JB
					I WAS DRIVING ON I-190 IN THE RIGHT HAND LANE ON DEC 19, 2003. A CAR COMING UP AN
					ENTRANCE RAMP MERGED INTO MY LINE ALMOST HITTING ME. I SWERVED TO AVOID THE CRASH
					BUT SUBSEQUENTLY HIT SOME BLACK ICE AND WAS UNABLE TO RECOVER CONTROL. I HIT THE
					CONCRETE BARRIER HEAD ON. THE INSURANCE COMPANY'S (PROGRESSIVE) CLAIMS AGENT FIGURES I WAS GOING ABOUT 50 MPH AT IMPACT. THE IMPACT SO EXTREME THAT MY TRACKER
					SHIFTED ITSELF INTO 4WD AND TURNED ON THE HIGHBEAMS. BASICALLY ANYTHING THAT COULD
					GO FORWARD DID. THE WHOLE FRONT OF THE VEHICLE WAS PUSHED BACK 6" AND MY LISCENCE
					PLATE WAS RIPPED OFF, BUT YET MY AIRBAGS NEVER DEPLOYED. IF IT WEREN'T FOR MY SEATBELT, I MAY NOT BE HERE TO TYPE THIS. I HAD SEVERE WHIPLASH, AS WELL AS, PUTTING MY LEFT KNEE
					THROUGH MY DASH BOARD. THE IMPACT OF THE CRASH SHOULD HAVE HIT AT LEAST ONE, IF NOT
					ALL, SENSORS. I FEEL THIS IS A MAJOR PROBLEM. I WILL BE FILING A FORMAL COMPLAINT WITH
10052731	CHEVROLET	TRACKER	2003	2003-12-19	CHEVY REGARDING THIS ISSUE.*AK WHILE DRIVING 37 MPH THE VEHICLE WAS INVOLVED IN A HEAD ON COLLISION. THE AIR BAGS DID
					NOT DEPLOY UPON IMPACT. THE PASSENGER SUSTAINED SEVERE WHIPLASH. PLEASE PROVIDE
10097100	CHEVROLET	TRACKER	2003	2004-03-20	ADDITIONAL INFORMATION. *JB
					I WAS DRIVING HOME FROM WORK WHEN MY CAR SWERVED TO THE RIGHT AND WENT OF THE
					ROAD AND HIT A GROVE OF TREES HEAD ON. MY CAR WAS TOTALED AND NONE OF MY AIRBAGS WENT OFF. WHY DOES THIS HAPPEN I COULD HAVE BEEN KILLED. ALSO I RECEIVED A SAFETY
					NOTICE ABOUT MY CHEVEROLET TRACKER 4 DAYS BEFORE THIS HAPPENED HAVING A PROBLEM
					WITH THE FRONT SUSPENSION CROSSMEMBER DOE SOMEONE HAVE TO DIE BEFORE A RECALL IS
					DONE AND WHY DIDN'T MY AIR BAGS GO OFF SOMEONE PLEASE LOOK AT THIS CAR BEFORE IT GETS HAULED OFF BY THE ADJUSTER!!!!! I WAS AIRLIFTED TO THE HOSPITAL THE FIRE DEPARTMENT
10216640	CHEVROLET	TRACKER	2003	2008-01-27	CUT THE ROOF OF MY CAR OFF TO GET ME OUT NO AIRBAGS WHAT HAPPENED!!! *TR
					CONSUMER STATES THAT WHILE DRIVING APPROXIMATELY 35-40MPH SLID OFF ROAD AND
8023281	CHEVROLET	TRAILBLAZER	2003	2002-11-19	CRASHED INTO A DITCH HEAD-ON. BOTH DRIVER AND PASSENGER AIR BAGS DID NOT DEPLOY. TS
10040870	CHEVROLET	TRAILBLAZER	2003	2003-09-25	TRAVELING 55 MPH WHEN ANOTHER VEHICLE CROSSED THE ROAD CAUSING ME TO HIT THE SIDE OF HIS VEHICLE HEAD ON. NO AIR BAGS DEPLOYED.
10040870	CHEVROLET	TRAILBLAZER	2003	2003-03-23	LOSING CONTROL OF MY VEHICLE ON ICY PAVEMENT, VEHICLE SLID OFF OF THE ROAD, HEAD-ON
					INTO A TREE. DRIVERS SIDE AND PASSENGER SIDE AIR BAGS FAILED TO DEPLOY. SERIOUS INJURIES
					OCCURED , WHICH MAY HAVE BEEN LESSENED IF THE SAFETY FEATURES WE PAY FOR ACTUALLY WORK.*AK ER DOCTORS AND STATE POLICE WERE TERRIBLY ANNOYED , SINCE THERE HAVE BEEN
					SEVERAL REPORTS OF SAME FAILURE IN DESIGN. NO RESPONSE FROM DEALER OR
10054479	CHEVROLET	TRAILBLAZER	2003	2004-01-16	MANUFACTURER, AS OF YET !!!*AK
10055534	CHEVROLET	TRAILBLAZER	2003	2004-01-11	AFTER HITTING A TREE HEAD ON AIR BAGS DID NOT DEPLOY. *AK
					WHILE DRIVING AT 40 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A FRONTAL COLLISION.
10065438	CHEVROLET	TRAILBLAZER	2003	2004-03-24	CONSUMER WAS WEARING SEAT BELTS, BUT NONE OF THE AIR BAGS DEPLOYED. CONSUMER SUSTAINED A BROKEN NOSE, SCRAPES, AND BRUISES TO CHEST AND WRIST. *AK
10005100	0.12.11.022.1	TO HEDE LEEK	2000	200 : 00 2 :	CHEVROLET TRAILBLAZER 2003 UPON IMPACT AIRBAG DID NOT DEPLOY. *BF THE CONSUMER
10113264	CHEVROLET	TRAILBLAZER	2003	2004-08-01	REAR ENDED ANOTHER VEHICLE. *JB
					2003 CHEVY TRAILBLAZER AIR BAGS NEVER CAME OUT AFTER HAVING IMPACT INTO TWO TREES
10174616	CHEVBOLET	TRAILBLAZER	2003	2006-11-22	FORCING THE DRIVER INTO THE STEERING WHEEL. NOTHING AT THIS TIME HAS BEEN CORRECTED TO REPAIR THE SUV. GM NEED TO BE ALERTED OF THIS FAILURE TO CORRECT THE PROBLEM! *NM
10174616	CHEVROLET	TRAILBLAZER	2003	2006-11-22	TO REPAIR THE 30V. GWINEED TO BE ALERTED OF THIS PAILORE TO CORRECT THE PROBLEM: NW
					TL*THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 40 MPH, THE CONTACT
					SWERVED TO AVOID AN ANIMAL AND CRASHED INTO A TREE. THE FRONT AIR BAGS FAILED TO DEPLOY. THE VEHICLE IS CURRENTLY AT A TOW YARD AND WILL BE TOWED TO THE INSURANCE
					COMPANY FOR INVESTIGATION. THE MANUFACTURER FILED A REPORT AND THE CONTACT IS
10208796	CHEVROLET	TRAILBLAZER	2003	2007-11-10	AWAITING A CALL BACK. THE CURRENT AND FAILURE MILEAGES WERE 60,000.
					TL*THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 32 MPH, THE CONTACT
					CRASHED INTO A BUILDING. THE VEHICLE WAS DESTROYED. THE AIR BAGS FAILED TO DEPLOY.
					THE CONTACT SUSTAINED INJURIES TO HER MOUTH AND EYE. THE AMBULANCE ARRIVED ON THE SCENE AND TRANSPORTED THE CONTACT TO THE HOSPITAL. A POLICE REPORT WAS FILED.
					CHEVROLET HAS NOT BEEN NOTIFIED. THE VIN, ENGINE SIZE, AND NUMBER OF CYLINDERS WERE
10219898	CHEVROLET	TRAILBLAZER	2003	2008-02-08	UNKNOWN. THE CURRENT AND FAILURE MILEAGES WERE 71,000. TL*THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 45 MPH, THE CONTACT
					REAR ENDED ANOTHER VEHICLE. THE FRONT AIR BAGS FAILED TO DEPLOY. THERE WERE NO
10222722	CUEVROLET	TDAILDI AZED	2002	2009 02 12	INJURIES AND A POLICE REPORT WAS FILED. THE VIN AND ENGINE SIZE WERE UNKNOWN. THE
10223723	CHEVROLET	TRAILBLAZER	2003	2008-03-13	FAILURE AND CURRENT MILEAGES WERE 77,000. THE AIRBAG DID NOT DEPLOY IN A FRONT-END COLLISION THAT WILL MOST LIKELY TOTAL THE
10229337	CHEVROLET	TRAILBLAZER	2003	2008-05-28	VEHICLE. THE OTHER VEHICLE'S DID DEPLOY. *TR
10308388	CHEVROLET	TRAILBLAZER	2003	2009-12-26	HAD CAR ACCIDENT WAS HIT BY ANOTHER VEHICLE AND HIT A RETAINING WALL GOING ABOUT 45 MILES AN HOUR AND AIR BAG DID NOT DEPLOY 2003 TRAIL BLAZER. *TR
_000000	O. L. VINOLLI		_505		The state of the s

	1	T	ı		
					TL*THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 45-50 MPH IN INCLEMENT WEATHER, THE CONTACT CRASHED INTO A RETAINER WALL. SHE STATED THAT OTHER PASSING VEHICLES PUSHED HER VEHICLE INTO THE RETAINER WALL. THE AIR BAG DID NOT DEPLOY. SHE WAS ALSO INJURED WHEN THE CRASH OCCURRED. THE MANUFACTURER STATED THAT THEY WOULD TAKE PICTURES OF THE VEHICLE. THE VEHICLE HAS NOT BEEN REPAIRED. A POLICE REPORT WAS FILED. THE FAILURE AND THE CURRENT MILEAGES WERE 82,000. THE CONSUMER STATED IT
10313800	CHEVROLET	TRAILBLAZER	2003	2009-12-26	WAS A HIT AND RUN ACCIDENT. UPDATED 04/07/10.*JB
10315428	CHEVROLET	TRAILBLAZER	2003	2008-06-03	2003 CHEVROLET TRAILBLAZER. S10 COMEBACK FWD LTR TO POTUS RE COMPLAINT AGAINST GM REGARDING DEFECTIVE AIRBAG, INVOLVE IN CAR ACCIDENT AND THE AIRBAG DID NOT DEPLOY. *TGW THE CONSUMER STATED ANOTHER VEHICLE HIT A DEER, CROSSED THE CENTER LANE AND HIT THEIR VEHICLE HEAD ON. THE CONSUMER STATED THE SEAT BELTS DID NOT RESTRAIN THEM. *JB UPDATED PHONE NUMBER 05/28/10. *JB
10392644	CHEVROLET	TRAILBLAZER	2003	2011-01-23	TL*THE CONTACT OWNS A 2003 CHEVROLET BLAZER. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 45 TO 50 MPH IN THE RAIN HE CRASHED HEAD ON INTO ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. THERE WERE NO AIR BAG WARNING INDICATIONS PRIOR TO THE CRASH. THE DRIVER SUSTAINED A CONCUSSION AND INJURIES TO HIS NECK, KNEE, AND FEET. A POLICE REPORT WAS FILED. THE DRIVER WAS TRANSPORTED TO THE HOSPITAL BY AMBULANCE. THE MANUFACTURER WAS CONTACTED AND OFFERED NO ASSISTANCE. THE FAILURE COULD NOT BE DIAGNOSED SINCE THE INSURANCE COMPANY DEEMED THE VEHICLE AS BEING DESTROYED. THE FAILURE AND CURRENT MILEAGE WAS APPROXIMATELY 130,000. THE VIN WAS UNAVAILABLE. UPDATED 5/2/11 *CN UPDATED 1/11/11 *CN
					MY WIFE AND I WERE INVOLVED IN A HEAD ON COLLISION (HIT BY A DRUNK DRIVER) OUR AIR BAGS DID NOT DEPLOY, I SUSTAINED A C7 FRACTURE, SCALPED BY THE REAR VIEW MIRROR (22 STITCHES TO HOLD MY SCALP) 6 STITCHES ON MY NOSE AND BRUISED KNEES. MY WIFE HAS A BROKEN NOSE
10425103	CHEVROLET	TRAILBLAZER	2003	2011-09-03	ALL THE BONES IN HER RIGHT FOOT BROKEN AND BRUISED KNEES. *TR TL* THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT HE CRASHED INTO A LIGHT POLE WHILE DRIVING AT UNKNOWN SPEEDS AND THE AIR BAGS DID NOT DEPLOY. THE CONTACT SUSTAINED INJURIES BUT WAS NOT TRANSPORTED TO THE HOSPITAL. THE POLICE WAS NOTIFIED OF THE CRASHED AND A REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT NOTIFIED. THE VIN WAS NOT AVAILABLE. THE FAILURE MILEAGE
10468222	CHEVROLET	TRAILBLAZER	2003	2010-05-07	WAS 170,000.
10523466	CHEVROLET	TRAILBLAZER	2003	2013-07-04	WHILE TRAVELING IN SLOW TRAFFIC, THE CAR IN FRONT OF MY WIFE STOPPED. BY THE TIME SHE NOTICED THEY STOPPED IT WAS TOO LATE AND SHE HIT THE BACK OF THEIR FORD EXPLORER MOVING AT AROUND 20-30MPH. THE FRONT END OF OUR TRAILBLAZER WAS CRUSHED. MY DAUGHTER AND WIFE WERE WEARING THEIR SEAT BELTS. THE OFFICERS AND PARAMEDICS ON THE SCENE WERE SHOCKED THAT THE AIRBAGS DID NOT COME OUT WITH THE AMOUNT OF FRONT END DAMAGE. THEY HAD TO CUT THE BATTERY WIRES TO PREVENT THE AIRBAG FROM COMING OUT LATER WHEN SHE CLEANED OUT THE TRAILBLAZER. AN EXAMPLE OF HOW MUCH DAMAGE WAS TAKEN TO THE FRONT END, THE CORNER FENDERS WERE PUSHED BACK SO FAR THEY COULDN'T OPEN WITHER FRONT DOOR. THE FENDERS WERE CRUSHED INTO THE DOORS KEEPING THEM SHUT. I WOULD THINK WITH AN IMPACT LIKE THAT THE AIRBAGS WOULD HAVE CAME OUT, IT WAS A SQUARE HIT MEANING EVEN DAMAGE ACROSS THE FRONT END. *TR
10551243	CHEVROLET	TRAILBLAZER	2003	2013-09-26	DRIVING APPROXIMATELY 40 TO 43 MPH WHEN ANOTHER VEHICLE TURNED DIRECTLY IN FRONT OF ME. TOTAL FRONTAL DAMAGE BUCKLING UP HOOD ON MY CAR AS I HIT OTHER VEHICLE IN FRONTEND PASSENGER SIDE. THEIR AIRBAG DEPLOYED BUT MINE DIDN'T, EVEN WITH TOTAL FRONTEND DAMAGE TO MY CAR. HAD SEATBELT ON, BUT DUE TO IMPACT STILL PULLED MY WHOLE BODY FORWARD (LIKE CRASH TEST DUMMY). THIS WAS A VERY HARD CRASH TOTALING MY CAR. *TR
10568108	CHEVROLET	TRAILBLAZER	2003	2008-02-14	TL* THE CONTACT OWNS A 2003 CHEVROLET TRAIL BLAZER. THE WAS DRIVING 40 MPH, AND CRASHED INTO THE SIDE OF ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE RIGHT SHOULDER, SPINAL STENOSIS AND FRACTURED KNEES. A POLICE REPORT WAS FILED OF THE INCIDENT. THE CONTACT STATED THAT SHE HAD ALSO BEEN INVOLVED IN TWO PRIOR CRASHES IN WHICH THE AIR BAGS FAILED TO DEPLOY. THE PREVIOUS CRASHES DID NOT RESULT IN ANY INJURIES AND A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS INSPECTED BY A REPRESENTATIVE SENT BY THE MANUFACTURER BUT THEY WERE UNABLE TO DETERMINE THE CAUSE OF THE AIR BAG FAILURE. THE FAILURE MILEAGE WAS 80,000. *TR
10596289	CHEVROLET	TRAILBLAZER	2003	2007-11-11	TL* THE CONTACT OWNS A 2003 CHEVROLET TRAIL BLAZER. THE CONTACT STATED THAT WHILE DRIVING AN UNKNOWN SPEED, THE CONTACT ABRUPTLY APPLIED THE BRAKES TO AVOID A CRASH. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO A CEMENT BARRIER. THE VEHICLE THEN ROLLED OVER AND LANDED IN AN EMBANKMENT. THE DRIVER'S SIDE AIR BAG FAILED TO DEPLOY. THE CONTACT SUFFERED INJURIES TO THE NECK AND A BROKEN LEG. THE CONTACT ALSO STATED THAT THE IGNITION SWITCH WAS REPLACED TWICE PRIOR TO THE CRASH. THE VIN WAS NOT AVAILABLE. THE VEHICLE WAS DESTROYED. THE CAUSE OF THE FAILURE WAS UNKNOWN. THE FAILURE AND CURRENT MILEAGE WAS 70,000.
10606954	CHEVROLET	TRAILBLAZER	2003	2006-08-08	AIRBAGS DID NOT DEPLOY DURING ACCIDENT. VEHICLE WENT THROUGH A GUARD RAIL, SUSTAINED FRONT END DAMAGE. *TR
			_505	1.2.2.00.00	

10654364	CHEVROLET	TRAILBLAZER	2003	2002-10-26	2003 CHEVROLET TRAILBLAZER. CONSUMER STATED HER HUSBAND WAS INVOLVED IN AN ACCIDENT, AND THE AIR BAGS DID NOT DEPLOY. CONSEQUENTLY, HE DIED FROM HIS INJURIES. *SS UPDATED 02/09/15. *JB
10660781		TRAILBLAZER	2003	2014-11-23	TL* THE CONTACT OWNED A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 70 MPH, A DEER JUMPED IN FRONT OF THE VEHICLE CAUSING THE CONTACT TO CRASH. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED A NECK AND BACK INJURY THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 170,000.
10681428	CHEVROLET	TRAILBLAZER	2003	2015-01-24	TL* THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 35 MPH, THE VEHICLE SLID ON ICE AND CRASHED INTO A CEMENT WALL. THE AIR BAGS DID NOT DEPLOY AND THE SEAT BELT DID NOT RESTRAIN THE CONTACT. THE CONTACT SUSTAINED CHEST, NECK, AND KNEE INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DRIVEN TO THE CONTACT'S RESIDENCE. THE VEHICLE WAS THEN TAKEN TO AN INDEPENDENT MECHANIC, BUT WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 70,000.
10694201	CHEVROLET	TRAILBLAZER	2003	2013-05-06	TL* THE CONTACT OWNED A 2003 CHEVROLET TRAILBLAZER. THE CONTACT STATED THAT WHILE DRIVING AT 50 MPH DURING INCLEMENT WEATHER CONDITIONS, THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO AN EMBANKMENT. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED SPINE INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 90,000. UPDATED 5/11/15*CN
10721783	CHEVROLET	TRAILBLAZER	2003	2015-05-12	TL* THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER EQUIPPED WITH BF GOODRICH RUGGED TRAIL T/A TIRES, SIZE: P245/65RI7. WHILE DRIVING AT 65 MPH, THE CONTACT HEARD A VIBRATION COMING FROM THE TIRES. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED INTO A POLE. THE VEHICLE ROLLED OVER MULTIPLE TIMES AND THE AIR BAGS FAILED TO DEPLOY. IN ADDITION, THE CONTACT NOTICED THAT THE THREADS FROM THE REAR DRIVER SIDE TIRE HAD SEPARATED. THE CONTACT SUSTAINED HEAD, SHOULDER, ELBOW, AND HIP INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VEHICLE AND TIRE MANUFACTURERS WERE NOT NOTIFIED OF THE FAILURE. THE VEHICLE FAILURE MILEAGE WAS 116,000 AND THE TIRE FAILURE MILEAGE WAS 40,000. THE DOT NUMBER WAS UNAVAILABLE.
10787837	CHEVROLET	TRAILBLAZER	2003	2015-10-29	TL* THE CONTACT OWNED A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 20 MPH UPHILL, A VEHICLE TRAVELING DOWNHILL CRASHED HEAD ON INTO THE CONTACT'S VEHICLE. THE FRONTAL AIR BAGS DID NOT DEPLOY. THE PASSENGER SUSTAINED WHIPLASH AND BRUISES TO THE ELBOW, CHEST, AND STOMACH THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE PASSENGER WAS ALSO INJURED AND TAKEN TO THE HOSPITAL, BUT WAS RELEASED THE SAME DAY. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE VIN WAS INVALID. THE APPROXIMATE FAILURE MILEAGE WAS 141,000.
10850437	CHEVROLET	TRAILBLAZER		2016-02-03	TL* THE CONTACT OWNED A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 50 MPH, THE VEHICLE SLID ON BLACK ICE AND CRASHED INTO A DITCH. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED A CUT TO THE HEAD AND A SEVERE BACK INJURY THAT REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED AND TOWED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 186,000.
10863408	CHEVROLET	TRAILBLAZER	2003	2016-05-03	TL* THE CONTACT OWNS A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 25 TO 35 MPH, AN ANIMAL APPEARED IN THE ROAD. THE CONTACT SWERVED AND CRASHED INTO A TELEPHONE POLE. THE AIR BAGS DEPLOYED. THE VEHICLE WAS TOWED TO THE CONTACT'S RESIDENCE. THE MANUFACTURER WAS NOT AWARE OF THE FAILURE. A POLICE REPORT WAS NOT FILED. THE CONTACT SUSTAINED HEAD, NECK, AND CHEST INJURIES THAT REQUIRED MEDICAL ATTENTION. THE FAILURE MILEAGE WAS 135,000UPDATED 06/15/16 *BF *CN
10927873	CHEVROLET	TRAILBLAZER	2003	2016-11-22	TL* THE CONTACT OWNED A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 78 MPH, A TIRE BLEW OUT. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THE VEHICLE WAS DESTROYED AND TOWED. THE AIR BAGS FAILED TO DEPLOY. THE DRIVER SUSTAINED AN INJURED LEFT SHOULDER AND NECK, AND A HEAD ABRASION, WHICH REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 115,000.
10934115		TRAILBLAZER	2003	2016-11-29	TL* THE CONTACT OWNED A 2003 CHEVROLET TRAILBLAZER. WHILE DRIVING 40 MPH IN WET WEATHER, THE VEHICLE HYDROPLANED, DROVE OFF A CLIFF, AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED CHEST, KNEE AND ARM INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS TOWED TO A TOWING AGENCY WHERE IT WAS DEEMED DESTROYED. THE FAILURE MILEAGE WAS 160,000. UPDATED 03/01/17*LJ *JS

TITE THE CONTRACT DWISS A 2003 CHEVROLET TRAILBLAZER, WHILE DRIVING 35 MPHI, THE VEHICLE WAS NOTOURS ON THE CONTROL TO WAS PLAND THE WAS NOT COLUSION. THE CONTROL TO WAS PLAND THE CONTROL TO THE LET LESS AND LET FRAME, WHICH END MISS AND THE CONTROL THE WAS NOT DHE LET FRAME, WHICH END MISS AND THE CONTROL THE CONTRO						
19959991						THAT CAUSED THE ACCIDENT WAS GOING FASTER THAN I WAS GOING. MY AIRBAGS DID NOT
WAS INVOLVED IN A HEAD ON COLUSION. THE CONTACT S VENICLE WAS STRUCK FROM THE FRONT END BY AND AND INVOLVED IN A HEAD ON COLUSION. THE CONTACT SUSTAINED INJURIES TO THE LEFT LEG AND LEFT ARM, WHICH REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS ROBED FROM A POLICE REPORT OF THE VEHICLE WAS NOTHER. THE AND LEFT ARM, WHICH REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS STORDED. THAN AS NOT DETERMINED WHITE ARM OF THE FAILURE. THE FAILURE MASS DESTROYED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MISS DESTROYED. THE WAS IN AN ACCIDENT WITH OUR NEW 2003 GMC ENVOY SLT, PURCHASED IN NOVEMBER OF 2003. TO AVOID ON A HILL AND MINH THE TREE THE REGIST FROM TO PRESENCES SIDE OF THE VEHICLE, SHE HIT THE TREE WITH SIDE FROM CONTACT HE PROVIDED BY THIS WIND CONTACT HE PROVIDED BY THE WAS IN AN ACCIDENT WITH OUR NEW 2003 GMC ENVOY SLT, PURCHASED IN NOVEMBER OF 2003. 2004-01-05. 10055821	10969901	CHEVROLET	TRAILBLAZER	2003	2017-03-25	ACCOUNTABLE FOR THEIR NEGLIGENCE? WE WERE ON A TWO LANE CITY STREET.
CONTACT SUSTAINED INJURIES TO THE LEFT LEG AND LEFT ARM, WHICH REQUIRED MEDICAL ATTENION. THE VEHICLE WAS 100-100. May DESTROVED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MAS DESTROVED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MAS DESTROVED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MAS DESTROVED. THE WAS IN AN ACCIDENT WITH OUR NEW 2003 GMC ENVOY S.T., PURCHASED IN NOVEMBER OF 2002. TO AVOID REAR REDORD THE THE FAILURE THE FAILURE OF THE ROAD, DOWN AN HILL AND AND HIT A TREE IT HIS RIGHT FRONT OF THE ROAD, ON THE ROAD, DOWN AN HILL AND AND HIT A TREE IT HIS RIGHT FRONT OF THE ROAD, ON THE ROAD, DOWN AN HILL AND AND HIT A THE REH HIS RIGHT FRONT OF THE VEHICLE RESULTED IN A TOTAL LOSS. WHICH CONTENTS IS THE ARBS AN EVEN ENVEROR SERVED THE RENOVED THE VEHICLE RESULTED IN A TOTAL LOSS. WHICH RIGHT FRONT OF THE PRONT OF THE ROAD, DOWN AND HILL AND HIS TO THE OWN OF THE FORT OF THE PRONT OF THE VEHICLE RESULTED IN A TOTAL LOSS. WHICH RIGHT FRONT OF THE PRONT OF THE VEHICLE RESULTED IN THE VEHICLE RESULTED						, , , , , , , , , , , , , , , , , , , ,
ATTENTION. THE VEHICLE WAS TOWED, IT WAS NOT DETERMINED WHETHER OR NOT THE VEHICLE WAS DESTROYED. THE MANUBACTURER WAS NOT MADE AWARE OF THE FALLURE. THE FAILURE DESTROYED. THE MANUBACTURER WAS NOT MADE AWARE OF THE FALLURE THE FAILURE WAS DESTROYED. THE WAS NOT AN ACCIDENT WITH OUR NEW 2003 GMC ENVOY SIT, PURCHASED IN NOVEMBER OF 2003. TO AVOID REAR POINT THE CRUTH FROM THE PARK OF PERSON. THE FAILURE THE FAILURE OF THE F						
WAS DESTROYED THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MARKED MA						·
MY WIFE WAS IN AN ACCIDENT WITH OUR NEW 2003 GMC ENVOY SLT, PURCHASED IN NOVEMBER OF 2003. TO AVOID REAR RADING THE CAR IN ROOT OF HER, SHE SWERVED THE RWYO OF OF THE ROOD, DOWN AN HILL AND AND HIT AT THE ARE IN THE ROOT FOR THE ROYOU OF OF THE ROOT OF THE WHILLCE. SHE HIT THE TERE WITH SUCH FORCE THAT THE DAMAGE TO THE FROM TO THE VINICE RESULTED IN A TOTAL LOSS MY CONCERN IS THE ARE RAGE SNEWED REPORTED FOR THE VINICE RESULTED IN A TOTAL LOSS MY CONCERN IS THE ARE RAGE SNEWED REPORTED FOR THE VINICE RESULTED IN A TOTAL LOSS MY CONCERN IS THE ARE RAGE SNEWED REPORTED FOR THE VINICE RESULTED IN A CICIDENT. I WOULD LIKE TO KNOW MORE INFORMATION AS TO THE PROPERTY OF THE VINICE REAR ENDED AND HIM AND EXCEPT REPORTED. 10075184 GMC ENVOY 2003 2004-05-20 MANUFACTURES DID NOT EXCEPT RESPONSIBILITY. *SC WHILE DRIVING JOIN MIRE AND STATEMENT OF THE PROBLEM. *AK THE MANUFACTURE REPORT SHARE AND A CICIDENT AFTER BEING STRUCK IN A STRIOUS FROM TEND NOT EXCEPT RESPONSIBILITY. *SC WHILE DRIVEN SHARE AND A CICIDENT AFTER BEING STRUCK IN A STRIOUS FROM TEND NOT EXCEPT RESPONSIBILITY. *SC CONSUMERS VINICE WAS INVOICED IN A FRONT COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMERS STRUCK IN A STRIOUS FROM TEND A FROM TEND AND A FROM THE AND A FROM THE ADDRESS OF THE AREA SO THE AREA AREA SO THE AREA SO T						
02 203. TO AVOID REAR REDNING THE CARE NETWORT OF HER SHE SWERVED THE ENVOY OFF OF THE ROAD, DOWN A HILL AD AND AND HER TERE IN THE RIGHT FOR PASSENCERS DOE OF THE VEHICLE. SHE HIT THE TREE WITH SUCH FORCE THAT THE DAMAGE TO THE REVOLT OF THE VEHICLE RESULTED IN A TOTAL LOSS. MY CONCERN IS THE AIR BAGS SHEVEN REVER DREFLOVED IN THIS ACCIDENT. I WOULD LIKE TO KNOW WHY? AND I WOULD LIKE TO KNOW MORE INFORMATION AS TO CONSUMERS VEHICLE REAR ENDED ANOTHER VEHICLE TO KNOW WHY? AND I WOULD LIKE TO KNOW MORE INFORMATION AS TO CONSUMERS VEHICLE REAR ENDED ANOTHER VEHICLE TS MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY, DEALERSHIP WAS NOTHING BUT ON THE ROUBLEM. "AK THE PROBLEM." AND THE PROPERTION OF THE AIR BAGS SHEW IN A GIVE THE PROBLEM." AND THE P	10970795	CHEVROLET	TRAILBLAZER	2003	2017-03-25	MILEAGE WAS 150,000.
THE ROAD, DOWN A HILL AND AND HIT A TIRE IN THE RIGHT FRONT OR PASSENGER SIDE OF THE VEHICLE. SHE HITT THE TERE WITH SLICH FORCE THAT THE DANGE TO THE VEHICLE RESULTED IN A TOTAL LOSS. MY CONCERN IS THE AIR BAGS INVER INVERT DRIVER FOR THE VEHICLE RESULTED IN A TOTAL LOSS. MY CONCERN IS THE AIR BAGS NEVER INVERT DRIVE PROVIDED IN HIS ACCIDENT. INVOIDING LIKE TO KNOW WAY AND INVOIDING TO KNOW MORE INPEDIVED IN HIS ACCIDENT. INVOIDING LIKE TO KNOW WHAT AND INVOIDING HER PROMISED AND TO THE OPERATION OF THE AIR BAGS SIZE MIN A GAK CHEEN TO KNOW MORE INPEDIVED IN HIS ACCIDENT. WAS AND INVOIDING THE AIR BAGS SIZE MIN A GAK CHEEN TO KNOW THE AIR BAGS DID NOT DEPLOY. DEALERSHIP WAS NOTHED, BUT DID HOT RESOLVE THE PROBLEM. "AK THE WANUSACTURER DID NOT DEPLOY. DEALERSHIP WAS NOTHED, BUT DID HOT RESOLVE THE PROBLEM. "AK THE WANUSACTURER." AND AND THE AIR BAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOLS FRONT FIND CONTROL THE PROBLEM. "AK THE BAGS DID NOT DEPLOY HOT EXCEPT RESPONSIBILITY. "SC. CONSUMERS VEHICLE WAS INVOIVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER VEHICLE WAS INVOIVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER WILL NOTHLY MANUSACTURER." AK POLICE REPORT INVOIVED AND AND AND AND AND AND AND AND AND AN						MY WIFE WAS IN AN ACCIDENT WITH OUR NEW 2003 GMC ENVOY SLT, PURCHASED IN NOVEMBER
VEHICLE. SHE HIT THE TREE WITH SUCH FORCE THAT THE DAMAGE TO THE REVEN THE PEND TO PET BY VEHICLE RESULTED IN A TOTAL LOSS. MY CONCERN ST THE AIR BAGS STORY EN REVER DEFLOVED IN THIS ACCIDENT. I WOULD LIKE TO KNOW WHY? AND I WOULD LIKE TO KNOW MORE INFORMATION AS TO CONSUMERS VEHICLE REAR ENDED ANOTHER VEHICLE TO KNOW WHY? AND IN WOULD LIKE TO KNOW MORE INFORMATION AS TO CONSUMERS VEHICLE REAR ENDED ANOTHER VEHICLE TAS MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY, DEALBRISH WAS NOTHING BUT OIL DO NOT RESOUR THE PROBLEM. "AK THE MADE OF THE AIR BAG SYSTEM IN A GMC ENVOY 2003 2004-05-20 WHILE DRIVING, UPON IMPACT, THE REPORT SHOW AND THE PROBLEM." "AK THE MADE OF THE PROBLEM." "AK THE PROBL						·
RESULTED IN A TOTAL LOSS. MY CONCERN IS THE AREAS REVER NEVER DEPLOYED IN THIS ALCOPENT. I WOULD LIKE FOR SNOW WARD RIN FORMATION AS TO THE OPERATION OF THE AREA SSYTEM IN A GMC ENVOY. 2003 2004-04-05 TO THE OPERATION OF THE AREA SSYTEM IN A GMC ENVOY. 2003 2004-05-20 MANUFACTURER IS USED ON THE REPORT WAS NOTHER, BUT DID NOT RESOLVE THE PROBLEM. *AK. THE MANUFACTURER IS DID NOT EXECUTE DESONSIBILITY. *SO.* WHILE DRIVING UPON INTERCET THE ARE BAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOUS FRONT END COLLISION. *FB.* *SC.* CONSUMERS VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOUS FRONT END COLLISION. *FB.* *SC.* CONSUMERS VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER WILL NOTIFY MANUFACTURE. *AKPOLICE REPORT INTERCED.* THE AREA SO.* TO NOT BE TO THE AREA SO.* TO SERVE AREA SO.* TO THE AREA SO.* TO THE AREA SO.* TO SELVE AREA SO.* T						·
100761821 GMC						
CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE AT 25 MPH. UPON IMPACT, AIR RAGS DID 10076184 GMC ENVOY 2003 2004-05-20 MANUFACTURER DID NOT EXCEPT RESPONSIBILITY. "SC WHILE DRIVING UPON IMPACT THE AIR BAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOUS FRONT END COLLISION." BF "SC CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOUS FRONT END COLLISION." BF "SC CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER WILL NOTIFY MANUFACTURER." AME. "POLICE REPORT INVOLVED IN A FRONT COLLISION ACCIDENT AT 15 MPH. DUE TO WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER WAS INFORMED BY CONSUMER." "AK THE CONSUMER STATED THAT THE VEHICLE COULD DAILY BE TURNED OFF BY CUTTING THE BATTERY CABLES." "TC CAGINET ON 21/17/2009 FRONT CRASH TO OTHER VEHICLE AND AIR BAG DID NOT DEPLOY HOOD DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, THE WHILE ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T O OPE . 1DO UNDERSTAND THAT THE ACCIDENT WAS DITCH. HE AIR BAGS DID NOT DEPLOY AND THE CONTEXT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED NITO A CURB AND THE VEHICLE TRINED OVER IN A DITCH. HE AIR BAGS DID NOT DEPLOY AND THE CONTEXT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED NITO A CURB AND THE VEHICLE TRANED OVER IN A DITCH. HE AIR BAGS DID NOT DEPLOY AND THE CONTEXT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED NITO A CURB AND THE VEHICLE WAS DESTROYED. THE FAULURE MILES OF THE CONTEXT COWNS A 2003 GMC ENVOY. THE CONTEXT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED NITO A CURB AND THE VEHICLE WAS DESTROYED. THE FAULURE MILES OF THE CONTEXT COWNS A 2003 GMC ENVOY. THE CONTEXT STATED THAT WHILE DRIVING AT VALINGUES APPOLICE REPORT WAS PICKOWN THE CONTEXT. THE VEHICLE WAS DESTROYED. THE FAULUR	10065821	GMC	FNVOV	2003	2004-04-05	
10103918 GMC ENVOY 2003 2004-05-20 MANUFACTURER DID NOT EXCEPT RESPONSIBILITY. "SC ENVOY 2003 2004-11-01 SERIOUS FRONT END COLLISION." BF "SC CONSUMERS VERICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR RAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOUS FRONT END COLLISION." BF "SC CONSUMERS VERICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR RAGS DID NOT DEPLOY. CONSUMER WILL NOTIFY MANUFACTURER." PAIL." POLICE REPORT INCLUDED ENVOY 2003 2004-11-22 INCLUDED ENVOY 2003 2004-01-18 CALES. "TC CABLES. TC CABLES. "TC CABLES. "TC CABLES. "TC CABLES. "TC CABLES. TC CABLES. "TC CABLES. "TC CABLES. "TC CABLES. "TC CABLES. TC CABLES. "TC CABLES. "TC CABLES. "TC CABLES. "TC CABLES. TC CABLES. "TC ANY HUSBAND FELL ASLEEP AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CABLES THE CABLES BUT THE AIR BAGS DID NOT GO DOTE, 100 UNDERSTAND THAT THE ACCIDENT WAS DITCH. THE AIR BAGS DID NOT GO DOTE, 100 UNDERSTAND THAT THE ACCIDENT WAS DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT SUSTAINED NECK AND LOWER BACK INVERSE. A POLICE REPORT WAS PELOD OF THE INCIDENT. THE VEHICLE WAS DEBMED DESTROYED AND DITCH. THE AIR BAGS DID NOT DEPLOY WAS PEROL BAD THE VEHICLE TRAVELED OWEN AND DITCH. THE AIR BAGS DID NOT DEPLOY WAS PEROL BAD THE VEHICLE WAS DESTROYED. AND DITCH. THE AIR BAGS DID NOT DEPLOY WAS P	10003821	divic	LIVOI	2003	2004-04-03	
WHILE DRIVING, UPON IMPACT THE AIR BAGS DID NOT DEPLOY AFTER BEING STRUCK IN A SERIOUS FRONTE FRO COLLISION." 88 * 52. CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY, CONSUMER WILL NOTIFY MANUFACTURE."AKPOLICE REPORT MINICIPED VEHICLE WAS INVOLVED IN A FRONT COLLISION ACCIDENT AT 15 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER WAS INFORMED BY CONSUMER. "AK THE CONSUMER STATED THAT THE VEHICLE COULD ONLY BE TURNED BY FOUNDING THE BATTERY CABLES." TE CONSUMER STATED THAT THE VEHICLE COULD ONLY BE TURNED OFF BY CUTTING THE BATTERY CABLES. "TE ACCIDENT ON 2/12/2009 FRONT CRASH TO OTHER VEHICLE AND AIR BAG DID NOT DEPLOY HOOD DAMAGE, MINISHELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATION DAMAGE, MINISHELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATION DAMAGE, MINISHELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATION DAMAGE, MINISHELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATION DAMAGE, MINISHELD DAMAGE, THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE ANY HUSBAND FELL ASLEEP AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS DIDN'THE VEHICLE WAS DEWNED DESTROYED THE CONTACT SWATE DEPLOY AND THE CONTACT SUSTAINED BACK INJURIES. A POLICE REPORT WAS FILED OF THE VEHICLE WAS DEWNED DESTROYED THE VEHICLE WAS DEWNED DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A C	10075101	0.40	5111/01/	2000	2004.05.00	·
CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AT 35 MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER WILL NOTIFY MANUFACTURER.* AK	10076184	GMC	ENVOY	2003	2004-05-20	
BAGS DIO NOT DEPLOY. CONSUMER WILL NOTIFY MANUFACTURER. "AKPOLICE REPORT INCLUDED INCLUDED VEHICLE WAS INVOLVED IN A FRONT COLLISION ACCIDENT AT 15 MPH DUE TO WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER WAS INFORMED BY CONSUMER. "AK THE CONSUMER STATED THAT THE VEHICLE CUND FE TURTURED OF FEY CUTTING THE BATTERY CABLES." "TO	10101930	GMC	ENVOY	2003	2004-11-01	,, ,
10103710 GMC ENVOY 2003 2004-01-12 VEHICLE WAS INVOLVED IN A FRONT COLLISION ACCIDENT AT 15 MPH DUE TO WEATHER UPON IMPACT, ARI BAGS DID NOT DEPLOY, DEALER WAS INFORMED BY CONSUMER. "AK THE CONSUMER STATED THAT THE VEHICLE COULD ONLY BE TURNED OFF BY CUTTING THE BATTERY CABLES." "IC) 7200 FRONT CRASH TO OTHER VEHICLE AND AIR BAG DID NOT DEPLOY HOOD DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, ETR MY HUSBAND FELL ASLEEP AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAB IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. "TO OUNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBAND FAULT BUT IDDN'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF." TO OUNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBAND FAULT BUT IDDN'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. "TO OUNDERSTAND THAT THE ACCIDENT WAS 100% MY BURNESHOOD FROM THE SEVERAL TREES. THE CAB IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF." THE THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CUBB AND THE VEHICLE TURNED OVER BACK INJURIES. A POLICE REPORT WAS RICED OF THE INCIDENT. THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE VARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE AIR WAS INDURING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE WAS DEEMED DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS NOVIDED IN A CRASH. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS NOVIDED IN A CRASH. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS NOVIDED IN A CRASH. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILE DRIVING AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPO						•
IMPACT, AIR BAGS DID NOT DEPLOY. DEALER WAS INFORMED BY CONSUMER. "AK THE CONSUMER STATED THAT THE VEHICLE COULD ONLY BE TURNED OFF BY CUTTING THE BATTERY CABLES. "TC ACCIDENT ON 2/37/2009 FRONT CRASH TO OTHER VEHICLE AND AIR BAG DID NOT DEPLOY HOOD DAMAGE, MINDSHELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, MINDSHELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, ENGINE DAMAGE, THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS 1008 MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. "TR TH' THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SUGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT SUSTAINED NECK AND LOWER BACK INJURIES. A POLICE REPORT WAS FILED OF THE INCIDENT. THE VEHICLE WAS DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILED TO DEPLOY AND THE CONTACT SUSTAINED NAD THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE AIR BAGS FALED TO THE POLY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE AIR BAGS AND AND RUNK POWER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERY POLICE TO THE WAS NOT AVAILABLE. THE AIR	10103710	GMC	ENVOY	2003	2004-11-22	
CONSUMER STATED THAT THE VEHICLE COULD ONLY BE TURNED OFF BY CUTTING THE BATTERY CABLES. *TC ACCIDENT ON 2/37/2009 FRONT CRASH TO OTHER VEHICLE AND AIR BAG DID NOT DEPLOY HOOD DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, THE WHELL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. 1DO UNDERSTAND THAT THE ACCIDENT WAS 10281810 GMC ENVOY 2003 2009-08-25 100% MY HUSBANDS FAULT BUT! DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. *TR TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SHIGHTLY CRASHED INTO A CURB AND THE VEHICLE TWAD OVER INA AD ITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SHIGHTLY CRASHED INTO A CURB AND THE VEHICLE WAS DESTROYED. AND TOWNED TO A SALVAGE YARD. THE MANUFACTURE WAS NOT MADE AWARE OF THE FAILURE. TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE WAS DESTROYED. THE FAILURE MILEAGE WAS UNAVAILABLE. TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT OWNS A 1001 A CRASH. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT O'T FRAFFIC, CAUSING EVERYONE TO SLAW ON THIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP! IN TIME BEFORE REAR-ENDING ANOTHER WAS TO TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *15 I WAS DRIVING ABOUT 440 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT O'T MALLS TO INVESTIGATE ARD HE TO DO THE CALLED A REP FOR GMC, TO COM						
CABLES. **TC ACCIDENT ON 2/17/2009 FRONT CRASH TO OTHER VEHICLE AND AIR BAG DID NOT DEPLOY HOOD DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, WINDSHIELD BUT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRRAGS DIDN'T GO OFF. IDO UNDERSTAND THAT THE ACCIDENT WAS 1009-08-25 1009's MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR RAGS DIDN'T GO OFF. *TR TIL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE WAS DEEMED DESTROYED AND TWO WENDS AND TOWNED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. 10554787 GMC ENVOY 2003 2013-11-25 THE FRONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT OWNS A 2003 KEEP WAS PRESTROYED AND TOWNED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. 10560852 GMC ENVOY 2003 2014-01-16 THE VIEW WAS NOT AVAILABLE. THE AIR PRAGS FAILED TO DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE WAS DESTROYED. THE VIEW WAS NOT AVAILABLE. THE AIR PRAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIEW WAS NOT AVAILABLE. THE AIR PRAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIEW WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. 10560852 GMC ENVOY 2003 2014-01-16 THE VIEW WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. 10TH THE AIR AND A CONTACT WAS THE PROVING THE SHARE SALVER PROVING THE VIEW AND THE STROYED AND THE PROVING PROVING THE VIEW AND THE PROVING PROVING THE VIEW AND THE PROVING PROVING THE VIEW AND THE PROVING PROVING PROVING THE VIEW						'
DAMAGE, WINDSHIELD DAMAGE, ALL FRONT DAMAGE, DOORS COULD NOT OPEN RADIATOR DAMAGE, ENGINE DAMAGE, TR MY HUSBAND FELL ASLEEP AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBAND FELL ASLEEP AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. *TR TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. THE VAIN WAS NOT CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. DOT ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE AIR PROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. "TR WY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. "IS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. "IS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO ST	10103904	GMC	ENVOY	2003	2004-01-18	CABLES. *TC
10259161 GMC ENVOY 2003 2009-02-17 DAMAGE, ENGINE DAMAGE. *TR MY HUSBAND FELL ASLEEP AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. *TR TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SUGHTLY CRASHED INTO A CURB AND THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE INCIDENT. THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. 10554787 GMC ENVOY 2003 2013-11-25 THE FAILURE MILEAGE WAS UNAVAILABLE. TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS FILED OF THE HILCIDENT. THE VEHICLE WAS DEEMED DESTROYED. AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. 10560852 GMC ENVOY 2003 2014-01-16 THE FAILURE MILEAGE WAS UNAVAILABLE. 10560852 GMC ENVOY 2003 2014-01-16 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560852 GMC ENVOY 2003 2014-01-16 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560852 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560852 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560854 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560855 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560856 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560857 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560858 THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 10,0,000. 10560859 THE VIN WAS NOT AVAILABLE. THE PROPED THE VIN WAS NOT AVAILABLE. THE APPROXIMATE AND THE CONTACT						
CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. *TR TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT AN DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED THA OF ATTEM THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. "THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. "THE VIN WAS NOT TO THE FIND A TREE. THE AIR BRASKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. "JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC EMBAGS DID NOT DEPLOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC EMBAGS DID NOT DEPLOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC EMBAGS DID NOT DEPLOY MY STOP BULL CAN SOMEONE HELP ME, IST HERE ANTHHING I CAN DO I HEART HAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO	10259161	GMC	ENVOY	2003	2009-02-17	
CAR IS TOTALED BUT THE AIRBAGS DIDN'T GO OFF. I DO UNDERSTAND THAT THE ACCIDENT WAS 100% MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. *TR TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT AN DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED THA OF ATTEM THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. "THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. "THE VIN WAS NOT TO THE FIND A TREE. THE AIR BRASKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. "JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC EMBAGS DID NOT DEPLOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC EMBAGS DID NOT DEPLOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC EMBAGS DID NOT DEPLOY MY STOP BULL CAN SOMEONE HELP ME, IST HERE ANTHHING I CAN DO I HEART HAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						MV HUSBAND FELL ASLEED AT THE WHEEL ON HIS WAY TO WORK AND HIT SEVERAL TREES. THE
TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT SUSTAINED NECK AND LOWER BACK INJURIES. A POLICE REPORT WAS FILED OF THE INCIDENT. THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE FAIRURE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. THE VIN WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *IS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEAGE I. TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS SELCULSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. IT THINK THAT IS BRUNCH OF BULL. CAN SOMEONE HELP ME, IS THERE ANYTHING I CAN DO I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
UNKNOWN SPEED, HE SLIGHTLY CRASHED INTO A CURB AND THE VEHICLE TURNED OVER IN A DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT SUSTAINED NECK AND LOWER BACK INJURIES. A POLICE REPORT WAS FILED OF THE INCIDENT. THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. TIL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. **TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *!S I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY, MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY, MY ENVOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY, I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME , IS THERE ANYTHING I CAN DO I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO	10281810	GMC	ENVOY	2003	2009-08-25	100% MY HUSBANDS FAULT BUT I DON'T UNDERSTAND WHY THE AIR BAGS DIDN'T GO OFF. *TR
DITCH. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT SUSTAINED NECK AND LOWER BACK INJURIES. A POLICE REPORT WAS FILED OF THE INCIDENT. THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. TIL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. 6MC ENVOY 2003 2014-01-16 *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS 10592465 GMC ENVOY 2003 2014-04-14 THE AIRBAGS NEVER DEPLOYED. *JS 10493 THE AIRBAGS NEVER DEPLOYED. *JS 10592465 GMC ENVOY 2003 2014-04-14 THE AIRBAGS NEVER DEPLOYED. *JS 10592465 GMC ENVOY 2003 2014-04-14 THE AIRBAGS NEVER DEPLOYED. *JS 10592465 GMC ENVOY 2003 2014-04-14 THE AIRBAGS DID NOT THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR., PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME JIS THERE ANYTHING I CAN DO JI HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT AN
INJURIES. A POLICE REPORT WAS FILED OF THE INCIDENT. THE VEHICLE WAS DEEMED DESTROYED AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. THE ONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *IS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULLL CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
AND TOWED TO A SALVAGE YARD. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS UNAVAILABLE. TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *IS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME, IS THERE ANYTHING I CAN DO I. HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
TL* THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. 10560852 GMC ENVOY 2003 2014-01-16 *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME, IS THERE ANYTHING I CAN DO JI HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
VARIOUS SPEEDS, THE CONTACT WAS INVOLVED IN A CRASH. THE VEHICLE TRAVELED DOWN AN EMBANKMENT AND CRASHED INTO A TREE. THE AIR BAGS FAILED TO DEPLOY AND THE CONTACT SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. 10560852 GMC ENVOY 2003 2014-01-16 *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE. I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO	10554787	GMC	ENVOY	2003	2013-11-25	
SUSTAINED INJURIES TO THE ARMS. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY. WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
THE VIN WAS NOT AVAILABLE. THE APPROXIMATE FAILURE AND CURRENT MILEAGE WAS 100,000. *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
AND DO I HEAR THAT A PERSON CAN PROWE TO SAM OM CIF A PERSON S AIRBAGS DON'T GO *TR MY DAUGHTER WAS DRIVING THE ENVOY AT ABOUT 45 MPH WHEN A DRUNK DRIVER PULLED OUT IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
IN FRONT OF TRAFFIC, CAUSING EVERYONE TO SLAM ON THEIR BRAKES, AND MY DAUGHTER WAS NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO	10560852	GMC	ENVOY	2003	2014-01-16	
NOT ABLE TO STOP IN TIME BEFORE REAR-ENDING ANOTHER VEHICLE. THE CAR IS TOTALED BUT THE AIRBAGS NEVER DEPLOYED. *JS I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
I WAS DRIVING ABOUT 40 MPH WHEN I WENT THREW A YELLOW LIGHT WHEN A OLDER LADY TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						· ·
TURN IN FRONT OF ME, I HIT HER ON THE PASSENGER SIDE BETWEEN THE FRONT N BACK DR, , PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO	10592465	GMC	ENVOY	2003	2014-04-14	THE AIRBAGS NEVER DEPLOYED. *JS
PUSHING N ROLLING N TOTALING HER SMALL SUV. SHE WAS NOT SERIOUS HURT. MY AIRBAGS DID NOT DEPLOY. MY ENVOY WAS STILL DRIVEABLE . I TOOK MY ENVOY TO MY LOCAL GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
GMC DEALER TO HAVE THEM FIND PROB WHY THE AIRBAGS DIDN'T GO OFF, THEY OR I CALLED A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME, IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						· · ·
A REP FOR GMC, TO COME TO SIOUX FALLS TO INVESTIGATE AND HE TOLD ME THAT THE REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME, IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						
REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR DEPLOY. I THINK THAT IS BUNCH OF BULL. CAN SOMEONE HELP ME ,IS THERE ANYTHING I CAN DO .I HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						·
DO .1 HEAR THAT A PERSON CAN RECEIVE CASH FROM GMC IF A PERSON S AIRBAGS DON'T GO						REASON THEY DIDN'T DEPLOY WAS BECAUSE I WASN'T GOING FAST ENOUGH FOR IMPACT FOR
						·
	10615166	GMC	ENVOY	2003	2012-06-04	

					TL*THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT 5
					MPH, THE CONTACT OWNS A 2003 GMC ENVOY. THE CONTACT STATED THAT WHILE DRIVING AT 5 MPH, THE CONTACT DEPRESSED THE ACCELERATOR PEDAL INSTEAD OF THE BRAKE PEDAL WHICH CAUSED THE VEHICLE TO CRASH INTO A TREE. AS A RESULT, THE AIR BAG FAILED TO DEPLOY. THE CONTACT SUSTAINED INJURIES TO THE NECK AND LEFT SHOULDER WHICH REQUIRED MEDICAL
					ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS NOT REPAIRED. THE VIN WAS NOT
10682693	GMC	ENVOY	2003	2015-02-10	AVAILABLE. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 189,325.
10062093	GIVIC	EINVOY	2003	2015-02-10	FRONT AIR BAG DID NOT DEPLOY, DRIVING IN SNOW SLID AN HIT A TREE WAS DRIVING ON A
10816234	GMC	ENVOY	2003	2015-12-19	HIGHWAY.
					TL* THE CONTACT OWNED A 2003 GMC ENVOY. WHILE DRIVING APPROXIMATELY 25 MPH AND
					ATTEMPTING TO MAKE A LEFT TURN, THE CONTACT CRASHED INTO THE FRONT END OF ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. THERE WERE NO WARNING INDICATORS ILLUMINATED.
					THE CONTACT SUSTAINED INJURIES THAT DID NOT REQUIRE MEDICAL ATTENTION. A POLICE
					REPORT WAS FILED. THE VEHICLE WAS DECLARED TOTALED BY THE INSURANCE COMPANY AND
					TOWED FROM THE SCENE. THE DEALER AND MANUFACTURER WERE NOT MADE AWARE OF THE FAILURE. THE VEHICLE WAS NOT DIAGNOSED. THE FAILURE MILEAGE WAS APPROXIMATELY
11093358	GMC	ENVOY	2003	2018-04-20	300,000.
					WHILE DRIVING ON A RESIDENTIAL STREET CONSUMER FELL ASLEEP BEHIND THE WHEEL AND HIT
					ANOTHER VEHICLE ON THE FRONT DRIVER'S SIDE. SLIGHT INJURIES WERE SUSTAINED BY THE PASSENGERS OF THE OTHER VEHICLE. CONSUMER SUFFERED RIB CONTUSIONS EVEN THOUGH
					SEAT BELTS WERE WORN. NONE OF THE AIR BAGS DEPLOYED. CONSUMER WAS GIVEN A
10037631	GMC	YUKON	2003	2003-08-17	CITATION BY THE POLICE THAT ARRIVED ON THE SCENE.*AK
					DT*: THE CONTACT STATED THE VEHICLE WAS INVOLVED IN A T-BONE COLLISION AT 10MPH AND
					THE AIRBAGS DID NOT DEPLOY. THERE WAS NO PRE-BRAKING PRIOR TO IMPACT. ALTHOUGH THE
					OCCUPANTS WERE WEARING SEATBELTS, MINOR INJURIES WERE SUSTAINED. THE VEHICLE WAS
10152567	CNAC	VIIIVONI	2002	2006 02 10	TOTALED BY THE INSURANCE AGENCY. THE POLICE WERE ON THE SCENE AND A REPORT WAS
10152567	GMC	YUKON	2003	2006-03-10	TAKEN. THE VEHICLE WAS NOT SEEN BY A DEALER FOR INSPECTION. DT: THE CONTACT STATED WHILE DRIVING ON THE INTERSTATE DURING RUSH HOUR AT 55 MPH, A
					VEHICLE HIT THE WALL AND TAIL SPINNED IN FRONT OF CONTACT'S VEHICLE. THE CONTACT HIT
					THE VEHICLE WITH A FRONTAL IMPACT CAUSING SEVERE DAMAGE. UPON IMPACT, THE NONE OF
					THE CONTACT'S AIR BAGS DEPLOYED. THE CONTACT WAS WEARING A SEATBELT HOWEVER INJURIES WERE SUSTAIN TO THE SHOULDERS, BACK AND NECK. WHEN THE VEHICLE WAS TAKEN TO
					THE DEALERSHIP, THEY DETERMINED THE VEHICLE WAS OPERATING PROPERLY HOWEVER THE
					AIRBAGS DID NOT DEPLOY. THE MANUFACTURER HAS BEEN ALERTED. A POLICE REPORT WAS
10160618	ISUZU	ASCENDER	2003	2006-03-21	FILED AT THE SCENE. TL*THE CONTACT OWNS A 2003 ISUZU AXIOM. WHILE DRIVING LESS THAN 20 MPH, THE CONTACT
					REAR-ENDED THE PRECEDING VEHICLE. THE FRONT END OF HER VEHICLE WAS DAMAGED. THE AIR
					BAGS FAILED TO DEPLOY. THE DRIVER SUSTAINED MINOR NECK, LEG, AND BACK INJURIES. THE
					VEHICLE WAS TOWED TO A REPAIR SHOP AND COULD POSSIBLY BE LABELED AS DESTROYED. A POLICE REPORT WAS FILED. THE CURRENT AND FAILURE MILEAGES WERE 135,850 UPDATED
					05/08/09 *BF THE CONSUMER STATED THE DRIVER IN FRONT OF HIM/HER PULLED HIS
					EMERGENCY BRAKE BECAUSE THE DRIVER IN FRONT OF HIM STOPPED SUDDENLY AND THE
					CONSUMER NEVER SAW THE DRIVERS BRAKE LIGHTS. UPDATED 05/12/09. *JB UPDATED
10266207	ISUZU	AXIOM	2003	2009-04-11	DRIVING IN A LARGE PARKING LOT, HIT A LARGE CEMENT POLE DOING 20 MILES PER HOUR.AIR
					BAGS DID NOT DEPLOY. HAD NOT PUT MY SEAT BELT ON YET & HIT & SHATTERED THE WINDSHIELD
					KNOCKING OUT ALL OF MY FRONT UPPER TEETH. FRACTURED MAXILLA .WHY DID AIR BAGS NOT
11325218	ISUZU	AXIOM	2003	2020-05-15	DEPLOY? *TR WHILE DRIVING 40 MPH VEHICLE VEERED AND HIT A TELEPHONE POLE, AND AIR BAGS DIDNOT
					DEPLOY. DRIVER AND PASSENGER WERE INJURED. DEALER CONTACTED. HAD FRONTAL IMPACT.
8003267	CADILLAC	ESCALADE	2002	2001-07-19	*AK
10064075	CHEVIDOLET	ACTRO	2002	2004 02 45	WHILE DRIVING 40 MPH VEHICLE WAS INVOLVED IN A FRONTAL COLLISION. UPON IMPACT, DUAL
10064975	CHEVROLET	ASTRO	2002	2004-02-15	AIRBAGS DID NOT DEPLOY. NO INJURES WERE REPORTED. *AK
					HIGH SPEED CAR ACCIDENT ON 1/3/07 DRIVER SEAT BELT DID NOT WORK CORRECTLY, BELT DID
	0.15.15		25.5	2007 6: 22	NOT LOCK UPON HARD BRAKING OR UPON CAR CRASH I HIT MY CHEST ON STEERING WHEEL AND
10178492	CHEVROLET	ASTRO	2002	2007-01-03	MY KNEES ON DASHBOARD, MY AIRBAG DID NOT DEPLOY EITHER. *JB CONSUMER STATES THAT WHILE DRIVING AT 35MPH. VEHICLE WAS IN A COLLISION. CONSUMER
10026532	CHEVROLET	BLAZER	2002	2003-06-20	STATES THAT BOTH FRONT AIRBAGS DID NOT DEPLOY.DEALER NOTIFIED.*AK
					VEHICLE RAN INTO THE BACK OF A SEMI-TRACTOR TRAILER AND AIR BAGS DID NOT DEPLOY
10031054	CHEVROLET	DIAZED	2002	2002 06 20	BECAUSE IT DIDN'T CONSUMER SUSTAINED INJURIES, PAIN AND SUFFERING. DEALER NOTIFIED.
10031954	CHEVROLET	DLAZEK	2002	2003-06-20	*MR *CB THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AND THE FRONT AIR BAGS DID NOT DEPLOY.
					THE DRIVER SUFFERED NECK AND BACK INJURIES. THE FRONT PASSENGER SUFFERED CHEST
10048587	CHEVROLET	BLAZER	2002	2003-10-29	INJURIES. PLEASE PROVIDE FURTHER DETAILS. *JB

10347200	CHEVROLET	BLAZER	2002	2010-07-30 2011-05-23	TL* THE CONTACT OWNS A 2002 CHEVROLET BLAZER. THE CONTACT WAS DRIVING APPROXIMATELY 35 MPH, AND CRASHED INTO AN UNOCCUPIED PARKED VEHICLE. THE AIR BAGS WOULD NOT DEPLOY WITH THE LEVEL OF IMPACT IN THE CRASH. WHILE THE FRONT DRIVER SIDE SHOULDER SEAT BELT WAS BEING WORN, IT FAILED TO FUNCTION AND CAUSED THE CONTACT TO MOVE IN A FORWARD POSITION AS A RESULT HER FACE STRUCK THE STEERING WHEEL. THE CONTACT SUSTAINED A BROKEN NOSE, BRUISES ON BOTH ARMS AND SHOULDER AREA. THE AMBULANCE, FIRE AND POLICE DEPARTMENT WERE CALLED TO THE SCENE. A POLICE REPORT WAS FILED OF THE INCIDENT. THE VEHICLE WAS TOWED TO A COLLISION FACILITY LOT. THE VEHICLE WAS COMPLETELY DESTROYED. THE FAILURE MILEAGE WAS APPROXIMATELY 130,000. UPDATED 10/13/10*BF UPDATED 10/14/10*JB MY 2002 CHEVY BLAZER X-TREME AIR BAGS DIDN'T DEPLOY ON A FRONT END COLLISION AT THE SPEED OF 45 MPH, MY CAR HAS TOTAL DAMAGE. *TR CONSUMER WAS INVOLVED IN AN ACCIDENT WHERE SHE WAS HIT HEAD ON THE RIGHT FRONT SIDE. THE AIRBAGS FAILED TO DEPLOY. CONSUMER WAS TOLD THE AIRBAGS DIDN'T HAVE TO DEPLOY BECAUSE THE VEHICLE WAS STATIONARY DURING BOTH HITS, CONSUMER WAS INJURED IN
567453	CHEVROLET		2002	2002-08-18	THE ACCIDENT. *JG
767453	CHEVROLET	SILVERADO	2002	2002-09-01	IN DIRECT FRONTAL IMPACT AT 45 MPH, AIRBAGS FAILED TO DEPLOY.*AK
767929 767963	CHEVROLET	SILVERADO	2002	2002-05-08	THIS TRUCK WAS INVOLVED IN A HEAD ON CRASH. I WAS RUNNING ABOUT 55 MPH AND THE OTHER VEHICLE WAS RUNNING APPROXIMATELY 35 MPH. THE TRUCK WAS A TOTAL LOSS WITH MOST OF THE DAMAGE DONE TO THE FRONT END.THE DRIVERS SIDE AIR BAG OR THE PASSENGER AIR BAG DID NOT DEPLOY. MR THIS VEHICLE WAS INVOLVED IN A HEAD-ON COLLISION WHILE TRAVELING AT 50 MPH. BOTH THE DRIVER SIDE AND PASSENGER SIDE AIR BAGS DID NOT DEPLOY. MR
					VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 25MPH. UPON IMPACT, AIRBAGS DID NOT
8000974	CHEVROLET	SILVERADO	2002	2001-12-10	DEPLOY. *AK *YH
8003037			2002	2001 12 10	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 40-45MPH. UPON IMPACT AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN CONTACTED. PLEASE PROVIDE ADDITIONAL INFORMATION.*AK
					WHILE DRIVING AT 35 MPH, THE VEHICLE WAS HIT BY AN AMBALANCE, THE AIR BAGS DIDN'T
8010265	CHEVROLET	SILVERADO	2002	2002-05-21	DEPLOY RESULTING IN MAJOR INJURIES TO DRIVER.*AK *MJ
8011057	CHEVROLET	SILVERADO	2002	2002-05-19	VEHICLE WAS INVOLVED IN A FRONTAL IMPACT GOING 35MPH. AIR BAG DIDN'T DEPLOY, AND LIGHT NEVER ILLUMINATED. CHEVROLET WAS CONTACTED, AND WILL BE SENDING AN INSPECTOR OUT FOR VEHICLE. PLEASE PROVIDE MORE INFORMATION.*AK VEHICLE WAS INVOLVED IN A 30-40 MPH FRONTAL COLLISION IN WHICH DRIVER'S AND PASSENGER'S AIR BAGS DID NOT DEPLOY, CAUSE UNKNOWN. PLEASE GIVE ANY FURTHER
8011088	CHEVROLET	SILVERADO	2002	2002-05-12	DETAILS.*AK
8016806	CHEVROLET	SILVERADO	2002	2002-08-19	CONSUMER WAS TRAVELING ABOUT 20MPH ON A SIDE STREET AND THERE WAS A CONCRETE PIPE LAYING ON THE ROAD, AND WITHOUT PRIOR WARNING SHE HIT THE PIPE. AIRBAGS DIDN'T GO OFF. AT DEALERSHIP IS AWARE OF PROBLEM.THE PIPE WAS A BROKE OFF LIGHT POLE. THE FRAME ON THE VEHICLE IS BENT. *JG VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WITH A TREE TRAVELING APPROXIMATLY 30-
8017234	CHEVROLET	SILVERADO	2002	2002-08-19	40MPH. AND AIR BAGS DID NOT DEPLOY.*AK
0017234	CHEVILOLET	SIEVERNIDO	2002	2002 00 13	WHILE DRIVING AT 72 MPH CONSUMER HIT ANOTHER VEHICLE HEAD ON AND NONE OF THE AIR
					BAGS DEPLOYED. CONTACTED DEALER, AND DEALER STATED THAT THE VEHICLE ACTED LIKE IT
8019177	CHEVROLET	SILVERADO	2002	2002-08-23	SHOULD HAVE.AK
0004555	0.15.15			2005	CONSUMER STATES WHILE DRIVING 45MPH HAD A HEAD ON COLLISION AIR BAG DID NOT DEPLOY.
8021266	CHEVROLET	SILVERADO	2002	2002-07-19	TS
8024161	CHEVROLET	SILVERADO	2002	2002-11-19	CONSUMER STATES THAT WHEN HIT AT 55 MPH IN THE FRONT CENTER OF THE VEHICLE THE AIR BAG DID NOT DEPLOY CAUSING MINOR INJURIES TO THE CONSUMER. DEALER NOTIFIED. MR CONSUMER COMPLAINED ABOUT HAVING PROBLEMS WITH THE AIR BAG DEPLOYMENT. ALSO,
10004706	CHEVROLET	SILVERADO	2002	2002-12-16	WHILE DRIVING VEHICLE WAS INVOLVED IN A COLLISION, AND AIR BAGS DID NOT DEPLOY .PASSENGER WAS DRIVING AT 50 MPH WHEN PASSING OVER A BRIDGE ON A RAINY DAY, AND WATER FROM THE RIVER WAS SPLASHED ON THE FRONT WINDSHIELD WHICH CAUSED THE DRIVER TO LOOSE CONTROL OF THE VEHICLE. MANUFACTURE WAS NOT CONTACTED AT THE TIME OF THIS PHONE CALL. *AK
					WHILE DRIVING VEHICLE WAS IN A FRONTAL COLLISION, BUT NONE OF THE AIR BAGS DEPLOYED
					UPON IMPACT. THE DRIVER WAS NOT INJURED BECAUSE THEY WERE WEARING THERE SEAT
10005976	CHEVROLET		2002	2003-01-29	BELTS.*AK
10009099	CHEVROLET	SILVERADO	2002	2003-02-21	THE VEHICLE HIT A TREE, AND NONE OF THE AIR BAGS DEPLOYED.* JB *TS
10015540	CHE//DOLET	CILVEDADO	2002		THE VEHICLE WAS INVOLVED IN A FRONT END COLLISION YET NEITHER FRONTAL AIR BAGS
10015548	CHEVROLET	SILVERADO	2002		DEPLOYED. *NLM THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AND NONE OF THE AIR BAGS DEPLOYED.
10019853	CHEVROLET	SILVERADO	2002		*JB
					WHILE DRIVING AT 43 MPH VEHICLE WAS INVOLVED IN A LEFT FRONT COLLISION. UPON IMPACT,
10042035	CHEVROLET	SILVERADO	2002		FRONT AIR BAGS DID NOT DEPLOY, AND PASSENGER SUSTAINED INJURIES. *AK

10073268	CHEVROLET	SILVERADO	2002	2002-08-11	I WAS AT A COMPLETE STOP AT A RED LIGHT WHEN A YOUNG LADY RAN THE LIGHT FROM THE OPPOSITE DIRECTION. SHE HIT ANOTHER TRUCK THEN CROSSED OVER INTO MY LANE HITTING ME ON MY RIGHT FRONT BUMPER. LESS THAN 3 SECONDS LATER THE OTHER TRUCK HIT ME HEAD ON AT 35-40 MPH HEAD ON. THE IMPACT WAS HARD ENOUGH TO THROW ME BACKWARDS INTO SOME MOTORCYCLES BEHIND ME. MY FRONTAL AIRBAGS DID NOT DEPLOY DURING EITHER HIT.
10080276	CHEVROLET	SILVERADO	2002	2004-06-27	WHILE DRIVING 45 MPH THE DRIVER ATTEMPTED TO AVOID A DEER IN THE STREET. AS A RESULT THE DRIVER LOST CONTROL OF THE VEHICLE AND HIT A TREE HEAD ON. THE CONSUMER STATED THAT,"NEITHER FRONTAL AIR BAG DID DEPLOYED ON IMPACT". THE CONSUMER WILL CONTACT THE DEALER. *NM
10115806	CHEVROLET	SILVERADO	2002	2005-03-24	A PIECE OF FURNITURE WAS LOCATED IN THE MIDDLE OF THE HIGHWAY WHILE DRIVING, CAUSING THE DRIVER TO HIT THE FURNITURE. DRIVER LOST CONTROL OF A VEHICLE, AND IT CRASHED INTO A CONCRETE WALL. DRIVER'S SIDE SEAT BELT FAILED, AND THE AIRBAGS DID NOT DEPLOY. DRIVER REFUSED MEDICAL ATTENTION AT THAT TIME AND WENT TO THE HOSPITAL ON HIS OWN. VEHICLE WAS TOWED BY THE INSURANCE COMPANY. *AK
10127515	CHEVROLET	SILVERADO	2002	2005-07-05	DT: CONTACT STATES WHILE DRIVING APPROXIMATELY 45 MPH THERE WAS A FRONT END COLLISION. UPON IMPACT, NEITHER AIR BAG DEPLOYED. *AK
10246829	CHEVROLET	SILVERADO	2002	2008-10-13	TL*THE CONTACT OWNS A 2002 CHEVROLET SILVERADO. WHILE DRIVING 30 MPH, THE CONTACT STRUCK A DEER AND SWERVED INTO A DITCH. HIS CHEST SLAMMED INTO THE STEERING WHEEL AND WAS INJURED. THE AIR BAGS FAILED TO DEPLOY AND THE SEAT BELT DID NOT RETRACT. THE DRIVER'S SIDE BUMPER WAS CRUSHED INTO THE FRONT GRILL ALL THE WAY ACROSS TO THE PASSENGER SIDE OF THE VEHICLE. THE CONTACT CALLED THE INSURANCE AGENT, BUT NO POLICE REPORT WAS FILED. HE WAS THE ONLY OCCUPANT IN THE VEHICLE AND THE SEAT BELT WAS WORN PROPERLY AT THE TIME OF THE CRASH. THERE WAS NO MAINTENANCE PERFORMED ON THE AIR BAGS OR SEAT BELT PRIOR TO THE FAILURES. THE CONTACT FILED A COMPLAINT WITH GM CONCERNING HIS AIR BAGS AND SEAT BELT (COMPLAINT NUMBER 71-670143505). GM IS NOT TAKING RESPONSIBILITY FOR THE AIR BAG FAILURE. IN ADDITION, NO ONE CAME OUT TO INSPECT THE VEHICLE. THE FAILURE MILEAGE WAS 61,752.
10281236	CHEVROLET	SILVERADO	2002	2007-11-29	TL*THE CONTACT OWNS A 2002 CHEVROLET SILVERADO. WHILE DRIVING APPROXIMATELY 45 MPH ON NORMAL ROAD CONDITIONS, A VEHICLE CRASHED INTO THE FRONT OF THE DRIVER SIDE. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL AFTER SUSTAINING INJURIES TO THE HEAD, NECK AND LIP. THE AMBULANCE AND POLICE ARRIVED AND A POLICE REPORT WAS FILED. THE AIR BAGS FAILED TO DEPLOY WITH THE MASSIVE LEVEL OF IMPACT. THERE WERE NO WARNING LIGHT INDICATORS ILLUMINATED ON THE INSTRUMENT PANEL AFTER THE CRASH. THE FRONT END OF THE VEHICLE SUSTAINED SEVERE DAMAGE. THE VEHICLE WAS TOWED TO A COLLISION CENTER AND THE VEHICLE WAS REPAIRED. THE CONTACT HAD CONCERNS OF THE SAFETY RISK INVOLVED. THE FAILURE MILEAGE WAS 40,000 AND THE CURRENT MILEAGE WAS 55,000.
10679097	CHEVROLET	SILVERADO	2002	2015-01-16	WHILE DRIVING AT 45 MPH VEHICLE WAS FORCED OFF OF THE ROAD INTO ONCOMING TRAFFIC. CONSUMER SWERVED TO AVOID A HEAD ON COLLISION WITH ANOTHER VEHICLE. THIS ACTION CAUSED THE VEHICLE TO CRASH THROUGH A FENCE, RUN INTO A DITCH, AND COLLIDE HEAD ON
10039711	CHEVROLET	SUBURBAN	2002	2003-08-27	WITH AN OAK TREE. SEAT BELTS WERE WORN, BUT AT THE TIME OF THE IMPACT, THE LATCH CAME APART. VEHICLE WAS EQUIPPED WITH FRONT AND SIDE AIR AIR BAGS. UPON IMPACT, THEY DID NOT DEPLOY. CONSUMER'S KNEE WAS BROKEN, AND HE SUFFERED A CONCUSSION. POLICE AND MEDICAL HELP DID ARRIVE ON THE SCENE. MANUFACTURER AND THE DEALER HAVE BEEN NOTIFIED OF THE INCIDENT. *AK
					I WAS HIT ON THE HEAD INSIDE MY 2002 SUBURBAN, WEARING MY SEAT BELT AT 48 MPH BY AN ONCOMING MAZDA MIATA. MY STEERING COLUMN COLLAPSED, I WENT INTO ONCOMING 3 LANES OF TRAFFIC, WENT UP A CURB, WENT THROUGH A BRICK RETAINING WALL, AND HIT A TELEPHONE POLE. MY AIRBAG DID NOT DEPLOY ON ANY OF THE 3 IMPACTS. WHY? ALSO, MY
10041031	CHEVROLET	SUBURBAN	2002	2003-01-07	DRIVER?S SEAT CAME OFF THE TRACK. *LA THE CONSUMER WAS INVOLVED IN AN ACCIDENT. THE CONSUMER WAS DRIVING ABOUT 60 MPH
10108747	CHEVROLET	SUBURBAN	2002	2004-11-11	AND REAR ENDED ANOTHER VEHICLE AND THE AIR BAGS FAILED TO DEPLOY. ALSO THE SEAT BELTS DID NOT HOLD THE DRIVER AND PASSENGER CAUSING THEM TO GO FORWARD INTO THE WINDSHIELD. PROVIDE FURTHER DETAILS. *JB
10121922	CHEVROLET	SUBURBAN	2002	2005-05-14	DT: HUSBAND HAD AN ACCIDENT, CAR PULLED OUT IN FRONT OF HIM AND HIT THEM ON DRIVER AND BACK SEAT PASSENGER SIDE HEAD. UPON IMPACT, AIR BAG DID NOT DEPLOY.*AK
568470	CHEVROLET	TAHOE	2002	2002-06-05	ON TWO OCCASIONS THE FRONT AIR BAGS FAILED TO DEPLOY UPON FRONT IMPACT. THE VEHCILE WAS INSPECTED BY A CRASH INVESTIGATOR WHO TOLD THE CONSUMER THAT THE VEHICLE OPERATED AS DESIGNED. *NLM
8022842	CHEVROLET	ТАНОЕ	2002	2002-10-10	THE TRUCK HIT A WALL HEAD ON BETWEEN 33-35 MPH. THE AIR BAGS FAILED TO DEPLOY UPON IMPACT ALLOWING THE DRIVER TO HIT THE WINDSHIELD WITH HIS HEAD SHATTERING IT. GENERAL MOTORS SENT SOMEONE TO DIAGNOSE THE TRUCKS' CONDITION WHICH THE CONSUMER WAS TOLD "EXCEPTIBLE STANDARDS". PLEASE DESCRIBE DETAILS TS

CHEVROLET	TAHOE	2002	2003-12-04	HAD A FRONT END COLLISION INTO THE SIDE OF ANOTHER VEHICLE WHOM RAN A RED LIGHT. WE ESTIMATED OUR IMPACT SPEED AT 30 MPH UPON COLLIDING TOGETHER. NEITHER FRONT AIRBAGS DEPLOYED. SUFFERED NECK AND BACK BRUISING AND MUSCLE STRAIN.*AK
				ON JANURAY 23. 2004, I WAS REAR-ENDED ON THE FREEWAY. I WAS GOING ABOUT 65-70 MPH. A PERSON HIT ME FROM THE REAR, HE WAS TRAVELLING AROUND 100-110 MPH. I LOST CONTROL
				OF MY TAHOE, I WENT SIDEWAYS, THEN I SHOT FORWARD AND HIT THE CENTER DIVIDER(ON THE CENTER RIGHT SIDE OF MY CAR) AT ABOUT 65 MPH OR FASTER, I WAS SHOT BACKWARDS INTO A GUARD RAIL AND CAME OFF OF THAT AND THEN THE TAHOE ROLLED ON TO ITS SIDE, SKID FOR ABOUT 30 FEET AND THEN IT FINALLY STOPPED. MY AIR BAGS(FRONT NOR SIDE) NEVER DEPOLYED.
				I FEEL THAT IF THEY HAD MY WIFE NOR I WOULD HAVE BEEN INJURED. I KNOW THAT THEY ARE DESIGNED TO DEPLOY WHEN YOU HIT SOMETIME LIKE A BRICK WALL AT ABOUT 10-15 MPH. WHAT
CHEVROLET	TAHOE	2002	2004-01-23	DO YOU CALL HITTING A CEMENT DIVIDER AT OVER 65 MPH.*AK
				I WAS TRAVELING DOWN TO FREEWAY, DOING ABOUT 65-70 MPH. I WAS REAR ENDED BY A GUY GOING BETWEEN 100-110 MPH, I WAS THROWN OUT OF CONTROL. I HIT THE CENTER DIVIDER ALMOST HEAD ON AT ABOUT 70 MPH. I THEN BOUNCED OFF THE DIVIDER, CAME CLEAR AGCROSS ALL LANES AND HIT THE REAR GUARD RAIL, I BOUNDED OFF THAT AND ROLLED ON ITS SIDE. IN ALL
CHEVROLET	TAHOE	2002	2004-01-23	MY AIR BAGS NEVER DEPLOYED.*AK
				I WAS DRIVING MY 2002 TAHOE ABOUT 30-35 MPH WHEN I BLACKED OUT AND LOST CONTROL OF THE VEHICLE. I HIT A COLUMN OUTSIDE A HOTEL WHICH WAS ABOUT 2X2 FEET WITH STEEL WITHIN THE CENTER OF THE COLUMN. MY TRUCK WAS A TOTAL LOST AND THE FRONT AIRBAGS DID NOT
CHEVROLET	TAHOE	2002	2005-11-15	DEPLOY AS THEY WERE SUPPOSED TO. *JB
CHEVROLET	TAHOE	2002	2006-03-09	DT*: THE CONTACT STATED WHILE DRIVING 55 MPH, THE FRONT DRIVER SIDE TIRE HAD A BLOW OUT, CAUSING THE VEHICLE TO HIT BOTH GUARD RAILS WITH THE FRONT END. THE AIRBAGS DID NOT DEPLOY. ALTHOUGH THE SEATBELT WAS WORN, THE CONTACT SUSTAINED A CONCUSSION. THERE WAS A POLICE REPORT TAKEN AT THE SCENE. THE VEHICLE WAS TOWED TO AN AUTO BODY SHOP, WHERE IT WAS DEEMED A TOTAL LOSS BY THE INSURANCE COMPANY.
				ON MY WIFE'S WAY HOME FORM WORK SHE WAS INVOLVED IN AN ACCIDENT, WERE SHE REAR ENDED ANOTHER VEHICLE, THE CRASH WAS AT ABOUT 35 TO 45 MILES PER HOUR AND IT AFFECTED THE FRONT DRIVER SIDE OF OUR 2002 CHEVY TAHOE. THE IMPACT WAS SO SIGNIFICANT THAT THE FRAME OF THE TAHOE WAS BENT. THE CRASH PRETTY MUCH MIMICKED THE SAME OFF CENTER FRONT CRASH THAT THE INSURANCE INSTITUTE FOR HIGHWAY SAFETY CONDUCTS ON THEIR TESTING. THE PROBLEM WAS THAT THE FRONT AIRBAGS NEVER DEPLOYED ALTHOUGH THE ACCIDENT HAPPENED UNEXPECTEDLY, MY WIFE WAS WEARING HER SEAT BELT AND DIDN'T SUSTAINED SERIOUS INJURIES. OUR CONCERN IS THAT THE BAGS NEVER DEPLOYED AND THAT THEY MIGHT DEPLOY AT ANYTIME. THE AUTO BODY SHOP RECOMMENDED BY OUR INSURANCE COMPANY TOLD US THAT BECAUSE THE CRASH IMPACT WAS OFF CENTERED THE AIRBAG SENSOR WERE NEVER TRIGGERED. AFTER SEEING SO OF THE INSURANCE INSTITUTE FOR HIGHWAY SAFETY TEST THE BAGS SHOULD HAVE DEPLOYED. ALSO IT WAS DETERMINED THAT THE FRAME HAS TO BE REPLACED AND ALL THE BODY PARTS FIXED AND REPLACED. IF THE FRAME HAS TO BE REPLACED HOW SAFE WOULD THAT VEHICLE BE? I AM OPEN FOR ANY FARTHER CONVERSATIONS ABOUT
CHEVROLET	TARUE	2002	2000-03-24	THIS TOPIC. THANK YOU. *JB I WAS DRIVING MY 2002 CHEVY TAHOE, A GENTLEMAN RAN A STOP SIGN, I HIT HIM AT 39 MPH, HEAD ON IN MY TAHOE, T-BONED HIS TRUCK. NEITHER AIRBAG DEPLOYED, NOR DID MY SEATBELT KEEP ME FROM HITTING THE STEERING WHEEL AND MY HEAD KNOCKING ME OUT. GM SENT SOMEONE TO LOOK AT MY CAR WHICH HAS BEEN DEEMED A TOTAL LOSS. I HAVE YET TO HEAR BACK FROM GM ON THIS INCIDENT. I PURCHASED THIS CAR BRAND NEW THINKING IT WAS SAFE. THE ONE TIME I NEEDED MY SEATBELT TO WORK, IT FAILED. THE COMPUTER IN MY CAR SHOWED BOTH SEATBELTS WERE ON AND IN WORKING ORDER, IT SHOWED THE CRASH WAS AT 39 MPH YET THE AIRBAGS DID NOT DEPLOY AND THEY WERE IN PROPER WORKING ORDER. WHATEVER ANSWER GM GIVES ME WILL NOT BE GOOD ENOUGH UNLESS THEY ADMIT TO FAULTINESS IN THEIR
CHEVROLET	TAHOE	2002	2010-07-28	EQUIPMENT. *TR
CHEVROLET	TAHOE	2002	2012-04-08	REAR ENDED A VEHICLE GOING APPROX. 70 MPH AND HAD EXTENSIVE FRONT END DAMAGE HOWEVER THE AIR BAGS FAILED TO DEPLOY. DRIVER HIT HEAD ON STEERING WHEEL AND PASSENGER SUFFERED SEVER HEAD INJURY. *JS
CUE) 20 C E	TAUG-	2000		TRAFFIC STOPPED IN FRONT OF ME UNEXPECTEDLY, I SWERVED TO AVOID CAR IN FRONT OF ME AND HIT CONCRETE WALL. AIR BAGS DID NOT WORK. MY FACE HIT STEERING WHEEL, CAUSING
CHEVROLET		2002	2014-07-08	TL* THE CONTACT OWNS A 2002 CHEVROLET TAHOE. WHILE DRIVING 45 MPH, THE CONTACT'S VEHICLE WAS REAR ENDED BY ANOTHER VEHICLE. AND CRASHED INTO A GUARD RAIL. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED AND THE VEHICLE WAS DESTROYED. THE CONTACT'S HEAD STRUCK THE STEERING WHEEL AND HE WAS TRANSPORTED TO THE HOSPITAL BY AMBULANCE. THE CONTACT SUSTAINED SPINAL CORD AND NECK INJURIES. THE DOCTOR X-RAYED THE CONTACT AND DIAGNOSED HIM WITH BURNING PARESTHEGIC, HYPER-ESTHESIA, AND CENTRAL CORD SYNDROME. THE CONTACT WAS RELEASED FROM THE HOSPITAL TWO DAYS AFTER THE CRASH. THE FAILURE MILEAGE WAS 285,000.
	CHEVROLET CHEVROLET CHEVROLET CHEVROLET CHEVROLET CHEVROLET CHEVROLET	CHEVROLET TAHOE CHEVROLET TAHOE CHEVROLET TAHOE CHEVROLET TAHOE CHEVROLET TAHOE CHEVROLET TAHOE CHEVROLET TAHOE	CHEVROLET TAHOE 2002 CHEVROLET TAHOE 2002	CHEVROLET TAHOE 2002 2004-01-23 CHEVROLET TAHOE 2002 2004-01-23 CHEVROLET TAHOE 2002 2005-11-15 CHEVROLET TAHOE 2002 2006-03-09 CHEVROLET TAHOE 2002 2006-03-24 CHEVROLET TAHOE 2002 2010-07-28 CHEVROLET TAHOE 2002 2012-04-08 CHEVROLET TAHOE 2002 2013-02-14

	1	1	1		
					TL - THE CONTACT OWNS A 2002 CHEVROLET TAHOE. THE CONTACT STATED THAT WHILE THE DRIVER WAS DRIVING AT 45 MPH AND ATTEMPTED TO AVOID A CRASH WITH ANOTHER VEHICLE. AS A RESULT, THE DRIVER CRASHED INTO A GUARDRAIL AND THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT WAS TAKEN TO A HOSPITAL AND SUSTAINED INJURIES TO THE RIBS, THE COLLAR BONES, A BRAIN TRAUMA AND A COLLAPSED LUNG. THE DRIVER SUFFERED FROM FATAL INJURIES. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT
10641399	CHEVROLET	TAHOE	2002	2011-06-07	NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 73,000. DR
10667110	CHEVROLET	TAHOE	2002	2011-06-07	TL* THE CONTACT OWNS A 2002 CHEVROLET TAHOE. THE CONTACT STATED THAT THE DRIVER CRASHED INTO A GUARD RAIL AND THE AIR BAGS FAILED TO DEPLOY. THE DRIVER SUSTAINED MASSIVE HEAD TRAUMA, BROKEN RIBS AND BLEEDING FROM THE BRAIN, RESULTING IN A FATALITY. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE CONTACT WAS UNAWARE IF THE VEHICLE WAS DIAGNOSED OF THE FAILURE. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 72,000.
10668043	CHEVROLET	ТАНОЕ	2002	2014-11-07	TL* THE CONTACT OWNS 2002 CHEVROLET TAHOE. THE CONTACT STATED THAT WHILE DRIVING 45 MPH, ANOTHER VEHICLE CRASHED INTO THE CONTACT'S VEHICLE CAUSING THE VEHICLE TO SPIN AND BECOME UNCONTROLLABLE. IN ADDITION, ANOTHER VEHICLE CRASHED INTO THE VEHICLE CAUSING IT TO ROLL OVER SEVERAL TIMES BEFORE CRASHING INTO A GUARD RAIL. THE AIR BAGS FAILED TO DEPLOY. THE DRIVER SUSTAINED CRITICAL INJURIES AND THE FRONT PASSENGER SUSTAINED FATAL INJURIES. BOTH THE CONTACT AND FRONT PASSENGER REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 130,000.
10746088	CHEVROLET	ТАНОЕ	2002	2011-06-07	TL* THE CONTACT OWNED A 2002 CHEVROLET TAHOE. WHILE DRIVING AT APPROXIMATELY 45 MPH, THE CONTACT CRASHED INTO A GUARD RAIL. THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED A FRACTURED COLLAR BONE, SEVERAL BROKEN RIBS, HEAD TRAUMA, BRAIN BLEEDING, AND STROKES. THE CONTACT WAS PLACED INTO A MEDICALLY INDUCED COMA AND ON A RESPIRATORY MACHINE, BUT LATER DIED. THE VEHICLE WAS TOWED TO A SAVAGE YARD. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 73,000.
11382901	CHEVROLET	ТАНОЕ	2002	2020-11-17	TL- THE CONTACT OWNS A 2002 CHEVROLET TAHOE. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 25 MPH WHEN THE VEHICLE RAN ACROSS BLACK ICE CAUSING THE CONTACT TO LOSE CONTROL OF THE VEHICLE. THE VEHICLE BEGAN TO SPEND UNCONTROLLABLY EVENTUALLY CRASHING INTO A CONCRETE WALL WITH THE FRONT-END OF THE VEHICLE. NO AIR BAGS DEPLOYED. THE CONTACT RECEIVED INJURIES TO THEIR KNEE, SHOULDER, NECK, BACK, AND EYE. MEDICAL ATTENTION WAS NEEDED. A POLICE REPORT WAS FILED. THE VEHICLE TOWED AND DEEMED TOTALED. THE DEALER WAS NOT CONTACTED. THE MANUFACTURER WAS NOT MADE AWARE OF THE ISSUE. THE APPROXIMATE FAILURE MILEAGE WAS 150,000. GL
					WHILE DRIVING AT 45 MPH CONSUMER T-BONED ANOTHER VEHICLE HEAD ON AND NONE OF THE AIR BAGS DEPLOYED. CONTACTED DEALER, AND THE DEALER WAS AWARE OF THE PROBLEM, BUT
8017394	CHEVROLET	TRACKER	2002	2002-08-09	THEY HAD NO SOLUTION. *AK
10087309	CHEVROLET	TRACKER	2002	2004-07-20	WHILE DRIVING AT 40 MPH CONSUMER'S VEHICLE COLLIDED WITH THE LEFT SIDE OF ANOTHER VEHICLE RUNNING A STOP SIGN. CONSUMER WAS WEARING SEAT BELTS, BUT AIR BAGS DID NOT DEPLOY. CONSUMER AND A PASSENGER SUSTAINED VARIOUS BONE FRACTURES AND BRUISES. THE POLICE AND AN AMBULANCE DID ARRIVED ON THE SCENE.*AK
10264048	CHEVROLET	TRACKER	2002	2009-03-29	TL*THE CONTACT OWNS A 2002 CHEVROLET TRACKER. WHILE DRIVING AT AN UNKNOWN SPEED, THE VEHICLE LEFT THE ROAD, AND STRUCK A TREE WITH THE FRONT PASSENGER SIDE AND FENDER. THE FRAME WAS BENT IN TWO PLACES, BUT THE AIR BAGS FAILED TO DEPLOY. THERE WERE NO INJURIES. THE SEAT BELT WAS NEVER SERVICED AND WAS WORKING FINE PRIOR TO THE CRASH. A POLICE REPORT WAS FILED. THE FAILURE MILEAGE WAS 95,000.
		- Sites		00 25	AFTER A COLLISION WHERE MY TRACKER HIT ANOTHER VEHICLE AT AROUND 55 MPH ON A HIGHWAY, MY VEHICLE HIT DEAD ON TO THE SIDE OF ANOTHER (T-BONE) AND MY SENSOR
10970730	CHEVROLET	TRACKER	2002	2017-04-05	SHOULD HAVE TRIGGERED MY AIRBAGS AND DID NOT.
					WHILE BEING DRIVEN APPROXIMATELY 20 TO 25 MPH VEHICLE WENT OFF THE ROAD AND CRASHED INTO A LARGE OAK TREE. BOTH FRONTAL AIR BAGS FAILED TO DEPLOY DURING THE CRASH. BODY SHOP STATED THAT AIR BAGS SHOULD HAVE DEPLOYED DUE TO DAMAGE VEHICLE RECEIVED. DEALERSHIP HAS NOT EXAMINED VEHICLE TO DETERMINE IF THERE WAS A PROBLEM WITH THE AIR BAG SYSTEM. PLEASE PROVIDE ANY ADDITIONAL INFORMATION /
8002085	CHEVROLET	TRAILBLAZER	2002	2002-01-03	DOCUMENTATION.**AK
8010014	CHEVROLET	TRAILBLAZER	2002	2002-04-08	CONSUMER STATES THAT DURING A VEHICLE CRASH THE SIDE AIRBAG DID NOT DEPLOY.*JB WHILE TRAVELING ABOUT 40MPH THE VEHICLE WAS INVOLVED WITH A FRONTAL COLLISION.
8022437	CHEVROLET	TRAILBLAZER	2002	2002-11-01	NEITHER AIRBAG DEPLOY PLEASE PROVIDE ADDITIONAL INFORMATION. DEALER IS AWARE OF THE PROBLEM. TS
10011300	CHEVROLET	TRAILBLAZER	2002	2002-11-01	THE VEHICLE WAS INVOLVED IN A COLLISION, AND THE AIR BAGS DID NOT DEPLOY.*JB
10013030	CHEVIDOLET	TDAILDI AZED	2002	2002.02.40	HYDROPLANED HEAD ON INTO A TREE DOING ABOUT 40 MPH. HIT THE TREE HARD ENOUGH TO BREAK THE ENGINE MOUNTS AND SHIFT THE ENGINE FORWARD INTO THE FAN, PLUS SOME TRANSMISSION DAMAGE. THE AIR PAGS DID NOT DEDLOY. *NI M.
10013828	CHEVKULET	TRAILBLAZER	2002	2003-03-19	TRANSMISSION DAMAGE. THE AIR BAGS DID NOT DEPLOY. *NLM

	1		1	1	ON FED ETH 2002 LIDEAR FAIDER A CTORDER VEHICLE WHILL COINC AS MILEC AN HOLIR MAY CHIN
					ON FEB 5TH, 2003 I REAR ENDED A STOPPED VEHICLE WHILE GOING 45 MILES AN HOUR. MY CHIN HIT THE STEERING WHEEL BUT NO AIRBAG DEPLOYED. THE BODY SHOP WAS UNABLE TO
10014453	CHEVROLET	TRAILBLAZER	2002	2003-02-05	DETERMINE WHY THE AIR BAG DID NOT DEPLOY. *NLM
					CONSUMER WAS HIT TWICE IN A SIDE AND FRONTAL COLLISION WHILE TRAVELING
10015367	CHEVROLET	TRAILBLAZER	2002	2003-04-02	APPROXIMATELY 30MPH. NEITHER THE FRONTAL OR SIDE AIR BAGS DEPLOYED. *NLM
					THE VEHICLE WAS INVOLVED IN A COLLISION, AND THE AIR BAGS FAILED TO DEPLOY. *AK THE
10027280	CHEVROLET	TRAILBLAZER	2002	2003-07-12	CONSUMER SUFFERED INJURIES. *JB
					WHILE CONSUMER WAS DRIVING 25-28 MPH VEHICLE WAS T-BONED FROM ANOTHER VEHICLE AT
10044550	CHEVROLET	TRAILBLAZER	2002		ESTIMATED SPEED OF 30 MPH. UPON IMPACT, FRONTAL AIR BAGS FAILED TO DEPLOY. *AK
2001.000	CHETHOLE		2002		VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WHILE DRIVING BETWEEN 50-55MPH. UPON
					IMPACT, THE AIR BAGS FAILED TO DEPLOY. AS A RESULT, DRIVER SUSTAINED CHEST INJURIES
10113109	CHEVROLET	TRAILBLAZER	2002	2004-12-12	WHEN IT IMPACTED THE STEERING WHEEL.*AK
10114818	CHEVROLET	TRAILBLAZER	2002	2005-03-24	CRASH AT 35 MPH (FRONT END SQUARE) DRIVER AND PASSENGER AIR BAGS FAILED TO DEPLOY.
10114616	CHEVROLET	TRAILBLAZER	2002	2003-03-24	DURING A 30 MPH VEHICLE FRONTAL COLLISION FRONT AIR BAGS DID NOT DEPLOY. CONSUMER
					SUSTAINED MINOR INJURIES. THE VEHICLE WAS TOWED. DEALERSHIP WAS NOTIFIED, BUT DID NOT
					RESOLVE THE PROBLEM. *AKPROBLEM WA SDISCUSSED WITH THE DEALER IN DETAIL BUT DID
10115232	CHEVROLET	TRAILBLAZER	2002	2005-02-09	NOT KNOW HOW TO RESOLVE PROBLEM. *AK
					WHILE DRIVING SE COMPLETE WE AN CHILD THAT DROVE WERE AN CHILD THAT DROVE WERE
					WHILE DRIVING 55-60 MPH, VEHICLE HIT AN SUV THAT DROVE INTO LANE. VEHICLE THEN HIT BY TRACTOR TRAILER. VEHICLE CRASHED WITH GREAT FORCE INTO HIGHWAY DIVIDER AND LOST
					FRONT LEFT WHEEL, CAUSING VEHICLE TO CONTINUE TO CRASH ALONG DIVIDER, BOTH FRONT
					AIRBAGS AND BOTH SIDE AIRBAGS FAILED TO DEPLOY. PASSENGER IN VEHICLE SUSTAINED
					FRACTURES TO ORBITAL BONES AND MAXILLARY BONE IN SKULL. MAJOR RECONSTRUCTIVE
10118790	CHEVROLET	TRAILBLAZER	2002	2005-04-22	SURGERY WAS REQUIRED. THE VEHICLE WAS DETERMINED TO BE A TOTAL LOSS.
					DT: AIR BAG DID NOT DEPLOY IN A OFF CENTER FRONTAL COLLISION. WHILE TRAVELING ABOUT
					35-40 MPH CONSUMER'S VEHICLE HIT THE REAR OF ANOTHER VEHICLE. IT WAS AT A GARAGE
					NEAR THE ACCIDENT SITE. NO ONE LOOKED AT THE VEHICLE BUT THE RESCUE SERVICES WERE SURPRISED THAT THE AIRBAGS DID NOT DEPLOY. INTERMITTENTLY THE SRS LIGHT WOULD COME
10122088	CHEVROLET	TRAILBLAZER	2002	2005-05-24	ON. TOOK VEHICLE TO DEALER AND IT WAS REPAIRED IN JULY 2004. *AK *JB
10122000	OHE VIIOLE I	TTO TIEDES TEET	2002	2005 05 2 .	
					DT: CONSUMER'S VEHICLE WAS INVOLVED IN AN ACCIDENT ON SEPTEMBER 15, 2005. UPON
					IMPACT, NONE OF THE AIR BAGS DEPLOYED. BACK IN SEPTEMBER OF 2002 CONSUMER'S WAS
					INVOLVED IN A HEAD ON COLLISION WITH THIS SAME VEHICLE, AND THE AIR BAGS NEVER
10136929	CHEVROLET	TRAILBLAZER	2002	2005-09-15	DEPLOYED AT THAT TIME EITHER. HAD THE VEHICLE REPAIRED AT THE GMC DEALERSHIP. *AK
					DT: THE CONTACT STATED VEHICLE WENT OFF THE ROAD AND HIT TREES AT 50-55 MPH. UPON
					IMPACT, THE AIRBAGS DID NOT DEPLOY. THE VEHICLE WAS TOTALED. THE FRONT END
					COLLAPSED, THE ENGINE WAS IN THE FIREWALL, AND THE BODY WAS PUSHED OFF OF THE FRAME.
					THE CONTACT SUSTAINED MINOR BRUISES AND ABRASIONS. A POLICE REPORT WAS TAKEN AT
10144322	CHEVROLET	TRAILBLAZER	2002	2005-11-08	THE SCENE. THE DEALERSHIP STATED THEY HAVE NEVER HEARD OF THIS HAPPENING. *AK
					DT*: THE CONTACT STATED WHILE TRAVELING 35 MPH WITH PRIOR BRAKING, THE VEHICLE
					VEERED OFF THE ROAD AND SLID INTO A DITCH. THERE WAS FRONT END DAMAGE; THE FRAME RAIL AND HOOD BENT. THE AIRBAGS DID NOT DEPLOY WHEN THIS OCCURRED. THE CONTACT WAS
					NOT IN THE VEHICLE AND THE DRIVER WAS UNAWARE OF WHAT CAUSED THE VEHICLE TO VEER
					OFF THE ROAD. THE DRIVER SUSTAINED HEAD TRAUMA AND THE SEAT BELT WAS NOT WORN.
					THERE WAS A POLICE REPORT TAKEN AT THE SCENE. THE VEHICLE WAS TOWED TO AN
					INDEPENDENT REPAIR SHOP, BUT HAS NOT BEEN INSPECTED BY A MECHANIC. UPDATED
10157599	CHEVROLET	TRAILBLAZER	2002	2006-05-15	06/16/06. *JB
					DT*: THE CONTACT STATED WHILE DRIVING 40 MPH ON A GRAVEL ROAD, CONTROL OF THE
					VEHICLE WAS LOST AND IT CRASHED INTO A TREE HEAD ON. THE AIR BAGS DID NOT DEPLOY.
					THERE WAS NO PRIOR BRAKING AND SEAT BELTS WERE WORN. THE DRIVER SUSTAINED MINOR INJURIES. THE VEHICLE WAS LATER TOWED TO AN INDEPENDENT REPAIR SHOP. THE DEALER WAS
10172513	CHEVROLET	TRAILBLAZER	2002	2006-07-01	ALERTED.
					TL*THE CONTACT OWNS A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 15
					MPH, THE CONTACT STRUCK A PATCH OF ICE AND THE VEHICLE CRASHED INTO A LIGHT POLE. THE
40254222	CUEVE CO	TD 4 II D: 475	2002	2000 01 00	VEHICLE WAS COMPLETELY DESTROYED AND NONE OF THE AIR BAGS DEPLOYED. A POLICE REPORT
10254230	CHEVROLET	TRAILBLAZER	2002	2009-01-08	WAS FILED AND THERE WERE NO INJURIES. THE FAILURE AND CURRENT MILEAGES WERE 56,000.

	1			1	T
10257808	CHEVROLET	TRAILBLAZER	2002	2009-01-21	WELL SERVICED 90K MILES. TRAVELING AT 35MPH PUSHED BREAKS ALL THE WAY DOWN (FRACTURING RIGHT ANKLE) SLOWED ME DOWN BUT FAILED TO STOP AT UPCOMING RED LIGHT. STRUCK MEDIUM SIZE VEHICLE INJURING OTHER DRIVER AND CAUSING CONSIDERABLE DAMAGE TO BOTH VEHICLES. CHEVY DEALER COLLISION/SERVICE CENTER ESTIMATED \$8K IN REPAIRS. IN OTHER WORDS IT COSTS MORE TO REPAIR IT THAN WHAT THE VEHICLE IS WORTH. ALSO: "MASTER CYLINDER IS BAD" AND AIR BAGS DID NOT DEPLOY. CHEVY TECH. SAID "IMPACT WAS NOT BIG ENOUGH". AFTER READING SOME EIGHT OTHER COMPLAINTS VERY SIMILAR TO THIS. I AM CONCERNED ABOUT DRIVING THIS OR GETTING INTO ANOTHER ONE. IS THERE NOT A BREAK LIGHT SERVICE SENSOR THAT I SHOULD HAVE NOTED.? SERVICE MANUAL FOR SCHEDULED MAINTENANCE SAYS TO CHECK FRONT AND REAR AXLE FLUID AND ADD FLUID AS NEEDED EVERY 5K TO 7K MILES AFTER 67.5K MILES. *TR
					I WAS IN A CAR ACCIDENT, WHERE I WAS TRAVELING AT ABOUT 35 MPH. AN AGGRESSIVE DRIVER
10263896	CHEVROLET	TRAILBLAZER	2002	2009-03-26	SPEED AROUND ME AND CUT ME OFF AND THAN STOMPED ON THIS BRAKES IN FRONT OF ME. DUE TO THAT I SWERVED TO MISS HIM CLIPPING HIS RIGHT BACK LIGHT AD BUMPER WITH MY LEFT HEADLIGHT AND BUMPER. AS I WAS SWERVING I HIT A TREE JUST ABOUT DEAD ON WITH MY AR. THE MAJORITY OF THE IMPACT OCCURRED JUST ABOUT 6 INCHES TO THE LEFT (IF LOOKING AT THE CAR) OF THE CENTER OF THE FRONT OF THE CAR. I HIT THE TREE AT A SPEED OF ABOUT 28-30 MPH. AFTER INITIAL IMPACT I WAS RUSHED TO THE HOSPITAL DUE TO UNCONSCIOUS AND FACIAL CONTUSIONS. DURING THE FIRST MOMENTS AFTER THE ACCIDENT, ONE OF THE FIRST THINGS OFFICERS, EMTS AND WITNESSES SAID WAS "I CAN'T BELIEVE THE AIRBAGS DIDN'T GO OFF". IN THE RECENT DAYS AFTER THE ACCIDENT I HAVE HAD SEVERAL MECHANICS AND SUCH APPRAISE THE CAR, THE ONE COMMON THEME THEY ALL SHARE IS THAT THEY SUSPECT THERE MIGHT NOT BE AN AIRBAG WHERE IT BELONGS. OR THE LACK THERE OF. *TR
10294686	CHEVROLET	TRAILBLAZER	2002	2009-11-20	HIT HEAD ON BY ANOTHER CAR TOTALING MY CAR, AIRBAGS DID NOT DEPLOY. *TR
10314643	CHEVROLET	TRAILBLAZER	2002	2010-01-07	INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6) I WAS TRAVELING SOUTHBOUND ON KY HWY 1531 (EASTWOOD FISHERVILLE RD). WHEN I APPROACHED A SHARP CURVE IN THE ROADWAY, I OBSERVED A HONDA ODYSSEY MINIVAN TRAVELING NORTHBOUND TOO FAST FOR THE ICY, SNOWY ROAD CONDITIONS. THE MINIVAN DRIVER LOST CONTROL OF HER VEHICLE AND STRUCK MY 2002 TRAILBLAZER HEAD-ON IN THE SOUTHBOUND LANE. AT THE TIME OF IMPACT, MY TRAILBLAZER WAS COMPLETELY STOPPED WITH MY RIGHT FOOT PRESSED FIRMLY ON THE BRAKE PEDAL. THE HONDA ODYSSEY AIRBAGS FULLY DEPLOYED. MY TRAILBLAZERS AIRBAGS DID NOT DEPLOY. BOTH VEHICLES WERE TOTAL LOSS. MY TRAILBLAZER WAS TOWED TO GM REPAIR SHOP BAUCHMAN CHEVROLET IN LOUISVILLE KY. IT REMAINS STORED IN ITS ORIGINAL POST-ACCIDENT CONDITION. I HAVE RETAINED OWNERSHIP TITLE OF THIS VEHICLE. GM REPAIR SHOP NOTED EXTENSIVE FRAME DAMAGE AND BROKEN AIRBAG SENSOR. THIS IS THE SECOND FRONT END INJURY CRASH INVOLVING THIS TRAILBLAZER WHERE THE AIRBAGS FAILED TO DEPLOY. SEE ALSO ODI CASE # 10314629. GM WAS NOTIFIED OF INCIDENT AND AGAIN I OPENED AN INVESTIGATION WITH GM AS TO WHY THE AIRBAGS FAILED TO DEPLOY. AS OF THIS DATE (2/26/2010) GM INVESTIGATORS HAVE NOT INSPECTED THE VEHICLE. (GM CASE [XXX]). I SUFFERED LOW BACK INJURIES AS A RESULT OF THIS ACCIDENT. THIS INJURY OCCURRED 8 WEEKS AFTER SPINAL FUSION SURGERY. I HAVE BEEN IN PHYSICAL THERAPY SINCE THE ACCIDENT FOR JOINT DAMAGE IN THE SACRAL ILLIUM AREA. *TR
					TL*THE CONTACT OWNS A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 70 MPH THE VEHICLE WAS INVOLVED IN A CRASH IN WHICH THE AIR BAGS DID NOT DEPLOY. A POLICE REPORT WAS FILED. THE CONTACT WAS INJURED. THE VEHICLE WAS DESTROYED AND TOWED TO AN INDEPENDENT REPAIR SHOP. THE MANUFACTURER EXAMINED THE VEHICLE BUT DID NOT INFORM THE CONTACT OF THE CAUSE OF FAILURE; HOWEVER, THEY DID OFFER HIM A
10343917 10378297	CHEVROLET	TRAILBLAZER TRAILBLAZER	2002	2009-12-04	SETTLEMENT. THE FAILURE AND CURRENT MILEAGES WERE 150,000. THE VIN WAS UNAVAILABLE. AIRBAGS DIDN'T DEPOLY AND ROOF CAVED. *TR
10386658		TRAILBLAZER		2007-03-06	TL* THE CONTACT OWNS A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 70 MPH IN RAINY WEATHER, THE CONTACT DROVE OVER A PUDDLE OF WATER AND LOST CONTROL OF THE VEHICLE. SHE THEN ENGAGED THE BRAKES AND THE VEHICLE SWERVED ABNORMALLY. THE VEHICLE SPUN AROUND AND CRASHED INTO THE OUTER MEDIAN. THE AIR BAGS DID NOT DEPLOY AND THE CONTACT SUSTAINED A SHOULDER INJURY. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE APPROXIMATE FAILURE MILEAGE WAS 152,000.
					I WAS DRIVING AND A GUY IN A CAR CAME OVER IN MY LANE AND HIT ME HEAD ON CAUSING ME TO FLIP MY VEHICLE 4 TIMES, MY AIRBAGS DIDN'T COME OUT AND THE GUY THAT HIT ME WAS
10587773	CHEVROLET	TRAILBLAZER	2002	2014-05-10	UNDER THE INFLUENCE, MY VEHICLE WAS TOTALED. *TR

_	_	1	1	1	
10626676	CHEVROLET	TRAILBLAZER	2002	2008-03-10	I STRUCK A VEHICLE THAT BROADSIDE WHEN HE RAN A STOP SIGN. I WAS GOING APPROXIMATELY 30 TO 35 MPH WHEN I STRUCK HIS VEHICLE. THE AIR BAGS DID NOT DEPLOY. I WAS TAKEN AWAY IN AN AMBULANCE AND HAD DAMAGE TO MY CERVICAL SPINE, STOMACH AND MID SPINE. I DID INQUIRE WHERE I HAD THE VEHICLE REPAIRED, ABOUT \$8K IN DAMAGES, ABOUT WHY THE AIRBAGS DIDN'T DEPLOY. THEY SAID THEY DIDN'T KNOW BUT CHECKED AND SAID THE AIRBAG SYSTEM WAS FUNCTIONING? I SEE MANY SUCH "STORIES" ABOUT TRAILBLAZER AIRBAGS NOT DEPLOYING ON THIS SITE. IT REALLY BE NICE TO SEE SOMETHING DONE ABOUT THIS SITUATION. THIS VEHICLE HAS BEEN IN SEVERAL WRECKS AND THE AIRBAGS HAVE NEVER DEPLOYED!!!!! NOTE, I HAVE WRITTEN TO CHEVROLET/GM ABOUT THIS ISSUE BUT DON'T REALLY EXPECT THEM TO RESPOND! SOME SUPPORT FROM THE NHTSA WOULD REALLY BE APPRECIATED AND IS NEEDED BEFORE ANYONE ELSE GET HURT WHEN THE AIRBAGS DON'T DEPLOY! *TR
40750046	CUENTIOLET		2002	2044 40 45	TL* THE CONTACT OWNED A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 15 MPH ON A RAINY ROAD, THE CONTACT CRASHED INTO ANOTHER VEHICLE AND THE AIR BAGS FAILED TO DEPLOY. THE CONTACT SUSTAINED A HEAD INJURY THAT REQUIRED MEDICAL ATTENTION. THE DRIVER AND PASSENGER OF THE OTHER VEHICLE SUSTAINED UNKNOWN INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS DESTROYED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE AND VIN
10761168	CHEVROLET	TRAILBLAZER TRAILBLAZER	2002	2014-10-15	WERE UNAVAILABLE. TL* THE CONTACT OWNS A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 10 MPH ON AN INCLINE DURING INCLEMENT WEATHER CONDITIONS, THE CONTACT'S VEHICLE VEERED INTO ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. THERE WERE NO WARNING INDICATORS ILLUMINATED. THE MANUFACTURER WAS NOT MADE AWARE OF THE ISSUE. A POLICE REPORT WAS FILED. THE CONTACT SUFFERED A HEAD CONCUSSION THAT REQUIRED MEDICAL ATTENTION. THE FAILURE MILEAGE WAS NOT PROVIDED.
					THE VEHICLE WAS INVOLVED IN A HEAD ON CRASH INTO A TELEPHONE POLE AND THE AIR BAGS DID NOT DEPLOY. THE FRONT SEAT PASSENGER WAS INJURED AND THE DRIVER STRUCK THE STEERING WHEEL AND DIED AT THE HOSPITAL FROM INTERNAL INJURIES. WE ARE TRYING TO DETERMINE WHY THE AIRBAGS DID NOT DEPLOY. THE PASSENGER WAS NOT WEARING A SEAT
10825823	CHEVROLET	TRAILBLAZER	2002	2016-01-09	BELT AND IT ALSO APPEARS THAT THE DECEASED DRIVER WAS NOT WEARING A SEAT BELT.
10872510	CHEVROLET	TRAILBLAZER	2002	2016-05-26	DRIVING APPROXIMATELY 30 MILES PER HOUR, WOMAN PULLED OUT IN FRONT OF ME TO TURN ONTO THE FREEWAY. A VEHICLE NEXT TO ME HONKED THEIR HORN AND MISSED HITTING HER BUT I HIT HER ON THE PASSENGER REAR PANEL OF HER CAR, DAMAGING HER VEHICLE AND BENDING THE REAR TIRE AT AN ANGLE. THE AIRBAG DID NOT DEPLOY AND WAS ON. I WAS TRAVELING ON A CITY STREET, GOING WESTBOUND, THE OTHER DRIVER WAS TURNING TO GO NORTHBOUND.
10899776	CHEVROLET	TRAILBLAZER	2002	2016-08-29	TL* THE CONTACT OWNS A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 25 MPH, THE CONTACT'S VEHICLE CRASHED INTO A BUS AND SUSTAINED SIGNIFICANT DAMAGE TO THE FRONT END. THE AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS TOWED. THE DRIVER SUSTAINED INJURIES TO THE NECK, HEAD, TORSO, AND A DISLOCATED FINGER. MEDICAL ATTENTION WAS REQUIRED. A POLICE REPORT WAS FILED. THE CAUSE OF THE FAILURE WAS NOT DIAGNOSED. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 122,000.
10957467	CHEVROLET	TRAILBLAZER	2002	2017-02-26	MY WIFE WAS IN A HEAD ON COLLISION WHERE SHE HIT A TREE GOING APPROXIMATELY 45 MILES AN HOUR. SHE WAS ON A COUNTY ROAD AND LOST CONTROL OF THE VEHICLE, HITTING THE TREE ON PRIVATE PROPERTY. THE AIRBAGS DID NOT DEPLOY, WHEN THEY SHOULD HAVE. SHE HIT HER HEAD ON THE STEERING WHEEL AT IMPACT. I HAVE UPLOADED PICTURES OF THE DAMAGE TO THE VEHICLE AND A PICTURE SHOWING THE AIRBAGS DID NOT DEPLOY.
11042967	CHEVROLET	TRAILBLAZER	2002	2016-11-22	TL* THE CONTACT OWNED A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING APPROXIMATELY 60 MPH, THE CONTACT SWERVED TO AVOID ANOTHER VEHICLE AND CRASHED INTO A MEDIAN FACING ONCOMING TRAFFIC. THE VEHICLE FLIPPED OVER EIGHT TIMES AND LANDED IN A DITCH ON THE OPPOSITE SIDE OF THE HIGHWAY. THE AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS TOWED AND DEEMED TOTALED. A POLICE REPORT WAS FILED. THE CONTACT PASSED OUT AND RECEIVED INJURIES TO THE HEAD, NECK, BACK, AND SHOULDER. MEDICAL ATTENTION WAS REQUIRED. THE DEALER WAS NOT CONTACTED. THE VEHICLE WAS INCLUDED IN NHTSA CAMPAIGN NUMBER: 04V201000 (SEAT BELTS). THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 100,000.

			I	1	1
11289369	CHEVROLET	TRAILBLAZER	2002	2019-11-29	TL* THE CONTACT OWNED A 2002 CHEVROLET TRAILBLAZER. WHILE DRIVING AND TURNING, THE VEHICLE HYDROPLANED AND STRUCK A CONCRETE WALL HEAD ON. THE VEHICLE THEN VEERED TO THE LEFT AND STRUCK THE CENTER DIVIDER TWICE. THE AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS TOTALED AND TOWED. MOST OF THE DAMAGE WAS TO THE FRONT END OF THE VEHICLE AND THE DRIVER'S DOOR COULD NOT BE CLOSED. THE DRIVER SUSTAINED BRUISES WHERE THE SEAT WAS LOCATED. THE DRIVER WAS TRANSPORTED TO THE EMERGENCY ROOM FOR MEDICAL ATTENTION. THE DRIVER'S FACE WAS BRUISED AND A CAT SCAN WAS PERFORMED TO DETERMINE IF THERE WERE ANY BROKEN BONES, BUT THE TESTS WERE NEGATIVE. THE DRIVER ALSO TWISTED HER ANKLE AND THERE WAS A LITTLE BIT OF SWELLING ON HER KNEE. A POLICE REPORT WAS FILED. THE MANUFACTURER WANTED TO VISIT THE CONTACT'S HOME TO EXAMINE THE VEHICLE AND FIND OUT WHY THE AIR BAGS DID NOT DEPLOY. THE DEALER WAS NOT CONTACTED. THE CAUSE OF THE FAILURE WAS NOT DETERMINED. THE FAILURE MILEAGE WAS UNKNOWN.
F644F1	CMC	ENIVOV	2002	2001 01 12	SENDING THE VEHICLE OFF THE ROAD HITTING A STONE RETAINING WALL HEAD ON, NEITHER
566612	GMC GMC	ENVOY	2002	2001-01-13	PASSENGER NOR DRIVERS SIDE AIR BAGS DEPLOYED. NLM ALL OF THE EIGHT (8) AIR BAG EQUIPPED IN THE VEHICLE FAILED TO DEPLOY DURING FRONTAL IMPACT, ALTHOUGHT PROPERLY RESTRAINED THE CONSUMER STILL SUSTAINED SERIOUS INTERNAL INJURIES, INCLUDING A LACERATED LIVER.(ATTORNEY ON BEHALF OF CLIENTO NLM
					VEHICLE WAS INVOLVED IN FRONTAL COLLISION WITH POINT OF IMPACT JUST A LITTLE LEFT OF THE CENTER BUMPER. FRONT END, INCLUDING FRAME WAS TOTALLED. UPON IMPACT, NEITHER
8016732	GMC	ENVOY	2002	2002-07-17	AIR BAGS DEPLOYED. PLEASE DESCRIBE DETAILS. *AK
					CONSUMER COLLIDED IN THE REAR OF A TRACTOR TRAILER TRAVELLING APPROXIMATELY 60-
8023505	GMC	ENVOY	2002	2002-11-22	70MPH. BOTH THE DRIVER AND PASSENGER AIR BAGS DID NOT DEPLOY. TS
10002513	GMC	ENVOY	2002		WHILE TRAVELING AT 70 MPH ANOTHER VEHICLE WAS TRAVELING EAST BOUND CROSSED CONSUMERS PATH UNEXPECTANTLY, CAUSING CONSUMER TO HIT A TREE. CONSUMER STATES NONE OF THE AIRBAGS DEPLOYED. PLEASE PROVIDE ANY FURTHER INFORMATION.*JB
					CONSUMER LOST CONTROL OF VEHICLE AND HIT A LEDGE, AND NONE OF THE AIR BAGS DEPLOYED.
10000300	CMC	ENIVOV	2002	2003-02-21	*JB THE DEALER STATED THAT IF THE VEHICLE HIT 6 INCHES TO THE RIGHT, THEN THE AIR BAGS
10009390	GMC	ENVOY	2002	2003-02-21	WOULD HAVE DEPLOYED. *SCC WHILE DRIVING 50 MPH VEHICLE WAS INVOLVED IN A FRONTAL COLLISION, BUT AIR BAGS DID NOT
10029726	GMC	ENVOY	2002	2003-07-03	DEPLOY. DEALER NOTIFIED.*AK
10029894	GMC	ENVOY	2002	2003-07-15	CONSUMER STATED WHILE SHE AND HER HUSBAND WERE TRAVELING ON THE HIGHWAY AT APPROXIMATELY 40-50 MPH, THE VEHICLE IN FRONT OF THEM DECIDED TO MAKE A QUICK TURN, WHICH CAUSED HER HUSBAND TO HIT THE VEHICLE IN THE SIDE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. BOTH SHE AND HER HUSBAND SUSTAINED INJURIES. HIS KNEES WENT INTO THE DASH AND HE WAS SORE FROM HEAD TO TOE. THIS IMPACT CAUSED HER HEAD TO SNAP BACK, RESULTING IN A CHEST WALL INJURY/A STIFF NECK, AND BACK. THIS WAS A MALFUNCTION BECAUSE THE AIR BAGS SHOULD HAVE DEPLOYED BECAUSE OF THE RATE OF SPEED. *AK *CB THE CONSUMER ALSO FELT THE SEAT BELT DID NOT REALLY PERFORM AS DESIGNED. *JB
10063773	GMC	ENVOY	2002	2004-03-21	2002 GMC ENVOY SER#(XXX) AIR BAGS DID NOT DEPLOY DRIVER TAKEN BY LIFESTAR TO HARTFORD HOSPITAL THE WHOLE LEFT SIDE OF THE VEHICLE WAS CAVED IN ALL THE WAY TO THE FRONT SEAT. *NM UPDATED 07/30/2012 *JS INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)
10075683	GMC	ENVOY	2002	2004-05-14	WHILE DRIVING 30 MPH, THE CONSUMER WAS INVOLVED IN AN EIGHT VEHICLE PILE UP. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. AS A RESULT, THE DRIVER SUSTAINED SEVERE BACK AND LEG INJURIES. *AK *SC
10079342	GMC	ENVOY	2002	2004-06-16	WHILE DRIVING 55 MPH DRIVER APPLIED THE BRAKES TO SLOW DOWN THE SPEED AND CONSUMER LOST CONTROL, CAUSING THE VEHICLE TO HIT A GUARD RAIL AND ROLL OVER THREE TIMES. VEHICLE LANDED UPSIDE DOWN. UPON IMPACT, THE AIRBAG DID NOT DEPLOY, AND SEAT BELT DID NOT HOLD THE PASSENGER. *AK
10000336	GMC	ENVOY	2002	2004-11-01	AFTER BEING STRUCK HEAD ON BY A SEMI TRAILER AT 40 MPH AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS TOTALED.*AK
10101068	GMC	ENVOY	2002	2004-11-01	WHILE DRIVING 20 MPH CONSUMER'S VEHICLE COLLIDED WITH THE VEHICLE IN FRONT. UPON IMPACT, BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. DRIVER TO SUSTAINED MINOR INJURIES, AND WAS TRANSPORTED TO A HOSPITAL. THE VEHICLE WAS TOWED TO THE DEALER FOR INSPECTION. *AK
10129259	GMC	ENVOY	2002	2005-07-18	I WAS TRAVELLING AT APPROXIMATELY 35MPH AND AS I WAS HEADING TOWARD A SIGNAL LIGHT WHEN A VAN TURNED LEFT IN THE OPPOSITE DIRECTION OF TRAVEL. MY VEHICLE'S FRONT END STRUCK THE VAN'S PASSENGER SIDE DOOR. AIR BAGS DID NOT DEPLOY UPON IMPACT ALTHOUGH VAN'S BOTH FRONTAL AIR BAGS DID DEPLOY.MY FACE HIT THE STEERING WHEEL AND KNEES HIT THE BOTTOM OF THE DASHBOARD. PASSENGER WAS ALSO BRUISED ON KNEES

GMC	ENVOY	2002	2007-12-05	TL*THE CONTACT OWNS A 2002 GMC ENVOY. WHILE DRIVING 20 MPH UPHILL IN ICY WEATHER, THE VEHICLE SLID OFF THE ROAD. NONE OF THE AIR BAGS DEPLOYED AND THE VEHICLE WAS COMPLETELY DESTROYED. THE PASSENGER WAS SEVERELY INJURED. THE CONTACT FILED A FORMAL COMPLAINT WITH THE MANUFACTURER. HE HAS A COPY OF THE POLICE REPORT. THE CURRENT AND FAILURE MILEAGES WERE 115,000. UPDATED 01/07/08 *BF UPDATED *JB
				MY WIFE AND I WERE HEADED SOUTHBOUND ON 685 IN ROUND ROCK, TX IN OUR 2002 GMC ENVOY AT APPROX. 9:35 PM WHEN A DRIVER IN A MINI VAN RAN A RED LIGHT AT THE INTERSECTION OF 685 AND GATTIS SCHOOL RD. OUR VEHICLE STRUCK THEM IN THE REAR PASSENGER QUADRANT. THE SPEED LIMIT IS 60 MPH AT THIS INTERSECTION AND WE DID NOT
				HAVE TIME TO BRAKE. EVEN THOUGH THE FRONT OF OUR VEHICLE WAS CRUSHED INTO THE ENGINE COMPARTMENT, NO AIRBAGS DEPLOYED. MY WIFE, WHO IS IN THE HABIT OF WEARING HER SEATBELT (ALTHOUGH WE STILL CANNOT CONFIRM ONE WAY OR THE OTHER) STRUCK THE REAR VIEW MIRROR WITH HER HEAD WITH ENOUGH FORCE TO BREAK A HOLE IN THE WINDSHIELD
				WHERE IT WAS ATTACHED AND BREAK THE WINDSHIELD AROUND IT. SHE WAS TRANSPORTED TO THE HOSPITAL WITH A CONCUSSION AND HAD FOR A TIME GONE INCOHERENT AND UNRESPONSIVE WITH SHORT TERM MEMORY LOSS. SHE HAS HAD DAILY HEADACHES SINCE WITH SOME EXTREMELY SEVERE. SHE ALSO HAD MULTIPLE SEVERE CONTUSIONS DOWN HER LEFT SIDE,
				PARTICULARLY IN HER UPPER LEFT THIGH WITH A LARGE HEMOTOMA THAT IS STILL GIVING HER PROBLEMS. OUR VEHICLE WAS SUBSEQUENTLY TOTALED BY THE INSURANCE COMPANIES. WE HAVE CONTACTED GM ABOUT THE FAILURE OF THE AIRBAGS TO DEPLOY AND THEY ARE CURRENTLY INVESTIGATING AND SENT AN INVESTIGATOR TO DOWNLOAD THE COMPUTER
GMC	ENVOY	2002	2008-10-03	INFORMATION LAST WEEK. THERE IS A POLICE REPORT THAT WAS FILED BY THE TEXAS DPS INVESTIGATING OFFICER. *TR
GMC	ENVOY	2002	2011-11-16	CAR HAD A HEAD ON COLLISION WITH ANOTHER CAR THAT JUMP FROM THE OPPOSITE TRAFFIC. BOTH CARS WERE TOTALED BECAUSE OF THIS ACCIDENT, BUT MY AIRBAGS DID NOT DEPLOY AT THE TIME OF THE ACCIDENT. *KB
				MY SON (17) WAS COMING HOME AND CRASHED INTO A LIGHT POLE, WE DON'T KNOW WHAT CAUSED HIM TO CRASH NO ALCOHOL OR DRUGS WERE INVOLVED AND THE AIRBAGS DID NOT DEPLOYHE WAS TRAPPED IN THE CAR AND DIED FROM BLUNT FORCE TRAUMA TO THE HEAD.
GMC	ENVOY	2002	2013-07-07	*TR
GMC	ENVOY	2002	2014-06-28	I AND MY PASSENGER WERE IN AN ACCIDENT ABOUT A YEAR AGO, A VERY HARD FRONT END IMPACT, AND NONE OF THE AIR BAGS DEPLOYED. WE WERE BOTH TRANSPORTED TO THE ER BY AMBULANCE, I HIT THE STEERING WHEEL HARD SO HARD THAT IT BENT INWARDS AND BROKE MY NOSE ALSO HAD A CONCUSSION. HE WAS IN THE FRONT PASSENGER SEAT AND HIT THE FRONT DASH, WHERE THE AIR BAG SHOULD HAVE DEPLOYED, HE BROKE HIS FRONT TEETH AND ALSO HAD A CONCUSSION. I'VE ALSO HAD MANY OF THE SAME ISSUES THAT EVERY OTHER 02 OR 03 ENVOY HAS YET MY VIN PULLS NO RECALLS. THIS NEEDS TO BE INVESTIGATED!!! THANKS.
				I WAS ON MY WAY HOME ON HWY/US 151 GOING APPROX. 55-60 MPH (65 MPH ZONE) WHEN I HIT A DEER WHICH CAUSED MY VEHICLE TO LOSE CONTROL AND SLAMMED INTO THE START OF A GUARDRAIL AT NO LESS THAN 45 MPH BRINGING MY 2002 GMC ENVOY TO A COMPLETE STOP, AT MOST 2-3 FEET FROM INITIAL IMPACT TO BE EXACT. THE AIRBAGS DID NOT DEPLOY. FRONT DASH NOR SIDE IMPACT BAGS, NOTHING. N I HIT HARD. LUCKILY I WASNT SERIOUSLY INJURED ONLY MINOR BRUISING AND QUITE SORE FROM WHIPLASH AND BEING THROWN INTO THE DOOR AN A BIT SHAKEN N LUCKILY HAD NO PASSENGERS. AS FOR MY ENVOY, IT IS A TOTAL LOSS AND UNFORTUNATELY I ONLY HAD LIABILITY INSURANCE SO NOW IM SCREWED WITHOUT A VEHICLE
GMC	ENVOY	2002	2019-02-12	AND AFTER ALL OTHER PROBLEMS IVE FACED WITH MY GMC ENVOY I WILL NEVER OWN A GM AGAIN. TAKE GM PRODUCTS TO THE DUMP.
GMC	YUKON	2002	2002-10-13	CONSUMER STATES THAT AT 50 MPH UNDER RAINY CONDITIONS, CONSUMER LOSS CONTROL OF VEHICLE AND HIT A TREE. VEHICLE WAS TOTALLED. NONE OF THE VEHICLES AIRBAGS DEPLOYED. PLEASE PROVIDE ANY FURTHER INFORMATION. TS
GMC	YUKON	2002	2002-12-09	WHILE DRIVING AT 25 MPH THE VEHICLE WAS INVOLVED IN AN ACCIDENT WHERE AIRBAGS DID NOT DEPLOY. DEALER NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION. TS
GMC	YUKON	2002	2005-06-13	DT: CONSUMER GOT IN AN ACCIDENT AND TOTALED THE VEHICLE, THE FRONT AND SIDE AIR BAGS NEVER DEPLOYED. CONSUMER WAS GOING ABOUT 70 MPH AND HIT HEAD ON AND THE VEHICLE ROLLED 4 TIMES. *AK *SB
GMC	YUKON	2002	2005-07-15	DT: WHILE DRIVING DOWN THE MAIN ROAD AT 45 MPH, THE CONSUMER TOOK HIS EYES OFF THE ROAD AND WENT INTO THE GRAVEL AND THEN INTO A DITCH AND HIT A MAILBOX. THE CONSUMER WENT THROUGH THE PASSENGER SIDE WINDSHIELD. THE RIGHT WHEEL FELL OFF AND THE FRONT BUMPER SMASHED INTO THE ENGINE AND THE FRAME WAS BENT. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE VEHICLE WAS EQUIPPED WITH FRONT AND SIDE AIR BAGS. THE AIR BAG LIGHT WAS NOT ON AND NEVER HAD BEEN ON. THERE WERE NO PROBLEMS WITH VEHICLE BEFORE THIS INCIDENT. THERE WERE NO OTHER VEHICLES INVOLVED. THE VEHICLE HAS NEVER BEEN IN AN ACCIDENT THERE WERE NO RECALLS ON THE AIR BAGS. THE MANUFACTURER HAS NOT BEEN CONTACTED, BUT WILL BE CONTACTED TODAY. THERE WAS A POLICE REPORT WAS TAKEN. *AK
	GMC GMC GMC GMC GMC GMC	GMC ENVOY GMC ENVOY GMC ENVOY GMC ENVOY GMC YUKON GMC YUKON	GMC ENVOY 2002 GMC ENVOY 2002 GMC ENVOY 2002 GMC ENVOY 2002 GMC YUKON 2002 GMC YUKON 2002	GMC ENVOY 2002 2008-10-03 GMC ENVOY 2002 2011-11-16 GMC ENVOY 2002 2013-07-07 GMC ENVOY 2002 2014-06-28 GMC YUKON 2002 2002-10-13 GMC YUKON 2002 2002-12-09 GMC YUKON 2002 2005-06-13

40264762	CMC	Nu von	2002	2000 02 22	TL*THE CONTACT OWNS A 2002 GMC YUKON. WHILE DRIVING APPROXIMATELY 55 MPH, THE CONTACT CRASHED INTO ANOTHER VEHICLE. HIS VEHICLE WAS COMPLETELY DESTROYED AND NONE OF THE AIR BAGS DEPLOYED. THE DRIVER SUSTAINED MODERATE BODILY INJURIES. IT HAS NOT YET BEEN DETERMINED WHY THE AIR BAGS FAILED TO DEPLOY. THE CONTACT HAS PICTURES OF THE FAILED INCIDENT AND A COPY OF THE POLICE REPORT. HE FILED A COMPLAINT WITH THE
10261762	GMC	YUKON	2002	2009-02-23	MANUFACTURER. THE FAILURE AND CURRENT MILEAGES WERE 107,000.
10544196	GMC	YUKON	2002	2013-09-12	TL* THE CONTACT OWNS A 2002 GMC YUKON. THE CONTACT STATED THAT WHILE DRIVING 45 MPH, HE CRASHED INTO THE PASSENGER'S SIDE OF ANOTHER VEHICLE AND THE AIR BAGS FILED TO DEPLOY WITH THE IMPACT. IN ADDITION, THE SEAT BELT FAILED TO SECURE AS DESIGNED. THE CONTACT SUSTAINED A BRUISED RIB AND AN INJURY TO THE LEFT LEG. A POLICE REPORT WAS NOT FILED. THE VEHICLE WAS DESTROYED AND TOWED TO A SALVAGE FACILITY. THE MANUFACTURER WAS NOT NOTIFIED OF THE DEFECT. THE APPROXIMATELY FAILURE MILEAGE WAS 142,000.
10344130	GIVIC	TORON	2002	2013 03 12	TL*THE CONTACT OWNS A 2002 GMC YUKON. THE CONTACT STATED THAT AFTER BEING INVOLVED
					IN A COLLISION, THE AIR BAGS FAILED TO DEPLOY. THE DETAILS OF THE COLLISION WERE NOT AVAILABLE. THE VEHICLE WAS DESTROYED. A POLICE REPORT WAS FILED. THE CONTACT SUSTAINED BACK INJURIES THAT DID NOT REQUIRE MEDICAL ATTENTION. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 225,000. THE VIN WAS
10690133	GMC	YUKON	2002	2015-01-06	UNAVAILABLE.
					I SWERVED TO MISS A DEER AND I HIT A TREE RUNNING 47 MPH AND MY AIR BAGS DIDN'T DEPLOY AND NO ONE CAN TELL ME WHY. MY HUSBAND AND I WERE VERY LUCKY BUT WHY DIDN'T THE AIR BAGS DEPLOY? MY HUSBAND WAS OUT OF WORK FOR 5 MONTHS DUE TO TORN LIGAMENTS IN HIS
11298082	GMC	YUKON XL	2002	2019-02-05	SHOULDERS AND STILL HAS TO HAVE SURGERY. THE TRUCK IMPACTED A TREE WHILE DRIVING 40 MPH AND AS A RESULT THE TRUCK'S FRONT
					BUMPER WRAPPED AROUND THE TREE. NEITHER THE DRIVER'S SIDE NOR PASSENGER'S SIDE AIR BAG DEPLOYED UPON IMPACT. THE DRIVER SUSTAINED SEVERE INJURIES, BUT NO BROKEN BONES. THE CAUSE OF THE AIR BAG FAILURE IS YET TO BE DETERMINED. PLEASE PROVIDE ANY ADDITIONAL
10048726	ISUZU	AMIGO	2002		INFORMATION. *NLM WE WERE INVOLVED IN AN ACCIDENT ON 1270 IN ST.LOUIS, MO. A SEMI- TRUCK DOING
					APPROXIMATELY 35 MPH STRUCK US IN THE REAR AND FORCED US INTO THE PICK UP TRUCK IN FRONT OF US. THE AIR BAGS DID NOT DEPLOY, DESPITE THE SQUARE FRONT TO REAR IMPACT. THE FRONT PASSENGER SEAT IN MY VEHICLE BROKE, TWISTING THE PASSENGER TO THE SIDE,
764947	ISUZU	AXIOM	2002	2002-07-02	FACING THE STEERING WHEEL.*AK
10033920	ISUZU	AXIOM	2002	2003-08-13	CONSUMER STATED WHILE DRIVING AT 50 MPH CONSUMER'S VEHICLE REARENDED ANOTHER VEHICLE. UPON IMPACT, AIR BAGS FAILED TO DEPLOY. *AK
10050524	ISUZU	AXIOM	2002	2003-12-15	WHILE DRIVING AT 25 MPH LEFT FRONT TIRE BLEW OUT, DRIVER LOST CONTROL AND HIT A GUARD RAIL. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. GOODYEAR, SIZE P235/65R17, DOT# UNKNOWN. CONSUMER STATED THERE WAS NOT AN ISSUE WITH THE TIRE, BUT HIS SON RAN OVER SOMETHING AND BLEW THE TIRE. *AK
					DT: ON JULY 3RD THE CONSUMER RECEIVED A RECALL LETTER IN REFERENCE TO THE PASSENGER SIDE AIR BAG, RECALL # 03V113000. THE VEHICLE WAS TAKEN TO GALLES MOTOR CO. TO HAVE
40420420	16171	AVION	2002	2005 07 44	THE RECALL REPAIRED AT NO COST TO THE CONSUMER. ON JULY 11, 2005 THE CONSUMER'S WIFE HAD AN ACCIDENT IN WHICH SHE WAS INJURED. SHE REAR ENDED A CAR SITTING AT A RED LIGHT WHILE SHE WAS GOING 45 MPH. SHE WAS WEARING A SEAT BELT AT THE TIME BUT THE AIR BAGS DID NOT DEPLOY. THE WEATHER WAS DRY AND THE ROAD CONDITIONS WERE GOOD. THE VEHICLE HASN'T BEEN TAKEN TOT HE DEALER YET FOR INSPECTION. THE DEALER WAS CONTACTED AND THEY SAID FOR HIM TO TAKE IT TO A MECHANIC. HE HASN'T BEEN ABLE TO GET A HOLD OF
10128420	ISUZU	AXIOM	2002	2005-07-11	THE MFR. AT PRESENT, HIS CAR IS STILL AT THE WRECKING YARD. *NM DT*: THE CONTACT STATED ON DECEMBER 23, 2005 WHILE DRIVING AT 60 MPH ON A DRY HIGHWAY THE CONTACT WAS RUN OFF THE ROAD BY A TRUCK. THE VEHICLE THEN COLLIDED WITH THE ROAD PARTITION, AND CRUSHED THE ENTIRE FRONT END OF THE VEHICLE. THE AIR BAGS DID
					NOT DEPLOY, AND THE DRIVER SUFFERED BRUISING FROM THE SAFETY BELT. THERE IS A RECALL,
10148582	ISUZU	AXIOM	2002	2005-12-23	#02V213000 BUT THE CONTACT WAS NOT NOTIFIED OF THE RECALL WHEN THE VEHICLE WAS PURCHASED. UPDATED 02/28/06. *JB
					VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WITH A POLE AT 35-40MPH AND NEITHER
8023834	ISUZU	RODEO	2002	2002-10-25	AIRBAG DEPLOYED. VEHICLE IS TOTALED DRIVER IN A COMA DEALER IS AWARE OF THE PROBLEM. TS
					WHILE MERGING ONTO THE INTERSTATE VEHICLE DROVE OVER SOME BLACK ICE, VEHICLE THEN
10049812	ISUZU	RODEO	2002	2003-11-28	SPUN AROUND, HIT A CONCRETE BARRIER, AND A GUARD RAIL. UPON IMPACT, FRONT AIR BAGS DID NOT DEPLOY. THE DRIVER AND PASSENGER SUSTAINED MINOR INJURIES. *AK
4040***	16	D0250	225	2006 11 12	CAR WAS INVOLVED IN AN ACCIDENT WHERE IT STRUCK THE BACK OF ANOTHER VEHICLE. THE COLLISION WAS ENOUGH TO CAUSE OVER \$4000.00 IN DAMAGE TO THE ISUZU BUT THE AIR BAGS
10184163	ISUZU	RODEO	2002	2006-11-19	FAILED TO DEPLOY. *JB

LANDED ON THE ACCELERATION PEDAL AS HELD GOT CONSCIOUSNESS. THE CONTACT WAS NOT AWARE AS THE WHOLE CONTINUED TO ACCELERATE THO ONCOMING THE WHITE HELD THEN CRASHED INTO A TEST BEFORE FLIPPINE, THE STATE BETT BETT BETT BETT BETT BETT BETT		<u> </u>	1		Т	
THE VEHICLE IS DAMAGED, AS WELLA 8, BOTH SIDE MINDOWS AND THE RADIATOR, RONG OF THE AIRBAGS SERVING AS DEPLOYED CARRY IN PROPERLY THAT VEH PROVIDED IN THE MINDOWS AND THE RADIATOR RONG OF THE AIRBAGS SERVING AND THE PROVIDED AND THE MINDOWS AND THE RADIATOR AND THE MINDOWS AND TH	10443695	ISUZU	RODEO	2002	2011-05-18	MPH WHEN THE VEHICLE BEGAN TO ERRONEOUSLY DRIFT TO ONE SIDE. THE CONTACT LOST CONTROL OF THE VEHICLE AND THE VEHICLE MOVED INTO THE SHOULDER, CRASHING INTO THE BARRIER WALL ABRUPTLY. THE CONTACT WAS KNOCKED UNCONSCIOUS AND THE CONTACTS FOOT LANDED ON THE ACCELERATOR PEDAL AS HE LOST CONSCIOUSNESS. THE CONTACT WAS NOT AWARE AS THE VEHICLE CONTINUED TO ACCELERATE INTO ONCOMING TRAFFIC. THE VEHICLE THEN CRASHED INTO A TREE BEFORE FLIPPING. THE SEAT BELTS DETACHED FROM ITS HOUSING UNIT AND THE AIR BAGS NEVER DEPLOYED. THE CONTACT SUSTAINED SEVERE INJURIES TO THE HEAD, FACE, PELVIS AND SPINE. A PASSENGER WAS ALSO INJURED AND BOTH THE CONTACT AND THE PASSENGER WERE TRANSPORTED TO THE HOSPITAL. A POLICE REPORT WAS FILED OF THE INCIDENT AND THE VEHICLE WAS DESTROYED. THE FAILURE AND THE CURRENT MILEAGE WAS
THE VEHICLE IS DAMAGED, AS WELLA 8, BOTH SIDE MINDOWS AND THE RADIATOR, RONG OF THE AIRBAGS SERVING AS DEPLOYED CARRY IN PROPERLY THAT VEH PROVIDED IN THE MINDOWS AND THE RADIATOR RONG OF THE AIRBAGS SERVING AND THE PROVIDED AND THE MINDOWS AND THE RADIATOR AND THE MINDOWS AND TH						
WITH THE LET HALF OF THE RROW TO THE VAN. UPON IMPACT, FRONTAL AIR BAGS FAILED TO 2001 2001-06-19 DEPLOY. "AK WHILE DRIVING 35 MPH THE VEHICLE REAR ENDED A BUS YET THE AIRBAGS DID NOT DEPLOY, THE VEHICLE WAS A TOTAL LOSS. NIM." 19	10553570	ISUZU	RODEO	2002	2013-11-24	THE VEHICLE IS DAMAGED, AS WELL AS, BOTH SIDE WINDOWS AND THE RADIATOR. NONE OF THE AIRBAGS DEPLOYED CAUSING INJURIES TO TWO PEOPLE IN THE VEHICLE. THE OFFICER AT THE
2001 2001 2001 2001 2001 2001 2001 2001 2001 2001 2002						, and the second
DODG-23 OF CHEVROLET STRO 2001 2002-03-06 VEHICLE WAS A TOTAL LOSS. NUM "IG WHILE TRAVELING AD 35 MPH AND AS A RESULT OF AN ACCIDENT AIR BAGS DID NOT DEPLOY. PLEASE PROVIDE FURTHER INFORMATION." AN EVENICE WAS NOT DETERMINED, UPON IMPACT, BOTH AIR BAGS DID NOT DEPLOY. PLEASE PROVIDE FURTHER INFORMATION." AN EVENICE WAS NOT DETERMINED, UPON IMPACT, BOTH AIR BAGS DID NOT DEPLOY. DEALER WAS NOTIFIED. "AK "YH WHILE TRAVELING DID NOT DEPLOY, DEALER WAS NOTIFIED." AK "YH WHILE TRAVELING DID NOT DEPLOY, DEALER WAS NOTIFIED. "AK "YH WHILE TRAVELING DID NOT DEPLOY. BELAVER WAS NOTIFIED." AK "YH WHILE TRAVELING DID NOT DEPLOY. BELAVER WAS NOTIFIED. "AK "YH WHILE TRAVELING DID NOT DEPLOY. BELAVER WAS NOTIFIED." AK "YH WHILE TRAVELING DID NOT DEPLOY. BELAVER WAS NOTIFIED. "AK "YH WHILE TRAVELING DID NOT DEPLOY. BELAVER WAS NOTIFIED." AK "YH WHILE TRAVELING DID NOT DEPLOY. BELAVER WAS NOTIFIED. "AK "YH WILE DID NOT DEPLOY. BELAVER WAS NOTIFIED." AK "YH WILE DID NOT DEPLOY. BELAVER WHILE DEPLOY. BELAVER WHILE WE WHILE WAS NOTIFIED. AND WHILE TRAVELING WHEN VEHICLE WAS HIT IN FRONT CENTER AND HIT DID NOT DEPLOY. BELAVER WHILE DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION DEALER IS AWARD OF THE PROBLEM. PH WHILE TRAVELING AND HIT DID NOT RESOLVED WHILE TRAVELING DID NOT BELEVILLE WHILE DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION. TO DRIVES SIDE AIR BAG FALLED TO DEPLOY. IN A CARSH THROUGH: 1. A SKY FOOT TALL WOODDEN FERNE AND HIT DID NOT RESOLVED WHILE TRAVELING DID NOT RESOLVED HIS TAKE. WHILE DID NOT RESOLVED HIS TAKE. WHILE DEPLOY. PLEASE FILL DROWN WHILE TRAVELING DID NOT RESOLVED HIS PROBLEM. "AK "SCIENCE WAS AT A COMPLETE STOP AND ADOTHER VEHICLE UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MINOR INJURIES. THE DEPLOY. WAS A WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE WAS NOW OF THE REFOR	745117	CHEVROLET	ASTRO	2001	2001-04-19	·
Selection Chevrolet Blazer 2001 2001-08-10 8017-85 2018-07-09-10-08-10 8015-85 2018-07-09-10-08-10 8015-85 2018-07-09-10-08-10 8015-85 2018-08-10-08-1						WHILE DRIVING 35 MPH THE VEHICLE REAR ENDED A BUS YET THE AIRBAGS DID NOT DEPLOY, THE
PLEASE PROVIDE FURTHER INFORMATION "AS WELL'S WAS NOT DETERMINED, UPON IMPACT, 8015457 CHEVROLET BLAZER 2001 2001-08-10 BOTH AIR BAGS DID NOT DEPLOY, DEALER WAS NOTIFIED." AK "YH WHILE IN A FRONTAL IMPACT, NONE OF THE AIR BAGS DEPLOYED. DEALER CONTACTED." AK WHILE IN A FRONTAL IMPACT NONE OF THE AIR BAGS DEPLOYED. DEALER CONTACTED." AK WHILE IN A FRONTAL IMPACT NONE OF THE AIR BAGS DEPLOYED. DEALER CONTACTED." AK WHILE IN A FRONTAL IMPACT NONE OF THE AIR BAGS DEPLOYED. DEALER CONTACTED." AK WHILE DRIVING AT 35MPH AND WITH NO WASRING WHEN VEHICLE WAS HIT IN FRONT CENTER AIR BAGS DEPLOYED. DEALER CONTACTED." AND WHILE DRIVING AT 35MPH AND WITH NO WASRING WHEN VEHICLE WAS HIT IN FRONT CENTER AIR BAGS DID NOT DEPLOY. DEALER NOTHERD. "AND WITH NO WASRING WHEN VEHICLE WAS HIT IN FRONT CENTER AIR BAGS DID NOT DEPLOY. DEALER NOTHING AND WITH NO WASRING WHEN VEHICLE WAS HIT IN FRONT CENTER AIR BAGS DID NOT DEPLOY. DEALER NOTHING AND WITH NO WASRING WHEN VEHICLE WAS HIT IN FRONT CENTER OF THE VEHICLE THE AIR BAGS DID NOT DEPLOY. DEALER NOTHING AND WITHOUT PRIOR WASRINGS SHE HIT AND WITH NO WASRING WHEN VEHICLE WAS HIT IN FRONT CENTER OF THE VEHICLE THE AIR BAGS DID NOT DEPLOY. DEALER NOTHERD. "AND WITHOUT PRIOR WASRINGS SHE HIT AN ENDANGMENT. AND THE VEHICLE WAS AND THE WHICH WAS WITHOUT PRIOR WASRINGS SHE HIT AN ENDANGMENT. AND THE WHICH WAS WITHOUT PRIOR WASRINGS SHE HIT AN ENDANGMENT. AND THE VEHICLE WAS NOT BE PROVIDE ANY ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH CONSUMERS STATES WHILE DRIVING AT 33 MPH, THE ZENDER PROVIDE ANY ADDITIONAL INFORMATION AND NETHER PASSENCER OR DRIVES AIR BAG DEPLOYED, PLEASE PROVIDE ANY ADDITIONAL INFORMATION AND NETHER PROSENCER OR DRIVES AIR BAG DEPLOYED, PLEASE PROVIDE ANY ADDITIONAL INFORMATION AND NETHER PROBLEM. "ANY "SC CONSUMER'S VEHICLE WAS NOTHER WAS NOTHER WAS NOTHER WHILE DRIVING AT 33 MPH, THE ZENDER SUBJECT OF ANY ADDITIONAL INFORMATION AND NETHER PROBLEM. "ANY "SC CONSUMER'S VEHICLE WAS NOTHER BUSINESS OF ANY ADDITIONAL PROBLEM." "ANY "SC CONSUMER'S VEHICL	8006423	CHEVROLET	ASTRO	2001	2002-03-06	
894582 CHEVROLET BLAZER 2001 2002-07-05 WHILE IN A FRONTAL COLLISION. SPEED WAS NOT DETERMINED, UPON IMPACT, 8015457 CHEVROLET BLAZER 2001 2002-07-05 WHILE IN A FRONTAL COLLISION INTO A DIRT WALL UPON IMPACT, NOT STANDARD STANDA	886165	CHEVROLET	BLAZER	2001		
8015457 CHEVROLET BLAZER 2001 2002-07-05 WHILE IN A FRONTAL IMPACT NONE OF THE AIR BAGS DEPLOYED, DEALER CONTACTED.*AX VEHICLE WAS INVOLVED IN A FRONTAL COLLISION INTO A DIRT WALL UPON IMPACT, NEITHER 8017355 CHEVROLET BLAZER 2001 2002-07-07 WHILE DRIVING AT 53MPH AND WITH NO WARNING WHEN VEHICLE WAS HIT IN FRONT CENTER 8017766 CHEVROLET BLAZER 2001 2002-08-16 AND SAME AS DEPLOYED, FEEL FREE TO PROVIDE ANY FURTHER INFROMMATION.*AX WHILE DRIVING AT 53MPH AND WITH NO WARNING WHEN VEHICLE WAS HIT IN FRONT CENTER 8020006 CHEVROLET BLAZER 2001 2002-09-14 BAG DID NOT DEPLOY. DEALER NOTIFIED. *AX CONSUMER STATES THAT WHEN IN THE FRONT CENTER OF THE VEHICLE THE AIR 8023471 CHEVROLET BLAZER 2001 2002-09-01 NA FRONTACTION OF THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVING WITHOUT PRIOR WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVING WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVING WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVING WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVER SIDE AIR RAGE DID NOT DEPLOY. DEALER SHOW THE PROBLEM. PH CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NEITHER PASSENGER OR DRIVES SIR RAGE DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVES SIR RAGE DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVES SIR RAGE DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVES SIR RAGE DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVES SIR RAGE DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVES SIR RAGE DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS ORNERS SIDE AIR BAG FAILED TO DEPLOY. THE CONSUMER SUSTAINED WHE THAT CONTACT SIDE OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINK AND PLUMBING FATURES, WHILE SMASHING UP AND OVER THE PROBLEM. "AN "SC CONSUMER'S VEHICLE WAS NOTHIFIED BY THE CONSUMER'S WEHICLE WAS COMMING HEAD OF WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE WAS CONSUMER'S VEHICLE WHICH S						VEHICLE WAS INVOLVED IN A FRONTAL COLLISION. SPEED WAS NOT DETERMINED, UPON IMPACT,
VEHICLE WAS INVOIVED IN A FRONTAL COLLISION INTO A DIRT WALL UPON IMPACT, NEITHER 8017365 CHEVROLET BLAZER 2001 2002-07-07 AIR BAG DEPLOYED, FEEL FREE TO PROVIDE AND THE RENTER INFROMATION "AK WHILE DRIVING AT 35MPH AND WITH NO WARNING WHEN VEHICLE WAS HIT IN FRONT CENTER 8017786 CHEVROLET BLAZER 2001 2002-09-14 AIR BAGS DID NOT DEPLOY. DEALER NOTHIFED. "AK CONSUMER STATES THAT WHEN HIT AT MOMPH IN THE FRONT CENTER OF THE VEHICLE THE AIR BAGS DID NOT DEPLOY. DEALER NOTHIFED." AK CONSUMER STATES THAT WHEN HIT AT MOMPH IN THE FRONT CENTER OF THE VEHICLE THE AIR BAGS DID NOT DEPLOY. DEALER NOTHIFED. "NAK WHILE TRAVELING ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH SHARMAN SHE HIT AN ENBANKMENT. AND THE VEHICLE FUP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION TO BE ALER IS AWARE OF THE PROBLEM. PH SHARMAN SHE AND THE PROBLEM. THE PROSENCE OR DRIVES AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH. I. A SIX POOT TRAIL WOODEN HENCE AT JUMBING THAT THE SHARMAN SHE AND THE PROBLEM. "A K "SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP, AND AND OVER THE FIFTEEN-INCH CONCRETE FOR COUNTATION, FOR THE PROBLEM." A K "SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND AND OVER THE FIFTEEN-INCH WHICH SHE WAS DISHED INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. THE CONSUMER'S VEHICLE WAS A VEHICLE BEHIND CONSUMER'S VEHICLE WAS ENVOIVED IN A FRONT COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. ON IMPACT, AIR BAGS DID NOT DEPLOY. "AK CONTACTE THE WAS A WASHING THE WAS A VEHICLE BEHIND CONSUMER'S VEHICLE WAS INVOIVED IN A FRO	894582	CHEVROLET	BLAZER	2001	2001-08-10	BOTH AIR BAGS DID NOT DEPLOY, DEALER WAS NOTIFIED. *AK *YH
8017355 CHEVROLET BLAZER 2001 2002-09-14 AIR BAG DEPLOYED. FEEL FREE TO PROVIDE ANY FURTHER INFROMATION.*AK 8017786 CHEVROLET BLAZER 2001 2002-09-16 AIR BAGS DID NOT DEPLOY. DEALER NOTIFIED. *AK 8020006 CHEVROLET BLAZER 2001 2002-09-14 AIR BAGS DID NOT DEPLOY. DEALER NOTIFIED. *AK 802007 CHEVROLET BLAZER 2001 2002-09-14 WINLE TRAVELING AND UTIL TO YEAR OF THE VEHICLE THE AIR 802007 CHEVROLET BLAZER 2001 2002-09-14 WINLE TRAVELING ABOUT 55NPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AM 8023471 CHEVROLET BLAZER 2001 2002-09-01 IN ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NEITHER PASSENGER 90 OR BRIVES SIDE AIR BAG FAILED TO DEPLOY. DEALE PROVIDE ANY ADDITIONAL INFORMATION. TS 80 OR BRIVES SIDE AIR BAG FAILED TO DEPLOY IN A CAS STORY HOME THAT CONTAINED THE KITCHEN SINE FIXTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH 1006150 CHEVROLET BLAZER 2001 2004-02-24 CONCRETE FOUNDATION, FRONT-END FIRST.*AK WHILE DRIVING AT 53 MPH, THE 0.2 THE EXTERIOR SIDE OF A 2-5TORY HOME THAT CONTAINED THE KITCHEN SINE FIXTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH 10072173 CHEVROLET BLAZER 2001 2004-04-30 DEALERSHIP WAS MOTIFIED, BUT DID NOT RESULT BRONDERS STATINED MINIOR INJURIES. THE 10072173 CHEVROLET BLAZER 2001 2004-04-30 DEALERSHIP WAS MOTIFIED, BUT DID NOT RESULT BRONDERS STATINED MINIOR INJURIES. THE 10072173 CHEVROLET BLAZER 2001 2004-12-25 DEALERSHIP WAS MOTIFIED, BUT DID NOT RESULT BRONDERS STATINED MINIOR INJURIES. THE 10072173 CHEVROLET BLAZER 2001 2004-12-25 DEALERSHIP WAS MOTIFIED, BUT DID NOT RESULT BRONDERS. THE 10072173 CHEVROLET BLAZER 2001 2004-12-25 DEALERSHIP WAS MOTIFIED, BUT DID NOT RESULT BRONDERS. THE CONSUMER'S VEHICLE WAS AND ADDITION OF RESULT BRONDERS. THE CONSUMER'S VEHICLE WAS AND ADDITION OF RESULT BRONDERS. THE CONSUMER'S VEHICLE WAS AND ADDITION OF RESULT BRONDERS. THE CONSUMER'S VEHICLE WAS AND ADDITION OF RESULT BRONDERS. THE CONSUMER'S VEHICLE WAS AND ADDITION OF RESULT BRONDERS. THE CON	8015457	CHEVROLET	BLAZER	2001	2002-07-05	WHILE IN A FRONTAL IMPACT NONE OF THE AIR BAGS DEPLOYED. DEALER CONTACTED.*AK
WHILE DRIVING AT 35MPH AND WITH NO WARNING WHEN VEHICLE WAS HIT IN FRONT CENTER AIR BAGS DID NOT DEPLOY. DEALER NOTIFIED. "AK CONSUMER STATES THAT WHEN HIT AT A 0MPH IN THE FRONT CENTER OF THE VEHICLE THE AIR 8020006 CHEVROLET BLAZER 2001 2002-09-14 BAG DID NOT DEPLOY. DEALER NOTIFIED. "AK WHILE TRAVELING ABOUT SEMPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FUE AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NEITHER PASSENGER OF DRIVES SIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXTREM SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THEN 2. THE EXAD SIDE OF A PROTOT TALL WOODDEN FENCE AT LAMOST 30MPH. THE CONSUMER SUSTAINED MINOR INJURIES. THE 10072173 CHEVROLET BLAZER 2001 2004-02-24 CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE. UPON MIMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE 10103341 CHEVROLET BLAZER 2001 2004-11-11 BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MINOR INJURIES. AND WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE BRAD ON INJURIES. AND WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE BRAD ON TORDING THE VEHICLE OF TRIKE A CONSUMER'S VEHICLE WAS INVOLVED IN A						
8017786 CHEVROLET BLAZER 2001 2002-08-16 AIR BAGS DID NOT DEPLOY. DEALER NOTIFIED.*AK CONSUMER STATES THAT WHEN HIT AT 40MPH IN THE FRONT CENTER OF THE VEHICLE THE AIR 8020006 CHEVROLET BLAZER 2001 2002-09-14 BAG DID NOT DEPLOY. DEALER NOTIFIED. NILM WHILE TRAVELING ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN BAG AUTOMATICAL ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN BAG AUTOMATICAL ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN WHILE TRAVELING ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN BAG AUTOMATICAL ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN WHILE TRAVELING ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN CHEVROLET BLAZER 2001 2002-07-01 IN ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NETHER PASSENGER OR DRIVES AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS BURNING SIDE AIR BAG DEPLOY. THE CONSUMER SIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOY. THE CONSUMER SIDE ANY ADDITIONAL INFORMATION. TS WHILE DRIVING AT 753 MPH, THE CONSUMER SYSTEMICE BRAIND OWN THE FIFTEEN-INCH WHILE DRIVING AT 753 MPH, THE CONSUMER SYSTEMICE PROVIDE ANY ADDITIONAL INFORMATION. THE WARD AND A VEHICLE WAS ADDITIONAL INFORMATION. THE WARD AND A TRENDED AND ADDITIONAL INFORMATION. THE WARD AND A TRENDED AND ADDITIONAL INFORMATION. THE WARD AND ADDITIONAL INFORMATION. THE WARD AND ADDITIONAL INFOR	8017355	CHEVROLET	BLAZER	2001	2002-07-07	
8020006 CHEVROLET BLAZER 2001 2002-09-14 BAG DID NOT DEPLOY. DEALER NOTIFIED. NLM WHILE TRAVELING ABOUT SSMPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FLIP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION. THE VEHICLE FLIP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION. THE VEHICLE FLIP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL IN ADDITIONAL INFORMATION. TO REVIEW SIDE AIRBAG DEPLOY DEALER PROVIDED. PLEASE PROVIDE AIR AND ADDITIONAL INFORMATION. TO REVIEW SIDE AIR BAG DEPLOYED. PLEASE PROVIDE AND ADDITIONAL INFORMATION. TO REVIEW SIDE AIR BAG DEPLOYED. PLEASE PROVIDED OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINE AIR DRIVER'S SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THEN 2. THE EXTERIOR SIDE OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINE AND PULLIBRING FIXTURES USED OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINE AND PULLIBRING FIXTURES WILL SMASHING UP AND OVER THE FIFTEEN-INCH CONCRETE FOUNDATION, FRONT-END FIRST. *AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE CONSUMER SUSTAINED MINOR INJURIES. THE WILL SHOP SINE AND ANOTHER VEHICLE WAS COMING HEAD OF WHICH RESULTED IN A HEAD ON COLLISION. HOREVER, UPON IMPACT, AIR BAGS SID NOT DEPLOY. THE ADD NOT DEPLOY. CONSUMER SUSTAINED MAD ANOTHER VEHICLE WAS CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION. AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUBMICES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION. AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUBMICES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. AK DIT: CONTACT STATED THE AIR BAGS DID NOT DEPLOY. ON IN A HEAD ON CRASH. WHILE TRAVELING AN AROU	8017786	CHEVROLET	BLAZER	2001	2002-08-16	
WHILE TRAVELING ABOUT 55MPH ON THE HIGHWAY WITHOUT PRIOR WARNING SHE HIT AN ENBANKMENT. AND THE VEHICLE FLIP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL SHARMAN FOR PRIOR SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL ON THE ORIGINAL PRIOR SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL ON THE ORIGINAL PRIOR SIDE AIR BAG DIDN'T DEPLOY. PLEASE FILL ON THE ORIGINAL PRIOR SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THEN 2. THE STEROR SIDE OF A 2-STORY HOME THAT CONTAINED THE FIELD SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THEN 2. THE STEROR SIDE OF A 2-STORY HOME THAT CONTAINED THE FIELD SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THE 2. THE STEROR SIDE OF A 2-STORY HOME THAT CONTAINED THE FIELD SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN KITCHEN SINK AND PLUMBING FIXTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH CONCERTE FOUNDATION, FRONT-END FIRST. *AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED AND THE FIFTEEN-INCH CONCERTE FOUNDATION, FRONT-END FIRST. *AK WHILE DRIVING AT 53 MPH, THE CONSUMER SUSTAINED MINOR INJURIES. THE DEALERSHIP WAS NOTIFIED, BUT DID NOT RESOLVE THE PROBLEM. *AK *SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE. WAS COMING HEAD ON WHICH RESULTED IN A HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK VEHICLES SUPPED WHILE TRAVELING ON ICE AT 55 MPH, CAUSING THE VEHICLE TO STRIKE A CONCERTE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. *AK DT: CONTACT STATED THE VEHICLE HORD PLANED. THE CONTACT SOUTH OF STRIKE A CONCERTE RETAINING WALL, AND IT ROUTED SURFAINED THE PROPED OF THE VEHICLE WAS A MOMENTARY LOSS OF VEHICLE						
ENBANKMENT. AND THE VEHICLE FLIP AND THE DRIVER SIDE AIRBAG DIDN'T DEPLOY. PLEASE FILL N ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NEITHER PASSENGER OR DRIVES SIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THEN 2. THE EXTERIOR SIDE OF A 2-STORY HOME THAT CONTAINED TH KITCHEN SINK AND PULMBING FIXTURE, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH CONCRETE FOUNDATION, FRONT-END FIRST. *AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE DOTESTAL STORY HOME THAT IN THE PROPERTY OF THE FIFTEEN-INCH CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE WAS COMING HEAD ON WHICH RESULTED IN A HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER STAINED MINDRIES. THE CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER STAINED MINDRIES. THE CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE NAMIPACTURER. **AK CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. **AK DT: CONTACT STATED THE AIR BAGS DID NOT DEPLOY IN A HEAD ON CRASH. WHILE TRAVELING AIR ABOUT 60 MPH THE VEHICLE HYDRO PLANED. THE CONTACT DEPLOY THE VEHICLE WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A BUYER FOR THE VEHICLE HYDRO PLANED. THE CONTACT LORD FREE REMEDY. VEHICLE WAS TOTALED. **AK DT: CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A BUYER FOR THE VEHICLE HYDRO PLANED. THE CONTACT LORD FREE REMEDY. VEHICLE WAS TOTALED. **AK MODERNIE THE VEHICLE	8020006	CHEVROLET	BLAZER	2001	2002-09-14	
CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NEITHER PASSENGER OR DRIVES AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS OR DRIVES AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THEN 2. THE EXTERIOR SIDE OF A 2-STORY HOME THAT CONTAINED TH KITCHEN SINK AND PLUMBING FISTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH CONCRETE FOUNDATION, FRONT-END FIRST.*AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE DEALER SHIP WAS NOTIFIED, BUT DID NOT RESOLVE THE PROBLEM. *AK *SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE BEHIND CONSUMER'S VEHICL WHICH SHE WAS PUSHED INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10101364 CHEVROLET BLAZER 2001 2004-11-11 BASS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-22 WAS A SOUND IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-22 WAS A SOUND IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-22 WAS A SOUND IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-22 WAS A SOUND IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-22 WAS A SOUND IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-25 DEPLOY. *AK 10105341 CHEVROLET BLAZER 2001 2004-12-25 DEPLOY. *AK 10106657 CHEVROLET						
10002341 CHEVROLET BLAZER 2001 OR DRIVES AIR BAG DEPLOYED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION. TS DRIVER SIDE AIR BAGG FALLED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THAP 2. THE EXTERIOR SIDE OF A 2-5TORY HOME THAT CONTAINED TH KITCHEN SINK AND PLUMBING FIXTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH CONCRETE FOUNDATION, FRONT-END FIRST. *AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE DEALERSHIP WAS NOTIFIED, BUT DID NOT RESOLVE THE PROBLEM. *AK *SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE WAS COMING HEAD OI WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE BEHIND CONSUMER'S VEHICLE WAS PUSHED INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK DT: CONTACT STATED THE AIR BAGS DID NOT DEPLOY IN A HEAD ON CRASH. WHILE TRAVELING AN ABOUT 60 MPH THE VEHICLE SUSTAINED INJURIES. *AR BAGS DID NOT DEPLOY. *AK DT: CONTACT TAS THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT TO THE VEHICLE. STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT STATED THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS A MODMENTARY LOSS OF VEHICLE CONTACT. THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLO	8023471	CHEVROLET	BLAZER	2001	2002-07-01	IN ADDITIONAL INFORMATION DEALER IS AWARE OF THE PROBLEM. PH
DRIVER SIDE AIR BAG FAILED TO DEPLOY IN A CRASH THROUGH: 1. A SIX FOOT TALL WOODEN FENCE AT ALMOST 30MPH, THEN 2. THE EXTERIOR SIDE OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINK AND PLUMBINES SEMASHING UP AND OVER THE FIFTEEN-INCH CONCRETE FOUNDATION, FRONT-END FIRST.*AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE DEALERSHIP WAS NOTIFIED, BUT DID NOT RESOLVE THE PROBLEM. *AK *SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE WAS COMING HEAD ON WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE BEHIND CONSUMER'S VEHICLE WHICH SESULTED IN A HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK VEHICLE SUPPED WHILE TRAVELING ON ICE AT 55 MPH, CAUSING THE VEHICLE TO STRIKE A CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. THE CONTACT STATED WHILE DRIVING 55 MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTACT. AIR BAGS DID NOT DEPLOY. THE CONTACT STATED WHILE DR						CONSUMER STATES WHILE DRIVING 30MPH HAD FRONT END COLLISION AND NEITHER PASSENGER
FENCE AT ALMOST 30MPH, THEN 2. THE EXTERIOR SIDE OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINK AND PLUMBING FIXTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH CONCRETE FOUNDATION, FRONT-END FIRST.*AK WHILE DRIVING AT 53 MPH, THE CONSUMER'S VEHICLE REAR ENDED ANOTHER VEHICLE. UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE DEALERSHIP WAS NOTIFIED, BUT DID NOT RESOLVE THE PROBLEM. *AK *SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE WAS COMING HEAD OF WHICH SHE WAS PUSHED INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MINOR INJURIES. *AK CONSUMER'S VEHICLE WAS INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE 10105341 CHEVROLET BLAZER 2001 2004-12-22 MANUFACTURE. *AK VEHICLE SLIPPED WHILE TRAVELING ON ICE AT 55 MPH, CAUSING THE VEHICLE TO STRIKE A CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONTACT STATED THE AIR BAGS DID NOT DEPLOY. CONTACT LOST CONTROL OF THE VEHICLE AND ABOUT 60 MPH THE VEHICLE HYDRO PLANED. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THREE PEOPLE SUSTAINED INJURIES. A POLICE REPORT WAS TAKEN. THE DEALER WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A DEVER POR THE VEHICLE, HAVE ON FREE REMEDY. VEHICLE WAS TOTALED.**AK DT*: THE CONTACT STATED WHILE DRIVING 55 MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE, AND ON FREE REMEDY. VEHICLE WAS TOTALED.**AK MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. HER POULCE WERE ALERTED, AND A REPORT	10002341	CHEVROLET	BLAZER	2001		
IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE DEALERSHIP WAS NOTIFIED, BUT DID NOT RESOLVE THE PROBLEM. *AK *SC CONSUMER'S VEHICLE WAS AT A COMPLETE STOP AND ANOTHER VEHICLE WAS COMING HEAD OI WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE BEHIND CONSUMER'S VEHICLE WHICH SHE WAS PUSHED INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK CHEVROLET BLAZER 2001 2004-12-22 MANUFACTURER. *AK VEHICLE SLIPPED WHILE TRAVELING ON ICE AT 55 MPH, CAUSING THE VEHICLE TO STRIKE A CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THREE PEOPLE SUSTAINED INJURIES. A POLICE REPORT WAS TAKEN. THE DEALER WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A DT*: THE CONTACT STATED WHILE DRIVING 55 MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE, STNUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT	10060150	CHEVROLET	BLAZER	2001	2004-02-24	FENCE AT ALMOST 30MPH, THEN 2. THE EXTERIOR SIDE OF A 2-STORY HOME THAT CONTAINED THE KITCHEN SINK AND PLUMBING FIXTURES, WHILE SMASHING UP AND OVER THE FIFTEEN-INCH
WHICH RESULTED IN A HEAD ON COLLISION. THERE WAS A VEHICLE BEHIND CONSUMER'S VEHICLE WHICH SHE WAS PUSHED INTO DUE TO THE HEAD ON COLLISION. HOWEVER, UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED MAJOR INJURIES. *AK CONSUMER'S VEHICLE WAS INVOLVED IN A FRONT COLLISION AT 40 MPH DUE TO INCLEMENT WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK VEHICLE SLIPPED WHILE TRAVELING ON ICE AT 55 MPH, CAUSING THE VEHICLE TO STRIKE A CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. *AK DT: CONTACT STATED THE AIR BAGS DID NOT DEPLOY IN A HEAD ON CRASH. WHILE TRAVELING AT ABOUT 60 MPH THE VEHICLE HYDRO PLANED. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THREE PEOPLE SUSTAINED INJURIES. A POLICE REPORT WAS TAKEN. THE DEALER WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A DT*: THE CONTACT STATED WHILE DRIVING SS MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE, AND THEY OFFERED NO FREE REMEDY. VEHICLE WAS TOTALED. *AK DT*: THE CONTACT STATED WHILE DRIVING SS MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT	10072173	CHEVROLET	BLAZER	2001	2004-04-30	IMPACT, THE AIR BAGS DID NOT DEPLOY. THE CONSUMER SUSTAINED MINOR INJURIES. THE
WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK VEHICLE SLIPPED WHILE TRAVELING ON ICE AT 55 MPH, CAUSING THE VEHICLE TO STRIKE A CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. *AK DT: CONTACT STATED THE AIR BAGS DID NOT DEPLOY IN A HEAD ON CRASH. WHILE TRAVELING AT ABOUT 60 MPH THE VEHICLE HYDRO PLANED. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THREE PEOPLE SUSTAINED INJURIES. A POLICE REPORT WAS TAKEN. THE DEALER WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A BUYER FOR THE VEHICLE, AND THEY OFFERED NO FREE REMEDY. VEHICLE WAS TOTALED. *AK DT*: THE CONTACT STATED WHILE DRIVING 55 MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT	10101364	CHEVROLET	BLAZER	2001	2004-11-11	
CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT DEPLOY.*AK DT: CONTACT STATED THE AIR BAGS DID NOT DEPLOY IN A HEAD ON CRASH. WHILE TRAVELING AT ABOUT 60 MPH THE VEHICLE HYDRO PLANED. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THREE PEOPLE SUSTAINED INJURIES. A POLICE REPORT WAS TAKEN. THE DEALER WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A BUYER FOR THE VEHICLE, AND THEY OFFERED NO FREE REMEDY. VEHICLE WAS TOTALED.*AK DT*: THE CONTACT STATED WHILE DRIVING 55 MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT	10105341	CHEVROLET	BLAZER	2001	2004-12-22	WEATHER. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER CONTACTED THE MANUFACTURER. *AK
ABOUT 60 MPH THE VEHICLE HYDRO PLANED. THE CONTACT LOST CONTROL OF THE VEHICLE AND CRASHED. THREE PEOPLE SUSTAINED INJURIES. A POLICE REPORT WAS TAKEN. THE DEALER WAS CONTACTED BUT OFFERED NO ASSISTANCE. THE MANUFACTURER INFORMED HER THEY HAVE A BUYER FOR THE VEHICLE, AND THEY OFFERED NO FREE REMEDY. VEHICLE WAS TOTALED.*AK DT*: THE CONTACT STATED WHILE DRIVING 55 MPH, THERE WAS A MOMENTARY LOSS OF VEHICLE CONTROL, THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT	10106657	CHEVROLET	BLAZER	2001	2004-12-25	CONCRETE RETAINING WALL, AND IT ROLLED OVER. UPON IMPACT, AIR BAGS DID NOT
CONTROL, THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT	10142568	CHEVROLET	BLAZER	2001	2005-10-05	BUYER FOR THE VEHICLE, AND THEY OFFERED NO FREE REMEDY. VEHICLE WAS TOTALED.*AK
	10174898	CHEVROLET	BLAZER	2001	2006-11-05	CONTROL, THE VEHICLE STRUCK A NEARBY TREE STUMP, AND THE AIRBAGS DID NOT DEPLOY. THE CONTACT WAS WEARING A SEAT BELT, BUT NO INJURIES WERE SUSTAINED. THERE WAS MODERATE DAMAGE TO THE FRONT OF THE VEHICLE. THE POLICE WERE ALERTED, AND A REPORT

	1			1	
10175892	CHEVROLET	BLAZER	2001	2001-12-04	MY DAUGHTER WAS IN A CAR CRASH. UNFORTUNATELY MY DAUGHTER WAS AT FAULT. SHE WAS GOING 55 MPH AND HIT A CAR THAT WAS STOPPED AT A LIGHT HER AIR BAG DID NOT DEPLOY. SHE HAS NECK AND BACK PAINS. *JB
					A FRONTAL IMPACT OCCURRED AT 40 MPH AS ANOTHER MOTORIST PULLED OUT IN FRONT OF ME. THE AIR BAGS DID NOT DEPLOY. THE FRONT DRIVER SEAT BELT DID NOT PROPERLY RESTRAIN ME AND I WAS FORCED INTO THE ROOF AT THE TRIM EDGE OF THE WINDSHIELD, SUSTAINING A
10184395	CHEVROLET	BLAZER	2001	2005-05-19	MINOR SCALP LACERATION, CERVICAL DISC DAMAGE, AND A CONCUSSION. THE VEHICLE WAS TOTALED BY NATIONWIDE INSURANCE. *JB
40454000	CUEVADOLET	014750	2001	2012 04 05	TL* THE CONTACT OWNS A 2001 CHEVROLET BLAZER. THE CONTACT STATED THAT WHILE DRIVING 40 MPH, THE CONTACT CRASHED INTO THE SIDE OF ANOTHER VEHICLE. THE CONTACT STATED THAT THE FORCE OF THE IMPACT CAUSED THE VEHICLE TO BOUNCE OFF THE SECOND VEHICLE. THE AIR BAGS DID NOT DEPLOY. THE PASSENGER SUSTAINED INJURIES TO THE LEFT ANKLE AND KNEES, AS WELL AS A BROKEN THUMB. THE CONTACT WAS TRANSPORTED TO THE HOSPITAL AS A PRECAUTIONARY MEASURE. THE VEHICLE WAS NOT INSPECTED FOR THE CAUSE OF FAILURE NOR
10454988	CHEVROLET	BLAZER	2001	2012-04-06	REPAIRED. THE FAILURE AND THE CURRENT MILEAGES WERE 122,000. CRASHED INTO 14FOOT UHAUL GOING ABOUT 65MPH AIR BAGS NEVER WORKED. PLEASE ADVISE!
752662	CHEVROLET	SILVERADO	2001	2001-09-22	*AK A TWO IMPACT WRECK ,WITH THE SECOND AT 55 MPH HIT HEAD ON,NO AIRBAG OR ONSTAR
754465	CHEVROLET	SILVERADO	2001	2001-08-04	DEPLOYMENT. *AK
757639	CHEVROLET	SILVERADO	2001	2002-01-16	DRIVER'S SIDE AIRBAG DID NOT DEPLOY DURING A FRONTAL IMPACT CRASH AT APPROXIMATELY 40 MPH.*AK
765623	CHEVROLET	SILVERADO	2001	2002-07-24	NO AIRBAGS DEPLOYED DURING FRONTAL COLLISION AT 40 MPH CRASH. OCCUPANT OF OTHER VEHICLE HAD TO BE EXTRACATED FROM HER VEHICLE AND LIFE FLIGHTED TO MEDICAL FACILITY.*AK
894462	CHEVROLET	SILVERADO	2001	2001-08-04	CONSUMER'S VEHICLE REAR ENDED A BIG WEIGHT TRUCK AT APPORXIMATELY 65 MPH, AND NEITHER DRIVER'S SIDE NOR PASSENGER'S SIDE AIRBAGS DEPLOYED. DEALER HAS BEEN EXAMINING THE VEHICLE.*AK
896975	CHEVROLET	SILVERADO	2001	2001-09-22	WHILE TRAVELING APPROXIMATELY 55 MPH, VEHICLE REAR ENDED A U-HAUL TRUCK THAT WAS ALSO IN MOTION. APPROXIMATELY \$4600.00 DAMAGE WAS DONE TO THE FRONT END OF VEHICLE, AND AIR BAGS FAILED TO DEPLOY. DEALERSHIP STATED THAT AIR BAGS FAILED TO DEPLOY BECAUSE BOTH VEHICLES WERE IN MOTION. PLEASE PROVIDE ANY ADDITIONAL INFORMATION / ATTACHMENTS. *NOTE: DRIVER OF VEHICLE SUFFERED ARM, WRIST, AND LEG INJURIES.*AK
899261	CHEVROLET	SILVERADO	2001	2001-10-11	WHILE OPERATING VEHICLE IN WET ROAD CONDITIONS, AND TRAVELING APPROXIMATELY 50 TO 55 MPH VEHICLE HYDROPLANED AND CRASHED INTO A CEMENT BARRIER. BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. NO EXAMINATION OF THE VEHICLE HAS TAKEN PLACE TO DETERMINE A CAUSE FOR THIS PROBLEM. *NOTE: DRIVER RECEIVED SEVERE FACIAL INJURIES. PLEASE PROVIDE ANY ADDITIONAL INFORMATION / DOCUMENTATION. *AK
8001948	CHEVROLET	SILVERADO	2001	2002-01-07	VEHICLE WAS INVOLVED IN 20-25 MPH FRONTAL COLLISION IN WHICH DRIVERS AND PASSENGERS AIR BAGS DID NOT DEPLOY, CAUSE UNKNOWN, DEALER HAS BEEN NOTIFIED. *AK*SLC
8002768	CHEVROLET	SILVERADO	2001	2002-01-16	FRONTAL IMPACT AT 65MPH TOTALLED VEHICLE; UPON IMPACT, AIR BAGS DIDN'T DEPLOY. DELAER WAS NOTIFIED.*AK
8004056	CHEVROLET		2001	2002-02-05	CONSUMER HAD A HEAD-ON COLLISION AT 55 MPH AND NEITHER AIRBAG DEPLOYED. DRIVER AND PASSENGER SUFFERED CHEST/NECK AND LEG INJURIES. VEHICLE WAS TOTALLED.*AK CONSUMER STATES THAT A PERSON FROM THE OTHER VEHICLE WAS KILLED IN THE ACCIDENT. *SLC
8004268	CHEVROLET	SILVERADO	2001	2002-02-17	WHILE DRIVING AT 55 MPH CONSUMER'S VEHICLE RAN INTO ANOTHER VEHICLE HEAD-ON, BUT NONE OF AIR BAGS DEPLOYED. HAS NOT CONTACTED DEALER.*AK
330-1200	CHEVILOLET	SIEVENADO	2001	2002 02 17	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION OF APPROXIMATELY 50 MPH, AND NEITHER
8005327	CHEVROLET	SILVERADO	2001	2002-02-27	FRONTAL AIR BAG DEPLOYED. DEALER / MANUFACURER WERE NOTIFIED. FEEL FREE TO PROVIDE ANY FURTHER INFORMATION.*AK
8006559	CHEVROLET	SILVERADO	2001	2002-03-23	CONSUMER STATES WHILE DRIVING 30-35 MPH WITHOUT WARNING OCCURRED IN A FRONTAL COLLISION THE AIR BAGS NOT DEPLOY CAUSING MINOR INJURIES. NLM
8009248	CHEVROLET	SILVERADO	2001	2002-03-06	WHILE TRAVELING ON HIGWAY HIT ANOTHER VEHICLE/ VEHICLE IN ANOTHER LANDE TO OVOID CAR HE HIT AND RAN INTO MERIDIAN STRIP. UPON IMPACT, DUAL AIRBAGS DIDN'T DEPLOY. DEALERSHIP WASAWARE OF PROBLEM.*AK
					WHILE DRIVING TRUCK AT 40 MPH VEHICLE INVOLVED IN A FRONTAL COLLISION WITH ANOTHER SPEEDING VEHICLE. UPON IMPACT, AIR BAGS FAILED TO DEPLOY. TRUCK WAS TAKEN TO DEALERSHIP, AND THEY INFORMED OWNER THAT "THERE WAS NO REASON FOR AIR BAGS NOT TO
8012069	CHEVROLET	SILVERADO	2001	2002-06-08	DEPLOY". PLEASE DESCRIBE DETAILS. *AK
8012818	CHEVROLET	SILVERADO	2001	2002-06-08	IN A FRONTAL COLLISON WHILE DRIVING AT 60MPH NONE OF THE AIR BAGS DEPLOYED. VEHICLE HAD MAJOR DAMAGE. *AK
8017140	CHEVROLET	SILVERADO	2001	2002-08-18	IN A FRONTAL COLLISION NONE OF THE AIR BAGS DEPLOYED ON IMPACT, CAUSING INJURIES TO DRIVER.*AK. ALSO THE PASSENGER WAS INJURED.*JB
					CONSUMER STATES: WHILE DRIVING AT THE SPEED OF 45MPH WAS INVOLVED IN A FRONTAL COLLISION NEITHER AIR BAG DEPLOYED. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDED ANY
10001355	CHEVROLET	SILVERADO	2001		ADDITIONAL IN FORMATION. TS

					WHILE TRAVELING AT 65 MPH, CONSUMER STATES' ANOTHER DRIVER PULLED INFRONT AND
					CONSUMER HIT THAT VEHICLE ON ITS SIDE. NONE OF THE VEHICLES ARE BAGS DEPLOYED.
40004774	CHEV/DOLET	CILL /ED A D O	2004		CONSUMER FEELS THAT THIS COLLISION WAS A HARD IMPACT AND AIRBAGS SHOULD HAVE
10001771	CHEVROLET	SILVERADO	2001		DEPLOYED. CONSUMER WAS IN A ACCIDENT AND HIT A WALL AND THE AIR BAGS DIDN'T DEPLOY UPON
10006756	CHEVROLET	SILVERADO	2001	2003-01-30	CONTACT. PH
					FRONTAL IMPACT ON FREEWAY AT 45 MPH CHEVROLET, SILVERADO 4X4 TOTALED. AIRBAGS DID
10020745	CHEVROLET	SILVERADO	2001	2003-05-23	NOT DEPLOY UPON IMACT.*AK
					PROBLEM WITH AIRBAG SYSTEM ON 2001 CHEVROLET PICK UP TRUCK. *MR THE VEHICLE
					COLLIDED WITH A MOVING ANIMAL AND THE AIRBAG(S) DIDN'T DEPLOY. (THE ANIMAL WAS ABOUT SIX HUNDRED POUNDS AND THE CONSUMER HAD DRIVEN THE VEHICLE AT A NORMAL
10024534	CHEVROLET	SILVERADO	2001	2002-03-12	SPEED) *SCC *JB
10041290	CUEV/DOLET	SILVERADO	2001	2002 10 17	A 2001 CHEVY SILVERADO WAS STRUCK ON THE SIDE AND SENT INTO A TREE AT BETWEEN 30-35 MPH. THERE WAS SIGNIFICANT FRONT END DAMAGE AND THE AIR BAGS DID NOT DEPLOY. *LA
10041290	CHEVROLET	SILVERADO	2001	2003-10-17	WHILE DRIVING AT 55 MPH CONSUMER LOST CONTROL OF VEHICLE WHILE TRAVELING UP A HILL.
					THEN VEHICLE STRUCK A WOODEN FENCE. ONE BEAM OF THE FENCE CAME THROUGH THE
					WINDSHIELD, STRIKING THE CONSUMER IN THE HEAD, EVENTUALLY KILLING HIM. ALSO, TWO
					PASSENGERS SUSTAINED INJURIES. IN THE CONFUSION, CONSUMER DEPRESSED THE GAS PEDAL
					INSTEAD OF THE BRAKES AND STRUCK A FIRE HYDRANT. ALL PASSENGERS AND THE CONSUMER
					WERE WEARING SEAT BELTS. HOWEVER, THE AIR BAGS DID NOT DEPLOY. POLICE ARRIVED ON THE SCENE AND MADE A REPORT. MANUFACTURER AND DEALER HAD BEEN NOTIFIED OF THE
10042759	CHEVROLET	SILVERADO	2001	2000-12-31	INCIDENT. *AK
					LAWYER REPRESENTING CONSUMER WHO WAS INJURED WHEN THE DRIVER'S SIDE AIRBAG FAILED
10059656	CHEVROLET	SILVERADO	2001	2001-12-19	TO DEPLOY. *LA (LAWYER CLYDE JACKSON ON BEHALF OF CLIENT)* JB
					I WAS DRIVING EAST ON F.M. 356 AT ABOUT NOON. I WAS TRAVELLING ABOUT 50 MPH. A CAR
					TURNED IN FRONT OF ME AND I ATTEMPTED TO PASS THE CAR. I WAS UNABLE TO DUE TO
					ONCOMING TRAFFIC, SO I QUICKLY RETURNED TO MY LANE. ONE OF MY TIRES WENT OFF ONTO
					THE UNPAVED SHOULDER AND I WENT DOWN A SMALL EMBANKMENT. IT WAS MUDDY SO I
					COULD NOT STOP. I HIT A LARGE PINE TREE HEAD ON AND STOPPED. BOTH OF US WERE WEARING
					OUR SEATBELTS. MY AIRBAG FAILED TO DEPLOY CAUSING MY HEAD AND TORSO TO STRIKE THE
					STEERING WHEEL. I SUFFERED 6TH NERVE PAULSEY AND AN ANUERISM DEVELOPED ON MY AORTA. THE AORTA HAD TO BE SURGICALLY REPAIRED. MY GRANDDAUGHTER'S AIRBAG HAD
					BEEN TURNED OFF DUE TO HER SMALL SIZE. SHE SUFFERED A BROKEN LEG AND A SLIGHT
10072926	CHEVROLET	SILVERADO	2001	2001-12-19	CONCUSSION. THE TRUCK WAS TOTALLED. *AK
					WHILE DRIVING CONSUMER WAS TOWING A TRAILERTHE DRIVER'S SIDE REAR TIRE TREADS
					SEPARATED FROM THE TRAILER. CONSUMER WAS NOT ABLE TO MAINTAIN CONTROL OF THE
					VEHICLE, AND COLLIDED INTO A CONCRETE BARRIER. UPON IMPACT, BOTH FRONTAL AIR BAGS DID
					NOT DEPLOY. PASSENGER SUSTAINED HEAD INJURIES, AND WAS TRANSPORTED TO A HOSPITAL BY
10079979	CHEVROLET	SILVERADO	2001	2004-06-25	AN AMBULANCE. VEHICLE AND TRAILER WERE TOTALED. *AK *NM
					CONSUMER'S, VEHICLE WAS REAR ENDED WHILE DRIVING 50 MPH. THE VEHICLE WAS FORCE INTO
					A SPIN AND THEN, IT HIT A CONCRETE ROAD DIVIDER. UPON IMPACT, NEITHER FRONTAL AIR BAGS
					DEPLOYED. DRIVER SUSTAINED INJURIES, AND HAD TO BE TRANSPORTED TO A LOCAL HOSPITAL.
					DEALER AND MANUFACTURER WERE NOTIFIED. *AK THE CONSUMER STATED THAT THE SEAT
10102512	CHEVADOLET	CILVEDADO	2001	2004 12 05	BELT DID NOT KEEP HER FROM HITTING HER CHEST ON THE STEERING WHEEL. AFTER THE FRONT
10103512	CHEVROLET	SILVERADO	2001	2004-12-05	AND THE BACK OF THE VEHICLE HIT THE CONCRETE DIVIDER THE AIR BAGS DID NOT DEPLOY. *TC AIR BAGS FAILED TO DEPLOY IN A 45 MPH FRONT END COLLISION ON MY 2001 CHEVROLET
10107706	CHEVROLET	SILVERADO	2001	2004-12-29	SILVERADO. *NM
					WHILE TRAVELING AT 55 MPH CONSUMER LEFT THE FREEWAY AND STRUCK A LARGE PILE OF DIRT.
					UPON IMPACT, THE AIR BAGS DID NOT DEPLOY. CONSUMER SUSTAINED HEAD AND BACK
10109017	CHEVROLET	SILVERADO	2001	2005-01-04	INJURIES. WAS TAKEN TO THE EMERGENCY ROOM. THE VEHICLE WAS TOTALED.*AK *AK
					THERE WAS AN ACCIDENT ON HINE 4 2005. HIDDNIADACT THE DRIVER'S CIDE FRONTAL ALBOAC
					THERE WAS AN ACCIDENT ON JUNE 1, 2005. UPON IMPACT, THE DRIVER'S SIDE FRONTAL AIRBAG FAILED TO DEPLOY. THE PASSENGER SIDE AIRBAG HAD BEEN TURNED OFF. THE DRIVER SUSTAINED
					MINOR INJURIES. THE CONSUMER REAR ENDED A TRAILER A POLICE REPORT WAS TAKEN. NO
10138394	CHEVROLET	SILVERADO	2001	2005-06-01	AIRBAG WARNING LIGHT CAME ON.*AK UPDATED 11/02/05. *JB
			-	•	•

CHEVROLET	SILVERADO	2001	2013-11-14 2014-01-01	MY FIANCE AND I WERE DRIVING HOME AND AS WE ENTERED TOWN GOING APPROXIMATELY 35-45 MPH THE VEHICLE SWERVED OFF THE ROAD AND COLLIDED INTO A TELEPHONE POLE BREAKING IT IN HALF CAUSING THE TOP HALF OF THE TELEPHONE POLE TO SWING DOWN AND SMACK INTO THE WINDSHIELD. HE SMACKED HIS FACE OFF OF THE STEERING WHEEL AND I WAS LAYING DOWN ON THE SEAT AND ROLLED OFF AND BROKE THE ASHTRAY HOLDER WITH MY FACE. DURING THE IMPACT NOT A SINGLE AIRBAG DEPLOYED EVEN THOUGH THE AIRBAGS WERE ALL IN WORKING ORDER. THE IMPACT WAS SO SEVERE THAT THE TAILGATE OF THE TRUCK BENT OUTWARD, THE RADIATOR WAS RIPPED OUT FROM BENEATH THE VEHICLE AND THE FRONT PASSENGER SIDE WAS TOTALED. I WAS THEN PUT INTO A NECK BRACE, STRAPPED TO A GURNEY AND RUSHED TO THE HOSPITAL. I WILL REITERATE THE FACT THAT NONE OF THE AIRBAGS DEPLOYED CAUSING THE BOTH OF US TO BE INJURED. WE LUCKILY SURVIVED THE CRASH BUT HAD THE AIRBAGS DEPLOYED THE BOTH OF US WOULD HAVE SUFFERED MINIMAL INJURIES. *TR I REAR ENDED SOMEONE GOING ABOUT 70 MPH AND MY AIR BAGS DID NOT DEPLOY. *TR NO DEPLOYMENT OF THE AIR BAG DURING ACCIDENT CAUSING THE CONSUMER TO JAM HIS HAND ON THE STEERING WHEEL AND TO INJURE HIS BACK. NLM
CHEVROLET	JUBURDAN	2001		FRONT AIRBAGS FAILED TO DEPLOY DURING A HEAD ON COLLISION AT 30 MPH. FINAL DAMAGE
CHEVROLET	SUBURBAN	2001	2001-05-24	ESTIMATE UNKOWN DUE TO PENDING SAFETY INVESTIGATION. *AK
		2001	2000-12-27	COSNUMER WAS DRIVING AT APPROXIMATELY 35-40 MPH, WENT OFF ROAD TO AVOID ONCOMING VEHICLE, RAN INTO DITCH HEAD ON, AND HIT A TREE. VEHICLE WAS TOTALED. UPON IMPACT, DUAL AIRBAGS DID NOT DEPLOY, CAUSING MINOR INJURIES.*AK CONSUMER HAD A FRONT COLLISION AT 35-40 MPH, AND NEITHER AIRBAG DEPLOYED. CONSUMER SUFFERED NECK/ BACK AND KNEE INJURIES. VEHICLE AT DEALERSHIP AT THIS TIME. PLEASE ADD FURTHER DETAILS.*AK
CHEVROLET	SUBURBAN	2001	2001-11-26	WHILE DRIVING AT 45 MPH CONSUMER T BONED ANOTHER VEHICLE, AND THEN SPUN OUT OF CONTROL, AND RAN INTO A DITCH. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. CONTACTED DEALER, AND THE DEALER WAS NOT WILLING TO DO ANYTHING. *AK *YH
CHEVROLET	SUBURBAN	2001	2002-07-10	AT 45MPH VEHICLE CRASHED. UPON IMPACT, AIRBAGS DID NOT DEPLOY. CAUSE UNKNOWN. DEALER NOTIFIED.*AK
CHEVROLET	SUBURBAN	2001		THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION, AND THE NONE OF THE AIR BAGS DEPLOYED. *JB
CHEVROLET	SUBURBAN	2001	2003-09-27	WHILE DRIVING 60 MPH VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AND AIR BAGS DID NOT DEPLOY. *AK
CHEVROLET	SUBURBAN	2001	2003-10-08	WHILE DRIVING, ANOTHER MOTORIST FAILED TO STOP AT A RED LIGHT AND THE CONSUMER HIT HIM ON THE PASSENGER'S SIDE AND THE AIR BAGS DID NOT DEPLOY. *AK *SC *JB
CHEVROLET	SUBURBAN	2001	2008-11-06	TL*THE CONTACT OWNS A 2001 CHEVROLET SUBURBAN. ON NOVEMBER 6, 2008, THE CONTACT WAS INVOLVED IN A SERIOUS CRASH. THE AIR BAGS FAILED TO DEPLOY AND THE ENTIRE FRONT END AND PASSENGER SIDE OF THE VEHICLE WERE DAMAGED. THE VEHICLE WAS DESTROYED. THE CONTACT HAS PICTURES AND A POLICE REPORT. THERE WERE NO OTHER PASSENGERS IN THE VEHICLE AND THE CONTACT WAS WEARING HER SEAT BELT AT THE TIME. THERE WAS NO MAINTENANCE PERFORMED ON THE AIR BAGS PRIOR TO THE CRASH. THE SPEED WAS UNKNOWN. THE FAILURE MILEAGE WAS 100,000. TL*THE CONTACT OWNS A 2001 CHEVROLET SUBURBAN. THE CONTACT STATED THAT ON MAY 18, 2010, WHILE DRIVING AT 45 MPH, THE VEHICLE COLLIDED WITH AN ONCOMING VEHICLE. THE AIR BAGS DID NOT DEPLOY. THE VEHICLE SUSTAINED EXTENSIVE DAMAGES AND WAS TOWED FROM
CHEVROLET	SUBURBAN	2001	2010-05-18	THE SCENE. THE CONTACT AND PASSENGERS SUSTAINED INJURIES AND WERE TAKEN TO THE HOSPITAL. A POLICE REPORT WAS FILED. THE CONTACT HAD NOT CALLED THE DEALERSHIP OR THE MANUFACTURER AT THE TIME OF THE COMPLAINT. THE FAILURE AND CURRENT MILEAGES WERE APPROXIMATELY 105,000.
CHEVROLET	SUBURBAN	2001	2015-06-15	MY SON WAS DRIVING AND REAR ENDED A MAN GOING APPROXIMATELY 50 MPH. THE FRONT END SUSTAINED A GREAT DEAL OF DAMAGE, INCLUDING, BUT NOT LIMITED TO, THE ENGINE BEING PUSHED BACK SEVERAL INCHES. THE AIR BAGS DID NOT DEPLOY. MY SON SUSTAINED MINOR WHIPLASH TYPE INJURIES TO HIS NECK AND BACK.
CHEVROLET	SUBURBAN	2001	2015-06-18	TL* THE CONTACT OWNED A 2001 CHEVROLET SUBURBAN. WHILE DRIVING AT 55 MPH UPHILL, THE CONTACT DEPRESSED THE BRAKE PEDAL AND THE VEHICLE HYDROPLANED. AS A RESULT, THE CONTACT CRASHED INTO THE REAR OF A PICK-UP TRUCK. THE AIR BAGS FAILED TO DEPLOY. A POLICE REPORT WAS FILED. THERE WAS ONE INJURY THAT REQUIRED MEDICAL ATTENTION. THE VEHICLE WAS DESTROYED AND TOWED TO AN INDEPENDENT MECHANIC. THE MANUFACTURER WAS NOT MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 270,000.
		2001	2002-07-10	TAHOE WAS TRAVELING UPHILL ON PRIVATE GRAVEL DRIVE WHEN HIT BY TRUCK TRAVELING DOWNHILL AROUND BLIND CURVE. TRUCK WAS TRAVELING AT BETWEEN 20 AND 25 MPH WHEN IT HIT TAHOE. BOTH OF TRUCK'S AIRBAGS INFLATED. MY AIRBAGS DID NOT INFLATE, AND I HIT THE STEERING WHEEL WITH MY STOMACH AND CHEST.*AK
	CHEVROLET CHEVROLET	CHEVROLET SUBURBAN CHEVROLET SUBURBAN	CHEVROLET SUBURBAN 2001 CHEVROLET SUBURBAN 2001	CHEVROLET SILVERADO 2001 2014-01-01 CHEVROLET SUBURBAN 2001 2001-05-24 CHEVROLET SUBURBAN 2001 2000-12-27 CHEVROLET SUBURBAN 2001 2002-02-05 CHEVROLET SUBURBAN 2001 2002-02-05 CHEVROLET SUBURBAN 2001 2002-07-10 CHEVROLET SUBURBAN 2001 2003-09-27 CHEVROLET SUBURBAN 2001 2003-10-08 CHEVROLET SUBURBAN 2001 2008-11-06 CHEVROLET SUBURBAN 2001 2010-05-18 CHEVROLET SUBURBAN 2001 2015-06-15 CHEVROLET SUBURBAN 2001 2015-06-18

					LUT DV A DED LIGHT DUNINED (AF /FOMDU) ON DDU/FDIC CIDE LUT A CECOND CAD TUEN A
					HIT BY A RED LIGHT RUNNER (45/50MPH) ON DRIVER'S SIDE, HIT A SECOND CAR, THEN A CONCRETE POST HEAD ON. NOT ONE OF THE FOUR AIR BAGS ENGAGED AT ANYTIME. THE CAR
					WAS TOTALED. I HAVE DOCUMENTATION, PICTURES, POLICE REPORT, AND HAVE CONTACTED
					CHEVY, THEY HAVE NO CLEAR RESPONSE ON WHY? IF YOU WOULD LIKE MORE DETAIL ON INJURES
					OR HAVE ANY QUESTION PLEASE FILL FREE TO CONTACT ME. THANK YOU FOR YOUR TIME,
766175	CHEVROLET	TAHOE	2001	2002-07-19	DANIELLE HURST-STONE. *AK
					VEHICLE WAS INVOLVED IN AN ACCIDENT WHILE TRAVELING AT 50 MPH WHEN VEHICLE T-BONED
					A VEHICLE CROSSING AN INTERSECTION. AIRBAGS FAILED TO DEPLOY. DEALERSHIP COULD NOT
					PROVIDE A REASON FOR FAILURE OF AIRBAGS TO DEPLOY. *AK THE MAUFACTURER INDICATED
					THAT THE VEHICLE SKIDDED 20 TO 25 FEET AFTER IMPACT AND THE AIR BAG FAILED TO DEPLOY
884576	CHEVROLET	TAHOE	2001	2001-03-21	FOR THIS REASON. THE CONSUMER DISAGREES. *YH
					DRIVER'S SIDE AND PASSENGER'S SIDE AIRBAGS FAILED TO DEPLOY IN A FRONT END COLLISION.
899507	CHEVROLET	TAHOE	2001	2001-11-01	DEALER HAS YET TO BE CONTACTED. PLEASE PROVIDE FURTHER DETAILS.*AK
					DRIVER AND PASSENGER FRONTAL AIRBAGS FAILED TO DEPLOY WHEN CONSUMER WAS INVOLVED
					IN A 40MPH FRONTAL COLLISION. DEALER HAS YET TO BE CONTACTED. PLEASE PROVIDE FURTHER
8000772	CHEVROLET	TAHOE	2001	2001-12-01	DETAILS.*AK
					WHILE TRAVELING ONTO ON INTERSECTION ANOTHER VEHICLE RAN THE RED LIGHT AND HIT
8017829	CHEVROLET	TAHOE	2001	2001-09-19	CONSUMER'S VEHICLE. UPON IMPACT, DUAL AIRBAGS DIDN'T DEPLOY.DEALERSHIP WAS AWARE OF PROBLEM.*AK *YH
8017829	CHEVROLET	TAHUE	2001	2001-09-19	WHILE TRAVELING AT 35 MPH CONSUMER WAS HIT HEAD-ON, AND VEHICLE ALMOST TIPPED
					OVER. UPON IMPACT, FRONT AIR BAGS FAILED TO DEPLOY. PLEASE PROVIDE ANY FURTHER
8018113	CHEVROLET	TAHOE	2001	2002-04-05	INFORMATION.*AK
8018113	CHEVROLLI	TAHOL	2001	2002-04-03	THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION, AND NONE OF THE AIR BAGS DEPLOYED.
10018205	CHEVROLET	TAHOE	2001	2003-05-05	*NLM *PH *JB
1001010	CHETHOLE:	17.11.02	2001	2000 00 00	WHILE DRIVING 50 MPH. THE CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION.
					UPON IMPACT, THE AIRBAGS DID NOT DEPLOY. THE DRIVER SUSTAINED SEVERE HEAD INJURIES
10044753	CHEVROLET	TAHOE	2001	2003-10-12	AND WAS TAKEN TO A HOSPITAL. *AK *JB *NM
					WHILE DRIVING 40 MPH DRIVER HIT THE BRAKES SUDDENLY AND VEHICLE HIT THE CURB AND
					ROLLED TWICE. UPON IMPACT, AIRBAGS DID NOT DEPLOY. PEOPLE WERE EJECTED FROM THE
10046166	CHEVROLET	TAHOE	2001	2003-08-03	VEHICLE. AS A RESULT,THEY DIED. *AK
10066520	CHEVROLET	TAHOE	2001	2004-04-12	FRONTAL AIRBAGS DID NOT DEPLOY IN COLLISION. *AK
					I WAS DRIVINEG ON THE FREEWAY. THE CRUISE CONTROL WAS SET AT 70 MPH. IT WAS RAINING I
					WENT THROUGH A PUDDLE AND THE CAR HYDROPLANED AND HEADED TOWRD THE CONCRETE
					MEDIAN, IT WOULD NOT STRAIGHTEN AND I HIT THE MEDIAN HEAD ON. THE AIRBAGS DID NOT
10072577	CHEVROLET	TAHOE	2001	2004-04-30	DEPLOY.*AK
10148912	CHEVROLET	TAHOE	2001	2004-12-06	HEAD-ON COLLISION AT 50 MPH AND AIRBAGS DID NOT INFLATE.*AK
					DRIVING IN LARGE PARKING LOT APPROX 25 MPH, LIGHT POLE WITH CONCRETE BASE WAS IN
					BLIND SPOT AS I WAS TURNING. HIT THE CONCRETE HEAD ON, \$12,000 WORTH OF DAMAGE TO
					MY TRUCK, FRAME BENT, FRONT END REPLACED AND THE AIR BAGS FAILED TO DEPLOY. THE DEALER HAD NO EXPLANATION OTHER THAN THE DAMAGE MUST HAVE BEEN IN JUST THE WRONG
10197689	CHEVROLET	TAHOE	2001	2003-11-03	SPOT. I WENT TO THE HOSPITAL WITH HEAD AND NECK INJURIES. *JB
10223626	CHEVROLET	TAHOE	2001	2008-03-28	AIRBAGS FAILED TO DEPLOY IN HEAD-ON CRASH. *TR
10223020	CHEVROLET	TAHOL	2001	2008-03-28	I WAS INVOLVED IN A COLLISION IN MY 2001 CHEVROLET TAHOE WHERE I REAR ENDED A CAR. MY
					VEHICLE WAS TRAVELING 54 MPH AND THE OTHER VEHICLE WAS SLOWING TO TURN WITHOUT
10365882	CHEVROLET	TAHOE	2001	2010-11-12	BLINKERS OR BRAKE LIGHTS. MY AIRBAGS DID NOT DEPLOY. *TR
1111002	3				A VEHICLE PULLED IN FRONT OF US AND OUR VEHICLE T BONED THAT VEHICLE. NONE OF ARE AIR
					BAGS DEPLOYED. WE WERE INJURED. THAT PERSON'S INSURANCE COMPANY CONTACTED US THE
					DAY AFTER THE ACCIDENT AND QUESTIONED WHY THE AIR BAGS DID NOT COME OUT? WE
10607227	CHEVROLET	TAHOE	2001	2007-07-04	WANTED TO KNOW WHY ALSO. *TR
					THE VEHICLE AIRBAGS FAILED TO DEPLOY IN ACCIDENT WERE IT RECEIVED SEVERE FRONT END
10783656	CHEVROLET	TAHOE	2001	2015-10-16	DAMAGE.
					TL* THE CONTACT OWNS A 2001 CHEVROLET TAHOE. WHILE DRIVING AT 45 MPH, ANOTHER
]					VEHICLE FAILED TO YIELD AND THE CONTACT CRASHED INTO THE DRIVER SIDE OF THAT VEHICLE.
					THE AIR BAGS FAILED TO DEPLOY. THE CONTACT DID NOT SUSTAIN ANY INJURIES. A POLICE REPORT
					WAS FILED. THE VEHICLE WAS TOWED TO AN AUTO BODY REPAIR CENTER FOR BODY REPAIRS, BUT
					WAS NOT DIAGNOSED FOR THE AIR BAG FAILURE. THREE YEARS LATER, WHILE DRIVING 25 MPH,
					THE CONTACT CRASHED INTO AN ANIMAL AND THEN INTO A GUARDRAIL. THE AIR BAGS FAILED TO
					DEPLOY. THE CONTACT SUSTAINED BACK INJURIES THAT REQUIRED MEDICAL ATTENTION. A POLICE
					REPORT WAS FILED. THE VEHICLE WAS TOWED TO AN AUTO BODY REPAIR CENTER, BUT WAS NOT
40000			255		DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE
10820375	CHEVROLET	TAHOE	2001	2014-01-18	MILEAGE WAS 120,000. THE VIN WAS UNAVAILABLE.
					WHILE TRAVELING AT 45 TO 50 MPH ANOTHER VEHICLE IN FRONT SLAMMED ON VEHICLE'S
					BRAKES, AND CONSUMER'S VEHICLE REAR ENDED THE OTHER VEHICLE. NONE OF AIRBAGS
					DEPLOYED, AND DRIVERS SIDE SEATBELT FAILED TO LOCK. CONSUMER WAS INJURED BY STEERING
001063	CHE/DOLET	TDACKED	2001	2001 07 02	WHEEL. CONSUMER HAD VEHICLE TOWED TO DEALER. PLEASE PROVIDE ANY FURTHER
891862	CHEVROLET	TRACKER	2001	2001-07-02	INFORMATION.*AK IN AN ACCIDENT, VEHICLE HIT A POLE AND UPON IMPACT AIRBAGS DID NOT DEPLOY, CAUSING
Ī	CHEVROLET	TRACKER	2001	2002-05-28	MINOR INJURIES TO DRIVER.*AK *YH
8011220		I I DAY VED	12001	12002-03-20	HANDA HADONIES TO DIVIVEIV. AIV. TH

					CONCLINED STATED WILLIE DRIVING AT NORMAL SPEED AND WEADING SEAT BELT HAD A FRONT
10033620	CHEVROLET	TRACKER	2001	2003-08-11	CONSUMER STATED WHILE DRIVING AT NORMAL SPEED AND WEARING SEAT BELT HAD A FRONT COLLISION ,AND NEITHER OF THE AIR BAGS DEPLOYED. NO WARNING LIGHT APPEARED PRIOR TO THE CRASH. POLICE REPORT AND PICTURES ARE AVAILABLE. *AK
					WHILE DRIVING 50 MPH DRIVER STRUCK A DEER HEAD ON. UPON IMPACT, DRIVER SIDE AIRBAG
10033912	CHEVROLET	TRACKER	2001		DIDN'T DEPLOY. THE DRIVER SUSTAINED SLIGHT INJURIES FROM MAKING CONTACT WITH THE STEERING WHEEL. *AK
					TL*THE CONTACT OWNS A 2001 CHEVROLET TRACKER. WHILE DRIVING 40 MPH ON A MAJOR
					HIGHWAY, THE CONTACT CRASHED INTO ANOTHER VEHICLE THAT WAS STOPPED IN THE ROAD. THE AIR BAGS FAILED TO DEPLOY. THE VEHICLE WAS DESTROYED. THE CONTACT WAS INJURED
					AND TRANSPORTED TO THE HOSPITAL. A POLICE REPORT WAS FILED. THE CURRENT AND FAILURE
10226797	CHEVROLET	TRACKER	2001	2008-04-17	MILEAGES WERE 130,000.
					DRIVER OF VEHICLE WHILE TRAVELING 35 MPH HIT A FORD F150 THAT MADE A U-TURN FROM THE RIGHT SHOULDER OF THE ROAD. DRIVER DID NOT HAVE TIME TO HIT BRAKES. AIRBAG DID NOT
10263033	CHEVROLET	TRACKER	2001	2009-02-01	DEPLOY. DRIVER WAS INJURED. *TR
10298267	CHEVBOLET	TDACKED	2001	2010-01-03	AIRBAG DID NOT DEPLOY ON CHEVY TRACKER 2001 AFTER BEING REAR ENDED AT 100 MPH WHILE
10298207	CHEVROLET	TRACKER	2001	2010-01-03	TRAVELING AT A SPEED OF 69 MPH AND HIT THE CENTER DIVIDER HEAD ON. *TR AT A 25MPH VEHICLE CRASHED AND AIRBAGS DID NOT DEPLOY. CAUSE UNKNOWN DEALER
8014453	CHEVROLET	TRAILBLAZER	2001		NOTIFIED.*AK
					WHILE DRIVING APPROXIMATELY 58 MPH IN RAINY WEATHER WITH A TRAILER ATTACHED, TRAILER
					STARTED TO FISHTAIL WHILE GOING DOWN HILL. TRAILER HAD SWUNG AROUND AND BROKE
					FREE OF THE HITCH AND HIT THE SIDE OF TRUCK. TRUCK GRAZED AN ENBANKMENT, AND WENT INTO THE MEDIUM STRIP, HITTING ANOTHER VEHICLE HEAD ON. VEHICLE WAS TOTALED, AND
					DRIVER SUFFERED A HEAD INJURY AND FRACTURED VERTEBRATE. NEITHER AIR BAG DEPLOYED
8018335	CHEVROLET	TRAILBLAZER	2001		UPON THE FRONTAL IMPACT. PLEASE DESCRIBE DETAILS. *AK
					THE VEHICLE HAS BEEN INVOLVED IN TWO ACCIDENTS IN WHICH NEITHER TIME DID THE AIR BAGS DEPLOY, DURING ONE ACCIDENT THE CONSUMER SAYS SHE ALSO DOESNT REMEMBER THE SEAT
					BELT TIGHTENING CAUSING HER TO STRICK HER HEAD ON THE STEERING WHEEL AND KNEES TO HIT
566304	GMC	YUKON	2001		THE DASH. *MJ
					VEHICLE INVOLVED IN A FRONTAL COLLISION AT APPROXIMATELY 75 MPH WITH A FORD ESCORT. UPON IMPACT, BOTH AIR BAGS DID NOT DEPLOY. PASSENGER SUSTAINED A BACK INJURY, AND
					DRIVER RECEIVED BRUISES TO NECK AND HEAD. DEALER NOTIFIED. FEEL FREE TO PROVIDE ANY
878870	GMC	YUKON	2001	2000-12-23	FURTHER DETAILS ON THIS MATTER. *AK
					VEHICLE INVOLVED IN A FRONTAL COLLISION WITH A DODGE, NEON , SPEED WAS UNDETERMINED. UPON IMPACT, BOTH AIR BAGS DID NOT DEPLOY. DEALER / MANUFACTURER NOTIFIED, AND NO
					RESPONSE WAS RECEIVED. PLEASE FEEL FREE TO PROVIDE ANY FURTHER DETAILS ON THIS MATTER.
883017	GMC	YUKON	2001	2000-10-17	*AK WHILE DRIVING VEHICLE WAS INVOLVED IN AN ACCIDENT, AIR BAGS DID NOT DEPLOY. *AK THE
					CONSUMER STATED THAT THE VEHICLE WAS HIT VERY HARD. THE IMPACT DAMAGED THE
					INSTRUMENT PANEL, BROKE THE WINDSHIELD, AND THE FRONT AND REAR PASSENGER DOORS
6900594	GMC	YUKON	2001	2001-09-18	NEEDED REPAIR. *YH CONSUMER WAS INVOLVED IN A FRONT END COLLISION AT 70MPH, AND FRONTAL AIR BAGS DID
8004110	GMC	YUKON	2001		NOT TO DEPLOY. PASSENGER SUSTAINED MAJOR BODY INJURIES.*AK
					WHILE DRIVING 2 MPH VEHICLE WAS STRUCK ON DRIVER'S DOOR, CAUSING EXTENSIVE DAMAGE
					TO FRONT END AS WELL. NEITHER AIRBAG DEPLOYED. CONSUMER SUFFERED HEAD INJURIES.
0004365	CNAC	WIII/ON	2004	2004 42 04	DAMAGE TO VEHICLE WAS \$ 10000.00. PRIOR TO THIS, CONSUMER OWNED ANOTHER VEHICLE
8004365	GMC	YUKON	2001	2001-12-04	JUST LIKE THIS ONE. IT ALSO HAD A FRONT CRASH AND AIRBAGS DID NOT DEPLOY. *AK WHILE TURNING LEFT AT 15 MPH\ ANOTHER VEHICLE TRAVELING AT 45 HIT CONSUMER'S VEHICLE
					ON FRONT DRIVER'S SIDE . UPON IMPACT, AIRBAGS DID NOT DEPLOY. PLEASE PROVIDE ANY
8006721	GMC	YUKON	2001	2002-03-30	FURTHER INFORMATION.*AK THE CONSUMER WAS APPROACHING AN INTERSECTION AND WITHOUT WARNING, ANOTHER
					DRIVER CUT IN FRONT OF THE CONSUMER VEHILCE. THE DRIVER APPLIED THE BRAKES, BUT THE
					PEDAL WENT TO THE FLOOR. THIS CAUSED THE OTHER VEHICLE TO COLLIDE INTO ON THE
					PASSENGER 'S SIDE AND PUSHED THE VEHICLE INTO A TREE. BOTH FRONTAL AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED INJURIES AND WAS TRANSPORTED BY AMBULANCE TO THE
					HOSPITAL. THE VEHICLE WAS TOWED TO THE DEALER. PLEASE FILL IN ADDITIONAL INFORMATION.
10099161	GMC	YUKON	2001	2004-11-01	*JB TL* - THE CONTACT OWNS A 2001 GMC YUKON WITH A CURRENT AND FAILURE MILEAGE OF
					110,000 MILES. THE CONTACT'S VEHICLE WAS INVOLVED IN A CRASH WHILE DRIVING AT 35 MPH,
					AND THE AIR BAGS DID NOT DEPLOY. THE CRASH TOOK PLACE ON A DRY DAY. THE DRIVER BEGAN
					CHOKING AND PASSED OUT. THE VEHICLE THEN RAN INTO THE BACK OF A TRUCK SITTING AT A STOP LIGHT. THE FRONT OF THE CONTACTS VEHICLE WAS DAMAGED. THE VEHICLE WAS TOWED
10187683	GMC	YUKON	2001	2007-03-29	TO DEALER. *AK
					LETTER FROM SENATOR SCOTT ON BEHALF OF CONSTITUENT RE GMC YUKON. *SMD THE
10587988	GMC	YUKON	2001	2011-05-04	CONSUMERS HUSBAND WAS KILLED IN AN ACCIDENT, AND THE AIR BAG DID NOT DEPLOY. *JB
				•	

1		1	1	
GMC	YUKON XL	2001	2014-10-17	INITIALLY TRAVELING AT 75 MPH N/B ON HWY 99 IN FRESNO COUNTY, LOST VISION (MEDICAL INCIDENT), WIFE INSISTED I PULL OVER. STRUCK GUARD RAIL ON RIGHT SIDE OF ROAD. SECOND TRY TO PULL OVER CAUSED MY VEHICLE TO IMPACT A VERIZON JUNCTION BOX AND THEN150 FEET OF SIX-FOOT CHAIN-LINK FENCING WITH ANTI-CLIMB GUARDS THAT CAME OFF THE FENCE AND SHATTERED THE WINDSHIELD. THE AIR BAGS DID NOT DEPLOY. MY INSURANCE AGENT TOLD ME HE WAS GOING TO REPORT THIS INCIDENT TO YOU, BUT SINCE I HAVEN'T HEARD ANYTHING FROM YOU FOLK I'VE ASSUMED MY AGENT DID NOT FOLLOW THROUGH. MY WIFE AND I SUSTAINED ONLY MINOR INJURIES FROM FLYING GLASS. WE HAVE PHOTO'S OF THE VEHICLE. *TR
ISUZU	RODEO	2001	2005-06-30	AIR BAGS. THERE WAS NO WARNING LIGHTS ON TO INDICATE A PROBLEM. LAST TIME THE CAR WAS CHECKED THERE WAS NO INDICATION OF A PROBLEM. THE DRIVER WAS THE ONLY PERSON INJURED WITH A TOOTH KNOCKED OUT.*AK
				I HAD A BLOW OUT ON MY 2001 ISUZU RODEO, CAUSING MY VEHICLE TO GO OFF THE ROAD TO THE RIGHT RUNNING INTO ANOTHER VEHICLE. THE SEAT BELT CAME OFF, THE AIRBAGS DID NOT WORK. I SUSTAINED HEAD INJURIES CAUSING SEIZURES, A DISPLAYED SHOULDER, AND A FRACTURED JAW. DUE TO THE HEAD INJURIES I WAS UNCONSCIOUS AND UNABLE TO KEEP
ISUZU	RODEO	2001	2006-03-11	CONTROL OF THE VEHICLE. *NM TL*THE CONTACT OWNS A 2001 ISUZU RODEO. WHILE DRIVING 65 MPH WITH THE CRUISE CONTROL ACTIVATED, THE CONTACT WAS INVOLVED IN A HIGH IMPACT VEHICLE CRASH. THE MEDIAN ON THE HIGHWAY SUSTAINED PROPERTY DAMAGE. THE VEHICLE WAS DESTROYED. THE AIR BAGS FAILED TO DEPLOY. THE DEALER HAS NOT BEEN NOTIFIED. THE CONTACT SUSTAINED MODERATE INJURIES TO HIS NECK AND SHOULDERS. A POLICE REPORT WAS FILED. THE CURRENT AND FAILURE MILEAGES WERE 97,000. THE CONSUMER PROVIDED PICTURES OF THE VEHICLE. UPDATED 09/06/07 *TR
ISUZU	RODEO	2001	2014-03-13	I WAS TURNING ONTO A STREET. THE STREET WAS COVERED IN OIL OR SOME TYPE OF SLICK ELEMENT. I SKIDDED AND FELL INTO A DITCH. MY AIRBAG DID NOT DEPLOY. *TR
CADILLAC	ESCALADE	2000	2002-12-05	WHILE DRIVING AT 30 MPH VEHICLE WAS INVOLVED IN A HEAD ON COLLISION AND AIRBAGS DID NOT DEPLOY. DEALER CONTACTED. PLEASE PROVIDE ADDITIONAL INFORMATION. TS
CADILLAC	ESCALADE	2000	2002-12-11	THE CONSUMER HAD AN ACCIDENT THE AIR BAG DIDN'T DEPLOY. *DT CONSUMER WAS TRAVELING 30MPH WHILE IT WAS RAINING THAT EVENING, AND THERE WAS A SCHOOL BUS IN FRONT OF CONSUMER'S VEHICLE. CONSUMER APPLIED BRAKES AND HIT THE SCHOOL BUS FROM BEHIND. THE COLLISION IMPACT WAS SO HARD THAT VEHICLE MOVED THE
CHEVROLET	ASTRO	2000	2000-04-04	SCHOOL BUS. ALSO, THE DUAL AIRBAGS DIDN'T DEPLOY AT ALL. *AK
CHEVROLET	ASTRO	2000	2000-09-01	WHILE DRIVING 55 MPH AND MAKING A TURN HAD A FRONTAL IMPACT. FRONT BUMPER WAS SMASHED AND FELL OFF. ALSO, DRIVER'S AND PASSENGER'S AIRBAGS DID NOT DEPLOY, WHICH DID NOT PROTECT OCCUPANTS IN THIS CRASH. DEALER WAS NOT WILLING TO ASSIST CONSUMER. PLEASE PROVIDE FURTHER INFORMATION.*AK
CHEVROLET	ASTRO	2000	2001-01-17	WHILE DRIVING ABOUT 30 MPH CRASHED INTO ANOTHER VEHICLE THAT CROSSED IN FRONT. UPON IMPACT, BOTH AIR BAGS FAILED TO DEPLOY. CURRENTLY, COMPANY WAS CONCERNED ABOUT PROBLEM WITH AIR BAGS. *AK
CHEVROLET	ASTRO	2000	2000-12-11	A FRONTAL COLLISION AT 20 MPH IMPACT WITH A TREE, AND BOTH AIR BAGS DID NOT DEPLOY. DRIVER SUSTAINED CHEST INJURY. VEHICLE AT BODY SHOP. PLEASE FEEL FREE TO PROVIDE ANY FURTHER DETAILS ON THIS MATTER. *AK
CHEVROLET	ASTRO	2000		CONSUMER WAS INVOLVED IN A FRONTAL COLLISION IN WHICH DRIVER'S AND PASSENGER'S AIR BAGS DID NOT DEPLOY. PLEASE GIVE ANY FURTHER DETAILS.*AK
CHEVROLET	ASTRO	2000	2001-12-12	WHILE TRAVELING AT 65 MPH, CONSUMER RAN INTO THE SIDE OF ANOTHER VEHICLE, HEAD-ON, UPON IMPACT NEITHER AIR BAG DEPLOYED, CONSUMER CONTACTED DEALER, AND THEY WERE NOT WILLING TO DO ANYTHING. *AK *JG
		2000	2002-01-01	CONSUMER HAD A HEAD ON COLLISION AND AIR BAGS DID NOT DEPLOY. CONSUMER WAS INJURED. *AK *JB
CHEVROLET	ASTRO	2000	2002-11-07	CONSUMER STATES THAT WHILE ON AN EXPRESS WAY, CONSUMER REAR ENDED A TANKER TRUCK. CONSUMERS VEHICLE WAS TOTALLED. CONSUMER STATES' NONE OF THE VEHICLES AIRBAGS DEPLOYED. PLEASE PROVIDE ANY FURTHER INFORMATION. TS
CHEVROLET	ASTRO	2000	2003-12-16	CHECY ASTRO CARGO VAN 2000, FRONTAL COLLISION RESULTING IN TOTAL LOSS BY INSURANCE CARRIER. NEITHER FRONT AIR BAG OPERATED.
CHEVROLET	BLAZER	2000	2000-07-21	IN A HEAD-ON COLLISION WITH A GUARDRAIL, BOTH FRONT AIR BAGS FAILED TO DEPLOY.*AK
CHEVROLET	BLAZER	2000		CONSUMER WAS DRIVING AT APPROXIMATELY 30-35 MPH ,AND TO AVOID A CRASH CONSUMER RAN INTO A TREE HEAD-ON. UPON IMPACT, DUAL AIRBAGS DID NOT DEPLOY, CAUSING INJURIES.*AK
CHEVROLET	BLAZER	2000	2002-07-02	CONSUMER STATES AT A 25MPH VEHICLE CRASHED, HOWEVER THE AIRBAGS DID NOT DEPLOY. CAUSE UNKNOWN. DEALER NOTIFIED.*JB CONSUMER ADDS VEHICLE WAS STRUCK HEAD ON BY AN OUT OF CONTROL VEHICLE TRAVELING 45 MILES. THE RIGHT FRONT FENDER CONTACTED SQUARELY AGAINST CONSUMERS FRONT BUMPER. RESULTING IMPACT TOTALLED CONSUMERS BLAZER. INSPECTORS WERE AMAZED THAT AIR BAGS DID NOT DEPLOY. *TT
CHEVROLET	BLAZER	2000		WHILE DRIVING 25-30 MPH AND WITHOUT WARNING INVOLVED IN A HEAD-ON COLLISION. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED.*AK THERE WERE 2 INJURIES. *YH
	ISUZU ISUZU ISUZU ISUZU CADILLAC CADILLAC CHEVROLET CHEVROLET	ISUZU RODEO ISUZU RODEO ISUZU RODEO ISUZU RODEO CADILLAC ESCALADE CADILLAC ESCALADE CHEVROLET ASTRO CHEVROLET BLAZER CHEVROLET BLAZER	ISUZU	ISUZU

WHILE DRIVING 25 MPH ANDWITHOUT WARNING A HEAD ON COLLISION OF IMPACT, AIR BAGS DID NOT DEPLOY, AND DRIVER SUSTAINED MINOR INJUR FRONT CRASH AT 40 MPH, VEHICLE HIT A TREE. NEITHER AIRBAG DEPLOYED, MINOR INJURIES. AMOUNT OF DAMAGE UNKNOWN AT THIS TIME. TS VEHICLE WAS IN A FRONTAL COLLISION, BUT NONE OF THE AIRBAG DEPLOYED DRIVER SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIRBAG DEPLOYED DRIVER SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIRBAG DEPLOYED DRIVER SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIRBAG DEPLOYED. THE VEHICLE WAS INVOLVED IN A COLLISION BUT THE DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DIB BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY SUFFICIE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUMENT OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLISION WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLISION BUT THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER IMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER SIMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND;	RIES.*AK DRIVER SUFFERED ED UPON IMPACT. THE EDETAILS. IR BAGS DEPLOYED. HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
CHEVROLET BLAZER 2000 2002-11-01 MINOR INJURIES. AMOUNT OF DAMAGE UNKNOWN AT THIS TIME. TS VEHICLE WAS IN A FRONTAL COLLISION, BUT NONE OF THE AIRBAG DEPLOYED, MINOR SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIR 10014969 CHEVROLET BLAZER 2000 2003-03-15 *JB WHILE DRIVING 45 MPH THE VEHICLE WAS INVOLVED IN A COLLISION BUT THE DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DI BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY 10059300 CHEVROLET BLAZER 2000 2003-04-08 *JB WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS THE TRUCK IS THE TRUCK IS THE TRUCK IS THE TRUCK. THE TRUCK IS THE TRUCK IS THE TRUCK IS THE TRUCK. THE TRUCK IS THE TRUCK IS THE TRUCK IS THE TRUCK IS THE TRUCK. THE TRUCK IS THE TRUCK. THE TRUCK IS THE TRUCK. THE TRUCK IS THE TRUCK. THE TRUCK IS THE	DRIVER SUFFERED ED UPON IMPACT. THE E DETAILS. IR BAGS DEPLOYED. HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
8022825 CHEVROLET BLAZER 2000 2002-11-01 MINOR INJURIES. AMOUNT OF DAMAGE UNKNOWN AT THIS TIME. TS VEHICLE WAS IN A FRONTAL COLLISION, BUT NONE OF THE AIRBAG DEPLOYE 10006273 CHEVROLET BLAZER 2000 2003-02-01 DRIVER SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIR 10014969 CHEVROLET BLAZER 2000 2003-03-15 *JB WHILE DRIVING 45 MPH THE VEHICLE WAS INVOLVED IN A COLLISION BUT TH 10015762 CHEVROLET BLAZER 2000 2003-04-12 DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DI BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY: VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUME 10059300 CHEVROLET BLAZER 2000 2004-02-07 NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	ED UPON IMPACT. THE EDETAILS. IR BAGS DEPLOYED. HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, C, AND HIP INJURIES.
VEHICLE WAS IN A FRONTAL COLLISION, BUT NONE OF THE AIRBAG DEPLOYE DRIVER SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIRBAG DEPLOYE SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIR VEHICLE WAS INVOLVED IN A COLLISION BUT THE VEHICLE WAS INVOLVED IN A COLLISION BUT THE DEPLOY. *NLM 10015762 CHEVROLET BLAZER 2000 2003-04-12 DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DID BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY SUBSTITUTE OF THE FRONTAL AIR BAGS DID NOT AND	EDETAILS. IR BAGS DEPLOYED. HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
CHEVROLET BLAZER 2000 2003-02-01 DRIVER SUSTAINED HEAD, NECK AND BACK INJURIES. PLEASE PROVIDE MORE THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AI THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AI THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AI THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AI WHILE DRIVING 45 MPH THE VEHICLE WAS INVOLVED IN A COLLISION BUT TH DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DI BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY: WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	EDETAILS. IR BAGS DEPLOYED. HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
THE VEHICLE WAS INVOLVED IN A FRONTAL ACCIDENT, AND NONE OF THE AIR 10014969 CHEVROLET BLAZER 2000 2003-03-15 *JB WHILE DRIVING 45 MPH THE VEHICLE WAS INVOLVED IN A COLLISION BUT THE DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DIESTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY 3: WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUMENT OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLISTS MY THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK.	IR BAGS DEPLOYED. HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
10014969 CHEVROLET BLAZER 2000 2003-03-15 *JB WHILE DRIVING 45 MPH THE VEHICLE WAS INVOLVED IN A COLLISION BUT THE DEPLOY. *NLM CHEVROLET BLAZER 2000 2003-04-12 DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DISTRICT BLAZER 2000 2003-04-08 *JB WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUME VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUME NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLITING AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SLID ON THE CONSUMER LOSING CONTROL OF THE TRUCK.	HE AIR BAGS DID NOT ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
WHILE DRIVING 45 MPH THE VEHICLE WAS INVOLVED IN A COLLISION BUT THE DEPLOY. *NLM CHEVROLET BLAZER 2000 2003-04-12 DEPLOY. *NLM HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS DISELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY 3: WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUMENT NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLITHE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SEED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SEED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SEED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SEED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SEED IN THE CONSUMER LOSING CONTROL OF THE TRUCK.	ID NOT DEPLOY, SEAT 2000 CHEVY BLAZER. ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, C, AND HIP INJURIES.
HEAD ON COLLISION WITH SOLID CEMENT BRIDGE AT 40+ MPH. AIR BAGS D BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY 3 10016961 CHEVROLET BLAZER 2000 2003-04-08 *JB WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK,BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM
BELTS DID NOT LOCK IN PLACE ON IMPACT NOR DURING ROLL OVER ON MY 3 **JB WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK,BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM
10016961 CHEVROLET BLAZER 2000 2003-04-08 *JB WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	ST CONTROL OF THE MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, C, AND HIP INJURIES.
WHILE DRIVING 45 MPH THE DRIVER DROVE OVER SOME BLACK ICE AND LOS VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
VEHICLE. THE VEHICLE RAN INTO AN EMBANKMENT HEAD ON. THE CONSUM NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK SEED TO THE TRUCK SEED TO THE TRUCK.	MER STATED THAT ED THE DEALER. *NM ISION. UPON IMPACT, K, AND HIP INJURIES.
10059300 CHEVROLET BLAZER 2000 2004-02-07 NEITHER OF THE FRONTAL AIR BAGS DEPLOYED. THE CONSUMER CONTACTE WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK, BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	SION. UPON IMPACT,
WHILE DRIVING 55 MPH THE CONSUMER WAS INVOLVED IN FRONTAL COLLI THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK,BACK THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	ISION. UPON IMPACT, (, AND HIP INJURIES.
THE AIR BAGS DID NOT DEPLOY. THE DRIVER SUSTAINED MAJOR NECK,BACK 10106730 CHEVROLET BLAZER 2000 2004-12-14 THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS	C, AND HIP INJURIES.
10106730 CHEVROLET BLAZER 2000 2004-12-14 THE VEHICLE WAS TOTALED. *AK (SEE ALSO ODI REF. NO. 10106755 - SAME THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK IS TRUCK IN THE CONSUMER LOSING CONTROL OF THE TRUCK.	
THE TRUCK SLID ON A PATCH OF ICE 100 YARDS AFTER MERGING ONTO THE RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK F	
RESULTED IN THE CONSUMER LOSING CONTROL OF THE TRUCK. THE TRUCK	VEHICLE) *MJJ *TC
	INNER STATE. THIS
IMPACTED A CONCRETE BRIDGE; THEN SWUNG AROUND; THE REAR DRIVER S	FRONT DRIVER SIDE
	<i>'</i>
THIS THREW THE TRUCK INTO THE RIGHT HAND LANE, INTO THE GUARD RAIL FRONT PASSENGER SIDE; THEN THE TRUCK BOUNCED TO THE LEFT HAND LAN	-
GUARD RAIL HEAD ON. NONE OF THE AIR BAGS DEPLOYED UPON IMPACT. TH	
10108627 CHEVROLET BLAZER 2000 2005-01-18 SEVERE INJURIES TO THEIR NECK, BACK, AND LEFT SHOULDER. *NM	
T-BONE COLLISION, APPROXIMATELY 45 MPH. FRONT END OF VEHICLE BADL'	Y DAMAGED. NO
10132243 CHEVROLET BLAZER 2000 2005-08-06 AIRBAG DEPLOYMENT. *NM	
THE CONTACT'S SPOUSE OWNS THE 2000 CHEVROLET BLAZER. THE CONTRA	CT STATE THAT THIS
DAUGHTER WAS DRIVING APPROXIMATELY 30 MPH, THEN SHE HIT A DIVIDER	R AND THE VEHICLE
ROLLED OVER SEVERAL TIMES LANDING ON THE DRIVERS SIDE OF THE VEHIC	
DEPLOYED. THE DRIVER WAS INJURIES AND THE VEHICLE WAS TOTALED BY T 10226626 CHEVROLET BLAZER 2000 2008-04-30 COMPANY. THE CURRENT AND FAILURE MILEAGE IS 85210. JP	HE INSURANCE
HAD A FRONT END COLLISION. THE FRONT END WAS DESTROYED. NO AIR BA	GS WENT OFF. BOTH
VEHICLES CAME OFF A RED LIGHT, ALL VEHICLES STOPPED SUDDENLY AND M	IY TEUCK REAR ENDED
10609197 CHEVROLET BLAZER 2000 2013-07-10 A TOYOTA PICKUP. *TR	
TL* THE CONTACT OWNED A 2000 CHEVROLET BLAZER. WHILE DRIVING AT A	PPROXIMATELY 45
MPH, THE VEHICLE CRASHED HEAD ON INTO ANOTHER VEHICLE. THE AIR BAC	GS FAILED TO DEPLOY.
A POLICE REPORT WAS FILED AND NO INJURIES WERE REPORTED. THE VEHIC	
10693647 CHEVROLET BLAZER 2000 2015-01-31 THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE A CAR ATTEMPTED TO TURN IN FRONT OF US, HE DID NOT MAKE IT. WE WEF	
BETWEEN 38-40 MPH WHEN WE HIT THE OTHER VEHICLE HEAD ON. AIRBAG	
EITHER SIDE OF THE VEHICLE. THE TRUCK WAS TOTAL LOSS. THE OTHER PAR	RTY'S VEHICLE ALSO
731125 CHEVROLET SILVERADO 2000 1999-10-23 WAS A. *AK	
I CONTACTED SARAH SCHILLE OF GENERAL MOTORS ABOUT THIS FAILURE.SH INVESTIGATOR TO TOM BENSON TO LOOK AT THE TRUCK. HE DID WHATEVEF	
DATA FROM THE VEHICLE AND THEN TAKES PICTURES ETC. AND SENDS ALL O	
TO GM FOR EVALUATION. I FEEL THIS ACCIDENT WAS SEVERE ENOUGH FOR T	
AND I'M NOT SATISFIED AT ALL WITH GM'S RESPONSE TO THE SITUATION. I R	-
REPORT AND A COPY OF THE DEPLOYMENT CRITERIA FOR THE AIRBAGS I WA	
INFORMATION WILL NOT BE SUPPLIED. HOW AM I TO KNOW IF THIS IS A FAIL INFORMATION SHOULD NOT BE PRIVATE TO THE MANUFACTURER ONLY. I W	
734605 CHEVROLET SILVERADO 2000 2000-09-19 LOOK INTO THIS PROBLEM.	
HIT A GUARD RAIL HEAD ON, WENT OVER IT AND NOSE DIVED INTO A 10FT. I	· ·
739117 CHEVROLET SILVERADO 2000 2001-01-02 ONTO THE ROOF. NEITHER AIRBAG DEPLOYED AFTER HITTING THE FRONT EN	ND I WICE. AK
MY 2000 CHEVROLET SILVERADO TRUCK WAS INVOLVED IN A HEAD-ON COLL	ISION ON MAY 19, 01.
VEHICHLE WAS TRAVELING AT APPROXIMATELY 40 MPH. WHEN VEHICHLE W	
AND KNOCKED APPROXIMATELY 23 FT. BACKWARDS ONTO THE SHOULDER C	
IMPACT DRIVER SIDE AIRBAG DID NOT DEPLOY. DRIVER OF TRUCK RECIEVED ABRASIONS, AND BRUISING RESULTING FROM CONTACT WITH STEERING COI	·
745943 CHEVROLET SILVERADO 2000 2001-05-19 PANEL. BOTH VEHICHLES INVOLVED IN CRASH WERE DETERMINED TO BE TO	

THE DRIVER, DAVID IS ALVERADO 200 2002-08-22 DICTOR'S CARE "AKE DICTOR "AKE DICTOR" CARE "AKE DICTOR "AKE DICTOR" CARE "AKE DICTOR						THE 2000 CHEVROLET SILVERADO CRASHED HEAD ON INTO A TREE, THE AIRBAGS DID NOT DEPLOY.
2007-08-22 200						·
A						HIT AND CRACKED THE WINDSHIELD. HE WAS HOSPITALIZED FOR 5 DAYS AND IS STILL UNDER A
HEADNIS SOUTH ON HIGHWAY US. 1, TRAVILLING SSMM WITH CAUSE CONTROL ON, ADDITIONAL PROPERTY OF SHEED CLUPON MACH.		_			2002-08-22	
VINITIA COMING NORTH TURNED IN PROVIT, AND CONSUME HIT YERLIC ON THE SIDE. UPON IMPACT, DIVERS SIDE ARRANG DID NOT DEPLOY. CONTACTED DEALER, AND HE WAS NOT ABLE DIVERS SIDE ARRANG DID NOT DEPLOY. CONTACTED DEALER, AND HE WAS NOT ABLE DIVERS SIDE ARRANG DID NOT DEPLOY. CONTACTED DEALER, AND HE WAS NOT ABLE DIVERS SIDE ARRANG DID NOT DEPLOY. BUT THE PACK. DIVER HAD LOST CONTROL OF VEHICLE HIT A TELEPHONE POLE HEAD-ON WITH A SO-65 MPH MAPACT, AND THEN DROVE HIVO A HELD LUPON IMPACT, DUAL ARRANGS DID NOT DEPLOY. BUT THE PACK TH	767253	CHEVROLET	SILVERADO	2000		
### MAPER, DRIVERS DIE ARRAGO DI NOT DEPLOY, CONTACTED DEALER, AND HE WAS NOT ABLE ### S08533 HEYROLET SILVERADO 2000 2000-01-19 TO HEYROLET SILVERADO 2000 2000-00-08 ONIVER HAD LOST CONTROL OF VEHICLE HIT A TELEPHONE POLE HEAD-ON WITH A 50-05 MIPH ### MAPER, AND THEN DROVE RITO A PIELD. JUPON MIPHACE, DUELA, RIRBAGS DI NOT DEPLOY, BUT \$473388 CHEVROLET SILVERADO 2000 2000-00-08 ONIVER HAD LOST CONTROL OF VEHICLE DUPON MIPHACE, TAXAS PROVIDE FURTHER RINFORMATION. "AK CONSUMER WAS ROWNED BY BES SIMPH FRONTER COLSSION IN WASCE DUELA DRIVER, AND GOVERN FURTHER BY DEPLOY BUT \$472288 CHEVROLET SILVERADO 2000 2000-04-29 TO PROVIDE MAPER AS ROWNED BY AN STANCE COLOR ON THE REAS BUT AND THE THE AS A RESULT OF ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED, JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED, JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED, JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED, JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED, JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED, JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL WAS HEAVILY DIAMAGED. JEAGE SOFE ANN FURTHER BY DEPLOY ALSO, FRONTE BIOL HEAVILY DIAMAGED AS A SOFT BIOL HEAVILY DIAMAGED AS A SO						
### SEASON CHEVROLET SILVERADO 2000 2000-0-19 TO HEIP. "AK ### SEATELTS WERE ON AT THE TIME. AS A RESULT, PASSENGER HAD CRACKED STRENUM, AND SEATELETS WERE ON AT THE TIME. AS A RESULT, PASSENGER HAD CRACKED STRENUM, AND SEATELETS WERE ON AT THE TIME. AS A RESULT, PASSENGER HAD CRACKED STRENUM, AND CREEKER WERE NOT EPIDOR. BY A THE TIME. AS A RESULT, PASSENGER HAD CRACKED STRENUM, AND CREEKER WERE NOT EPIDOR. BY A STRENGER HAD CRACKED STRENUM, AND CREEKER WERE NOT EPIDOR. BY A STRENGER HAD CRACKED STRENUM, AND CREEKER WERE NOT EPIDOR. BY A STRENGER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD REAS CREEKER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD REAS CREEKER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD REAS CREEKER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD BASED WITH A STRENGER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD BASED WERE NOT BY A STRENGER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD BASED WERE AND EDIT HAD BASED WITH A STRENGER WERE NOT NOTIFIED AT THIS TIME. PLEASE FEEL FIRST LIFE AT 20 MPH, AND EDIT HAD BASED WERE AND E						
MARCET, AND THEN BOOVE INTO A FIELD. UPON IMPACT, DUAL, AIRBARS SO IN NOT PERFOY, BUT SCATEGORY SETS WERE ON AT THE TIME. AS A RESULT ASSEMIGH FAND CARCED STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION. "AX PASSENGER TO SET STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION." AX PASSENGER TO SET STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION. "AX PASSENGER TO SET STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION." AX PASSENGER TO ME ASSESS TO ME TO THE PROVIDE FOR THE PASSENGER TO ME ASSESS TO ME ASSESSMENT AS ASSESS. TO ME ASSESS TO ME ASSESSMENT ASS	860353	CHEVROLET	SILVERADO	2000	2000-01-19	
MARCET, AND THEN BOOVE INTO A FIELD. UPON IMPACT, DUAL, AIRBARS SO IN NOT PERFOY, BUT SCATEGORY SETS WERE ON AT THE TIME. AS A RESULT ASSEMIGH FAND CARCED STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION. "AX PASSENGER TO SET STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION." AX PASSENGER TO SET STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION. "AX PASSENGER TO SET STENUM, AND DRIVER HAD MILD WHIPLASH FLESS FROUDE FURTHER INFORMATION." AX PASSENGER TO ME ASSESS TO ME TO THE PROVIDE FOR THE PASSENGER TO ME ASSESS TO ME ASSESSMENT AS ASSESS. TO ME ASSESS TO ME ASSESSMENT ASS						
SATISEAR CHEVROLET SILVERADO 2000 - 90-80 DIVERADO 2000 - 90-80 DIVERADO 2000 - 90-80 DIVERADO 2000 - 90-80 DIVERADO 2000 - 90-80						
1973-258						
CONSUMER WAS INVOIVED IN 55 MPH FRONTAL COLLISION IN WHICH DRIVER'S AND PASSINGE'S AIR BAGS DID NOT DEPLOY. ALSO, FRONT END WAS HAVILY DAMAGED, PLEASE GIVE ANY PURTHER DETAILS." AK	871368	CHEVROLET	SILVERADO	2000	2000-09-08	· · · · · · · · · · · · · · · · · · ·
ST2110	071300	CHEVROLLI	SILVERADO	2000	2000 03 08	
VEHICLE MAS INVOLVED IN A FRONTAL COLLISION WITH A TREE AT 20 MPH, AND BOTH AIR BAGS						PASSENGER'S AIR BAGS DID NOT DEPLOY. ALSO, FRONT END WAS HEAVILY DAMAGED. PLEASE
ST2528	872110	CHEVROLET	SILVERADO	2000		
STATE						·
NHILE TRAVELING AT SPEED 45 MPH WHEN REAR ENDED ANOTHER VEHICLE. UPON IMPACT, DRIVERS AIR BAG DID NOT DEPLOY. "AX CONSUMER WAS TRAVELING AT APPROXIMATELY 60 MPH WHEN A TRAFFIC IAM AHEAD OF HIM OCCURRED. CONSUMER APPLIED BRAKES AND ATTEMETED SLOW DOWN, OF WHICLE, BOTH FROYTAL AIRBAGS SHILED TO SLOW DOWN, AND REAR ENDED A VEHICLE IN FRONT OF HIM AND IS FRONT DRIVERS SIDE OF WHICLE, BOTH FROYTAL AIRBAGS SHILED TO DEPLOY. PLEASE PROVIDE ANY ADDITIONAL MINORMATION/ATTACHMENTS. "AX. WAS TRAVELING AND HAD LOST CONTROL OF VEHICLE DUE TO ITS DRIFTING. IT WENT SUBWAYS AND OFF THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING, DRIVEWAY WAS OF CONCRETE TILL AIRBAGS FAILED TO DEPLOY. BROWN AS ON THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING, DRIVEWAY WAS OF CONCRETE TILL ARDED ON BUMPER, THEN TUPPED ON TOP AIR BAGS FAILED TO DEPLOY. BROWN AS SUPERAD WIND OFF THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING, DRIVEWAY WAS OF CONCRETE TILL ARDED ON BUMPER, THEN TUPPED ON TOP AIR BAGS FAILED TO DEPLOY. BROWN AS SUPERAD WIND OFF THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING, DRIVEWAY WAS OF CONCRETE TILL ARDED ON BUMPER, THEN TUPPED ON TOP AIR BAGS FAILED TO DEPLOY. BROWN AS SUPERAD WIND OFF THE ROAD. THEN THE WAS NOT CONTROL. OF VEHICLE BOTH TO PAIR BAGS STALED TO DEPLOY. BROWN AS SUPERAD WIND OFF THE ROAD. THE ROAD. THE WAS NOT WHILE PASSENGERS AS IN BAG WAS AND WAS HOSTING. THE WENT AND AIR BAGS STALED TO DEPLOY. BROWN AS THE PASSENGER SAY BAG WAS AND THE PASSEN	077570	CHEVBOLET	CILVEDADO	2000	2000 04 20	·
STREAMS OHEVROLET SILVERADO 2000 ORIVERS AIR BAG DID NOT DEPLOY. *AK	0/2320	CHEVROLET	SILVERADO	2000	2000-04-29	
OCCUBRED. CONSUMER APPLIED BRAKES AND ATTEMPTED TO SLOW DOWN. DRAKES FALLED TO SLOW PHILED DOWN, AND REAR EDED A VEHICLE. HOOTH PRIMO THE POWN BROWN BRAKES FALLED TO OF VEHICLE. BOTH FRONTAL AIRBAGS FALLED TO DEPLOY. PLEASE PROVIDE ANY ADDITIONAL MINORAMATION, ATTACHMENTS. "AN WAS TRAYELING 60MPH AND LOST CONTROL OF VEHICLE DUE TO ITS DIFFTING. IT WENT SIDEWAYS AND OFF THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING, DRIVEWAY WAS FRAVELING 60MPH AND LOST CONTROL OF VEHICLE DUE TO ITS DIFFTING. IT WENT SIDEWAYS AND OFF THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING, DRIVEWAY WAS OF CONNETES THE LANDED ON DIMPIER, THEN HEIPED ON TOP. AIR BAGS FAILED TO DEPLOY. PRIVEY SHAPE THE LANDED ON BUMPER, THEN HEIPED ON TOP. AIR BAGS FAILED TO DEPLOY. OR WHILE TRAYELING AT APPROXIMATELY 45 TO SO MPH VEHICLE IMPACTED ANOTHER VEHICLE, CAUSING \$11,000 WORTH OF DANAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSURANCE COMPANY WA HAVING VEHICLE REPARED. PLEASE PROVIDE ANY ADMINISTRATION/ATTACHMENTS. AND WAS TURNED OFF. INSURANCE COMPANY WAS HAVING VEHICLE REPARED. PLEASE PROVIDE ANY ADMINISTRATION/ATTACHMENTS. AND STIFF NECK. "AK. HEAD COLLISION AT 60-55MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARMANY WAS HEAD COLLISION AT 60-55MPH, AND AIR BAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT WHILE DRIVING 3D AIR AND AIRBAGS DID NOT DEPLOY. DEALERSHIP WAS ANABED OF PRODREEM. "AN ORDINATE	878288	CHEVROLET	SILVERADO	2000		·
SLOW VEHICLE DOWN, AND REAR ENDED A VEHICLE IN FRONT OF HIM ON FRONT DRIVERS SIDE OF VEHICLE. BOTH FRONTAL AIRBAGS FAILED TO DEPLOY, PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS "AX WAS TRAVELING GOOD THE ROAD." THE ROAD. THEN, VEHICLE WENT AIR BOONS AFTER STRADDLING, DRIVEWA" WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY, DRIVERS SIDE OF PROVIDE ANY ADDITIONAL DRIVEWAY WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY, DRIVEWAY WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY, DRIVEWAY WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY, DRIVEWAY WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY, DRIVEWAY WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVEWAY WAS OF CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVER'S AIR BAG CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVER'S AIR BAG CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVER'S AIR BAG CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVER'S AIR BAG CONCRETE TILE, LANDED ON BUMPER, THEN FUPPED ON TOP. AIR BAGS TO SOME THE VEHICLE, BAG BOOT TO PRIOR WAS TURNED ON THE WAS AN AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WASHING VEHICLE REPAIRED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION, ATA WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS NO PRIOR WASHING AND AIR BAGS DID NOT DEPLOY. DRIVER'S SIDE AIRBAGS DID NOT DEPLOY. DRIVER'S INVOIVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG SIDE AND THE VEHICLE, BAG AUGUS MY WOULD NOT HERE WAS NOT HERE WAS SINGHED AND THE WENT AND THE RIFE WAS SINGH AIR BAG ON DRIVER WAS SINGH AIR BAG ON DRIVER'S AIR BAG ON DRIVER'S AIR BAG ON D						CONSUMER WAS TRAVELING AT APPROXIMATELY 60 MPH WHEN A TRAFFIC JAM AHEAD OF HIM
SILVERADO 2001-04-08 NEPORADITANA/TACHMENTS: **SAX						OCCURRED. CONSUMER APPLIED BRAKES AND ATTEMPTED TO SLOW DOWN. BRAKES FAILED TO
						·
WAS TRAVELING GOMPH AND LOST CONTROL OF VEHICLE DUE TO ITS DRIFTING. IT WENT SDEWAYS AND OFF THE ROAD. THEN, VEHICLE PARE ARB RORNE AFTER STRADDLONG. GNYEWA WAS OF CONCRETE TILE. LANDED ON BUMPER, THEN FLIPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVER SUFFRED INJURIES AND WAS HOSPITALIZED.**AIK WHILE TRAVELING AT APPROXIMATELY 45 TO 50 MPH VEHICLE IMPACTED ANDTHEN VEHICLE, CAUSING \$11,000 WORTH OF DAMAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSURANCE COMPANY WA HAVING VEHICLE REPAIRED. PLEASE PROVIDE PLEASE PROVIDE AND AUTOMATION/ATTACHMENTS. ***PRIVER EXPERIENCED NECK INJURIES AND STIFF NECK.**AIK HEAD COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNIN CONTACTED MANUFACTURER. AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.**AIK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER.**AIK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER.**AIK CONSUMER USST TOURTH ADD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER.**AIK CONSUMER USST TOURTH AND AIR AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER.**AIK CONSUMER STATED VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRBAG DIDNT DEPLOY, DEALERS HIP WAS AWARE OF PROOBLEM.**AK DRIVER RECEIVED BACK AND NECK INJURIES.**SLC CONSUMER STATED VEHICLE WAS INVOLVED IN AN ACCIDENT: UPON IMPACT, AIR THE BAG DID NOT DEPLOY, DEALERS HIP WAS AWARE OF PROOBLEM.**AK DRIVER RECEIVED BACK AND NECK INJURIES.**SLC CONSUMER STATED VEHICLE WAS INVOLVED IN AN ACCIDENT: UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DEALERS HIP WAS AWARE OF PROOBLEM.**AK THE PRO- WHILE DRIVING WAS HIT HEAD OND BY AND THE WEY AND THE RECEIVED WHILE DRIVING WAS HIT HEAD OND BY AND THE WEY AND THE WEY AND THE WEY AND THE RECEIVED ON BY AND THE WEY AND THE WEY AND THE RECEIVED ON THE WEY AND THE RE	886000	CHEVROLET	SILVERADO	2000	2001-04-08	
WAS OF CONCRETE TILE. LANDED ON BUMPER, THEN FLIPPED ON TOP. AIR BAGS FAILED TO DEPLOY. DRIVER SUFFERED INJURIES AND WAS HOSPITALIZED.*AK WHILE TRAVELING AT APPROXIMATELY 45 TO 50 MPH VEHICLE IMPACTED ANOTHER VEHICLE, CAUSING \$11,000 WORTH OF DAMAGET TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSUBANCE COMPANY WA HAVING VEHICLE REPAIRED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS. ******OFFICIAL PROVIDED SILVERADO**** *****OFFICIAL PROVIDED SILVERADO**** ****OFFICIAL PROVIDED SILVERADO**** ****OFFICIAL PROVIDED SILVERADO**** ****OFFICIAL PROVIDED SILVERADO**** ****OFFICIAL PROVIDED SILVER		S. L. VINOLET	3.2.2.00			·
R87723 CHEVROLET SILVERADO 2000 2001-08-23 DEPLOY. DRIVER SUFFERED INJURIES AND WAS HOSPITALIZED.**AK WHILE TRAVELING AT APPROXIMATELY 45 TO 50 MPH VEHICLE IMPACTED ANOTHER VEHICLE, CAUSING \$11,000 WORTH OF DAMAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S SIR BAG WAS TURRED DEF. INSURANCE COMPANY WAS HAVING VEHICLE REPAIRED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS. **ORIVER EXPERIENCED NECK INJURIES AND STIFF NECK.**AK **HAD COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNING CONTACTED MANUFACTURER, NAD MANUFACTURER WAS NOT WILLING TO DO ANYTHING.**AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER.**AK **CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER UDST CONTROL OF THE VEHICLE, AND IT HIT A GUARDBAIL. UPON IMPACT, DRIVER'S SIDE AIRBAG DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PRODBLEM. **AK DRIVER RECEIVED BACK AND NECK INJURIES.** SLC **CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY. DEALERSHIP WAS AWARE OF PROBLEM. **AK DRIVER RECEIVED BACK AND NECK INJURIES.** SLC **CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY. DEALERSHIP WAS AWARE OF PROBLEM. **AK DRIVER RECEIVED BACK AND NECK INJURIES.** SLC **CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY. DEALERSHIP WAS AWARE OF PROBLEM. **AK DRIVER RECEIVED BACK AND NECK INJURIES.** SLC **CONSUMER STATED VEHICLE WAS INVOLVED IN A PRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY. DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PRAISED. **AK **YH DRIVER SAM SINVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG DID NOT DEPLOY. DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PRAISED. **AK **YH DRIVER SAM SINVOLVED IN A PRONTAL COLLISION. **AK **YH DRIVER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHIC						SIDEWAYS AND OFF THE ROAD. THEN, VEHICLE WENT AIR BORNE AFTER STRADDLING. DRIVEWAY
WHILE TRAVELING AT APPROXIMATELY 4S TO 50 MPH VEHICLE IMPACTED ANOTHER VEHICLE, CAUSING \$11,000 WORTH OF DAMAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSURANCE COMPANY WA HAVING VEHICLE REPRIADED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS. ***PRIVER EXPERIENCED NECK INJURIES AND STIFF NECK.**AK ***APPROXIMATELY 4S TO 50 MPH VEHICLE.**AK ***PRIVER EXPERIENCED NECK INJURIES AND STIFF NECK.**AK ***APPROXIMATELY 4S TO 50 MPH AD ALR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNIN CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.**AK WHILE DRIVING 30 TO 35 MPH HAD ACREASH, AND AIRBAGS DID NOT DEPLOY. DATE WAS NOT WILLING TO DO ANYTHING.**AK CONSUMER LOST CONTROLED DEALER.**AK ***CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CREASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROBLEM. "AK DRIVER RECEIVED BACK AND NECK INJURIES." "SLC CONSUMER STATED VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROBLEM." AND THE AIR BAG DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROBLEM." AND THE AIR BAG DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROBLEM." AND THE AIR BAG DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROBLEM." AND THE OTHER WHILE DRIVING WAS HIT HEAD—ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY, CONSUMER WAS DRIVING APPROXIMATELY 30MPH AND THE OTHER VEHICLE WAS TRAVELING APPROXIMATELY ADDITI						·
CAUSING \$11,000 WORTH OF DAMAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSURANCE COMPANY WAS HAVING VEHICLE REPAIRED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS. **PRIVER EXPERIENCED NECK INJURIES AND STIFF NECK.**AK **HEAD COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNIN CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.**AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRSAIGN DID NOT DEPLOY. DAMAGED FRONT CONSUMER LOST CONTROL OF THE VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRSAIGN DID NOT DEPLOY. DEALERSHIP WAS AWARE OF PROOBLEM. **AK DRIVER RECEIVED BACK AND NECK INJURIES.** SILC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY. DEALER DID NOT DEPLOY. DEALER BAG DID NOT DEPLOY. DRIVER SILVERADO **SOURCE SILVERADO*** **ONSUMER STATED VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGERS SIDE ON TO DEPLOY. ON SUMER VAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGERS SIDE DID NOT DEPLOY. ON SUMER VAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGERS SIDE DID NOT DEPLOY. ON SUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.* AK THERE WERE 2 INJURIESS. *YH **WHILE DRIVING, VEHICLE WAS TRAVELING APPROXIMATELY 40-50MPH.* AK THERE WERE 2 INJURIESS. *YH **WHILE DRIVING VAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 40-50MPH.* AK THERE WERE 2 INJURIESS. *YH **WHILE DRIVING VAS HIT HEAD-ON BY ANOTHER VEHICLE AND HIT A TREE, UPON IMPACT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORCECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORCECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER	887723	CHEVROLET	SILVERADO	2000	2001-04-23	DEPLOY. DRIVER SUFFERED INJURIES AND WAS HOSPITALIZED.*AK
CAUSING \$11,000 WORTH OF DAMAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSURANCE COMPANY WAS HAVING VEHICLE REPAIRED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS. **PRIVER EXPERIENCED NECK INJURIES AND STIFF NECK.**AK **HEAD COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNIN CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.**AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRSAIGN DID NOT DEPLOY. DAMAGED FRONT CONSUMER LOST CONTROL OF THE VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRSAIGN DID NOT DEPLOY. DEALERSHIP WAS AWARE OF PROOBLEM. **AK DRIVER RECEIVED BACK AND NECK INJURIES.** SILC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY. DEALER DID NOT DEPLOY. DEALER BAG DID NOT DEPLOY. DRIVER SILVERADO **SOURCE SILVERADO*** **ONSUMER STATED VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGERS SIDE ON TO DEPLOY. ON SUMER VAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGERS SIDE DID NOT DEPLOY. ON SUMER VAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGERS SIDE DID NOT DEPLOY. ON SUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.* AK THERE WERE 2 INJURIESS. *YH **WHILE DRIVING, VEHICLE WAS TRAVELING APPROXIMATELY 40-50MPH.* AK THERE WERE 2 INJURIESS. *YH **WHILE DRIVING VAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 40-50MPH.* AK THERE WERE 2 INJURIESS. *YH **WHILE DRIVING VAS HIT HEAD-ON BY ANOTHER VEHICLE AND HIT A TREE, UPON IMPACT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORCECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORCECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER						WHILE TRAVELING AT APPROXIMATELY 45 TO 50 MPH VEHICLE IMPACTED ANOTHER VEHICLE
HAVING VEHICLE REPAIRED. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS. **PORTIVE EXPERIENCED NECK INJURIES AND STIFF NECK.** AK **PORTIVE EXPERIENCED NECK INJURIES AND AND ARD STIFF NECK.** AK **PORTIVE EXPERIENCED NECK INJURIES AND AND ARD STIFF NECK.** AK **PORTIVE EXPERIENCED NECK INJURIES AND AND ARD STIFF NECK.** AK **PORTIVE EXPERIENCED NECK INJURIES AND AND ARD STIFF NECK.** AK **PORTIVE EXPERIENCED NECK INJURIES AND AND ARD STIFF NECK.** AK **PORTIVE EXPERIENCED NECK INJURIES AND AND ARD STIFF NECK.** AK **PORTIVE AND AND ARD ARD AND ARD STIFF NECK.** AK **PORTIVE AND ARD ARD AND ARD ARD ARD AND ARBACS OF PROBLEM.** AND ARD ARD ARD ARD ARD ARD ARD ARD ARD AR						CAUSING \$11,000 WORTH OF DAMAGE TO FRONT OF TRUCK. UPON IMPACT, DRIVER'S AIR BAG
891918 CHEVROLET SILVERADO 2000 2001-06-13 *DRIVER EXPERIENCED NECK INJURIES AND STIFF NECK.*AK HEAD COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNIN CONTACTED MANUFACTURER. AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.*AK WHILE DRIVING 30TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER.*AK CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS DIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS DIL ON HIGHWAY. CONSUMER LOST CONTROL OF THE VEHICLE. AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRBAGS DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PROOBLEM. *AK DRIVER RECEIVED BACK AND NECK INJURIES. *SLC CONSUMER LOST CONTROL OF THE VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROOBLEM. *AK PRIVER RECEIVED DID NOT DEPLOY, DEALERSHIP WAS AWARE OF PROOBLEM. *AK PRIVER RECEIVED DID NOT DEPLOY. OF ALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PERMISSION. *AK *IG WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WAS DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WAS DEPLOYED. *AK WEHICLE INVOLVED WAS IN A FRONTAL COLLISION, WEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH. *AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE RES DACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE HAD BOANT OF ISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE HAD BOANT OF ISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DR						FAILED TO DEPLOY WHILE PASSENGER'S AIR BAG WAS TURNED OFF. INSURANCE COMPANY WAS
READ COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY. THERE WAS NO PRIOR WARNIN CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING. "AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER. "AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT END OF TRUCK. CONTACTED DEALER. "AK CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER LOST CONTROL OF THE VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRBAG DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PROBBLEM. "AK DRIVER RECEIVED BACK AND NECK INJURIES." SIDE AIRBAG DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PROBBLEM. "AK DRIVER RECEIVED BACK AND NECK INJURIES." SIDE AIRBAG DIDN'T DEPLOY. DEALER SID IN OT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM BO01872 CHEVROLET SILVERADO 2000 2001-12-18 WHILE DRIVING, VEHICLE WAS INVOLVED IN A ROCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. "AK "YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH." AK THERE WERE 2 INJURIES. "YH IN A FRONTAL COLLISION, VEHICLE ROLLD 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED." APPROXIMATELY 40-50MPH." AK THERE WERE 2 INJURIES. "YH IN A FRONTAL COLLISION, VEHICLE ROLLD 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DID NO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40-9MPH." AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER STATED THE ROAD WAS UNEVEN AND THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER WAS AIRBORNE AND LANDED ON DRIVER'S						
892771 CHEVROLET SILVERADO 2000 2001-06-28 CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.*AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY, DAMAGED FRONT BY CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER STATED VEHICLE WAS INVOIVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM BO01872 CHEVROLET SILVERADO 2000 2001-12-11 WHILE DRIVING, VEHICLE WAS INVOIVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WHILE DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VE	891918	CHEVROLET	SILVERADO	2000	2001-06-13	*DRIVER EXPERIENCED NECK INJURIES AND STIFF NECK .*AK
892771 CHEVROLET SILVERADO 2000 2001-06-28 CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.*AK WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY, DAMAGED FRONT BY CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER STATED VEHICLE WAS INVOIVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM BO01872 CHEVROLET SILVERADO 2000 2001-12-11 WHILE DRIVING, VEHICLE WAS INVOIVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WHILE DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIMES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO DEPLOY. VE						HEAD COLLISION AT 60-65MPH, AND AIR BAGS DID NOT DEPLOY, THERE WAS NO PRIOR WARNING.
893040 CHEVROLET SILVERADO 2000 2001-06-25 END OF TRUCK. CONTACTED DEALER. *AK CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER STAYED LOST CONTROL OF THE VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRBAG DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PROBLEM. *AK DRIVER RECEIVED BACK AND NECK INJURIES. *SLC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PERMISSION. *AK *IG WHILE DRIVING VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40MPH, *AK CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES. *IB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND WAS AI	892771	CHEVROLET	SILVERADO	2000	2001-06-28	CONTACTED MANUFACTURER, AND MANUFACTURER WAS NOT WILLING TO DO ANYTHING.*AK
CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND THERE WAS OIL ON HIGHWAY. CONSUMER LOST CONTROL OF THE VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRBAG DIDN'T DEPLOY, DEALERSHIP WAS AWARE OF PROBLEM. *AK DRIVER RECEIVED BACK AND NECK INJURIES. *SLC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PERMISSION. *AK *19. WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER WHILLE WAS DRIVING APPROXIMATELY 40-50MPH. *AK THERE WERE 2 INJURIES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NO' DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH. *AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES. *JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION. *AK CHEVROLET SILVERADO 2000 2002-08-01 CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION. *AK						WHILE DRIVING 30 TO 35 MPH HAD A CRASH, AND AIRBAGS DID NOT DEPLOY. DAMAGED FRONT
CONSUMER LOST CONTROL OF THE VEHICLE, AND IT HIT A GUARDRAIL. UPON IMPACT, DRIVER'S SIDE AIRBAG DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PROOBLEM. *AK DRIVER RECEIVED BACK AND NECK INJURIES. *SLC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PERMISSION. *AK *JG WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURIED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS INJURIED. *AK *YH NA FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELURG APPROXIMATELY 40MPH. *AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE RIGHE SWAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE RIGHE SWAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE RIGHE SWAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE RIGHE SWAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE RIBES BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES. *JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	893040	CHEVROLET	SILVERADO	2000	2001-06-25	
SIDE AIRBAG DIDN'T DEPLOY. DEALERSHIP WAS AWARE OF PROOBLEM. *AK DRIVER RECEIVED BACK AND NECK INJURIES. *SLC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PERMISSION. *AK *JG WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 40-SOMPH. *AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 40-MPH. *AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES. *JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION. *AK						
BACK AND NECK INJURIES. *SLC CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAG DID NOT DEPLOY, DEALER ID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM PERMISSION. *AK *JG WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH BO16756 CHEVROLET SILVERADO 2000 2002-08-04 DEPLOYED.*AK CHEVROLET SILVERADO 2000 2002-08-04 DEPLOYED.*AK SOLOTOR SILVERADO 2000 2002-08-05 DEPLOYE. WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT, AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISH AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISH AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISH AFTER COMING BACK ON THE ROA						·
DID NOT DEPLOY, DEALER DID NOT CHECK VEHICLE, BECAUSE GM WOULD NOT GIVE THEM 8001868 CHEVROLET SILVERADO 2000 2001-12-18 PERMISSION. *AK *JG WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER 8014186 CHEVROLET SILVERADO 2000 2002-07-03 VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH. *AK THERE WERE 2 INJURIEES. *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND THE AIR BAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 40-50MPH. *AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH. *AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.* JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION. *AK	895573	CHEVROLET	SILVERADO	2000	2001-08-29	
8001872 CHEVROLET SILVERADO 2000 2001-12-18 PERMISSION.*AK *JG 8001872 CHEVROLET SILVERADO 2000 2001-12-11 WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH 8016756 CHEVROLET SILVERADO 2000 2002-08-04 DEPLOYE. WEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DID NO' DEPLOYE. YEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NO' DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER 8017393 CHEVROLET SILVERADO 2000 2002-08-25 WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						CONSUMER STATED VEHICLE WAS INVOLVED IN A FRONTAL CRASH OF 30 MPH, AND THE AIR BAGS
WHILE DRIVING, VEHICLE WAS INVOLVED IN AN ACCIDENT. UPON IMPACT, AIR BAG ON DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH. *AK THERE WERE 2 INJURIEES. *YH BO14186 CHEVROLET SILVERADO 2000 2002-07-03 VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH. *AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NO'DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH. *AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES. *JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLI WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION. *AK WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLI WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION. *AK						, , , , , , , , , , , , , , , , , , ,
B01872 CHEVROLET SILVERADO 2000 2001-12-11 DRIVER/PASSENGER SIDE DID NOT DEPLOY, DRIVER WAS INJURED. *AK *YH WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH 8014186 CHEVROLET SILVERADO 2000 2002-07-03 VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NO' DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER 8017393 CHEVROLET SILVERADO 2000 2002-08-25 WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	8001868	CHEVROLET	SILVERADO	2000	2001-12-18	
WHILE DRIVING WAS HIT HEAD-ON BY ANOTHER VEHICLE AND BOTH DRIVER AND PASSENGERS AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH, AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIES. *YH 8016756 CHEVROLET SILVERADO 2000 2002-08-04 PROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NO' DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER 8017393 CHEVROLET SILVERADO 2000 2002-08-25 WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	8001872	CHEVROLET	SILVERADO	2000	2001-12-11	
AIRBAGS DID NOT DEPLOY. CONSUMER WAS DRIVING APPROXIMATELY 30MPH ,AND THE OTHER VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRINGT HET RIEES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.* JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLI WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	2002072	S. L. VINOLET	3.2.2.00			THE THE PARTY OF T
8014186 CHEVROLET SILVERADO 2000 2002-07-03 VEHICLE WAS DRIVING APPROXIMATELY 40-50MPH.*AK THERE WERE 2 INJURIEES. *YH IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NO' DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERD INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						
IN A FRONTAL COLLISION, VEHICLE ROLLED 4 TIMES. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						·
8016756 CHEVROLET SILVERADO 2000 2002-08-04 DEPLOYED.*AK VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NOT DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	8014186	CHEVROLET	SILVERADO	2000	2002-07-03	
VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NODEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	8016756	CHEVROLET	SILVERADO	2000	2002-08-04	
DEPLOY. VEHICLE WAS TRAVELING APPROXIMATELY 40MPH.*AK CONSUMER STATED THE ROAD WAS UNEVEN AND THE RIGHT SIDE TIRES WAS CAUGHT IN A WASHOUT, CONSUMER TRIED TO BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	2010/30	CHEVIOLET	SILVENADO	2000	2002 00 04	VEHICLE INVOLVED WAS IN A FRONTAL COLLISION WITH A TREE, UPON IMPACT AIR BAGS DID NOT
BRING THE TIRES BACK ON THE ROAD BUT OVERCORECTED, THE VEHICLE THEN BEGAN TO FISHTA AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						·
AFTER COMING BACK ON THE ROAD, SLID ACROSS THE HIGHWAY AND HIT A TREE, THE DRIVER SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						·
8017393 CHEVROLET SILVERADO 2000 2002-08-25 SUFFERED INJURIES.*JB WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						·
WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	8017393	CHEVROI FT	SILVERADO	2000	2002-08-25	· ·
WAS AIRBORNE AND LANDED ON DRIVER'S SIDE. NONE OF THE AIRBAGS DEPLOYED, AND CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK	-01.000	S. L. VINOLET	3.2.2.00			
8017521 CHEVROLET SILVERADO 2000 2002-08-01 CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK						WHILE TRAVELING AT 55 MPH LOST CONTROL OF VEHICLE AND HIT A CONCRETE DIVIDER, VEHICLE
	004===	011-11-1			2000	·
	8017521	CHEVROLET	SILVERADO	2000	2002-08-01	CONSUMER SUSTAINED LEG INJURY. PLEASE PROVIDE ANY FURTHER INFORMATION.*AK
UPON A FRONTAL IMPACT AT ESTIMATED SPEED OF 55 MPH, NEITHER DUAL AIR BAG DEPLOYED.						UPON A FRONTAL IMPACT AT ESTIMATED SPEED OF 55 MPH. NEITHER DUAL AIR BAG DEPLOYED
CHEVROLET TOLD CONSUMER THAT AIR BAGS DEPLOY IN CERTAIN SITUATIONS. OWNER HAS						·
8018038 CHEVROLET SILVERADO 2000 RECEIVED A RECALL NOTICE FOR AIR BAGS. PLEASE DESCRIBE DETAILS. *AK	8018038	CHEVROLET	SILVERADO	2000		RECEIVED A RECALL NOTICE FOR AIR BAGS. PLEASE DESCRIBE DETAILS. *AK

10137048	CHEV/BOLET	SILVERADO	2000	2005-09-11	DT: CONSUMER'S VEHICLE WAS INVOLVED IN A CAR ACCIDENT ON SEPTEMBER 11, 2005 WHILE DRIVING 50-55 MPH. IT WAS A HEAD ON COLLISION. UPON IMPACT, DRIVER'S SIDE AIR BAG DID NOT DEPLOY. THE CONSUMER HAD NOT CONTACTED THE DEALER OR MANUFACTURER. *AK
10120031	CHEVIOLET	SIEVENADO	2000	2003 07-01	
10122067 10128831	CHEVROLET	SILVERADO SILVERADO	2000	2005-03-19	REPORT) NO AIRBAG DEPLOYMENT OF EITHER VEHICLE. AIR BAGS DID NOT DEPLOY UPON IMPACT
					TRUCKS. ESTIMATED IMPACT SPEED 90 MPH (60 MPH VEHICLE 2, 30 MPH VEHICLE 1 PER CHP
10120946	CHEVROLET	SILVERADO	2000	2005-05-06	YARD AND WE ARE AWAITING THE RESPONSE FROM THE INSURANCE ADJUSTOR. OFF CENTER HEAD ON CRASH WITH 2 SIMILAR 2000 CHEVY SILVERADO EXTENDED CAB PICK UP
10120046	CHEV/DOLET	CILVEDADO	2000	2005 05 06	DO NOT UNDERSTAND WHY WE WERE NEVER NOTIFIED OF THIS. THE TRUCK IS NOW IN A STORAGE
					NEVER NOTIFIED OF THIS BEFORE THE INCIDENT, BUT ARE CURRENTLY RECEIVING UPDATES TODAY.
					WHEEL. MY WIFE CHECKED THE INTERNET AFTER THE INCIDENT AND FOUND THERE WAS A RECALL FOR THE AIRBAG MODULE ON THE YEAR OF MY 2000 CHEVROLET SILVERADO TRUCK. WE WERE
					PASSENGER AIRBAG MODULES, ALSO THE STEERING WHEEL BENT RESEMBLING AN AIRPLANE
					BONE, 2 BLACK EYES AND FRACTURED RIBS DUE TO THE INACTIVATION OF THE DRIVERS AND
					I WAS IN A HEAD ON COLLISION AND RECEIVED A COMPOUND FRACTURE TO MY RIGHT FEMUR
10113830	CHEVROLET	SILVERADO	2000	2005-03-08	PROVIDED BY RICKY'S WIFE KAREN FLIMP. *AK
					INSPECTION. THE CAUSE HAD NOT BEEN DETERMINED AT THIS TIME. THIS INFORMATION WAS
					IMPACT, BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. VEHICLE WAS TOWED TO A GARAGE FOR
10111181	CHEVROLET	SILVEKADO	2000	2004-12-23	WHILE DRIVING 20 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A FRONTAL COLLISION. UPON
10111121	CHEVPOI ET	SILVEDADO	2000	2004-12-23	AND WAS TRANSPORTED TO THE LOCAL HOSPITAL BY AMBULANCE. DEALER AND MANUFACTURER WERE NOTIFIED. *AK
					MPH. UPON IMPACT, NEITHER FRONTAL AIR BAG DEPLOYED. CONSUMER SUSTAINE DINJURIES,
					WAS INVOLVED IN A REAR END COLLISION, IT CRASHED INTO ANOTHER VEHICLE IN FRONT AT 50
10100704	CITEVIOLET	SILVENADO	2000	2003 01-11	RECALL CAMPAIGN 02V078 00 CONCERNING AIR BAG SENSING MODULE. CONSUMER'S VEHICLE
10108404	CHEVROLET	SILVERADO	2000	2005-01-11	PICS OF THE TRUCK AND THE CRASH SITE I CAN SEND IF NECESSARY. I CAN ALSO PROVIDE THE LOCATION OF THE TRUCK SO IT CAN BE INSPECTED.*AK
					SOFTWARE SCREWUP SOMETHING NOT HOOKED UP RIGHT IN THE AIRBAG SYSTEM ETC). I HAVE
					WILL AT LEAST BE INVESTIGATED TO MAKE SURE THIS IS NOT A SYSTEMIC PROBLEM (I.E.
					LATER 7 WEEKS PREMATURE. AS FOR WHAT WAS DONE TO CORRECT THE PROBLEM I'M HOPING IT
					IN THE LOWER LEG/ANKLE. AS A RESULT OF THE WATER BREAKING MY SON WAS BORN 3 DAYS
					BLOOD AROUND THE BRAIN, A BROKE CHEEK BONE, AND FRACTURED HIP. MY WIFE WAS 33 WEEKS PREGANANT AT THE TIME AND HER WATER BROKE AND SHE GOT A COMPOUND FRACTURE
					DEPLOYED (THE TRUCK IS TOTALLED). I HIT THE STEERING WHEEL AND GOT A CONCUSSION WITH
					THAN 30 MPH INTO A DIRT WALL IN WHICH NEITHER THE DRIVER'S NOR PASSENGER'S AIRBAGS
					VEHICLE (2000 CHEVY SILVERADO). THEN MY TRUCK HAD A FULL FRONTAL IMPACT AT GREATER
					THE EVENT WAS A CAR PULLED OUT IN FRONT OF ME WHICH STILL HIT THE DRIVER'S SIDE OF MY
10101301	CHEVROLET	SILVERADO	2000	2004-11-02	WAS INCT WILLING TO ASSIST THE CONSUMER. "AN
10101301	CHEV/DOLET	CII VEDADO	2000	2004-11-02	UPON IMPACT, AIR BAGS DID NOT DEPLOY. RECALL 02V178000 WAS ISSUED. MANUFACTURER WAS NOT WILLING TO ASSIST THE CONSUMER. *AK
					CONSUMER'S VEHICLE WAS INVOLVED IN A HEAD ON COLLISION WHILE DRIVING AT 25-30 MPH.
10081392	CHEVROLET	SILVERADO	2000	2004-06-22	SHOULDER, CHEST, BACK AND HIPS.
					THE DRIVER INJURED HIS NECK, BACK, HIPS AND PELVIS. THE PASSENGER INJURED HER RIGHT
					AIR BAGS DID NOT DEPLOY. *AK BOTH THE DRIVER AND THE PASSENGER SUSTAINED INJURIES.
					WHILE DRIVING 45-55 MPH CONSUMER'S VEHICLE WAS REAR-END BY A TRACTOR TRAILER. PUSHING CONSUMER'S VEHICLE OFF ROAD AND INTO A DITCH, FRONT END FIRST. UPON IMPACT,
10045511	CHEVROLET	SILVERADO	2000	2003-09-28	KNEE AND BACK PROBLEMS. *LA
					ABOUT 40-45 MPH, AND NEITHER AIR BAG DEPLOYED. I WAS SHIFTED IN THE VEHICLE AND HAVE
					I REARENDED A VEHICLE THAT WAS SITTING STILL IN THE MIDDLE OF THE ROAD, I WAS TRAVELING
10044432	CHEVROLET	SILVERADO	2000		40 MPH. DRIVER WAS INJURED. *AK
10029556	CHEVROLET	SILVERADO	2000	2003-07-17	BAGS DEPLOYED. *AK AIR BAGS DID NOT DEPLOY WHEN VEHICLE STRUCK A TREE HEAD ON. VEHICLE WAS TRAVELING AT
40020556	CUE) (2.0) 5=	CIII VED : D C	2022	2002 07 17	WHILE DRIVING AT 45MPH CONSUMER HAD A FRONT COLLISION ,AND NEITHER OF THE FRONT
10027230	CHEVROLET	SILVERADO	2000	2003-06-16	SIDE SEAT BELT DIDN'T RETRACT.*AK *PH *JB
					THE AIR BAGS DEPLOYED UPON IMPACT. DRIVER IMPACTED THE STEERING WHEEL, AND DRIVER'S
10022039	CHEVROLET	SILVERADO	2000	2003-04-11	THE VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WHILE DRIVING AT 40 MPH AND NONE OF
10022039	CHEVROLET	SII VEDADO	2000	2003-04-11	THE VEHICLE WAS INVOLVED IN FRONTAL COLLISION, AND THE AIR BAGS FAILED TO DEPLOY. THE CONSUMER WAS INJURED. *AK *TS *JB
10008151	CHEVROLET	SILVERADO	2000	2003-02-16	THE VEHICLE WAS INVOLVED IN AN ACCIDENT, AND THE AIR BAG FAILED TO DEPLOY.*JB
10008044	CHEVROLET	SILVERADO	2000	2003-01-26	AIR BAGS FAILED TO DEPLOY FROM FRONTAL IMPACT DURING MOTOR VEHICLE ACCIDENT
10005962	CHEVROLET		2000	2002 11 00	AIR BAGS FAILED TO DEPLOY IN A COLLISION, RESULTING IN A FATALITY. *AK *JB
8023044	CHEVROLET	SILVERADO	2000	2002-11-06	PROVIDE MORE DETAILS. TS
					VEHICLE WAS IN A FRONT COLLISON AND NONE OF THE AIR BAGS DEPLOYED UPON IMPACT. NONE OF THE OCCUPANTS IN THE VEHICLE WERE SERIOUSLY INJURED AT TIME OF THE ACCIDENT. PLEASE
8022592	CHEVROLET	SILVERADO	2000	2002-09-28	DEPLOYED. PLEASE PROVIDE ANY FURTHER INFORMATION. MR
					VEHICLE. CONSUMER STATES VEHICLE SLAMMED INTO A TREE AND NONE OF THE AIRBAGS
					CONSUMER WAS TRAVELING AROUND A CURVE, CONSUMER SUDDENLY LOST CONTROL OF

	1		1	1	
10139984	CHEVROLET	SILVERADO	2000	2005-06-17	DT: THE CONTACT'S SON WAS INVOLVED IN AN ACCIDENT ON 6-17-05. THE CONTACT RECEIVED A COPY OF THE CRASH REPORT. UPON IMPACT, NEITHER AIR BAG DEPLOYED. THE VEHICLE HIT SEVERAL TREES. THE POLICE REPORT STATED THE SPEED LIMIT WAS 55 MPH. THE PASSENGER'S HEAD WENT THROUGH THE WINDSHIELD, BUT PASSENGER WAS NOT SERIOUSLY HURT. NEITHER THE DRIVER NOR THE PASSENGER HAD TO GO TO THE HOSPITAL. THE CONTACT REPORTED THAT AIR BAG LIGHT ILLUMINATED IN THE CAR PRIOR TO THE INCIDENT. THE INSURANCE COMPANY HAS BEEN NOTIFIED. THE TRUCK WAS TOTALED. THE CONTACT TOOK PICTURES OF THE PINE TREE THAT WAS EMBEDDED IN THE HOOD. UPDATED 11/15/05. *JB TL*THE CONTACT OWNS A 2000 CHEVROLET SILVERADO. WHILE DRIVING 30 MPH HE DEPRESSED THE BRAKES AND CRASHED INTO THE VEHICLE IN FRONT OF HIM. THE AIR BAGS DID NOT DEPLOY. THE FRONT SEAT PASSENGER SUSTAINED A LACERATED SPLEEN AND CONTUSION OF THE HEART. A COMPLAINT WAS SUBMITTED TO THE MANUFACTURER (COMPLAINT # 71-546827970). THE CURRENT AND FAILURE MILEAGES WERE 128,000. UPDATED 02-01-08 *BF UPDATED 02/01/08
10199593	CHEVROLET	SILVERADO	2000	2007-08-10	*TR CONSUMER STATES THAT AIRBAGS DID NOT DEPLOY DURING ACCIDENT IN A 2000 CHEVROLET
10328507	CHEVROLET	SILVERADO	2000	1901-01-01	SILVERADO CAUSING SERIOUS INJURY. *GR
878851	CHEVROLET	SUBURBAN	2000	2000-12-11	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 60MPH. UPON IMPACT, AIRBAGS DID NOT DEPLOY. VEHICLE ROLLED OVER, AND VEHICLE EXPLODED. THERE WERE MINOR INJURIES.*AK
					WHILE DRIVING AT 25 MPH AN ACCIDENT OCCURRED, AND SEATBELT DID NOT TIGHTEN/ AIRBAG DID NOT DEPLOY PLEASE PROVIDE ANY FURTHER INFORMATION, AND IDENTIFICATION
8002321	CHEVROLET	SUBURBAN	2000		NUMBER.*AK
8017775	CHEVROLET	SUBURBAN	2000		A TIRE SHEARED OFF, ANOTHER TRUCK CROSSING MEDIAN BEGAN HEADING STRAIGHT TO CONSUMER'S VEHICLE. DRIVER ATTEMPTED TO MANUEVER, BUT RAN OFF THE ROAD. UPON FRONTAL OFF CENTERED IMPACT AT 60 MPH, AND DUAL AIR BAGS FAILED TO DEPLOY.*AK
557967 563859	CHEVROLET	TAHOE	2000	2000-09-01	RIGHT FRONT TIRE (NO MAKE OR MODEL PROVIDED) EXPERIENCED A BLOWOUT, CAUSING THE VEHICLE TO GO OFF THE ROAD, COME BACK ONTO THE ROADWAY, AND CRASH INTO A CEMENT WALL, THE CONSUMER STATED THAT HE BELIEVED THE BACK RIGHT TIRE EXPERIENCED A BLOWOUT AS WELL, DURING THE CRASH THE AIRBAG EXPERIENCED A NO DEPLOYMENT, ONE PERSON WAS INJURED DUE TO THE INCIDENT. (OHIO TRAFFIC CRASH REPORT) *SLC THE CONSUMER WAS INVOLVED IN A MAJOR ACCIDENT BUT THE DRIVER SIDE AIR BAGS FAILED TO DEPLOY. THE CONSUMER SUFFERED INJURIES. *YH
567545	CHEVROLET	TAHOE	2000	2000-11-11	CONSUMER WAS IN TWO ACCIDENTS. ONE IN NOVEMER OF 2000 AND THE OTHER IN SEPTEMBER OF 2002. THE AIR BAGS DID NOT DEPLOY IN EITHER INCIDENT. CONSUMER DESCRIBED THE INCIDENTS TO A REPRESENTATIVE OF GENERAL MOTORS. CONSUMER WAS INFORMED THAT THE AIR BAGS SHOULD NOT HAVE DEPLOYED, IN THE FIRST ACCIDENT THERE WAS ONE INJURY, IN THE SECOND ACCIDENT, THERE WERE TWO INJURIES. *JG HEAD ON COLLISION, IMPACT ON FRONT RIGHT SIDE, HIT AND SHEARED IN HALF A WOODEN
740413	CHEVROLET	TAHOE	2000	2001-02-01	UTILITY POLE, NO AIR BAG DEPLOYMENT ON EITHER SIDE, BUMPER IS CURLED UNDER FRONT END OF VEHICLE. *AK
767411	CHEVROLET	TAHOE	2000	2001-11-11	ON NOVEMBER 11,2000 I HAD A HEAD ON COLLISION (NOT MY FAULT) AND THE AIRBAGS DIDN'T DEPLOY. THEN ON SEPT 1,02 WE HAD A ACCIDENT ON INTERSTATE 95 THAT WE TOTALED THE TAHOE AND THE BODY SHOP CALLED GM SINCE THE AIRBAGS DIDN'T DEPLOY AGAIN. MR. LATTERMERE FROM GM CALLLED ME AND TOLD ME OVER THE PHONE AFTER I DESCRIBE THE ACCIDENT TO HIM THAT, AS HE DREW A PICTURE ON PAPER, "THAT THE AIR BAGS SHOULDN'T HAVE DEPLOYED". I FIND IT VERY DIFFICULT THAT A PERSON CAN DRAW A PICTURE AND TELL ME THIS. I WOULD LIKE FOR YOUR ORGANIZATION TO INSPECT THIS VECHILE AND RETRIEVE THE COMPUTER INFORMATION AND LET ME KNOW WHAT YOU THINK. GM SENT AN "INDEPEDENT" INSPECTOR OUT TO DO A REPORT BUT I HAVE NOTHING FROM HIM OR GM ON THE FINDING. I HAVE LEFT MESSAGES FOR MR. LATTERMERE TO CALL ME TO NO AVAIL.*AK
8018021	CHEVROLET	TAHOE	2000	2002-09-01	DEPLOY.*JB
10111305	CHEVROLET	TAHOE	2000	2005-01-02	WHILE DRIVING CONSUMER HIT A PATCH OF ICE WHICH SENT THE VEHICLE SLIDING, AND CAUSING AN ACCIDENT. HOWEVER, THE AIR BAGS DID NOT DEPLOY, AND CONSUMER WAS INJURED. CONSUMER CONTACTED THE DEALER, AND MANUFACTURER. *AK CONSUMER FEELS THAT MUCH OF THE PAIN AND SUFFERING MIGHT HAVE BEEN PREVENTED BY THE PROTECTION OF THE 4 AIR BAGS IN THIS TAHOE-NONE OF WHICH DEPLOYED UPON AN IMPACT THAT CRUSHED THE FRONT OF THE VEHICLE. JAMMED TH EFRONT PASENGER DOOR WHICH CONSUMER COULD NOT OPEN, AND BENT THE CAR'S FRAME BEYOND REPAIR. *BF
10150002	CHEVROLET	TAHOE	2000	2006-02-08	I WAS RECENTLY IN AN ACCIDENT AND MY 2 CHILDREN WERE IN THE VEHICLE WITH ME. I WAS IN A 5 CAR WRECK IN WHICH MY VEHICLE, AND THE ONE IN FRONT OF ME WERE TOTALED. UPON IMPACT ON THE FRONT OF MY TRUCK, MY AIR BAGS DIDN'T DEPLOY NOR DID MY SEAT BELTS LOCK. MY 11 YR OLD HIT HIS HEAD ON THE DASH, REQUIRING IMMEDIATE MEDICAL ATTENTION FOR A SEVERE LACERATION WHICH REQUIRED STITCHES. I LEARNED FROM GMC THERE WAS A RECALL ON MY TRUCK FOR AIR BAG MALFUNCTIONS AND I WAS NEVER NOTIFIED. *NM

	1			T	
10249443	CHEVROLET	ТАНОЕ	2000	2008-11-05	TL*THE CONTACT OWNS A 2000 CHEVROLET TAHOE. WHILE DRIVING APPROXIMATELY 35 MPH, THE VEHICLE CRASHED INTO A LAMP POST THAT WAS SURROUNDED BY CEMENT. THE FRONT END WAS PUSHED IN, WHICH CAUSED THE ENGINE TO SHIFT. THE AIR BAGS FAILED TO DEPLOY AND THE DRIVER SUSTAINED INJURIES TO HIS BACK AND NECK. THE VEHICLE WAS TOWED TO A LOCAL REPAIR SHOP AND THE MECHANIC STATED THAT THE AIR BAGS SHOULD HAVE DEPLOYED. THE DEALER WAS NOT NOTIFIED. THE MANUFACTURER FILED A CASE AND STATED THAT THEY WOULD BE IN TOUCH WITH THEIR DECISION. THE CURRENT AND FAILURE MILEAGES WERE 144,000.
					TL* THE CONTACT OWNS A 2000 CHEVROLET TAHOE. WHILE THE CONTACT'S SON WAS DRIVING 40
					MPH, HE CRASHED INTO A VEHICLE THAT RAN A RED LIGHT. THE AIR BAGS DID NOT DEPLOY. THE
					CONTACT'S SON SUSTAINED CHEST, LOWER BACK, AND NECK PAINS THAT REQUIRED MEDICAL ATTENTION. THE CONTACT'S SON WENT TO THE EMERGENCY ROOM TWO SEPARATE TIMES. A
					POLICE REPORT WAS FILED. THE VEHICLE WAS TOWED TO A TOW YARD. THE CONTACT WAS
					WAITING FOR FINALIZED INFORMATION FROM THE INSURANCE COMPANY TO DETERMINE IF THE
11190477	CHEVROLET	TAHOE	2000	2019-03-17	VEHICLE WAS TOTALED. THE DEALER AND MANUFACTURER WERE NOT CONTACTED. THE CAUSE OF THE FAILURE WAS NOT DETERMINED. THE FAILURE MILEAGE WAS UNKNOWN.
					HAD A DIRECT FRONTAL IMPACT, AND DRIVER AND PASSENGER AIRBAG DID NOT DEPLOY WHICH
864850	CHEVROLET	TRACKER	2000	2000-06-28	DID NOT PROTECT THE OCCUPANTS IN THE CRASH. NO PRIOR PROBLEMS WITH THE AIRBAG SYSTEM. *AK *ML
00.000					
					DRIVING AT APPROXIMATELY 50 MPH DRIVER SWERVED TO AVOID HITTING ANOTHER VEHICLE AND LOST CONTROL. VEHICLE WENT ACROSS FREEWAY AND HIT A STEEL BARRIER WITH THE RIGHT
					FRONT PASSENGER'S SIDE, AND CONTINUED ON FOR A BLOCK. THEN, WENT INTO A DITCH, NOSE
870591	CHEVROLET	TDACVED	2000	2000-07-22	FIRST UPON IMPACT, DUAL AIRBAGS DID NOT DEPLOY, CAUSING MINOR INJURIES IN STERIUM AND HEAD. NO INDICTATION OF AIRBAG BEING DEFECTIVE. VEHICLE WAS A TOTAL LOSS.*AK
870391	CHEVROLET	TRACKER	2000	2000-07-22	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WITH A 1985 528I, BMW, SPEED WAS NOT
					DETERMINED, AND BOTH AIR BAGS DID NOT DEPLOY. DEALER / MANUFACTURER WERE NOTIFIED,
883185	CHEVROLET	TRACKER	2000	2001-01-31	AND UNWILLING TO ASSIST IN THIS MATTER. FEEL FREE TO PROVIDE ANY FURTHER DETAILS ON THIS MATTER. *AK
					WHILE DRIVING AT 45 MPH CONSUMER'S VEHICLE WAS INVOLVED IN A DIRECT FRONTAL
891375	CHEVROLET	TRACKER	2000	2001-06-16	COLLISION. UPON IMPACT, NEITHER DRIVER'S SIDE NOR PASSENGER'S SIDE AIR BAGS DEPLOYED. DEALER WILL INSPECT VEHICLE. PLEASE PROVIDE ANY FURTHER DETAILS. *AK
002070					FRONTAL AIRBAGS DID NOT DEPLOY WHEN VEHICLE WAS INVOLVED IN A HEAD-ON ACCIDENT AT
897476	CHEVROLET	TRACKER	2000	2001-09-29	30-35 MPH. CONSUMER COLLIDED WITH ANOTHER VEHICLE WHILE MAKING A TURN. VEHICLE HAD FRONTAL DAMAGE. *AK 8SLC
558644	GMC	YUKON	2000	2000-12-16	THE AIRBAG DID NOT DEPLOY IN A HEAD ON COLLISION RESULTING IN INJURIES. NLM
8009240	GMC	YUKON	2000	2002-05-05	FRONTAL COLLISION AT 40-45 MPH, NEITHER AIRBAG DEPLOYED. DRIVER SUFFERED HEAD INJURY. *AK *YD
					DT: THE CONTACT STATED THAT WHILE TRAVELING 31 MPH ON A GRAVEL ROAD IN DRY CONDITIONS THE CONTACT LOST CONTROL OF THE VEHICLE AND IT STRUCK A TREE. UPON
					IMPACT, THE AIRBAGS DID NOT DEPLOY. THE FRONT PASSENGER HAD TO BE EXTRACTED FROM
					THE VEHICLE. THE DASHBOARD COLLAPSED INTO THE FRONT SEAT ALONG WITH THE FIREWALL. THERE WERE 3 INJURIES, AND A POLICE REPORT WAS TAKEN. THE VEHICLE WAS TOTALED. A GM
					REPRESENTATIVE RETRIEVED THE BLACK DETECTION BOX, VERIFIED THE SPEED OF 31 MPH, AND
10141260	CNAC	VIIIKONI	2000	2005 00 22	DETERMINED THAT THE AIRBAGS SHOULD HAVE DEPLOYED. GM PURCHASED THE SALVAGED
10141369	GMC	YUKON	2000	2005-09-23	VEHICLE FROM THE INSURANCE COMPANY AND DESTROYED IT. *AK
					MY WIFE AND DAUGHTER WERE INVOLVED IN A CRASH WITH OUR 2000 ISUZU AMIGO. MY WIFE
					IMPACTED A VEHICLE WHICH HAD CRASHED INTO ANOTHER VEHICLE AT APPROXIMATELY 25 MPH. NEITHER AIR BAG DEPLOYED NOR DID THE SEAT BELT TIGHTEN UP TO RESTRAIN MY WIFE, WHICH
					RESULTED IN HER IMPACTING THE STEERING WHEEL. AT THE SAME TIME, THE DRIVERS SEAT
729997	ISUZU	AMIGO	2000	2000-08-29	MOVED FORWARD AND DID NOT REMAIN STATIONARY.
					DURING A 40 MPH CRASH INTO A CONCRETE CENTER DIVIDER ON A INTERSTATE IN WHICH THE
					VEHICLE MADE CONTACT WITH THE FRONT AND DRIVER FRONT AREA, CAUSING EXTENSIVE DAMAGES. INCLUDING PUSHING BUMPER,GRILLE,HEADLIGHTS AND HOOD UP INTO THE ENGINE
					COMPARTMENT. TO MY SHOCK THE AIRBAGS DID NOT DEPLOY. WHAT IS UP WITH THIS? DO THEY
					JUST TELL YOU THEY ARE THERE AND THEY DON'T WORK WHEN YOU NEED THEM??? I WILL NOT PURCHASE ANOTHER ISUZU PRODUCT AND AM SEEKING A CLAIM AGAINST ISUZU TO FIND OUT
10052346	ISUZU	RODEO	2000	2004-01-04	WHAT THE PROBLEM MIGHT BE. THANK YOU FOR YOUR TIME!! *LA
					AIR BAGS ON 2000 ISUZU RODEO ARE DEFECTIVE.*MR THE CONSUMER WAS INVOLVED IN A
					FRONT END COLLISION YET NONE OF THE AIR BAGS DEPLOYED. THE CONSUMER CONTACTED THE MANUFACTURER ABOUT THE AIR BAGS BUT THE REPRESENTATIVE DID NOT SEEM TO BE TOO
40000777	161.50	00055	225-	2004 00 55	CONCERNED ABOUT THE SITUATION. THE CONSUMER BELIEVES THE AIR BAG SHOULD HAVE
10083770	ISUZU	RODEO	2000	2004-02-26	DEPLOYED AND DOESN'T FEEL SAFE IN THE VEHICLE. *NM

10087550	ISUZU	RODEO	2000	2004-02-26	VEHICLE WAS INVOLVED IN AN ACCIDENT WHILE TRAVELING AT 25 TO 30 MPH BUT THE AIR BAGS DID NOT DEPLOY.*MR THE CONSUMER WAS INVOLVED IN A FRONT END COLLISION YET NONE OF THE AIR BAGS DEPLOYED. THE CONSUMER CONTACTED THE MANUFACTURER ABOUT THE AIR BAGS BUT THE REPRESENTATIVE DID NOT SEEM TO BE TOO CONCERNED ABOUT THE SITUATION. THE CONSUMER BELIEVES THE AIR BAG SHOULD HAVE DEPLOYED AND DOESN'T FEEL SAFE IN THE VEHICLE. THE VEHICLE SUSTAINED \$6881. WORTH OF FRONT END DAMAGE. *NM
					I WAS IN AN ACCIDENT ON JULY 20,2006. A GIRL RAN A RED LIGHT AND I HIT HER IN THE PASSENGER SIDE OF HER CAR HEAD ON WITH MY 2000 ISUZU RODEO. IT WAS A FULL FRONTAL COLLISION FOR ME AND MY CHILDREN. LUCKILY, WE ARE ALWAYS BUCKLED UP BECAUSE NONE OF MY AIRBAGS DEPLOYED AT ALL. THE OTHER CAR WAS GOING ABOUT 60 MPH AND HER AIRBAG DEPLOYED WHEN I HIT HER BUT MINE DID NOT. LUCKILY, MY CHILDREN WERE NOT HURT BADLY BUT UNFORTUNATELY, I SUSTAINED NECK, BACK AND KNEE INJURIES. I WAS AND STILL AM VERY UPSET THAT MY AIRBAGS FAILED. EVEN THE OWNER OF THE BODY SHOP I USE WAS IN SHOCK THAT THEY DID NOT DEPLOY AS THE IMPACT WAS ENOUGH TO SPLIT THE FRAME OF MY RODEO AND TOTAL IT OUT. I WILL NOT BUY ANOTHER ISUZU AND I WILL ALSO NOT RECOMMEND THEM TO MY FAMILY OR FRIENDS IN THE FUTURE. THANK YOU FOR YOUR TIME, I HOPE I CAN HELP
10163811	ISUZU	RODEO	2000	2006-07-20	ANOTHER FAMILY FROM GETTING INJURED.
745106	ISUZU	TROOPER	2000	2001-05-02	THE ESTIMATES ARE NOT ALL IN YET, SO THE \$27,000 IS A GUESS AT THIS STAGE. MY FRIEND ALSO HAD A TROOPER WHOSE AIRBAGS FAILED AT LEAST ON ONE FRONT END CRASH.*AK WHILE DRIVING 45MPH T-BONED ANOTHER VEHICLE AND AIR BAGS DIDNOT DEPLOY. DRIVER AND
8009110	ISUZU	TROOPER	2000	2002-04-13	3 PASSENGERS SUSTAINED INJURIES. *AK
10160322	ISUZU	TROOPER	2000	2006-06-10	DT*: THE CONTACT STATED WHILE DRIVING 15 - 20 MPH THROUGH AT INTERSECTION ANOTHER VEHICLE RAN A STOP SIGN AND HIT THE CONTACT'S VEHICLE. THE VEHICLE RAN INTO A TREE SMASHING THE FRONT OF THE VEHICLE. THE FRONTAL AIR BAGS DID NOT DEPLOY. THE AIR BAG LIGHT DID NOT ILLUMINATE PRIOR TO THE INCIDENT. THE CONTACT WAS WEARING A SEATBELT, HOWEVER INJURIES WERE INCURRED. THE CONTACT HAD BRUISING TO THE FACE AND A SPRAINED HIP. A POLICE REPORT WAS FILED AT THE SCENE. THE VEHICLE WAS DEEMED TOTALED BY THE INSURANCE COMPANY.
					MY VEHICLE WAS STRUCK HEAD ON BY AN ONCOMING AUTO TRAVELING AT 45 MPH. MY VEHICLE WAS TRAVELING AT 35 MPH. THE IMPACT WAS AT 12:00. MY AIRBAG DID NOT DEPLOY NOR DID THE PASSENGER SIDE AIR BAG. I WAS 3 POINT BELTED AT THE TIME OF THE COLLISION. THE OTHER
744466	CHEVROLET	ASTRO	1999	2001-04-23	VEHICLE WAS A CHEVROLET BERRETA 2 DOOR AUTOMOBILE.*AK
757589	CHEVROLET	ASTRO	1999	2001-12-12	WAS IN FRONT IMPACT HEAD-N COLLISION ON 12/12/01. SPEED BETWEEN 40 AND 65 MPH. AIRBAGS FAILED TO DEPLOY.*AK
					AIR BAGS DID NOT DEPLOY IN A NEARLY HEAD-ON CRASH AT AN ESTIMATED SPEED OF 60 MPH. RELATIVE SPEED MAY HAVE BEEN LESS, BECAUSE VEHICLE WHICH THIS VAN HIT WAS SLIDING BACKWARDS IN THE SAME DIRECTION OF TRAVEL AS THE VAN. HOWEVER, CLOSING SPEED HAD TO BE SIGNIFICANT TO CAUSE IT TO BE DAMAGED BEYOND REPAIR WITHIN ITS \$13,000 VALUE. VEHICLE WAS A TOTAL LOSS. WE HAVE OWNED THIS VEHICLE SINCE NEW, NO MODIFICATIONS HAVE BEEN MADE TO IT, AND IT HAD NEVER BEEN IN AN ACCIDENT BEFORE THIS. DIGITAL PHOTOS
759758	CHEVROLET	ASTRO	1999	2002-02-19	OF DAMAGED VEHICLE ARE AVAILABLE IF DESIRED. *AK CONSUMER WAS TRAVELING ABOUT 35MPH ON A SIDE STREET AND ANOTHER VEHICLE VEERED
					INTO HIM BY CROSSING OVER INTO THE MERIDIAN STRIP. UPON IMPACT, NEITHER AIRBAG
873826	CHEVROLET	ASTRO	1999	2000-10-22	DEPLOYED, AND MORE THAN ONE PERSON WAS INJURED.*AK IN A FRONTAL COLLISION NONE OF THE AIR BAGS DEPLOYED ON IMPACT, CAUSING MAJOR
8016641	CHEVROLET	ASTRO	1999	2002-08-05	INJURIES TO DRIVER.*AK
10081510	CHEVROLET	ASTRO	1999	2004-06-22	WHILE DRIVING 40 MPH VEHICLE STALLED. THEN, VEHICLE SUDDENLY ACCELERATED. CONSUMER APPLIED THE BRAKES, BUT THEY WERE INOPERATIVE. THIS CAUSED THE VEHICLE TO CRASH INTO A TREE. UPON IMPACT, BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. DRIVER AND TWO PASSENGERS SUSTAINED MAJOR INJURIES, AND WERE TRANSPORTED TO THE HOSPITAL BY AMBULANCE. THE VEHICLE WAS TOWED TO A GARAGE. *AK
10087718	CHEVROLET	ASTRO	1999	2004-08-11	WHILE DRIVING CONSUMER TRIED TO AVOID A PERSON ON A BICYCLE ON THE ROAD. SWERVED IN ORDER NOT TO HIT THE PERSON, BUT WAS UNABLE TO MAINTAIN CONTROL OF THE VEHICLE, JUMPED A CURB, AND COLLIDED WITH A FIRE HYDRANT, AND STRIKING A TREE. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY DRIVER SUSTAINED HEAD AND NECK INJURIES, AND WAS TRANSPORTED BY AMBULANCE TO A HOSPITAL. VEHICLE WAS TOWED TO THE DEALER FOR INSPECTION. CONSUMER CONTACTED THE MANUFACTURER AND A REPRESENTATIVE CAME DOWN TO MEET WITH THE DEALER AND CONSUMER. THE REPRESENTATIVE INFORMED CONSUMER THAT THE VEHICLE WAS FUNCTIONING AS DESIGNED, AND THE RATE OF DECELERATION AND IMPACT WAS PRESENT. *AK

CONSUMER WAS TRAVELING 32MPH & HAD A HEAD-ON COLLSION. CONSUMER WAS WEARING SEAT BEET RESTRIANT AT THE HINE, BUT FRONTAL ARE BASE CLOSED THE CASE AT ONE POINT & REOPENED IT ONCE. CONSUMER CONTACTED THEM A SECOND TIME "AK "SLC WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF VEHICLE. DRIVEN'S SIDE SEATBELT DION'T HOLD, AND AIRBAGS DIDN'T BEET JUMPED IN FRONT OF VEHICLE. DRIVEN'S SIDE SEATBELT DION'T HOLD, AND AIRBAGS DIDN'T BEET JUMPED IN FRONT OF VEHICLE. DRIVEN'S SIDE SEATBELT DION'T HOLD, AND AIRBAGS DIDN'T BEET JUMPED IN FRONT OF VEHICLE. DRIVEN'S SIDE SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BEET JUMPED IN FRONT OF SHELL BEIT JUMPED IN FRONT OF THE TRUCK WENT INTO A SPILO DID WAYDE OF JUMPACT WITH ESTIMATED SPEED OF SHELL BEIT JUMPED IN FRONT OF THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVELL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T BE TRAVEL BY THE TRUCK SEATBELT						
1994/238	40305365		ASTRO	4000	2007 04 24	AND ICE, THE CONTACT LOST CONTROL OF THE VEHICLE AND SLID OFF THE ROAD. THE VEHICLE THEN STRUCK A TELEPHONE POLE. THE AIR BAGS FAILED TO DEPLOY. THE SEAT BELT FAILED TO RESTRAIN HIM AND HE STRUCK HIS HEAD ON THE WINDSHIELD. THE WOUND TOOK 24 STITCHES TO CLOSE. MOST OF THE VEHICLE WAS REPAIRED AT THE COST OF \$4,500. THE MANUFACTURER'S INVESTIGATOR CONCLUDED THAT THE AIR BAG WOULD NOT DEPLOY AT 25 MPH. THE ARKANSAS POLICE DEPARTMENT FILED REPORT NUMBER 07-00343. THE CURRENT MILEAGE WAS 146,661
VEHICLE IMPACTED A HORSE IN ROAD AT A SPEED OF 45 MPH. IMPACT WAS HEAD-ON. LEGS OF THE HORSE CONTACTED THE ROY. ELONGARY PROPELLING THE HORSE INTO THE WINSHELD AND DON'TO THE ROSC CONTACTED THE ROY. ELONGARY PROPELLING THE HORSE INTO THE WINSHELD AND DON'TO THE ROSC PASSES. SIGNIFICANT DENTING OF THE BUMPER THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE PROPERTY OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC POUR THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC PASSES OF THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC PASSES OF THE AIR BAGS FALLED TO DEPLOY. THE ROSC PASSES OF THE ROSC						
THE HORSE CONTACTED THE RONT BILMORE PROPELLING THE HORSE INTO THE WINDSENSILE DAND ONTO THE ROOT THE CAR SUSTAINED MANDE BANKE TO THE FORM TATHOUGH THERE WAS SIGNED CAN DEVELOP THE ROOT THE CAR SUSHING MANDE TO THE ROOT. THE GOOD YEAR THE ROOT THE CAR SUSHING MANDE TO THE ROOT TO DEPLOY. THE GOOD YEAR THE ROOT THE CAR SUSHING MANDE THE ROOT BANKE THE WAS SIGNED TO DEPLOY. THE GOOD YEAR THE ROOT TO CAR BUMBER AND BUMBER THE ARE BASS FALLED TO DEPLOY. THE GOOD YEAR THE ROOT TO CAR BUMBER AND BUMBER THE ARE BASS FALLED TO DEPLOY. THE GOOD YEAR THE WAS SUSHING MANDE THE ROOT TO THE HILL HIT TIME OVER THOSE TO THE WAS SIGNED TO SHAPE THE WAS SIGNED TO BE THE WAS SIGNED TO BE THE WAS SIGNED TO BE THE CONTROL THE WAS SIGNED TO BE THE WAS SIGNED THE WAS SIGNED TO BE THE WAS SIGNED	10347230	CHEVIOLET	ASTRO	1333	2010 00 03	AIRDAGS FAILED TO DELEGT IN AN ALTHOX. SO WILLTHEAD ON CRASH. TR
CHEVROLET BLAZER 1999 2002-09-15 TUNNED 2 TIMES LUPON IMPACT, AIR BAGS FAILED TO DEPLOY. *AK	716098	CHEVROLET	BLAZER	1999	1999-12-12	THE HORSE CONTACTED THE FRONT BUMPER PROPELLING THE HORSE INTO THE WINDSHIELD AND ONTO THE ROOF. THE CAR SUSTAINED MAJOR DAMAGE TO THE FRONT. ALTHOUGH THERE WAS SIGNIFICANT DENTING OF THE BUMPER THE AIR BAGS FAILED TO DEPLOY. THE ROOF OVER THE FRONT PASSENGER HAD MAJOR CRUSHING INCLUDING THE DRIVER'S FRONT PILLA. *AK
CONSUMER WAS TRAVELING ABOUT 32MPH IN GOOD WATHER CONDITIONS, AND WAS HIT BY SERVING HEAVING STAPPH AND HEAVING STORE DOOR AND THE FRONT HOOD. UPON IMPACT, AIRBAGS DIDN'T DEFLOY, DEALER WILL BE CONTACTED. *AB.						
CONSUMER WAS TRAVELING 32MPH & HAD A HEAD-ON COLLSION. CONSUMER WAS WEARING SEAT REST RESTRIANT THE HILB, BUT FRONTAL AIR BAGS CORD TIME.* AIK SEAT RESTRIANT THE HILB, BUT FRONTAL AIR BAGS CONTACTED THEM A SECOND TIME.* AIK SEAT RESTRIANT THE HILB, BUT FRONTAL AIR BAGS CONTACTED THEM A SECOND TIME.* AIK SEAT RESTRICT TO MY THOUGHT PROVIDED THE AIR BAGS CONTACTED THEM A SECOND TIME.* AIK SEAT RESTRICT TO MY THOUGHT PROVIDED THE AIR BAGS CONTACTED THEM A SECOND TIME.* AIK SEAT RESTRICT TO MY THOUGHT PROVIDED THE AIR BAGS CONTACTED THEM. THE TRUCK LID AVOID COLLIDING WITH THEM BUT SPUN AROUND HITTON CONCRETE WALL. INSTITUTE AIR BAGS DEPLOYED UP IMPACT WITH ESTIMATED SPEED OF 65 MPH. PLEASE DESCRIBE DETAILS. MR WAS DRIVING, WHEN ANOTHER VEHICLE BEAR RINGED VEHICLE UN FRONT OF TI, BLAZER AVOID HITTON CHICAGE UPON MACH. THE TRUCK LID AVOID COLLIDING WITH THEM BUT SPUN AROUND HITTON CONCRETE WALL. INSTITUTE AIR BAGS SEATED TO DEPLOY. MR WAS DRIVING, WHEN ANOTHER VEHICLE BEAR RINGED VEHICLE UN FRONT OF TI, BLAZER AVOID HITTON CHICAGE UPON MACH. THE TRUCK CHICAGE WAS INVOICED BY HARD AND CHARLES WAS READ FRONT OF THE MACH. THE TRUCK DID AVOID COLLIDING WITH THEM BUT SPUN AROUND HITTON CONCRETE WAS READ FRONT OF THE MACH. THE TRUCK DID AVOID COLLIDING WITH THE BUT SPUN AROUND HITTON CONCRETE WAS READ FRONT OF THE MACH. THE TRUCK DID AVOID COLLIDING WITH THE BUT SPUN AROUND HITTON CONCRETE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAGE WAS READ FRONT OF THE MACH. THE TRUCK CHICAG	767338	CHEVROLET	BLAZER	1999	2002-09-15	CONSUMER WAS TRAVELING ABOUT 42MPH IN GOOD WEATHER CONDITIONS, AND WAS HIT BY
SATA BELT RESTRAINT AT THE TIME, BUT FROMTAL AIR BAGS DIDN'T DEPLOY. DEALER CLOSED THE SATATOR OF POINT & REOPENED IT ONCE CONSUMER CONTACTED THEM A SECOND TIME." AIX WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVELING ON INTERSTATE AND WITHOUT PRIOR WARNING A DEER JUMPED IN FRONT OF WHILE TRAVEL ON THE TRAVEL OF THE JUMPED WARNING A DEER JUMPED IN FRONT OF SO THE FRONT OF THEM. THE RUCK DID AVOID COLLIDING WITH THEM BUT SUM AROUND HITTING CONCRETE WALL. RETITINE AN BRAGS DEPLOYED UP IMPACT WITH IS TIMATED SPEED OF SO MPH. PLEASE DESCRIBE DETAILS. MR WAS DRIVING, WHEN ANOTHER VEHICLE REAR ENDED VEHICLE IN FRONT OF IT. BLAZER AVOID HITTING VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES. VEHICLE HIT MEDIAN WALL WITH FRONT OF VEHICLE. UPON IMPACT, THE AIR BAGS STAILED TO DEPLOY. MILE HITTING VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES. VEHICLE HIT MEDIAN NONE OF THE NETHER AIR BAGS DEPLOYED. THE DEALER WAS NOTHERD. *N.ILM HITTING VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES. VEHICLE HIT MEDIAN NONE OF THE NETHER AIR BAGS DEPLOYED. THE DEALER WAS NOTHERD. *N.ILM HITTING VEHICLE ON WET ROAD & SPUN AROUND A STAILED AND CONCUSSION FOR PASSENGER RESULTED. **SATURD AND CONCUSSION FOR PASSENGER RESULTED.** **DEPLOY HITTING VEHICLE ON THE PASSENGER SOUTH AND CONCUSSION FOR PASSENGER RESULTED.** **DEPLOY HITTING ON A STAILED AND CONCUSSION FOR PASSENGER RESULTED.** **DEPLOY HITTING VEHICLE ON THE PASSENGER SOUTH AND CONCUSSION FOR PASSENGER RESULTED.** **THE	859664	CHEVROLET	BLAZER	1999	2000-04-04	
DOUGH STATE BLAZER 1999 2002-02-28 VEHICLE DRIVER'S SIDE STATEST DION'T HOLD, AND AIRBAGS DION'T DEFIDOY." AK THE TRUCK WENT THOT A SKED OW WET ROAD AFFER THOS THOR HOW THE ROAD AFFER THOS COLUSION THAT OCCURED IN FRONT OF THEM. THE TRUCK DID AVOID COLLIDING WITH THEM BUT SPUN AROUND HITTING CONCRETE WALL, NETHER AIR BAGS DEFLOYED UP IMPACT WITH ESTIMATED SPEED OF SOMPH, PLEASE DESCRIBE DETAILS. MR WAS DRIVING, WHEN ANOTHER VEHICLE REAR ENDED VEHICLE IN FRONT OF IT. BLAZER AVOID HITTING VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES, VEHICLE HIT MEDIAN MALL WITH FRONT OF VEHICLE. DON IMPACT, THE ASSES SALED TO DEPLOY. MR THE VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES, VEHICLE HIT MEDIAN MALL WITH FRONT OF VEHICLE. DURON IMPACT, THE MASS FAILED TO DEPLOY. MR THE VEHICLE WAS INVOLVED IN A FRONTAL COLUSION WITH A DEER WHILE DRIVING 60 MPH AND NOVOLVED IN HEAD ON COLUSION, BOTH GOING APPROXIMATELY 30 MPH, NEITHER FRONT AIR BAG DEFLOYED. SEVERE FACIAL INJURIES FOR ONE AND CONCUSSION FOR PASSENGER RESULTED. THE ALBERT SHOP OF THE AIR AIR AGS OF DEPLOYED. THE DERIVER CHEST. THIS SHOULD NEED TO THE AIR AIR AGS DID NOT DEPLOY. THIS CAUSED INJURY TO THE DRIVER CHEST. THIS SHOULD NEED TO THE AIR AIR AGS ON THE AIR AIR AGS OF DID NOT DEPLOY DEPLOY WHEN YOU HIT HEAD ON A ORD AND SOLL SHOULD NOT BE ALLOWED. "A WHILE DRIVING SI MPH, AND THE AD ON A ORD AND SOLL SHOULD NOT BE ALLOWED." "A WHILE DRIVING SI MPH, AND THE VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SHIN AROUND AND SLAM INTO AND FOR THE AIR BAGS DEPLOYED. "AK WHILE DRIVING SI MPH, AND THE VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SHIN AROUND AND SLAM INTO AND ROLL SHOULD NOT BE ALLOWED." "A WHILE DRIVING SI MPH, AND THE VEHICLE HIT CONSUMER'S VEHICLE OT HE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SHIN AROUND AND SLAM INTO AND ROLL BRADE OF THE AIR BAGS SEPLOYED." "A WHILE DRIVING SI MPH, THE VEHICLE HIT CONSUMER'S VEHICLE OTHER DETAILS." JB OTHER CONTACT SHAP	874736	CHEVROLET	BLAZER	1999	2000-10-20	SEAT BELT RESTRAINT AT THE TIME, BUT FRONTAL AIR BAGS DIDN'T DEPLOY. DEALER CLOSED THE CASE AT ONE POINT & REOPENED IT ONCE. CONSUMER CONTACTED THEM A SECOND TIME.*AK
OCCURED IN FRONT OF THEM. THE TRUCK DID AVOID COLLIDING WITH THEM BUT SPUN ARQUAD HITTING CONCRETE WALL. NETHER AIR BAGS DEPLOYED UP IMPACT WITH ESTIMATED SPEED OF 55 MPH. PLEASE DESCRIBE DETAILS. MR WAS DRIVING, WHEN ANOTHER VEHICLE REAR ENDED VEHICLE IN FRONT OF IT. BLAZER AVOID HITTING VEHICLE ON WET ROAD & SPUN ARQUAD AFTER APPLYING BRAKES. VEHICLE HIT MEDIAN WALL WITH FRONT OF VEHICLE. UPON IMPACT, HER ABRASS FAILED TO DEPLOY. MR 10017194 CHEVROLET BLAZER 1999 2003-04-18 NONE OF THE NETHER AIR BAGS DEPLOYED. THE DEALER WAS INVOICED ON A FRONTAL COLLISION WITH DEER WHILE DRIVING 60 MPH AND NONE OF THE INETITIES AIR BAGS FAILED. "NILM INVOICED IN HEAD ON COLLISION, BOTH GOING APPROXIMATELY 30 MPH, NETHER REFORM TAIR BAG DEPLOYED. THE DEALER WAS NOTHERD." NILM INVOICED IN HEAD ON COLLISION, BOTH GOING APPROXIMATELY 30 MPH, NETHER REFORM TAIR BAG DEPLOYED. THE DEALER WAS NOTHERD. "NILM INVOICED IN HEAD ON COLLISION, BOTH GOING APPROXIMATELY 30 MPH, NETHER REFORM TAIR BAG DEPLOYED. THE DEALER WAS NOTHERD." NILM INVOICED TO BE FIXED ASAP BY GM. INVIL. NEVER PURCHASE A CHEVY AGAIN. AIRBAGS THAT DO NOT DEPLOY WHEN YOU HIT HEAD ON AND ROLL SHOULD NOT BE ALLOWED. "LA WHILE DRIVING ON INVOICED TO BE FIXED ASAP BY GM. INVIL. NEVER PURCHASE A CHEVY AGAIN. AIRBAGS THAT DO NOT DEPLOY WHEN YOU HIT HEAD ON AND ROLL SHOULD NOT BE ALLOWED. "LA WHILE DRIVING ON ICY ROAD AT SO TO SS MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBAGS DEPLOYED. "ALK WHILE DRIVING ON ICY ROAD AT SO TO SS MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBAGS DEPLOYED." AIR AIRBAGS AND LANDED IN A DITCH. UPON IMPACT, MORE ON AND ROLL SHOULD NOT BE ALLOWED. "LA WHILE DRIVING ON ICY ROAD AT SO TO SS MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBAGS DEPLOYED." AIR AIRBAGS SA PROCESS. "AND LANDED IN A DITCH. UPON IMPACT, MORE OF THE AIRBAGS DEPLOYED." AND AIRBAGS AIRBA	8004945	CHEVROLET	BLAZER	1999	2002-02-28	VEHICLE. DRIVER'S SIDE SEATBELT DIDN'T HOLD, AND AIRBAGS DIDN'T DEPLOY.*AK
WAS DRIVING, WHEN ANOTHER VEHICLE REAR ENDED VEHICLE IN FRONT OF IT. BLAZER AVOID HITTING VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES. VEHICLE HIT MEDIAN WALL WITH FRONT OF VEHICLE. UPON IMPACT, THE AIR BAGS FAILED TO DEPLOY. MR 10017194 CHEVROLET BLAZER 1999 2003-04-18 NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE DELAKE WAS NOTHING 60 MPH AND NONE OF THE NETTHER AIR BAGS DEPLOYED. THE AIR BAGS DEPLOY. THE AIR BAGS DEPLOYED FURTHER DEPLAILS. THE AIR BAGS DEPL	8020401	CHEVROLET	BLAZER	1999		OCCURED IN FRONT OF THEM. THE TRUCK DID AVOID COLLIDING WITH THEM BUT SPUN AROUND HITTING CONCRETE WALL. NEITHER AIR BAGS DEPLOYED UP IMPACT WITH ESTIMATED SPEED OF
10017194 CHEVROLET BLAZER 1999 2003-04-18 NONE OF THE NEITHER AIR BAGS DEPLOYED. THE DEALER WAS NOTHED. *NLM 10021489 CHEVROLET BLAZER 1999 2003-06-10 *IB 10021489 CHEVROLET BLAZER 1999 2003-06-10 *IB 1003-06-10 *IB 1003-06-10 *IB 1003-06-10 *IB 1004-06-10 *IB 1005-06-10 *IB 1006-06-10 *IB 10	8021177	CHEVROLET	BLAZER	1999		HITTING VEHICLE ON WET ROAD & SPUN AROUND AFTER APPLYING BRAKES. VEHICLE HIT MEDIAN
INVOLVED IN HEAD ON COLLISION, BOTH GOING APPROXIMATELY 30 MPH, NEITHER FRONT AIR BAG DEPLOYED. SEVERE FACIAL INJURIES FOR ONE AND CONCUSSION FOR PASSENGER RESULTED. 10021489 CHEVROLET BLAZER 1999 2003-06-10 "IB THE AIRBAGS DID NOT DEPLOY. THIS CAUSED INJURY TO THE DRIVER CHEST. THIS SHOULD NEED TO BE FIXED ASAP BY GM. I. WILL NEVER PURCHASE A CHEVY AGAIN. AIRBAGS THAT DO NOT DEPLOY WHEN YOU HIT HEAD ON AND ROLL SHOULD NOT BE ALLOWED. "LA WHILE DRIVING ON ICY ROAD AT SO TO 55 MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBOGS CHEVROLET BLAZER 1999 2003-12-15 AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN A DITCH. UPON IMPACT, NOTE OF THE AIR BAGS DEPLOYED. "AK AIRBORNE AND LANDED IN AI						· ·
BAG DEPLOYED. SEVERE FACIAL INJURIES FOR ONE AND CONCUSSION FOR PASSENGER RESULTED. *18 CHEVROLET BLAZER 1999 2003-06-10 THE AIRBAGS DID NOT DEPLOY. THIS CAUSED INJURY TO THE DRIVER CHEST. THIS SHOULD NEED TO BE FIXED ASAP BY GM. I WILL NEVER PURCHASE A CHEVY AGAIN. AIRBAGS THAT DO NOT DEPLOY WHEN YOU HIT HEAD ON AND ROLL SHOULD NOT BE ALLOWED. *LA WHILE DRIVING ON ICY ROAD AT 50 TO 55 MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBAGS SHOE TO THE AIRBAGS NEVER WENT OFF IN A FRONT END COLLISION. WHILE DRIVING 35 MPH, ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH HE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO WED TO THE DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TO WED TO THE DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TOWED TO THE DEPLOY BY THE VEHICLE IN FRONT OF HERS. THE AIR BAGS FAILED TO DEPLOY, THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THIS TIME. PLEASE PROVIDE PURTHER DETAILS. *18 DT*: THE CONTACT STATED THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. *19/04/05 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THE MAINDFACTURER WAS CONTACTED. *08/04/05 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THE MAINDFACTURER WAS CONTACTED. *08/04/05 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICCCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. ***********************************	10017194	CHEVROLET	BLAZER	1999	2003-04-18	
BE FIXED ASAP BY GM. I WILL NEVER PURCHASE A CHEVY AGAIN. AIRBAGS THAT DO NOT DEPLOY WHEN YOU HIT HEAD ON AND ROLL SHOULD NOT BE ALLOWED. *LA WHILE DRIVING ON ICY ROAD AT 50 TO 55 MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBORNE AND LANDED IN A DITCH. JUPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK 10053865 CHEVROLET BLAZER 1999 2003-12-15 AIRBORNE AND LANDED IN A DITCH. JUPON IMPACT, NONE OF THE AIR BAGS DEPLOYED. *AK WHILE DRIVING 35 MPH, ANDTHE YEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. THE ROAD AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GRANGE FOR INSPECTION. THE BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GRANGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTED IN INJURIES OF THE CONTACT!S LEFT KNEE, LEBOW AND HEAD. A POLICE REPORT WAS FILED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS DOTERMINED BY THE INSURER TO BE TOTALED. THE AMAINCATURER WAS CONTACTED. OS/04/06 CHEVY DRIVE HIT CAR IN HER LANE FIRST, THEN RICCCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. **TI** 1099 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MAJENDIES	10021489	CHEVROLET	BLAZER	1999	2003-06-10	BAG DEPLOYED. SEVERE FACIAL INJURIES FOR ONE AND CONCUSSION FOR PASSENGER RESULTED.
CHEVROLET BLAZER 1999 2003-12-06 WHEN YOU HIT HEAD ON AND ROLL SHOULD NOT BE ALLOWED. *LA WHILE DRIVING ON ICY ROAD AT 50 TO 55 MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBORS SEVER WENT OFF IN A FRONT END COLLISION. WHILE DRIVING 35 MPH, ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE FOR SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TO WED TO THE DEALERSHIP FOR INSPECTION. *AK WHILE DRIVING 45 MPH, THE VEHICLE COLLIDED WITH THE VEHICLE IN FRONT OF HERS. THE AIR BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *BIB DIT*: THE CONTACT'S STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KNEE, ELBOW AND HEAD. A POLICE REPORT WAS FILED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. *TT 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS DO DRIVE ON DEPLOY. *BB						THE AIRBAGS DID NOT DEPLOY. THIS CAUSED INJURY TO THE DRIVER CHEST. THIS SHOULD NEED TO
WHILE DRIVING ON ICY ROAD AT 50 TO 55 MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT AIRBORNE AND LANDED IN A DITCH. UPON IMPACT,NONE OF THE AIR BAGS DEPLOYED. *AK 10063865 CHEVROLET BLAZER 1999 1999-03-23 THE AIRBAGS NEVER WENT OFF IN A FRONT END COLLISION. WHILE DRIVING 35 MPH, ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TOWED TO THE DEALERSHIP FOR INSPECTION. *AK WHILE DRIVING 45 MPH, THE VEHICLE COLLIDED WITH THE VEHICLE IN FRONT OF HERS. THE AIR BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETAININED AT THIS TIME. PLEASE PROVIDE PUTHTER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KNEE, ELBOW AND HEAD. A POLICE REPORT WAS FILED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS DOVED TO THE JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICCOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. *TI 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURIED AND VEHICLE WAS TOTALED. CONSUMER MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS WORKED PROPERLY. *KB NO DEPLOYMENT OF DRIVER AND PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED	10040240	CHEVBOLET	DLAZED	1000	2002 12 06	
10050546 CHEVROLET BLAZER 1999 2003-12-15 AIRBORNE AND LANDED IN A DITCH . UPON IMPACT,NONE OF THE AIR BAGS DEPLOYED. *AK 10063865 CHEVROLET BLAZER 1999 1999-03-23 THE AIRBAGS NEVER WENT OFF IN A FRONT END COLLISION. WHILE DRIVING 35 MPH,ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TOWED TO THE DEALERSHIP FOR INSPECTION. *AK WHILE DRIVING 45 MPH, THE VEHICLE COLLIDED WITH THE VEHICLE IN FRONT OF HERS. THE AIR BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE DEPLOY. THIS CAUSED THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KINE, ELBOW AND HEAD. A POLICE REPORT WAS FLIED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS MOVED TO THE JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. **TI 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MARBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER NABAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER NABAGS DID NOT DEPLOY HAD PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED	10049340	CHEVROLET	BLAZEN	1999	2003-12-00	WHEN TOO HIT HEAD ON AND ROLL SHOOLD NOT BE ALLOWED. LA
THE AIRBAGS NEVER WENT OFF IN A FRONT END COLLISION. WHILE DRIVING 35 MPH, ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TOWED TO THE DEALERSHIP FOR INSPECTION. *AK WHILE DRIVING 45 MPH, THE VEHICLE COLLIDED WITH THE VEHICLE IN FRONT OF HERS. THE AIR BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KNEE, ELBOW AND HEAD. A POLICE REPORT WAS FILED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS MOVED TO THE JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. 10161658 CHEVROLET BLAZER 1999 2006-06-03 *TI 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS WORKED PROPERLY. *KB NO DEPLOYMENT OF DRIVER AND PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED						WHILE DRIVING ON ICY ROAD AT 50 TO 55 MPH DRIVER LOST CONTROL OF VEHICLE. IT WENT
WHILE DRIVING 35 MPH, ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK. CONSUMER HAD THE VEHICLE TOWED TO THE DEALERSHIP FOR INSPECTION. *AK WHILE DRIVING 45 MPH, THE VEHICLE COLLIDED WITH THE VEHICLE IN FRONT OF HERS. THE AIR BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KNEE, ELBOW AND HEAD. A POLICE REPORT WAS FILED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS MOVED TO THE JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. 10161658 CHEVROLET BLAZER 1999 2006-06-03 **TT 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS WORKED PROPERLY, *KB NO DEPLOYMENT OF DRIVER AND PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED	10050546					·
BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KNEE, ELBOW AND HEAD. A POLICE REPORT WAS FILED AND PICTURES WERE TAKEN AFTER THE VEHICLE WAS MOVED TO THE JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. *TT 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS WORKED PROPERLY. *KB NO DEPLOYMENT OF DRIVER AND PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED	10087245					WHILE DRIVING 35 MPH,ANOTHER VEHICLE HIT CONSUMER'S VEHICLE ON THE PASSENGER SIDE. THIS CAUSED THE VEHICLE TO SPIN AROUND AND SLAM INTO ANOTHER VEHICLE HEAD ON. UPON IMPACT, BOTH FRONTAL AIR BAGS DID NOT DEPLOY, NOR DID THE DRIVERS SEAT BELT LOCK.
JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. **TT 1999 CHEVY BLAZER AIRBAGS FAILED TO DEPLOY IN AN ACCIDENT. CONSUMER STATES THAT THE AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER WAS INJURIES IF THE AIRBAGS WORKED PROPERLY. *KB NO DEPLOYMENT OF DRIVER AND PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED	10099164	CHEVROLET	BLAZER	1999	2004-10-21	BAGS FAILED TO DEPLOY. THIS CAUSED THE DRIVER TO SUSTAINED MAJOR INJURIES AND WAS TRANSPORTED TO THE HOSPITAL. THE VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. THE CAUSE HAS NOT BEEN DETERMINED AT THIS TIME. PLEASE PROVIDE FURTHER DETAILS. *JB DT*: THE CONTACT STATED THE VEHICLE IMPACTED A TREE, HEAD ON. THE FRONTAL AIRBAGS FAILED TO DEPLOY, RESULTING IN INJURIES OF THE CONTACT'S LEFT KNEE, ELBOW AND HEAD. A
AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER 10223949 CHEVROLET BLAZER 1999 2008-02-09 MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS WORKED PROPERLY. *KB NO DEPLOYMENT OF DRIVER AND PASSENGER SIDE AIR BAGS DURING COLLISION WITH FIXED	10161658	CHEVROLET	BLAZER	1999	2006-06-03	JUNKYARD. NO REPAIRS WERE MADE BECAUSE THE VEHICLE WAS DETERMINED BY THE INSURER TO BE TOTALED. THE MANUFACTURER WAS CONTACTED. 08/04/06 CHEVY DRIVER HIT A CAR IN HER LANE FIRST, THEN RICOCHETED HEAD ON INTO A TREE. NEITHER TIME DID AIRBAGS DEPLOY. *TT
	10223949	CHEVROLET	BLAZER	1999	2008-02-09	AIRBAGS DID NOT DEPLOY. CONSUMER WAS INJURED AND VEHICLE WAS TOTALED. CONSUMER MIGHT NOT HAVE THOSE INJURIES IF THE AIRBAGS WORKED PROPERLY. *KB
	548902	CHEVROLET	SILVERADO	1999	1999-08-13	OBJECT (TREE) CAUSED INJURY TO DRIVE. NLM

					THE 1999 CHEVROLET TRUCK EX SILV ANTILOCK BREAKS HAVE BEEN FAILING AT RANDOM TIMES SINCE APRIL 1 1999. FIRST AT SLOW SPEEDS AND THEN AT HIGH SPEEDS RANDOMLY. ON 720-1999 MY SPEED WAS 60 MI HR AND THE BRAKES FAILED WHEN A DEER CROSSED THE STATE HIGHWAY BETWEEN GRAHAM TX AND BRECKENRIDGE TX. THE BRAKES DELAYED AND I HIT THE DEER DEAD
709384	CHEVROLET	SILVERADO	1999	1999-07-20	CENTER OF MY BUMPER AND GRILL! THE AIR BAGS DIDNOT INFLATE EVER!
741598	CHEVROLET	SILVERADO	1999	2000-01-13	MY AIR BAG DID NOT ACTIVATE AND IN A DIRECT FRONT END COLLISION. THE SUN SETTING BLINDED ME AND I HIT DIRECTLY THE REAR OF THE CAR IN FRONT OF ME AND IT'S AIRBAG DEPLOYED AND THE CHAIN REACTION OF THE TWO CARS IN FRONT OF THE CAR I HIT AIRBAGS DEPLOWED. GM SAID MY AIRBAG WAS NOT DEFECTIVE AND I ASKED TO HAVE IT CHECKED TWO TIMES. IT SHOULD HAVE DEPLOYED AND IT DID NOT. I WAS NOT WEARING A SEAT BELT AND I SUFFERED HEAD INJURIES. I SOLD TRUCK BECAUSE I DID NOT WANT TO DIE NEXT FAILURE.
					DRIVER HIT A STOPPED VEHICLE ON THE INTERSTATE AT APPROXIMATELY 60 MPH. OCCUPANT OF
746679	CHEVROLET	SILVERADO	1999	2001-04-30	STALLED VEHICLE WAS KILLED AND OUR AIRBAGS DID NOT DEPLOY. WE FELT THAT IT SHOULD HAVE DEPLOYED AND GMC IS ARGUING THAT IT SHOULD NOT HAVE. ANY INFORMATION ABOUT AIRBAGS WOULD BE APPRECIATED. *AK
762651	CHEVROLET	SILVERADO	1999	2002-05-21	DRIVER & PASSENGER AIR BAGS DIDN'T DEPLOY IN A 65 MPH COMBINED SPEED , HEAD ON CRASH. *AK
842094	CHEVROLET		1999		VEHICLE WAS INVOLVED IN A FULL FRONTAL COLLISION AT 40 MPH, AND NEITHER DRIVER'S SIDE NOR PASSENGER'S SIDE AIRBAGS DEPLOYED. CHEVROLET AND DEALER REFUSED TO GIVE ANY EXPLANATION WHY AIR BAGS DID NOT DEPLOY. *AK
844072	CHEVROLET	SILVERADO	1999	1999-07-21	WHILE DRIVING 40 MPH , LOST CONTROL. VEHICLE WENT INTO A DITCH. UPON IMPACT, DRIVER'S AND PASSENGER'S AIRBAGS DID NOT DEPLOY WHICH DID NOT PROTECT THE OCCUPANT IN THIS CRASH. PLEASE PROVIDE FURTHER INFORMATION AND VIN#. *AK
851420	CHEVROLET	SILVERADO	1999	1999-08-13	CONSUMER WAS DRIVING AND A DEER JUMPED IN FRONT OF HIS VEHICLE. CONSUMER SWERVED TO THE RIGHT AND HE WENT INTO A TREE. AIRBAGS DIDN'T DEPLOY AT ALL, CONSUMER SUSTAINED HEAD INJURIES. *AK
854784	CHEVROLET	SILVERADO	1999	1999-10-08	WHILE DRIVING 60 MPH HAD A FRONTAL IMPACT, AND DRIVER'S AND PASSENGER'S AIR BAGS DID NOT DEPLOY WHICH DID NOT PROTECT THE OCCUPANT IN THIS CRASH. *AK *ML
858532	CHEVROLET	SILVERADO	1999	2000-03-01	CONSUMER'S DAUGHTER WAS IN A CAR CRASH. PASSENGER'S SEAT BELT DIDN'T HOLD. THE PASSENGER AND DRIVER WERE EJECTED FROM THE VEHICLE. ALSO, AIRBAGS DIDN'T DEPLOY. *AK
858811	CHEVROLET	SILVERADO	1999	2000-02-18	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 35 MPH. VEHICLE WAS TOTALLED, AND THE AIRBAGS DID NOT DEPLOY, RESULTING IN MINOR INJURIES. MANUFACTURER HAS INSPECTED THE VEHICLE, AND CLAIMS THAT THE AIR BAGS WERE NOT SUPPOSED TO DEPLOY IN THIS SORT OF ACCIDENT. *AK
859858	CHEVROLET	SILVERADO	1999	1999-04-03	WHILE TRAVELING ON A WET ROAD AT HIGHWAY SPEED OF 60 MPH VEHICLE HYDROPLANED, SPUN INTO A DITCH, AND COLLIDED INTO A TREE WITH BOTH SIDES AND FRONT OF VEHICLE. UPON IMPACT, AIR BAGS FAILED TO DEPLOY. MFR. NOTIFIED. *AK
866622	CHEVROLET	SILVERADO	1999	2000-07-27	CONSUMER WAS TRAVELING ABOUT 65 ON THE INTERSTATE AND FELL A SLEEP. HE HIT AN ENBANKMENT, AND AIRBAGS DIDN'T GO OFF, THERE WERE 2 INJURIES. *AK
871182	CHEVROLET	SILVERADO	1999	2000-04-29	WHILE DRIVING ABOUT 50 MPH AND WHEN EXITING A FREEWAY RAM STEPPED ON BRAKE PEDAL, BUT VEHICLE DID NOT STOP AND LOST CONTRO/ SPAN AND STRUCK A ROAD SIGN FRONT FIRST. UPON IMPACT, NONE OF THE AIR BAGS DEPLOYED.*AK
875702	CHEVROLET	SILVERADO	1999	2000-11-08	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 55-60MPH. UPON IMPACT, AIRBAGS DID NOT DEPLOY, RESULTING IN MINOR INJURIES. VEHICLE WAS TOTALLED. *AK
877481	CHEVROLET	SILVERADO	1999	2000-12-16	FRONT CRASH AT 50 MPH, VEHICLE TOTALLED, DRIVER INJURED WHEN SHE HIT STEERING WHEEL, AND AIRBAG DID NOT DEPLOY. *AK
.,,,,,,,	S. ETHOLET		2333		WHILE DRIVING 70 MPH CONSUMER HAD A FRONT CRASH. BUMPER BROKE IN TWO, AND FRONT END WAS PUSHED BACK ABOUT 4-6 INCHES. VEHICLE HIT A TREE. UPON IMPACT, AIRBAGS DID
886863	CHEVROLET	SILVERADO	1999	2001-04-21	NOT DEPLOY. *AK
891163	CHEVROLET	SILVERADO	1999	2001-06-23	WHILE TRAVELING 35-40 MPH ON A BRIDGE WITHOUT PRIOR WARNING BACKEND OF VEHICLE BEGAN TO FISHTAIL, CAUSING VEHICLE TO LOSE CONTROL. CONSUMER RELEASED FOOT FROM GAS TO CORRECT VEHICLE STEERING. VEHICLE WAS UNRESPONSIVE, RESULTING IN A FRONTAL COLLISON WITH A JERSEY WALL. UPON IMPACT, PASSENGER AIRBAGS FAILED TO DEPLOY, ENGINE WAS PUSHED SIX INCHES UNDER THE DASH. CONSUMER HAS YET TO CONTACT DEALER. *AK DRIVER WAS INJURED IN ACCIDENT. *SLC
					1999 CHEVROLET SILVERADO FAULTY DRIVER RESTRAINT SYSTEM. *MR THE VEHICLE WAS INVOLVED IN AN ACCIDENT. THE SAFETY BELT FAILED TO THE RESTRAIN THE DRIVER, AND THE AIR BAG DID NOT DEPLOY. *TS. THE DRIVER RECEIVED SERIOUS HEAD INJURIES. (LAWYER JOHN KELLY
10026451	CHEVROLET	SILVERADO	1999	2003-05-06	ON BEHALF OF CLIENT, JAMES SCOTT). *JB
					WHILE DRIVING APPROXIMATELY 20 MPH DRIVER LOST CONTROL OF THE VEHICLE AND IT CRASHED INTO A BRICK WALL. UPON IMPACT, BOTH FRONTAL AIR BAGS FAILED TO DEPLOY. DRIVER SUSTAINED MAJOR INJURIES, AND WAS TRANSPORTED TO THE HOSPITAL BY A HELICOPTER. THE
10113304	CHEVROLET	SILVERADO	1999	2005-02-03	VEHICLE WAS TOWED TO A GARAGE FOR INSPECTION. *AK

CHEVROLET SILVERADO 1999 2005-11-01 PREDICE WAS INCLUED IN A CROSS, IT HIT A GUARD RALL THIS WAS A FRONTAL IMPACT, AND THE DRIVER'S SOE ARE ARE DID TO PETOR PCH. THE VEHICLE WAS TOTALED.						DT THE CONTACT CTATED ANNUE TRAVELING AT CE ANDITHE FELL ACTIED AT THE MILEST. THE
10144603 CHEVROLET SUBURBAN 1999 2005-11-01. THE DRIVER'S SIDE AR BAG DID NOT DEPLOY. THE VEHICLE WAS TOTALED. ARRADS FLABED TO DEPLOY OF ROPMAN INTERSITES SPEED MARCH COLLEGE SOULD LOCK WOULD LOCK AUTOMATICALLY, WITHOUT ANY ADULT INTER CARL. HOWEVER, THERE WERE CHILDREN IN CAS ASSIST BACK SEEP SAMES TO PKEYS IN HAND AT LATINGS. CHEVROLET SUBURBAN 1999 2000-115 AL TIMES. CHEVROLET SUBURBAN 1999 2001-10-08 CHEVROLE SUBURBAN HEAD ON INTO THE CONCRETE MEDIAN, THE VEHICLE SPUN SEED DEPENDENT. AND SHAPE HEAD HE VEHICLE SPUN SEED DEPENDENT HEAD AND ADMINISTRATIVE SHAPE WERE CHILDREN IN CAS ASSIST HE FRAME BERT HOWAND SHAPE. FRAME SHAPE AND ADMINISTRATIVE FRAME SHAPE AND ADMINI						DT: THE CONTACT STATED WHILE TRAVELING AT 65 MPH HE FELL ASLEEP AT THE WHEEL. THE
ARRAGS FAILED TO DEPLOY ON FRONTAL INTERSTATE SPEED MACH, EDALER DISCLAMED SAROULNESS. DORD LOCK AUTOMACIALLY, WITHOUT ANY ADULT IN THE CAR. 7731578 CHEVROLET SUBURBAN 1999 2000-01-13 ALT TIMES. OMPHIC RIOSS WIND BLEW THE SUBURBAN HEAD ON INTO THE CONCRETE MEDIAN. THE VEHICLE SPUN ASD CORREST, WHICH THIS TO THE DITCH, THE FRONT END HIT AGAIN THE VEHICLE WITH UP THE OTHER SIDE OF THE EMBARMINENT AND STOPPED IN A PILLD, ENTIRE FRONTE NO. THE PRANK ENT HAT THE VEHICLE WITH UP THE OTHER SIDE OF THE EMBARMINENT AND STOPPED IN A PILLD, ENTIRE FRONTE NO. THE PRANK ENT AND THE PRANK	10144603	CHEVROLET	SILVERADO	1999	2005-11-01	
SERIOLISMESS, DIORICOS WOULD LOCK AUTOMATICALLY, WITHOUT ANY ADULT IN THE CARL. HOWEVER, THERE WERE CHURKEN IN ACK AS TEST BACK KEEP SARS SET OF KEYS IN HAND A HOWEVER, THERE WERE CHURKEN IN ACK NET SHARE SARS SET OF KEYS IN HAND A HOWEVER, THERE WERE CHURKEN IN ACK AND THE CARLS. SOUND SOURCES, WENT INTO THE DITCH, THE FRONT END BIT ACAN THE VEHICLE WENT UP THE OTHERS BUG IT THE MEMBRANEN TAND STORPED IN A FIELD. BEHTE HONG IT BOD OF THE FRAME NOT REPARABLE, THE BEAR PORTION OF THE FRAME BENT INTO A DIAMOND SHAPE. FRONT COSSISSMERISE BENT HAND ROSING WOULD UPWARDS AT A DIAGNOST SHAPE. FRONT COSSISSMERISE BENT HAND ROSING WOULD UPWARDS AT A DIAGNOST SHAPE. FRONT COSSISSMERISE BENT HAND ROSING WOULD UPWARDS AT A DIAGNOST SHAPE. FRONT COSSISSMERISE BENT HAND SHAPE S	10144003	CHEVILOLET	SILVEIUES	1333	2003 11 01	
ONEVROLET SUBURBAN 1999 2000-01-15 ALT TIMES. ONEVROLET SUBURBAN 1999 2000-01-15 ALT TIMES. ONEVROLET SUBURBAN 1999 2001-10-08 ROWERLOW, THE ENDIRED HEAD OF THE END						
90 MPPI CROSS WIND BLEVT THE SUBURBAN HEAD ON INTO THE CONCRETE MEDIAN. THE VEHICLE WENT UP THE OTHER SIDE OF THE MEDIAL THE ROOT TEN HIT AT EVEHICLE WENT UP THE OTHER SIDE OF THE FRAME RESTORED AND FITHE FRAME PROFITED HEAD AND FITHE FRAME PROFITED HEAD ADMINISTRATION OF THE FRAME RESTORED OF THE FRAME RESTORED OF THE FRAME RESTORED THE FRAME PROFITED OF THE FRAME RESTORED OF THE FRAME RESTORED THE FRAME PROFITED OF THE FRAME RESTORED OF THE FRAME RESTORED OF THE FRAME RESTORED OF THE FRAME RESTORED OF ADMINISTRATION OF THE FRAME RESTORED OF ADMINISTRATION OF THE FRAME RESTORED OF THE F						· · · · · · · · · · · · · · · · · · ·
SPUN 360 DEGREES, WENT INTO THE DITCH, THE FRONT TEND OF THE FRAME SPONT THE OF THE THE PRESIDE OF THE MEMBANIMENT AND SPOPED IN A PRICE PRONT END OF THE FRAME SPONT THE PRONT THE OF THE FRAME SPONT IN TO A DIAMOND SHAPE, FRONT CROSS-MEMBER BRAT AND ENGINE MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AT A 10 DEGREE ANGIEL AND REASON MOVED UNWARDS AND REASON MOVED AND REASON MOVED UNWARDS AND REASON MOVED AND REASON MO	731578	CHEVROLET	SUBURBAN	1999	2000-01-15	ALL TIMES.
THE OTHER SIDE OF THE EMBANNOMENT AND STOPPED IN A PERD. NYTHER FROM TE NO OF THE FAME BY ON DIAMOND SHAPE, FROM TO REPARABLE, THE REAR PORTION OF THE RAME BY ON DIAMOND SHAPE, FROM TO REPARABLE, THE REAR PORTION OF THE RAME BY ON DIAMOND SHAPE, FROM TO DEPLOY, AUST THE REAR PORTION OF THE RAME BY ON DIAMOND SHAPE, FROM TO DEPLOY, AUST THE REAR PORTION OF THE RAME BY ON DIAMOND SHAPE, FROM TO DEPLOY, AUST THE REAR PORTION OF KEX INJURY/SHOW AND THE REAR PORTION OF KEX INJURY/SHOW AND WAS STRUCK HEAD ON BY AND THE REAR PORTION OF KEX INJURY/SHOW AND WAS STRUCK HEAD ON BY AND THE REAR PORTION OF KEX INJURY SHOW AND WAS STRUCK HEAD ON BY AND THE REAR PORTION OF						60 MPH CROSS WIND BLEW THE SUBURBAN HEAD ON INTO THE CONCRETE MEDIAN. THE VEHICLE
FRAME FOR TREPARABLE, THE ERAR PORTION OF THE FRAME SENT INTO A DIAMOND SHAPE, BRONT CROSSAMMERS BEAT AND ROSINES WORD FLOWARDS AT A DIAMOND SHAPE, BRONT CROSSAMMERS BEAT AND ROSINES WORD FLOWARDS AT A DIAMOND SHAPE, BRONT CROSSAMMERS BEAT AND ROSINES WORD FLOWARDS AT A DIAMOND SHAPE, BRONT CROSSAMMERS BEAT AND ROSINES WORD FLOWARDS AND ACCIDENTLY REAR ENDED AND THER VEHICLE, ARR BASS DID NOT DEPLOY, CAUSING RECK HURKY/SHOULDER HURKY AND BACK HURWY, VEHICLE, ARR BASS DID NOT DEPLOY, CAUSING NECK HURKY/SHOULDER HURKY AND BACK HURWY, VEHICLE HUR WAS STRUCK HEAD-ON BY AND THE VEHICLE WORD SHAPE WAS TRAVELING ABOUT 45M HIGH HIGHWAY AND WAS STRUCK HEAD-ON BY AND THE VEHICLE HUR FROM THE WINCE WE WAS TRAVELING ABOUT 45M HIGH HIGHWAY AND WAS STRUCK HEAD-ON BY AND THE VEHICLE HUR FROM HIGHWAY AND ANOTHER VEHICLE HUR ARRAGE DIDN'T DEPLOY. CONSUMER WAS TRAVELING ABOUT 45M HIGH HIGHWAY AND ANOTHER VEHICLE WEERED INTO HER LANG, HITTING HER HEAD-ON, AND PUSHING VEHICLE HIT OANDTHER LANG. VEHICLE HIT TELEPHORP POLE, AND DUAL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELING ABOUT 45M HIGH HIGHWAY AND ANOTHER VEHICLE WEERED INTO HER LANG. HUR HIGHWAY AND ANOTHER VEHICLE WEERED INTO HER LANG. HUR HIGHWAY AND PUSHING WEIGHT HIGHWAY AND ANOTHER VEHICLE WEERED INTO HER LANG. HUR HIGHWAY AND ANOTHER VEHICLE WEERED INTO HER LANG. HUR HIGHWAY AND ANOTHER VEHICLE WEERED INTO HER LANG. HUR HIGHWAY AND WAS STRUCK WEILLE HIT TELEPHORP POLL, AND DUAL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. AND POLL ARRAGES DIDN'T DEPLOY. AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELED BY AND POLL ARRAGES DIDN'T DEPLOY. CONSUMER WAS TRAVELLED BY AND POLL ARRAGES DIDN'T DE						SPUN 360 DEGREES, WENT INTO THE DITCH, THE FRONT END HIT AGAIN THE VEHICLE WENT UP
FRONT CROSS/MEMBER BENT AND ENGINE MOVED UPWARDS AT A 10 DEGREE ANGLE. AIR BAGS 573287 CHEVROLET SUBURBAN 1999 1998-10-09 CONSUMER WAS TRAVELING ABOUT 30-35 MPH AND ACCIDENTLY BEAR ENDED ANOTHER VEHICLE. AIR BAGS DID NOT DEPLOY. CAUNDS NEXT KINDUNG PICK INJURY, SHOULDER INJURY AND EXCIP RILLY AND ACKID PILOTY. PAKE 1995 1998-10-09 CONSUMER WAS TRAVELING ABOUT 30-35 MPH AND ACCIDENTLY BEAR ENDED ANOTHER VEHICLE. AIR BAGS DID NOT DEPLOY. CAUNDS NEXT KINDUNG FILOTY. DPOIN IMPACT, FRONT DUAL AIR AND AND AND AND AND AND THE YELLIC VEHICLE WITH DEPLOY. CONSUMER WAS TRAVELING ABOUT 45 MPH ON HIGHWAY AND WAS STRUCK HEAD-ON BY ANOTHER VEHICLE WITH DEPLOY. CONSUMER WAS TRAVELING ABOUT 45 MPH ON HIGHWAY AND ANOTHER YELLIC VEHICLE HIT TELEPHONE POLE, AND DUAL AIRS SIDURED. THE LIBER OF THE AIR AND AND AND THE WHILE VEHICLE HIT TELEPHONE POLE, AND DUAL AIRS SIDURD TO PLOY. CONSUMER WAS INJURIED. CHEVROLET HER PILOTY ON THE LIBER HEAD-ON, AND YELLIGH HEA						THE OTHER SIDE OF THE EMBANKMENT AND STOPPED IN A FIELD. ENTIRE FRONT END OF THE
CHEVROLET SUBURBAN 1999 2001-10-08 FAILED TO DEPLOY, "ANE SUBURBAN 1999 1998-10-09" AN CHEVROLET SUBURBAN 1999 1998-10-09" AN CONSUMER WAS TRAVELUING ABOUT 30-35 MPH AND ACCIDENTLY BEAR ENDED ANOTHER VEHICLE, ARE RAGS DID NOT DEPLOY, CAUSING NECK INJURY/SHOULDER INJURY AND BACK INJURY, "A CONSUMER WAS TRAVELUING ABOUT 45 MPH ON HIGHWAY AND WAS STRUCK HEAD-ON BY ANOTHER VEHICLE WIDE OF STREEP, REPREVY THROUGHE END MIMPACT, FRONT DUAL AIRBAGS DIDN'T DEPLOY, CONSUMER WAS TRAVELUING ABOUT 45 MPH ON HIGHWAY AND ANOTHER VEHICLE WERE DINTO HER LANE, HITTING HER HEAD-ON, AND PUSHING VEHICLE INTO ANOTHER LANE. VEHICLE HIT TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY, CONSUMER WAS INJURED. "AK ON THE LANE, HITTING HER HEAD-ON, AND PUSHING VEHICLE INTO ANOTHER LANE. VEHICLE HITT HER PHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY, CONSUMER WAS INJURED. CHEVROLET HAS BEEN NOTHERD. "AK WEIGHT OF VEHICLE." "AK WAS THAT WEIGHT OF VEHICLE." "AK WEIGHT OF VEHICLE." "AK WAS THAT WEIGHT OF VEHICLE						
CONSUMER WAS TRAVELING ABOUT 30-35 MPH AND ACCIDENTLY REAR ENDED ANOTHER VEHICLE, ARR BASS DID NOT DEPLOY, CAUSING NECK INJURY/SHOULDER INJURY AND BACK INJURY OF VEHICLE WAS DID NOT DEPLOY, CAUSING NECK INJURY/SHOULDER INJURY AND BACK INJURY OF AND ACCIDENTLY ACCIDENTLY AND A						
VEHICLE, ARR BAGS DID NOT DEPLOY, CAUSING NECK INJURY/SHOULDER INJURY AND BACK INJURY. ANOTHER VEHICLE WHO ENTERED RESERVAY THROUGH EITH, FOR TO MAY STRUCK HEAD ON BY ANOTHER VEHICLE WHO ENTERED RESERVAY THROUGH EITH, FOR TO MILE VEHICLE HIT THE PHONE WHO ENTERED RESERVAY THROUGH EITH, FOR TO MILE VEHICLE HIT THE PHONE WHO ENTERED RESERVAY THROUGH EITH WAS STRUCK HEAD ON BY ANOTHER VEHICLE WHO ENTERED RESERVAY THROUGH EITH WAS STRUCK HEAD ON BY ANOTHER VEHICLE WHO ENTERED RESERVAY THROUGH EITH WAS STRUCK HEAD ON BY ANOTHER VEHICLE WHO ENTERED RESERVAY THROUGH EITH WAS STRUCK HEAD ON BY ANOTHER VEHICLE HIT THE PHONE POLE. AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. "AK WAS INJURED." AND STRUCK HEAD ON BY THE LANE, HITTING HER HEAD-ON, AND DUSHING VEHICLE HITD ANOTHER. HEAD ON THE THE LANE, HITTING HER HEAD-ON, AND DUSHING VEHICLE HITD ANOTHER. HEAD EITH THE PHONE POLE. AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED." CHEVROLET HAS BEEN NOTHERD." "AK WAS INJURED." AND STRUCK HEAD THE THE PHONE POLE OF THE WAS INJURED." AND STRUCK HEAD THE THE THE PHONE PHONE PHONE PHONE THE WAS INJURED." CHEVROLET HAS BEEN NOTHERD. "AK WAS INJURED." CHEVROLET AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTHERD PLEASE PROVIDE ADDITIONAL INFORMATION." AK WAS INJURED. THE PROVIDE AND STRUCK HEAD THE PROVIDE STRUCK HEAD THE PROVIDE AND STRUCK HEAD THE PROVIDE STRUCK HEAD THE PROVIDE STRUCK HEAD THERE IS NOTHING WHO HEND HE PROVIDE ADDITIONAL INFORMATION." AK WAS INJURED TO AND STRUCK HEAD THERE IS NOTHING WAS DRIVING A 1999 CHEVROLET AS INJURED. THE PROVIDE STRUCK HEAD THERE IS NOTHING WHO HE AND STRUCK HEAD THERE IS NOTHING WHO HEND HE ADDITIONAL INFORMATION. AND ANY AND STRUCK HEAD THERE IS NOTHING WAS DRIVING A 1999 CHEVROLET SALE WAS INJURED. THE PROVIDE AND STRUCK HEAD THERE IS NOTHING WAS DRIVING A 1999 CHEVROLET SALE WAS INJURED. THE WAS INJURED THE AND THE PROVIDE AND STRUCK HEAD THERE IS NOTHING WAS DRIVING AND STRUCK HEAD THERE IS NOTHING WAS DRIVED AND STRUCK HEAD THE PROVIDE AND STRUCK HEAD THE PROVIDE AND S	/5328/	CHEVROLET	SUBURBAN	1999	2001-10-08	
CHEVROLET SUBURBAN 1999 1998-10-09 *AK ANDTHER VERICLE WHO ENTERED RECEWAY THROUGH EXIT. UPON IMPACT, FRONT DUAL ANDTHER VERICLE WHO ENTERED RECEWAY THROUGH EXIT. UPON IMPACT, FRONT DUAL ANDTHER VERICLE WHO ENTERED RECEWAY THROUGH EXIT. UPON IMPACT, FRONT DUAL ANDTHER VERICLE WHO ENTERED RECEWAY THROUGH EXIT. UPON IMPACT, FRONT DUAL AND THE RESEARCH AND ADUL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE, AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE. AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET THE LEPHON POLE. AND DUAL ARRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET SHE WHILE DRIVING 303-35 MPH VEHICLE HIT A FIRE HYDRANT, THEN A TREE. NETHER ARRAG DEPLOYEE. AND VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, ARRAGS DIDN'T DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION."AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RECHEM THE THE ARRAGS DID NOT DEPLOY. HAVE EXCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RECHEM THE ARRAGS DID NOT DEPLOY. HAVE EXCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RECHEM THE ARRAGS DID NOT DEPLOY. HAVE EXCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RECHEM THE ARRAGS DID NOT DEPLOY. HAVE EXCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RECHEM THE ARRAGS DID NOT DEPLOY. HAVE EXCIDENT ON THE THE C						
CONSUMER WAS TRAVELING ABOUT AS MPIN ON HIGHWAY AND WAS STRUCK HEAD ON BY ANOTHER VEHICLE WHO ENTERED FREWAY THROUGH LIPON IMPACT, I DON IMPACT, FRONT DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. "AK CHORNER WAS TRAVELING ADORDOR TO HIGHWAY AND ANOTHER VEHICLE VERED INTO CHORNER WAS TRAVELING ADORDOR TO HIGHWAY AND ANOTHER VEHICLE CERED INTO CHORNER WAS INJURED." AK CHORNOR WAS ANOTHER VEHICLE HIT TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. "AK WHILE DRIVING SUBJECT AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. "AK WHILE DRIVING SUBJECT AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED." AND WHILE DRIVING SUBJECT AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET SUBURBAN 1999 2001-12-28 DEPLOY. DEALER HAS BEEN NOTHING. DAMAGE TO VEHICLE UNKNOWN AT THIS TIME. IMPACT WAS MINDLE OF HEAD ON AT PROPOMERY AND AIRBAGS DIDN'S AND AIRB	830803	CHEVROLET	SUBURRAN	1000	1008-10-00	
ANOTHER VEHICLE WHO ENTERED REEWAY THROUGH EXIT. UPON IMPACT, FRONT DUAL AND ANOTHER VEHICLE VERED INTO HER VEHICLE VEHI	023003	CHEVROLET	JUBURBAN	1999	1998-10-09	
276094 CHEVROLET SUBURBAN 1999 2000-12-01 AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. "AK CHEVROLET SUBURBAN 1999 2001-12-01 THE LARK, HITTING HER HEAD-ON, AND PUSHING VEHICLE INTO ANOTHER VEHICLE VERRED INTO HER LANK, HITTING HER HEAD-ON, AND PUSHING VEHICLE INTO ANOTHER VEHICLE HIT TELEPHORA POLI, AND DUJA. AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET HAS SEEN HOTHED. "AK WHILE DRIVING 30-35 MPH VEHICLE HIT & FIRE PUPDRAYT, THEN A TREE. NETHER AIRBAG DEPUTED, NO INJURIES. DAMAGE TO VEHICLE UNITABLE WHENCH WAS MIDDLE OF FRONT OF VEHICLE." "AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTHED. "PLASS PROVIDED DEPLOY. AND INJURIS. DAMAGE TO VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTHED. PLASS PROVIDED DEPLOY. BEAUTH HAS BEEN NOTHED. PLASS PROVIDED WITHOUT AND IMPACT, AIR BAGS DID NOT DEPLOY. BEAUTH HAS BEEN NOTHED. PLASS PROVIDED WITHOUT AND IMPACT, AIR BAGS DID NOT DEPLOY. IN A PROPOMINATE VIS AND INJURIS. DAMAGE TO VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. BEAUTH HAS BEEN NOTHING. PLASS PROVIDED WITHOUT AND IMPACT, AIR BAGS DID NOT DEPLOY. BEAUTH HAS BEEN NOTHING. PLASS PROVIDED WITHOUT AND IMPACT. AIR BAGS DID NOT DEPLOY. HAVE SERVED HAS ALROWED WITHOUT AND INTO A RESIDENCE VARD, STRIKING A TREE HEAD ON AT APPROXIMATE VIS A SINGLE PROVIDED WITHOUT AND A PROPOMINATE VIS A SINGLE PROVIDED WITHOUT AND A PROPOMINATE VIS AND A						
CONSUMER WAS TRAVELING ABOUT 40MPH ON HIGHWAY AND ANOTHER VEHICLE VERED INTO RET LANE, HITTING HER READ, AND PUSHING LED TO ANOTHER LANE, VEHICLE HIT TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET HAS BEEN NOTHED. *AK WHILE DRIVING 30-35 MPH VEHICLE HIT A FIRE HYDRANT, THEN A TREE. NEITHER AIRBAG DEPLOYED, NO INJURIES, DAMAGE TO VEHICLE UNKNOWN ATTHIS TIME. IMPACT WAS MIDDLE OF ROOT OF VEHICLE. *AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION.*AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION.*AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY RIGHT XWAY. I WAS DRIVING A 1999 CHEVROLET SUBUBBAN. IS ESSEVED INTO DONCOMING TRAFFE, INTO A BESIDECE VARIO, STRIKING A TREE HAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUISTED MY VEHICLE HAVE A DIAGNOSTIC VALULATION CONDUCTED, AS! NOTHING WORDS WITH THY AIR BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIRBAG LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WORDS WITH THY AIR BAGS DID NOT DEPORTSOINAL DIPLOMANCE AND THAT MY ACCIDENT DID NOT, MEET THE CRITERIA FOR AIR BAG DEPLOYMENT, HIGHLY DISAGREE WITH GMCKES EXPLANATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMANCE AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG 3 AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH HOUGH OF HORSE THE LECK OF PROFESSIONAL DIPLOMANCE AND FORMATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMANCE AND FORMATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMANCE AND FORMATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMANCE AND FORMATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMANCE AND FORMATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOM	876094	CHEVROLET	SUBURBAN	1999	2000-12-01	
TELEPHONE POLE, AND DUAL AIRRAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET HAS SEEN NOTIFIED. *AK WHILE DRIVING 30-35 MPH VEHICLE HIT A FIRE HYDRANT, THEN A TREE. NEITHER AIRRAG DEPLOYED, NO INJURIES, DAMAGE TO VEHICLE UNKNOWN AT THIS TIME. IMPACT WAS MIDDLE OF RONT OF VEHICLE. *AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. *PLASE PROVIDE ADDITIONAL INFORMATION.* AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. *PLASE PROVIDE ADDITIONAL INFORMATION.* AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY SA MILES PER HONOR HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEDODED WITH GMC HAVE ANALI UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOYMENT. I HIGHLY DISAGREE WITH GMCES SYRLAWATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMACY AND CONCIENT. I WOULD HAVE EXPONENTED HOUSE TO BE SON THE FROM LEET FRAME RAIL. THE IMPACT ALSO WAS GREAT REOUGH TO BASIS ETHE RARS OF THE VEHICLE OF THE GROUNDA AND SET IT DOWN A FOOT TO THE LEET OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING MET DE UNABLE TO WORK, MY CONFIDENCE THIS WITH SEMPLY THE PER SON IN HEAVE AND AND SET IT DOWN A FOOT TO THE LEET OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING MET DE UNABLE TO WORK, MY CONFIDENCE THAT THIS SYSTEM WOULD ALOW MET DOWN A FOOT TO THE LEET OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING MET DE UNABLE TO WORK ANY THE EVERT THE PER AND AND THIS VEHICLE FOR AND AND THE INTERNET WHICH MY VEHICLE WITH SOME CONFIDENCE THAT THIS						
CHEVROLET SUBURBAN 1999 2000-12-01 HAS BEEN NOTIFIED. *AX WHILE DRIVING 30-95 MPN VEHICLE HIT A FIRE HYDRANT, THEN A TREE. NEITHER AIRBAG DEPLOYED, NO INJURIES. DAMAGE TO VEHICLE UNKNOWN ATTHIS TIME. IMPACT WAS MIDDLE OF FRONT OF VEHICLE. *AX VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION. *AX VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION. *AX THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY BIGHT AWAY! WAS DRIVING A 1999 CHEVROLET SRUBURBAN. IS FREVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL LUNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY. I HAVE BAGSICALLY BEEN TOLD BY GMC THAT IF THE AIRBAG LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WIRONG WITH MY AIR BAGS PER A CUSTOMER RELIATIONSHIP MANAGER AND THAT MY ACCIDENT DID NOT, MEET THE CARC OF PROFESSIONAL DIPLOMACY AND CONCERN I WOULD HAVE EXPECTED MORE FROM ONE OF THE BROUND AND SET IT DOWN A REPORT OF THE WORLD ON THE PROVIDE OF THE GROUND AND SET IT DOWN A ROTOT TO THE LET OF THE INITIAL IMPACT. THIS OF A JUST DEPLOY HAVE A DIAGNOSTIC SHALL AND SET IT DOWN A ROTOT TO THE LET OF THE INITIAL IMPACT. THIS AS ASSO LEFT ME WYTHICLE HAVE DEALERSHIP TO BAYE D ADMOSTRICE SHALL AND AND FORT EVEN PROVIDED ONE COMPLETED TO MY SATISFACTION. I EXPECTED AT LEAST AN OFFERING TO HAVE THE VEHICLE OF THE GROUND AND SET IT DOWN A PROVIDE OF THE WORLD AND A PROVIDE ONE OF THE WEHL CAN DOWN AND THE MENT OF THE WEHL CHARD AND A PROVIDE ONE OF THE WEHL CHE TO REPORT THE DOT THE WEHL CHE OF THE WITH A SHALL AND A PROVIDE ONE CONTRICTED TO MY SATISFACTION. I EXPECTED AT LEAST						HER LANE, HITTING HER HEAD-ON, AND PUSHING VEHICLE INTO ANOTHER LANE. VEHICLE HIT
WHILE DRIVING 30-35 MPH VEHICLE HIT A FIRE HYDRANT, THEN A TREE. NETTHER AIBBAG DEPLOYED, DO INJURIES, DAMAGE TO VEHICLE UNKNOWN AT THIS TIME. IMPACT WAS MIDDLE OF RONT OF VEHICLE. "AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOYED, DO INJURIES, DAMAGE TO VEHICLE UNKNOWN AT THIS TIME. IMPACT WAS MIDDLE OF RONT OF VEHICLE. "AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED, PLEASE PROVIDE ADDITIONAL INFORMATION." AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED, PLEASE PROVIDE ADDITIONAL INFORMATION." AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE VARD, STRIKING A 1989 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE VARD, STRIKING A 1989 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING THA AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE VARD, STRIKING A 1989 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE VARD, STRIKING A 1989 CHEVROLETE AND AND ATTEM. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE VARD, STRIKING A 1989 CHEVROLETE AND AND AND ATTEM. I STRIKE AND AND AND ASSOCIATION ON THE MAY BE ADIAGNOSTIC EVALUATION CONDUCTED. ASSOCIATION ON THE AND AND AND ASSOCIATION ON THE AND						TELEPHONE POLE, AND DUAL AIRBAGS DIDN'T DEPLOY. CONSUMER WAS INJURED. CHEVROLET
DEPLOYED, NO INJURIES, DAMAGE TO VEHICLE UNKNOWN AT THIS TIME. IMPACT WAS MIDDLE OF FRONT OF VEHICLE. *AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION.*AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVE DID MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE VALUATION CONDUCTED, ASI WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY, I HAVE BASICALLY BEEN TOLD BY GMC THAT IT FITE AIRRAGALIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS PER A CUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT ON DID NOT, MEET THE CRITERIA FOR AIR BAG DEPLOYMENT. I HIGHLY DISAGREE WITH GMC'S EXPLANATION AND CRITICIZE THE LACE OR PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG SAUTO CORPORATIONS. MY VEHICLE STRUCK HEAD AND AND SET IT DOWN A FOOT TO THE LEET OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME OF DEPLOY HER LEET OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME OF DEPLOY HER LEET OF THE CRITERIA FOR AIR BAG DEPLOYMENT. HER CHEET OF A LOCAL DEPLOY HER LEET OF THE CRITERIA FOR AIR BAG DEPLOYMENT THE EVENT OF THE LEET OF THE CRITERIA FOR AIR BAG DEPLOYMENT OF A LOCAL DEPLOY HER WITH DOCUMENTED INJURIES CAUSING ME OF THE BIG AT THE STATE HAS NOT DEFINATION. AND THE LEET OF THE CRITERIA FOR AIR BAG DEPLOYMENT AND AND THE LEET OF THE CRITERIA FOR AIR BAG DEPLOYMENT AND AND THE LEET OF THE CRITERIA FOR AIR BAG DEPLOYMENT AND FORCE OF THE BEAT THE STORY AND THE CRITERIA FOR AIR BAG DEPLOYMENT AND FORCE OF THE PROPERT OF THE WITH DOCUMENTED INJURIE	877320	CHEVROLET	SUBURBAN	1999	2000-12-01	HAS BEEN NOTIFIED. *AK
2001-09-04 FRONT OF VEHICLE. *AK VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTHIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION. *AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YELD MY RIGHT AWAY. I MAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE ARE BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC. THAT IF THE AIRBAGS LIGHT IS FUNCTIONING IN THE DASHOADO OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY ARE BAGS PER ACUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT ON THE WITH A READ SHOUND AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIGS AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FROM THE FIRM FAR BALL. THE IMPACT ALSO WAS GREAT PROUGHT OT RASE THE READ OF THE BIGS AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FROM THE FIRM FAR BALL. THE IMPACT ALSO WAS GREAT ENOUGH TO TRASE THE READ OF THE BIGS AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FROM LEFT FRAM FAIL. THE IMPACT ALSO WAS GREAT ENOUGH TO TRASE THE READ OF THE BIGS AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FROM LEFT FAR BALL. THE IMPACT ALSO WAS GREAT ENOUGH TO TAKE THE CRITERIA FOR AIR BAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING MY AND THE OFFICE AND THE LEFT OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING MY AND THE OFFICE AND THE LEFT OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING MY AND THE CHIEF OF THE MET TO BE AND THE LEFT OF THE WITH THE CHIEF OF						WHILE DRIVING 30-35 MPH VEHICLE HIT A FIRE HYDRANT, THEN A TREE. NEITHER AIRBAG
VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT 20MPH. UPON IMPACT, AIR BAGS DID NOT DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION.* AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER PROVIDE ADDITIONAL INFORMATION.* AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER PROVIDE PRIVE FAILED TO YILLD MY RICHT AWAY. I MAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMOUND CITE. AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY. HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE REARBAG LIGHT IS FUNCTIONING ITS FUNCTIONING OF WY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS PER A CUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT DID NOT, MEET THE CRITERIA FOR AIR BAG DEPLOYMENT. I HIGHLY DISAGREE WITH GMCIE SEX PLANATION AND CENTRE CRITICATE THE LARD AS HORD FOR PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG ADTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH BROUGH FORCE TO BE PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG ADTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH FOUNDER FORCE TO BE ROAD THE ROY LEFT FRAME RAIL. THE IMPACT ALSO WAS GREAT ENDUGH TO RASE THE REAR OF THE VEHICLE OF THE GROUND AND SET IT DOWN A FOOT TO THE LEFT OF THE INITIAL IMPACT. THIS HASA ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLES AIR BAG SYSTEM HAS DIMINISHED TO SAY THE LEAST. THIS MATTER HAS NOT BEEN HANDLED NOR COMPLETED TO MY SATISFACTION. TAKE THE PAST HAS THE SYSTEM WOULD WORK IN THE EVENT IN EDUCATION. THE WITH THE PAST I WOULD LIKE MORE INFORMATION RELATED TO FAILED AIR BAG DEPLOYMENT AND GMC CHEVY SURBURBAN. WHILE DRIVING ST MPH, THE CONTACT CRASHED INTO THE FROM THE PAST AND SUFFERED A RECALL ON THE INTERNET WHICH MY VEHICLE FAILS UNDER RELATED TO AIRBAGS. THANK Y						, and the second
DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION. *AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIRBAG LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS PER A CUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT DID NOT, MEET THE CRITERIA FOR AIR BAG DEPLOYMENT. I HIGHLY DISAGREE WITH GMCIBS EXPLANATION AND CRITICIZE THE KOOR PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG 3 AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENDUGH FORCE TO BEND THE FRONT LEFT FRAME RAIL. THE IMPACT ALSO WAS GREAT FROUGH TO RAISE THE REAR OF THE VEHICLE OF THE GROUND AND SET IT DOWN A FOOT TO THE LEFT OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLEE AIR BAG SYSTEM HAS DIMINISHED TO SAY THE LEAST. THIS MATTER HAS NOT BEEN HANDLED NOR COMPLETED TO MY SATISFACTION. I EXPECTED AT LEAST AN OFFERING TO HAVE THE VEHICLE TAKEN TO A LOCAL DEALERSHIP TO HAVE A DIAGNOSTIC EVALUATION CONDUCTED. THIS WOULD ALLOW ME TO DRIVE THE VEHICLE WITH SOME CONFIDENCE THAT THE SYSTEM WOULD WORK IN THE EVENT I NEED IT AGAIN. I AM AT A STAND STILL AND I AM POSITIVE I AM NOT THE ONLY PERSON WHO HAS HAD THIS ROBDEM IN THE PAST. I WOULD LIKE MORE INFORMATION RELATED TO FAILED AIR BAG DEPLOYMENT AND GMC CHEVY SURBURBAN. I HAVE ALSO SEEN A BECALL ON THE INTERNET WHICH MY VEHICLE FALLS UNDER RELATED TO AIRBAGS. THANK YOU FOR YOUR TIME AND THE CAUSED THAT THE CONTACT OWNS A 1999 CHEVROLET SUBURBAN. WHILE DRIVING 55 M	896346	CHEVROLET	SUBURBAN	1999	2001-09-04	FRONT OF VEHICLE. *AK
DEPLOY. DEALER HAS BEEN NOTIFIED. PLEASE PROVIDE ADDITIONAL INFORMATION. *AK THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIRBAG LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS PER A CUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT DID NOT, MEET THE CRITERIA FOR AIR BAG DEPLOYMENT. I HIGHLY DISAGREE WITH GMCIBS EXPLANATION AND CRITICIZE THE KOOR PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG 3 AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENDUGH FORCE TO BEND THE FRONT LEFT FRAME RAIL. THE IMPACT ALSO WAS GREAT FROUGH TO RAISE THE REAR OF THE VEHICLE OF THE GROUND AND SET IT DOWN A FOOT TO THE LEFT OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLEE AIR BAG SYSTEM HAS DIMINISHED TO SAY THE LEAST. THIS MATTER HAS NOT BEEN HANDLED NOR COMPLETED TO MY SATISFACTION. I EXPECTED AT LEAST AN OFFERING TO HAVE THE VEHICLE TAKEN TO A LOCAL DEALERSHIP TO HAVE A DIAGNOSTIC EVALUATION CONDUCTED. THIS WOULD ALLOW MET O DRIVE THE VEHICLE WITH SOME CONFIDENCE THAT THE SYSTEM WOULD WORK IN THE EVENT I NEED IT AGAIN. I AM AT A STAND STILL AND I AM POSITIVE I AM NOT THE ONLY PERSON WHO HAS HAD THIS ROBDEM IN THE PAST. I WOULD LIKE MORE INFORMATION RELATED TO FAILED AIR BAG DEPLOYMENT AND GMC CHEVY SURBURBAN. I HAVE ALSO SEEN A BECALL ON THE INTERNET WHICH MY VEHICLE FALLS UNDER RELATED TO AIRBAGS. THANK YOU FOR YOUR TIME AND THE FAULT OF THE CONTACT OWNS A 1999 CHEVROLET SUBURBAN. WHILE DRIVING 55 MPH,						VEHICLE MACINIVOLVED IN A EDONTAL COLLICION AT 20MBH, LIDON IMPACT, AIR RACC DID NOT
THIS COMPLAINT IS IN REGARDS TO MY RECENT MOTOR VEHICLE ACCIDENT ON MAY 8, 2003. THE OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGD IDNOT DEPILOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIRBAG LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS ACUSTOMER RELATIONSHIP MAY BABGE AND THAT MY ACCIDENT DIA NOTHING WRONG WITH MY AIR BAGS A CUSTOMER RELATIONSHIP MAY BABGE AND AIR DAY COMPORTIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FROM A JATTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FROM LIFE FRAME RAIL. THE IMPACT ALSO WAS GREAT ENOUGH TO RAISE THE REAR OF THE VEHICLE OF THE GROUND AND SET IT DOWN A FOOT TO THE LIEFT OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSIMG ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLES AIR BAG SYSTEM HAS DIMINISHED TO SAY THE LEAST. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLE TAKEN TO A LOCAL DEALERSHIP TO HAVE A DIAGNOSTIC EVALUATION CONDUCTED. THIS WOULD ALLOW ME TO DRIVE THE VEHICLE WITH SOME CONFIDENCE THAT THE SYSTEM WOULD WORK IN THE EVENT I NEED IT AGAIN. I AM AT A STAND STILL AND I AM POSITIVE I AM NOT THE ONLY PERSON WHO HAS HAD THIS PROBLEM IN THE PAST. I WOULD FAND THE NEW THIS PAST OF A DIAGNOSTIC EVALUATION CONDUCTED. THIS WOULD ALLOW ME TO DRIVE THE VEHICLE WITH SOME CONFIDENCE THAT THE SYSTEM WOULD WORK IN THE EVENT I NEED IT AGAIN. I AM AT A STAND STILL AND I AM POSITIVE I AM NOT THE ONLY PERSON WHO HAS HAD THIS PROBLEM IN THE PAST. I WOULD KING MORE INFORMATION RELATED TO SAILD AND THIS PROBLEM IN THE PAST. I WOULD KEN PAST IN WELLOW TO THE LIFE OF THE VEHICLE TO A S	9001743	CHEVBOLET	CLIDLIDDANI	1000	2001 12 29	,
OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIR BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIR BAGS LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS PER A CUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT DID NOT, MEET THE CRITER FOR AIR BAG DEPLOYMENT. I HIGHLY DISAGREE WITH GMCIS EXPLANATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG 3 AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FRONT LEET FRAME RAIL. THE IMPACT ALSO WAS GREAT ENOUGH TO RAISE THE REAR OF THE VEHICLE OF THE GROUND AND SET IT DOWN A FOOTT OT THE LEET OF THE INITIAL IMPACT. THIS HAS ALSO LEET IM EWITH DOCUMENTED INVIRIES CAUSING ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLE!S AIR BAG SYSTEM HAS DIMINISHED TO SAY THE LEAST. THIS MATTER HAS NOT BEEN HANDLED NOR COMPLETED TO MY SATISFACTION. I EXPECTED AT LEAST AN OFFERING TO HAVE THE VEHICLE TAKEN TO A LOCAL DEALERSHIP TO HAVE A DIAGNOSTIC EVALUATION CONDUCTED. THIS WOULD ALLOW ME TO DRIVE THE VEHICLE WITH SOME CONFIDENCE THAT THE SYSTEM WOULD WORK IN THE EVENT I NEED IT AGAIN. I AM AT A STAND STILL AND POSITIVE I AM NOT THE OUTLY PERSON WHO HAS HAD THIS PROBLEM IN THE PAST. I WOULD LIKE MORE INFORMATION RELATED TO FAILED AIR BAG DEPLOYMENT AND GMC CHEVY SURBURBAN. I HAVE ALSO SEEN A RECALL ON THE INTERNET WHICH MY VEHICLE FALLS UNDER RELATED TO AIRBAGS. THANK YOU FOR YOUR TIME AND CONSIDERATION.* AK 10029300 CHEVROLET SUBURBAN 1999 2003-05-08 CONSIDERATION.* AK 11"THE CONTACT OWNS A 1999 CHEVROLET SUBURBAN. WHILE DRIVING SS MPH, THE CONTACT CR	8001742	CHEVROLET	JUBURBAN	1999	2001-12-28	DEFEOT. DEALER HAS BEEN NOTHIED. FEEASE PROVIDE ADDITIONAL INFORMATION. AR
TL*THE CONTACT OWNS A 1999 CHEVROLET SUBURBAN. WHILE DRIVING 55 MPH, THE CONTACT CRASHED INTO THE FRONT END OF ANOTHER VEHICLE. THE AIR BAGS FAILED TO DEPLOY. THE CONTACT WAS SEATED IN THE PASSENGER SEAT AND SUFFERED A CONTUSION ON HER LEFT LEG AND BRUISES ON HER RIGHT LEG. THE DEALER HAS NOT INSPECTED THE VEHICLE TO DETERMINE THE CAUSE OF FAILURE. THE VEHICLE WAS DESTROYED. THE CURRENT AND FAILURE MILEAGES WERE 115,000. DEER ACCIDENT, LOST CONTROL RAN HEAD ON INTO THE CURB, HIT A SIGN. FRAME IS BENT, WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER						OTHER DRIVER FAILED TO YIELD MY RIGHT AWAY. I WAS DRIVING A 1999 CHEVROLET SRUBURBAN. I SERVED INTO ONCOMING TRAFFIC, INTO A RESIDENCE YARD, STRIKING A TREE HEAD ON AT APPROXIMATELY 35 MILES PER HOUR. I HAVE CORRESPONDED WITH GMC VIA E-MAIL UNTO NOT MY SATISFACTION. I REQUESTED MY VEHICLE HAVE A DIAGNOSTIC EVALUATION CONDUCTED, AS I WANTED TO KNOW WHY THE AIR BAGS DID NOT DEPLOY. I HAVE BASICALLY BEEN TOLD BY GMC THAT IF THE AIRBAG LIGHT IS FUNCTIONING IN THE DASHBOARD OF MY TRUCK THEN THERE IS NOTHING WRONG WITH MY AIR BAGS PER A CUSTOMER RELATIONSHIP MANAGER AND THAT MY ACCIDENT DID NOT, MEET THE CRITERIA FOR AIR BAG DEPLOYMENT. I HIGHLY DISAGREE WITH GMCIS EXPLANATION AND CRITICIZE THE LACK OF PROFESSIONAL DIPLOMACY AND CONCERN. I WOULD HAVE EXPECTED MORE FROM ONE OF THE BIG 3 AUTO CORPORATIONS. MY VEHICLE STRUCK A TREE WITH ENOUGH FORCE TO BEND THE FRONT LEFT FRAME RAIL. THE IMPACT ALSO WAS GREAT ENOUGH TO RAISE THE REAR OF THE VEHICLE OF THE GROUND AND SET IT DOWN A FOOT TO THE LEFT OF THE INITIAL IMPACT. THIS HAS ALSO LEFT ME WITH DOCUMENTED INJURIES CAUSING ME TO BE UNABLE TO WORK. MY CONFIDENCE IN THIS VEHICLE'S AIR BAG SYSTEM HAS DIMINISHED TO SAY THE LEAST. THIS MATTER HAS NOT BEEN HANDLED NOR COMPLETED TO MY SATISFACTION. I EXPECTED AT LEAST AN OFFERING TO HAVE THE VEHICLE TAKEN TO A LOCAL DEALERSHIP TO HAVE A DIAGNOSTIC EVALUATION CONDUCTED. THIS WOULD ALLOW ME TO DRIVE THE VEHICLE WITH SOME CONFIDENCE THAT THE SYSTEM WOULD WORK IN THE EVENT I NEED IT AGAIN. I AM AT A STAND STILL AND I AM POSITIVE I AM NOT THE ONLY PERSON WHO HAS HAD THIS PROBLEM IN THE PAST. I WOULD LIKE MORE INFORMATION RELATED TO FAILED AIR BAG DEPLOYMENT AND GMC CHEVY SURBURBAN. I HAVE ALSO SEEN A RECALL ON THE INTERNET
CONTACT WAS SEATED IN THE PASSENGER SEAT AND SUFFERED A CONTUSION ON HER LEFT LEG AND BRUISES ON HER RIGHT LEG. THE DEALER HAS NOT INSPECTED THE VEHICLE TO DETERMINE THE CAUSE OF FAILURE. THE VEHICLE WAS DESTROYED. THE CURRENT AND FAILURE MILEAGES WERE 115,000. DEER ACCIDENT, LOST CONTROL RAN HEAD ON INTO THE CURB, HIT A SIGN. FRAME IS BENT, WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER	10029300	CHEVROLET	SUBURBAN	1999	2003-05-08	
AND BRUISES ON HER RIGHT LEG. THE DEALER HAS NOT INSPECTED THE VEHICLE TO DETERMINE THE CAUSE OF FAILURE. THE VEHICLE WAS DESTROYED. THE CURRENT AND FAILURE MILEAGES WERE 115,000. DEER ACCIDENT, LOST CONTROL RAN HEAD ON INTO THE CURB, HIT A SIGN. FRAME IS BENT, WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER						
THE CAUSE OF FAILURE. THE VEHICLE WAS DESTROYED. THE CURRENT AND FAILURE MILEAGES WERE 115,000. DEER ACCIDENT, LOST CONTROL RAN HEAD ON INTO THE CURB, HIT A SIGN. FRAME IS BENT, WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER						
10194121 CHEVROLET SUBURBAN 1999 2007-06-24 WERE 115,000. DEER ACCIDENT, LOST CONTROL RAN HEAD ON INTO THE CURB, HIT A SIGN. FRAME IS BENT, WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER						
DEER ACCIDENT, LOST CONTROL RAN HEAD ON INTO THE CURB, HIT A SIGN. FRAME IS BENT, WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER	1010/121	CHEVIDOLET	CHIDHIDDAN	1000	2007.06.24	
WINDSHIELD IS SHATTERED AND CAVED IN, FRONT PUSH GUARD IS BENT, AND FRONT PASSENGER	10134121	CHEVROLET	JUBUKBAN	1333	2007-00-24	
	10287421	CHEVROLFT	SUBURBAN	1999	2009-09-25	

	1	1	1		
10372658	CHEVROLET	SUBURBAN	1999	2010-12-21	TL* THE CONTACT OWNS A 1999 CHEVROLET SUBURBAN. THE CONTACT STATED THAT WHILE DRIVING APPROXIMATELY 40 MPH, HE CRASHED INTO THE PASSENGER SIDE OF ANOTHER VEHICLE. THE AIR BAGS DID NOT DEPLOY. THE CONTACT AND ANOTHER PASSENGER SUSTAINED MINOR ABRASIONS AND INJURIES TO THE NECK AND BACK. THE DRIVER OF THE SECOND VEHICLE WAS INJURED BUT THE EXTENT OF THE INJURIES WAS UNKNOWN. A POLICE REPORT WAS AVAILABLE. THE VEHICLE WAS TOWED TO AN INDEPENDENT MECHANIC WHERE THE CONTACT WAS INFORMED THAT THE VEHICLE WAS DEEMED AS DESTROYED. THE FAILURE MILEAGE WAS APPROXIMATELY 133,000. UPDATED 03/03/11
					THE VEHECLE WAS TRAVELING APPROX 40 MPH WHEN IT HIT BLACK ICE ANDM SLIDE OFF THE ROAD AND HIT A BIG ROCK ON THE PASSENGER SIDE FRONT. THE PASSENGER SIDE FRONT BODY AND AXLE WAS PUSHED BACK APPROX 6 TO 8". NIETHER AIR BAG OPENED PASSENGER OR DRIVER. THE PASSENGER MY WIFE SUFFERED A BROKEN BACK. THE VEHECLE WAS TOTALED BY THE INSURANCE. ONE REASON WE BOUGHT THE CHEVROLET TAHOE WAS BECAUSE OF THE DUEL AIR BAG. I FEEL THAT THE SEVERITY OF THE ACCIDENT THE AIR BAGS SHOULD HAVE OPENED. I HAVE TAKEN PICTURES AND STATE FARM INSURANCE IS ALSO INVESTIGATING THE ACCIDENT FOR THE
704617 757392		TAHOE TAHOE	1999 1999	1999-03-04 2002-01-22	FAILED AIR BAGS. DRIVERS AIRBAG FAILED TO DEPLOY IN A FRONT END ACCIDENT. *AK
737392	CHEVROLET	TANCE	1999	2002-01-22	THIS WAS A VERY HEAVY FRONT END COLLISION. THE VISUAL DAMMAGE EST. IS 10,000 DOLLARS AND STILL RISING THEY DO NOT HAVE THE INTERNAL DAMAGE EST. I CALLED GM AND FILED A FORMAL COMPLAINT. THEY TOLD ME THAT THEY WERE VERY BUSY AND DID NOT HAVE TIME TO INVESTIGATE THIS FAILURE. THEY ALSO TOLD ME THAT THIS WOULD COST THE TO MUCH MONEY TO DO AN INVESTIGATION. THE REP FROM GM TOLD ME THAT THEY COULD TELL IF THE WRECK WAS BAD ENOUGH BY THE DESCRIPTION OF THE WRECK OVER THE PHONE WITH OUT EVEN SEEING THE WRECK. THE DALLAS FIRE DEPARTMENT, DALLAS POLICE DEPARTMENT, TOW TRUCK DRIVER AND HUFFINES CHEVROLET WHICH IS A CERTIFIED CHEVROLET BODY SHOP SAID THAT THIS WAS WAY TO MUCH DAMAGE TO THE FRONT END AND THEY SHOULD HAVE WENT OFF. BUT COPRORATE GM SAID THAT IT WAS NOT AND THEY COULD TELL THAT WITHOUT SEEING THE VEHICLE. GM ALSO TOLD ME THAT THE OTHER VEHICLE IN THE ACCIDENT TOOK ALL THE IMPACT, WITHOUT EVEN SEEING THE VEHICLES HOW WOULD THEY NOW THIS? I STILL HAVE 10,000 DOLLARS OF FRONT END DAMAGE TO MY VEHICLE AND THAT IS WAY TO MUCH IF THE OTHER OTHER VEHICLE TOOK ALL THE IMPACT. THEY REPEATEDLY TOLD ME THAT IT WAS OK THAT THEY DID NOT GO OFF BECAUSE THE REST OF THE SAFTEY EQUIPMENT WORKED "I.E. SEATBELTS, CRUMPLE ZONES" BUT THAT DOES NOT CHANGE THE FACT THAT THE AIRBAG SYSTEM DID NOT WORK AND THIS WOULD HAVE KEPT MY 7 MONTH PREGNANT WIFE FROM HITTING THE DASH BOARD! IF YOU HAVE ANY QUESTION I WILL BE MORE THAN HAPPY TO ANSWER THEM LARGE OR SMALL. THANK
761485	CHEVROLET	TAHOE	1999	2002-04-19	YOU!*AK WHILE DRIVING DOWN THE ROAD AT 40 MPH ANOTHER VEHICLE RAN A STOP SIGN, CONSUMER
860103	CHEVROLET	ТАНОЕ	1999	2000-04-08	HIT OTHER VEHICLE DIRECTLY IN THE SIDE OF CAR. UPON IMPACT, AIR BAGS DID NOT DEPLOY. CONSUMER FELT AIR BAGS SHOULD HAVE DEPLOYED. *AK WHILE TRAVELING AT 45 MPH ANOTHER VEHICLE PULLED OUT IN FRONT OF CONSUMER'S VEHICLE
863306	CHEVROLET	TAHOE	1999		RESULTING IN AN ACCIDENT. UPON IMPACT, AIR BAGS DID NOT DEPLOY AT ANY TIME. ALSO, ABS LOCKED UP. PLEASE PROVIDE FURTHER INFORMATION. *AK CONSUMER WAS TRAVELING 55MPH ON HIGHWAY AND ANOTHER VEHICLE RAN IN FRONT. AND
878233	CHEVROLET	ТАНОЕ	1999	2000-12-29	CONSUMER'S VEHICLE HIT OTHER VEHICLE BROADSIDE. UPON IMPACT, AIRBAGS DIDN'T GO OFF.*AK
997011	CHEVIDOLET	TAUOF	1000	2001-04-13	CONSUMER WAS TRAVELING ABOUT 30MPH ON HIGHWAY AND WITHOUT PRIOR WARNING FRONT WNT INTO SHOULDERS OF A STEEP HILL. 45 DEGREE ANGLE, AND VEHICLE HIT A TREE.
887011	CHEVROLET	TAHOE	1999	2001-04-13	UPON IMPACT, DUAL BAGS DIDN'T GO OFF. DEALERSHIP WAS AWARE OF PROBLEM.*AK VEHICLE HIT A TREE. UPON IMPACT, SEAT BELT DID NOT RETRACT, AND AIR BAGS DID NOT
887171	CHEVROLET	TAHOE	1999	2000-12-27	DEPLOY, RESULTING IN INJURIES.*AK FRONT COLLISION AT 25-30 MPH, AND NEITHER AIRBAG DEPLOYED, CONSUMER SUFFERED
8006232	CHEVROLET	TAHOE	1999	2002-03-13	MINOR INJURIES.*AK
10040265	CHEVROLET	TAHOE	1999	2003-09-09	WHILE DRIVING 40 MPH VEHICLE WAS HIT IN THE FRONT CENTER. BOTH FRONTAL AIR BAGS DID NOT DEPLOY. *AK
					DURING A FRONT END COLLISION WHILE DRIVING AT 55 MPH FRONT AIR BAGS DID NOT DEPLOY. THREE PASSENGERS SUSTAINED MINOR INJURIES. CONSUMER HAD THE VEHICLE TOWED TO
10074130	CHEVROLET	TAHOE	1999	2004-04-27	DEALERSHIP FOR INSPECTION. *AK
10110864	CHEVROLET	ТАНОЕ	1999	2004-11-15	THE VEHICLE'S AIR BAGS DID NOT DEPLOY DURING A FRONTAL COLLISION. *NM COUNCIL FOR THE CONSUMER STATED THAT AIR BAGS NEED TO BE TESTED AT CHEVROLET'S EXPENSE. *TC *JB
10265716	CHEVROLET	ТАНОЕ	1999	2009-02-15	WHILE DRIVING MY 99 TAHOE DOWN A 4 LANE ROAD, A DRUNK HAD PULLED OUT INFRONT OF ME. I HAD SLAMMED ON MY BRAKES AND SWERVED TO AVOID HIM BUT STILL HIT HIM PRETTY HARD IN HIS REAR QUARTER PANEL. AS A RESULT OF THE ACCIDENT, I HAD SUFFERED A DOUBLE HEMATOMA TO MY BRAIN AND HAD BRAIN SURGERY TO STAY ALIVE. MY COMPLAINT WITH MY TAHOE IS 1) MY AIRBAG IN MY STEERING WHEEL DID NOT DEPLOY. I THINK IF IT DID, MY INJURY WOULD HAVE BEEN AVOIDED. 2) I QUESTION THE STOPPING ABILITY IF MY ANTI DIVE FRONT BRAKES. I WAS ON THE BRAKES HARD WITH THE VEHICLE NOSING DOWN BUT I THINK MY STOPPING DISTANCE SHOULD HAVE BEEN SHORTER. *TR

	-	1		_	
					TL*THE CONTACT OWNS A 1999 CHEVROLET TAHOE. THE CONTACT WAS DRIVING APPROXIMATELY 15 TO 20 MPH ON NORMAL ROAD CONDITIONS AND UNEXPECTEDLY, THE OPPOSING VEHICLE CRASHED INTO THE FRONT END OF THE VEHICLE WHICH RESULTED IN A HEAD ON COLLISION. THE POLICE AND AMBULANCE WERE CALLED TO THE SCENE. THE CONTACT SUSTAINED SEVERE INJURIES. THE AIR BAG FAILED TO DEPLOY WITH THE MASSIVE LEVEL OF IMPACT. THE VEHICLE WAS COMPLETELY DESTROYED. THE VEHICLE WAS TOWED TO A COLLISION
					CENTER. THE CONTACT HAD CONCERN OF THE SAFETY RISK INVOLVED. THE FAILURE MILEAGE WAS
10299900	CHEVROLET	TAHOE	1999	2010-01-10	141,000.
10350098	CHEVROLET	таное	1999	2009-02-17	I HAVE A 99 TAHOE THAT I WAS INVOLVED IN AN ACCIDENT. I HIT A CAR WHILE DOING 40MPH THAT HAD PULLED OUT INFRONT OF ME. MY AIR BAGS DIDN'T DEPLOY AND MY SAFETY BELT DIDN'T KEEP ME FROM HITTING THE STEERING WHEEL HARD. UPON REVIEW OF MY SAFETY BELT, I NOTICED THAT IT IS ROUTED INCORRECTLY AT THE TOP HOLDER. IT BINDS ON ITSELF PREVENTING IT FROM RETRACTING. MY PASSENGER SIDE IS ROUTED CORRECTLY AND WORKS PERFECTLY. I SUFFERED A BRAIN INJURY BECAUSE OF THIS AND AM QUITE CONCERNED. *TR
					TL* THE CONTACT OWNED A 1999 CHEVROLET TAHOE. WHILE DRIVING 35 MPH, THE CONTACT HAD A HEAD ON COLLISION WITH A LIGHT POLE. THE AIR BAGS DID NOT DEPLOY. THERE WERE NO WARNING INDICATORS ILLUMINATED. THE CONTACT WAS INURED AND RECEIVED MEDICAL ATTENTION. A POLICE REPORT WAS FILED. THE VEHICLE WAS TOTALED AND TOWED TO THE CONTACT'S RESIDENCE. AN UNKNOWN DEALER WAS MADE AWARE OF THE FAILURE, BUT DID NOT ASSIST. THE VEHICLE WAS NOT DIAGNOSED. THE MANUFACTURER WAS NOT MADE AWARE OF THE
11203728	CHEVROLET	TAHOE	1999	2019-04-20	FAILURE. THE FAILURE MILEAGE WAS UNKNOWN.
859422	CHEVROLET	TRACKER	1999	2000-03-28	VEHICLE REAR ENDED ANOTHER VEHICLE AT 25 MPH. UPON IMPACT, BOTH AIR BAGS FAILED TO DEPLOY. DEALER /MANUFACTURER WERE NOT CONTACTED AT THIS TIME. *AK CONSUMER'S WIFE WAS TRAVELING ABOUT 35MPH ON THE HIGHWAYAND ANOTHER VEHICLE
					DIDN'T YIELD AND VEERED INTO HER VEHICLE, AND FORCE HER OFF THE ROAD. THEN SHE WENT
865216	CHEVROLET	TRACKER	1999	2000-06-27	INTO A UTILITY POLE. UPON IMPACT, AIR BAGS DID NOT DEPLOY. *AK ALSO HORN IS DIFFICULT TO LOCATE ON THE STEERING WHEEL. *YH
003210	OHE THOSE I	TTO CONCEN	2333	2000 00 27	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION WITH A DOGE RAM PICK UP AT A IMPACT OF 30-
868967	CHEVROLET	TRACKER	1999	2000-08-25	35 MPH, AND AIR BAGS DIDNOT DEPOLY. DEALER NOTIFIED. FEEL FREE TO PROVIDE ANY FURTHER DETAILS. *AK
000907	CHEVROLET	IRACKER	1999	2000-08-23	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION BETWEEN 35-40 MPH, AND BOTH FRONTAL AIR
	01151150155	TD 4 01/ED	1000		BAGS DID NOT DEPLOY. DEALER / MANUFACTURER WERE NOTIFIED. FEEL FREE TO PROVIDE ANY
899309	CHEVROLET	TRACKER	1999	2001-11-10	FURTHER INFORMATION CONCERNING THIS MATTER. *AK WE CONTACTED GMC CUSTOMER SERVICE (VICTOR JOHNSON) AND REQUESTED AN
706419	GMC	YUKON	1999	1999-04-12	INVESTIGATION. GMC HAS NOW TOLD US THAT SINCE NO ONE WAS FATALLY INJURED THERE WILL BE NO INVESTIGATION. HOW CAN THEY DO THIS? MY WIFE HAS BEEN INJURED - PROBABLY PERMANENTLY- AND WE WANT TO KNOW WHY THEY DID NOT DEPLOY - AS THIS WAS A DIRECT FRONTAL IMPACT. I BELIEVE THAT THE MANUFACTURER HAS AN OBLIGATION TO US AND IS MERELY PLAYING A GAME AT THIS POINT. IS IT IN OUR BEST INTEREST TO HIRE AN ATTORNEY ON THE MATTER OR WHAT SHOULD WE DO? *AK OWNER APPLIED BRAKES AND THE VEHICLE KEPT GOING AND HIT ANOTHER VEHICLE. UPON IMPACT, NEITHER DRIVER'S SIDE NOR PASSENGER'S SIDE AIRBAGS DEPLOYED. DEALER HAS SEEN
853931	GMC	YUKON	1999		VEHICLE. *AK
862202	GMC	YUKON	1999	2000-05-17	VEHICLE WAS INVOLVED IN A FRONTAL COLLISION AT APPROXIMATELY 45 MPH WITH ANOTHER VEHICLE. UPON IMPACT, BOTH AIR BAGS FAILED TO DEPLOY. DEALER NOTIFIED. *AK CONSUMER INVOLVED IN AN ACCIDENT, REARENDED ANOTHER VEHICLE. VEHICLE TRAVELING AT
					APPROXIMATELY 50 MPH, AND AIR BAGS DID NOT DEPLOY. PLEASE FILL IN ANY ADDITIONAL
880890 8007774	GMC ISUZU	YUKON AMIGO	1999 1999	2001-02-01 2002-01-25	INFORMATION. *AK IN A CAR CRASH AIRBAGS DID NOT DEPLOY. *AK
	1.520		2333		CONSUMER WAS GOING AT ABOUT 55 AND ANOTHER VEHICLE HIT CONSUMER'S VEHICLE AT ABOUT 85 MPH . CONSUMER'S VEHICLE, IN TURN, HIT A UTILITY VEHICLE, AND WENT INTO A GAURDRAIL. UPON IMPACT, AIRBAGS DIDN'T DEPLOY. CONSUMER'S VEHICLE WAS TOTALLED.
862789	ISUZU	RODEO	1999	2000-05-19	*AK VEHICLE WAS INVOLVED IN A DIRECT FRONTAL IMPACT AT 35MPH. UPON IMPACT, AIR BAGS DID
895855	ISUZU	RODEO	1999	2001-08-10	NOT DEPLOY. PLEASE PROVIDE ADDITIONAL INFORMATION.*AK THE VEHICLE WENT AIRBORNE AND LANDED ON THE FRONT END AND THE AIR BAGS FAILED TO
10009019	ISUZU	RODEO	1999		DEPLOY.*JB
10019881	ISUZU	RODEO	1999		WHEN THE BRAKES WERE APPLIED, THE REAR OF THE VEHICLE SLID, AS A RESULT, THE CONSUMER REAR ENDED ANOTHER VEHICLE AND NONE OF THE AIRBAGS DEPLOYED. *JB
10044700	ICI IZ''	DODEO	1000	2002 40 27	WHILE DRIVING AT 60 MPH, HIT A DEER, AND NEITHER OF THE AIR BAGS DEPLOYED. DRIVER WORE
10186592	ISUZU	RODEO	1999	2003-10-27	THE SEAT BELT. *AK TL*- THE CONTACT OWNS A 1999 ISUZU RODEO, AND STATED THAT WHILE DRIVING ON THE ROAD AT 30 MPH THE VEHICLE IN FRONT OF THE CONTACT'S VEHICLE SLAMMED THE BRAKES SUDDENLY, CAUSING THE CONTACT TO DO THE SAME. THE CONTACT STATED THAT THE VEHICLE HAD SEVERE DAMAGE IN THE FRONT. UPON IMPAQCT, THE AIRBAGS DID NOT DEPLOY. THERE WERE NO WARNING LIGHTS CONCERNING THE AIRBAGS BEFORE AND SUBSEQUENT TO THE ACCIDENT. THE CONTACT COULD PROVIDE PICTURE IF NEEDED. THE FAILURE MILEAGE WAS 96,371 MILES. *AK
-0100JJL	13020		1333	2007 03-30	TELESCOPE WAS 30,371 WILLS. AN